

KOYAMA[®]

SUSPENSION PARTS

CATÁLOGO





Ing. Ito Koyama

Guardián de la Visión y Calidad KOYAMA

Los amortiguadores forman parte de lo que se denomina seguridad activa del vehículo y su principal función es mantener en contacto permanente el neumático del vehículo a la pista, un amortiguador en mal estado aumenta la distancia de frenado y nos puede hacer perder el control en cualquier momento especialmente en las curvas.

La principal función de los amortiguadores no es que estemos más o menos cómodos en nuestro vehículo o que notemos menos los baches e irregularidades en las pistas, es nuestra seguridad.

Cuando el amortiguador está demasiado rígido, aunque haya un aumento de la estabilidad, se reduce el confort, mientras que si está demasiado blando podemos perder el control del vehículo. Por eso es tan importante usar el amortiguador adecuado y mantenerlos siempre en buen estado, tomando en cuenta que el excesivo desgaste de los mismos puede poner en serio compromiso nuestra seguridad y la pérdida de confort.

Para mantener el equilibrio del vehículo siempre se recomienda cambiar los resortes y amortiguadores derecho e izquierdo del mismo eje tanto delantero como posterior para mantener una buena sensación de manejo.

Así como es muy importante mantener en buenas condiciones nuestros amortiguadores y resortes es bueno tener los trapecios, rótulas y terminales en perfecto estado para mantener una dirección sólida y sin desviaciones.

Una pieza en mal estado también produce desgaste a las piezas que trabajan con ella, así como la dirección en mal estado produce entre otros problemas un desgaste importante de los neumáticos. Cuando se utilicen trapecios y rótulas de dirección nuevas es necesario alinear el vehículo.

INDICE

AMORTIGUADORES	1
RESORTES	75
PALIERES, COPAS Y SEMIEJES	101
EJE COMPLETO	102
COPA DE PALIER	102
PALIER	105
TRICETAS	108
BOCAMAZAS	123
DIRECCIÓN	155
ESTABILIZADORES	156
RACK END	162
RACK UNIVERSAL	168
ROTULAS	169
TERMINALES	176
TRAPECIOS Y BOCINAS	182
BOCINAS	183
TRAPECIOS	185
CREMALLERAS DE DIRECCIÓN	209

1

Especialistas en:

AMORTIGUADORES



o **KOYAMA**
SUSPENSION PARTS


<https://ikoyama.com/img/724580413L.png>
[https://ikoyama.com/img/724580413L\(2\).png](https://ikoyama.com/img/724580413L(2).png)

BYD F0 10/UP

AMORTIGUADOR DEL LH 9250581

724580413L
<https://ikoyama.com/img/724580413R.png>
[https://ikoyama.com/img/724580413R\(2\).png](https://ikoyama.com/img/724580413R(2).png)

BYD F0 10/UP

AMORTIGUADOR DEL RH 9250580

724580413R
<https://ikoyama.com/img/622380210.png>
[https://ikoyama.com/img/622380210\(2\).png](https://ikoyama.com/img/622380210(2).png)

BYD F0 10/UP

AMORTIGUADOR POST RH LH 9130466

622380210
<https://ikoyama.com/img/1061001036.png>
[https://ikoyama.com/img/1061001036\(2\).png](https://ikoyama.com/img/1061001036(2).png)

BYD F3 05/17

AMORTIGUADOR DEL LH 1061001036

1061001036
<https://ikoyama.com/img/1061001037.png>
[https://ikoyama.com/img/1061001037\(2\).png](https://ikoyama.com/img/1061001037(2).png)

BYD F3 05/17

AMORTIGUADOR DEL RH 1061001037

1061001037
<https://ikoyama.com/img/F32915100.png>
[https://ikoyama.com/img/F32915100\(2\).png](https://ikoyama.com/img/F32915100(2).png)

BYD F3 05/UP

AMORTIGUADOR POST RH LH F32915100

F32915100
<https://ikoyama.com/img/F32905200.png>
[https://ikoyama.com/img/F32905200\(2\).png](https://ikoyama.com/img/F32905200(2).png)

BYD F3 18/UP

AMORTIGUADOR DEL LH F32905200

F32905200
<https://ikoyama.com/img/F32905100.png>
[https://ikoyama.com/img/F32905100\(2\).png](https://ikoyama.com/img/F32905100(2).png)

BYD F3 18/UP

AMORTIGUADOR DEL RH F32905100

F32905100

<https://ikoyama.com/img/G5147L.png>
CHANGAN ALSVIN 18/UP

[https://ikoyama.com/img/G5147L\(2\).png](https://ikoyama.com/img/G5147L(2).png)

AMORTIGUADOR DEL LH G5147L

G5147L



<https://ikoyama.com/img/G5147R.png>
CHANGAN ALSVIN 18/UP



[https://ikoyama.com/img/G5147R\(2\).png](https://ikoyama.com/img/G5147R(2).png)

AMORTIGUADOR DEL RH G5147R

G5147R



<https://ikoyama.com/img/G5148RL.png>
CHANGAN ALSVIN 18/UP

[https://ikoyama.com/img/G5148RL\(2\).png](https://ikoyama.com/img/G5148RL(2).png)

AMORTIGUADOR POST RH LH G5148

G5148RL

<https://ikoyama.com/img/S32070C-2904100.png> [https://ikoyama.com/img/S32070C-2904100\(2\).png](https://ikoyama.com/img/S32070C-2904100(2).png)

CHANGAN CS15 16/UP

AMORTIGUADOR DEL LH S32070C-2904100

S32070C-2904100

<https://ikoyama.com/img/S32070C-2904200.png> [https://ikoyama.com/img/S32070C-2904200\(2\).png](https://ikoyama.com/img/S32070C-2904200(2).png)
CHANGAN CS15 16/UP

AMORTIGUADOR DEL RH S32070C-2904200

S32070C-2904200



<https://ikoyama.com/img/S32070C-2915010.png> [https://ikoyama.com/img/S32070C-2915010\(2\).png](https://ikoyama.com/img/S32070C-2915010(2).png)
CHANGAN CS15 16/UP

AMORTIGUADOR POST RH LH S32070C-2915010

S32070C-2915010



<https://ikoyama.com/img/2904200W01.png>
CHANGAN CS35 13/18



[https://ikoyama.com/img/2904200W01\(2\).png](https://ikoyama.com/img/2904200W01(2).png)

AMORTIGUADOR DEL LH 2904200W01

2904200W01

<https://ikoyama.com/img/2904100W01.png> [https://ikoyama.com/img/2904100W01\(2\).png](https://ikoyama.com/img/2904100W01(2).png)
CHANGAN CS35 13/18

AMORTIGUADOR DEL RH 2904100W01

2904100W01



<https://ikoyama.com/img/2915010W01.png>

[https://ikoyama.com/img/2915010W01\(2\).png](https://ikoyama.com/img/2915010W01(2).png)

CHANGAN CS35 13/18

2915010W01

AMORTIGUADOR POST RH LH 2915010W01



<https://ikoyama.com/img/2904100AW01.png>

[https://ikoyama.com/img/2904100AW01\(2\).png](https://ikoyama.com/img/2904100AW01(2).png)

CHANGAN CS35 PLUS 19/UP

2904100AW01

AMORTIGUADOR DEL LH 2904100AW01



<https://ikoyama.com/img/2904200AW01.png>

[https://ikoyama.com/img/2904200AW01\(2\).png](https://ikoyama.com/img/2904200AW01(2).png)

CHANGAN CS35 PLUS 19/UP

2904200AW01

AMORTIGUADOR DEL RH 2904200AW01



<https://ikoyama.com/img/G1241L.png>

[https://ikoyama.com/img/G1241L\(2\).png](https://ikoyama.com/img/G1241L(2).png)

CHANGAN HONOR 11/UP

G1241L

AMORTIGUADOR DEL LH G1241L



<https://ikoyama.com/img/G1241R.png>

[https://ikoyama.com/img/G1241R\(2\).png](https://ikoyama.com/img/G1241R(2).png)

CHANGAN HONOR 11/UP

G1241R

AMORTIGUADOR DEL RH G1241R



<https://ikoyama.com/img/H1890RL.png>

[https://ikoyama.com/img/H1890RL\(2\).png](https://ikoyama.com/img/H1890RL(2).png)

CHANGAN HONOR 11/UP

H1890RL

AMORTIGUADOR POST RH LH H1890

<https://ikoyama.com/img/2904100CA01.png>

[https://ikoyama.com/img/2904100CA01\(2\).png](https://ikoyama.com/img/2904100CA01(2).png)

CHANGAN SUPERVAN 16/UP DFSK C37 16/UP

2904100CA01

AMORTIGUADOR DEL LH 2904100CA01

<https://ikoyama.com/img/2904200CA01.png>

[https://ikoyama.com/img/2904200CA01\(2\).png](https://ikoyama.com/img/2904200CA01(2).png)

CHANGAN SUPERVAN 16/UP DFSK C37 16/UP

2904200CA01

AMORTIGUADOR DEL RH 2904200CA01

<https://ikoyama.com/img/J432905010.png>

[https://ikoyama.com/img/J432905010\(2\).png](https://ikoyama.com/img/J432905010(2).png)

CHERY ARRIZO 3 11/21

J432905010

AMORTIGUADOR DEL LH J432905010

<https://ikoyama.com/img/J432905020.png>

[https://ikoyama.com/img/J432905020\(2\).png](https://ikoyama.com/img/J432905020(2).png)

CHERY ARRIZO 3 11/21

J432905020

AMORTIGUADOR DEL RH J432905020



<https://ikoyama.com/img/J432915010.png>

[https://ikoyama.com/img/J432915010\(2\).png](https://ikoyama.com/img/J432915010(2).png)

CHERY ARRIZO 3 11/21

J432915010

AMORTIGUADOR POST RH LH J432915010

<https://ikoyama.com/img/J602905010.png>

[https://ikoyama.com/img/J602905010\(2\).png](https://ikoyama.com/img/J602905010(2).png)

CHERY ARRIZO 5 17/UP

J602905010

AMORTIGUADOR DEL LH J602905010

<https://ikoyama.com/img/J602905020.png>

[https://ikoyama.com/img/J602905020\(2\).png](https://ikoyama.com/img/J602905020(2).png)

CHERY ARRIZO 5 17/UP

J602905020

AMORTIGUADOR DEL RH J602905020

<https://ikoyama.com/img/J602915010.png>

[https://ikoyama.com/img/J602915010\(2\).png](https://ikoyama.com/img/J602915010(2).png)

CHERY ARRIZO 5 17/UP

J602915010

AMORTIGUADOR POST RH LH J602915010



<https://ikoyama.com/img/96424026.png>

[https://ikoyama.com/img/96424026\(2\).png](https://ikoyama.com/img/96424026(2).png)

CHERY QQ 1.1 16V 2011

96424026

AMORTIGUADOR DEL LH(10)



<https://ikoyama.com/img/96424025.png>

[https://ikoyama.com/img/96424025\(2\).png](https://ikoyama.com/img/96424025(2).png)

CHERY QQ 1.1 16V 2011

96424025

AMORTIGUADOR DEL RH(10)

<https://ikoyama.com/img/J692905010.png>
[https://ikoyama.com/img/J692905010\(2\).png](https://ikoyama.com/img/J692905010(2).png)

CHERY TIGGO 2 16/UP

J692905010

AMORTIGUADOR DEL LH J692905010

<https://ikoyama.com/img/J692905020.png>
[https://ikoyama.com/img/J692905020\(2\).png](https://ikoyama.com/img/J692905020(2).png)

CHERY TIGGO 2 16/UP

J692905020

AMORTIGUADOR DEL RH J692905020


<https://ikoyama.com/img/J692915010.png>
[https://ikoyama.com/img/J692915010\(2\).png](https://ikoyama.com/img/J692915010(2).png)

CHERY TIGGO 2 16/UP

J692915010

AMORTIGUADOR POST RH LH J692915010

<https://ikoyama.com/img/T112905010.png>
[https://ikoyama.com/img/T112905010\(2\).png](https://ikoyama.com/img/T112905010(2).png)

CHERY TIGGO 3 10/22

T112905010

AMORTIGUADOR DEL LH T112905010

<https://ikoyama.com/img/T112905020.png>
[https://ikoyama.com/img/T112905020\(2\).png](https://ikoyama.com/img/T112905020(2).png)

CHERY TIGGO 3 10/22

T112905020

AMORTIGUADOR DEL RH T112905020

<https://ikoyama.com/img/T112915010.png>
[https://ikoyama.com/img/T112915010\(2\).png](https://ikoyama.com/img/T112915010(2).png)

CHERY TIGGO 3 10/22

T112915010

AMORTIGUADOR POST RH LH T112915010


<https://ikoyama.com/img/T152905010.png>
[https://ikoyama.com/img/T152905010\(2\).png](https://ikoyama.com/img/T152905010(2).png)

CHERY TIGGO 7 18/UP

T152905010

AMORTIGUADOR DEL LH T152905010

<https://ikoyama.com/img/T152905020.png>
[https://ikoyama.com/img/T152905020\(2\).png](https://ikoyama.com/img/T152905020(2).png)

CHERY TIGGO 7 18/UP

T152905020

AMORTIGUADOR DEL RH T152905020



<https://ikoyama.com/img/T152915010.png>

[https://ikoyama.com/img/T152915010\(2\).png](https://ikoyama.com/img/T152915010(2).png)

CHEVY TIGGO 7 18/UP

AMORTIGUADOR POST RH LH T152915010

T152915010



<https://ikoyama.com/img/96586885.png>

[https://ikoyama.com/img/96586885\(2\).png](https://ikoyama.com/img/96586885(2).png)

CHEVROLET AVEO SAIL KALOS 06/UP

AMORTIGUADOR DEL LH 333418

96586885



<https://ikoyama.com/img/96586886.png>

[https://ikoyama.com/img/96586886\(2\).png](https://ikoyama.com/img/96586886(2).png)

CHEVROLET AVEO SAIL KALOS 06/UP

AMORTIGUADOR DEL RH 333417

96586886



<https://ikoyama.com/img/96408735.png>

[https://ikoyama.com/img/96408735\(2\).png](https://ikoyama.com/img/96408735(2).png)

CHEVROLET AVEO SAIL KALOS 06/UP

AMORTIGUADOR POST RH LH 343423

96408735

<https://ikoyama.com/img/95948811.png>

[https://ikoyama.com/img/95948811\(2\).png](https://ikoyama.com/img/95948811(2).png)

CHEVROLET CAPTIVA 07/15

AMORTIGUADOR DEL LH 335845

95948811

<https://ikoyama.com/img/95948812.png>

[https://ikoyama.com/img/95948812\(2\).png](https://ikoyama.com/img/95948812(2).png)

CHEVROLET CAPTIVA 07/15

AMORTIGUADOR DEL RH 335844

95948812



<https://ikoyama.com/img/96626214.png>

[https://ikoyama.com/img/96626214\(2\).png](https://ikoyama.com/img/96626214(2).png)

CHEVROLET CAPTIVA 07/15

AMORTIGUADOR POST RH LH CORTO 345084

96626214



<https://ikoyama.com/img/25995943.png>

[https://ikoyama.com/img/25995943\(2\).png](https://ikoyama.com/img/25995943(2).png)

CHEVROLET CAPTIVA 07/15

AMORTIGUADOR POST RH LH LARGO

25995943

<https://ikoyama.com/img/23577933.png>

[https://ikoyama.com/img/23577933\(2\).png](https://ikoyama.com/img/23577933(2).png)

CHEVROLET CAPTIVA 20/UP

23577933

AMORTIGUADOR DEL LH 23577933

<https://ikoyama.com/img/23577934.png>

[https://ikoyama.com/img/23577934\(2\).png](https://ikoyama.com/img/23577934(2).png)

CHEVROLET CAPTIVA 20/UP

23577934

AMORTIGUADOR DEL RH 23577934



<https://ikoyama.com/img/333831.png>

[https://ikoyama.com/img/333831\(2\).png](https://ikoyama.com/img/333831(2).png)

CHEVROLET CORSA CHEVY TAXI 98/UP

333831

AMORTIGUADOR DEL RH LH 333831



<https://ikoyama.com/img/343265.png>

[https://ikoyama.com/img/343265\(2\).png](https://ikoyama.com/img/343265(2).png)

CHEVROLET CORSA CHEVY TAXI 98/UP

343265

AMORTIGUADOR POST RH LH 343265

<https://ikoyama.com/img/13331986.png>

[https://ikoyama.com/img/13331986\(2\).png](https://ikoyama.com/img/13331986(2).png)

CHEVROLET CRUZE 09/16

13331986

AMORTIGUADOR DEL LH 339382



<https://ikoyama.com/img/13279328.png>

[https://ikoyama.com/img/13279328\(2\).png](https://ikoyama.com/img/13279328(2).png)

CHEVROLET CRUZE 09/16

13279328

AMORTIGUADOR DEL RH 339381

<https://ikoyama.com/img/13279251.png>

[https://ikoyama.com/img/13279251\(2\).png](https://ikoyama.com/img/13279251(2).png)

CHEVROLET CRUZE 09/16

13279251

AMORTIGUADOR POST RH LH 348032



<https://ikoyama.com/img/23580385.png>

[https://ikoyama.com/img/23580385\(2\).png](https://ikoyama.com/img/23580385(2).png)

CHEVROLET GROOVE 20/UP

23580385

AMORTIGUADOR DEL LH 23580385

<https://ikoyama.com/img/23580386.png>

[https://ikoyama.com/img/23580386\(2\).png](https://ikoyama.com/img/23580386(2).png)

CHEVROLET GROOVE 20/UP

AMORTIGUADOR DEL RH 23580386

23580386



<https://ikoyama.com/img/7246302L.png>

[https://ikoyama.com/img/7246302L\(2\).png](https://ikoyama.com/img/7246302L(2).png)

CHEVROLET N200

AMORTIGUADOR DEL LH 7246302L

7246302L



<https://ikoyama.com/img/7246302R.png>

[https://ikoyama.com/img/7246302R\(2\).png](https://ikoyama.com/img/7246302R(2).png)

CHEVROLET N200

AMORTIGUADOR DEL RH 7246302R

7246302R



<https://ikoyama.com/img/24540456.png>

[https://ikoyama.com/img/24540456\(2\).png](https://ikoyama.com/img/24540456(2).png)

CHEVROLET N200

AMORTIGUADOR POST RH LH

24540456



<https://ikoyama.com/img/24526127L.png>

[https://ikoyama.com/img/24526127L\(2\).png](https://ikoyama.com/img/24526127L(2).png)

CHEVROLET N300

AMORTIGUADOR DEL LH 24526127L

24526127L



<https://ikoyama.com/img/24526127R.png>

[https://ikoyama.com/img/24526127R\(2\).png](https://ikoyama.com/img/24526127R(2).png)

CHEVROLET N300

AMORTIGUADOR DEL RH 24526127R

24526127R



<https://ikoyama.com/img/24546807.png>

[https://ikoyama.com/img/24546807\(2\).png](https://ikoyama.com/img/24546807(2).png)

CHEVROLET N300 11/21

AMORTIGUADOR POST LH RH 24546807

24546807



<https://ikoyama.com/img/23622390.png>

[https://ikoyama.com/img/23622390\(2\).png](https://ikoyama.com/img/23622390(2).png)

CHEVROLET N400 19/UP

AMORTIGUADOR DEL LH

23622390



<https://ikoyama.com/img/23622391.png>

CHEVROLET N400 19/UP

AMORTIGUADOR DEL RH

23622391



[https://ikoyama.com/img/23622391\(2\).png](https://ikoyama.com/img/23622391(2).png)



<https://ikoyama.com/img/23628770.png>

CHEVROLET N400 19/UP

AMORTIGUADOR POST RH LH

23628770

[https://ikoyama.com/img/23628770\(2\).png](https://ikoyama.com/img/23628770(2).png)



<https://ikoyama.com/img/96407819.png>

CHEVROLET OPTRA 05/13 DAEWOO NUBIRA 93/UP

AMORTIGUADOR DEL LH 339030

96407819



[https://ikoyama.com/img/96407819\(2\).png](https://ikoyama.com/img/96407819(2).png)



<https://ikoyama.com/img/96407820.png>

CHEVROLET OPTRA 05/13 DAEWOO NUBIRA 93/UP

AMORTIGUADOR DEL RH 339029

96407820

[https://ikoyama.com/img/96407820\(2\).png](https://ikoyama.com/img/96407820(2).png)



<https://ikoyama.com/img/96407821.png>

CHEVROLET OPTRA 05/13 R

AMORTIGUADOR POST LH 333420

96407821



[https://ikoyama.com/img/96407821\(2\).png](https://ikoyama.com/img/96407821(2).png)



<https://ikoyama.com/img/96407822.png>

CHEVROLET OPTRA 05/13 R

AMORTIGUADOR POST RH 333419

96407822

[https://ikoyama.com/img/96407822\(2\).png](https://ikoyama.com/img/96407822(2).png)



<https://ikoyama.com/img/90873217.png>

CHEVROLET SAIL 16/20

AMORTIGUADOR POST LH RH 90873217

90873217

[https://ikoyama.com/img/90873217\(2\).png](https://ikoyama.com/img/90873217(2).png)



<https://ikoyama.com/img/90904863.png>

CHEVROLET SAIL 16/UP

AMORTIGUADOR DEL LH 90904863

90904863

[https://ikoyama.com/img/90904863\(2\).png](https://ikoyama.com/img/90904863(2).png)



<https://ikoyama.com/img/90904862.png>

CHEVROLET SAIL 16/UP

AMORTIGUADOR DEL RH 90904862

90904862



[https://ikoyama.com/img/90904862\(2\).png](https://ikoyama.com/img/90904862(2).png)



<https://ikoyama.com/img/95917154.png>

CHEVROLET SONIC 11/UP

AMORTIGUADOR DEL LH 3330040

95917154



[https://ikoyama.com/img/95917154\(2\).png](https://ikoyama.com/img/95917154(2).png)



<https://ikoyama.com/img/95917155.png>

CHEVROLET SONIC 11/UP

AMORTIGUADOR DEL RH 3330039

95917155



[https://ikoyama.com/img/95917155\(2\).png](https://ikoyama.com/img/95917155(2).png)



<https://ikoyama.com/img/95077491.png>

CHEVROLET SONIC 15/UP

AMORTIGUADOR POST RH LH

95077491

[https://ikoyama.com/img/95077491\(2\).png](https://ikoyama.com/img/95077491(2).png)



<https://ikoyama.com/img/96424027.png>

CHEVROLET SPARK B/B 11' 1/4 10/UP

AMORTIGUADOR POST RH LH 343478

96424027

[https://ikoyama.com/img/96424027\(2\).png](https://ikoyama.com/img/96424027(2).png)



<https://ikoyama.com/img/96424026SP.png>

CHEVROLET SPARK LITE 06/12

AMORTIGUADOR DEL LH 96424026SP

96424026SP

[https://ikoyama.com/img/96424026SP\(2\).png](https://ikoyama.com/img/96424026SP(2).png)



<https://ikoyama.com/img/96424025SP.png>

CHEVROLET SPARK LITE 06/12

AMORTIGUADOR DEL RH 96424025SP

96424025SP

[https://ikoyama.com/img/96424025SP\(2\).png](https://ikoyama.com/img/96424025SP(2).png)



<https://ikoyama.com/img/95032447.png>

CHEVROLET SPARK MODERNO SPARK GT 14/UP

AMORTIGUADOR DEL LH 95032447

95032447

[https://ikoyama.com/img/95032447\(2\).png](https://ikoyama.com/img/95032447(2).png)



<https://ikoyama.com/img/95032448.png>

CHEVROLET SPARK MODERNO SPARK GT 14/UP

AMORTIGUADOR DEL RH 95032448

95032448



[https://ikoyama.com/img/95032448\(2\).png](https://ikoyama.com/img/95032448(2).png)



<https://ikoyama.com/img/95026519.png>

CHEVROLET SPARK MODERNO SPARK GT 14/UP

AMORTIGUADOR POST RH LH 95026519

95026519

[https://ikoyama.com/img/95026519\(2\).png](https://ikoyama.com/img/95026519(2).png)



<https://ikoyama.com/img/725680400R.png>

CHEVROLET SPIN 18/UP

AMORTIGUADOR DEL LH A57101

725680400R



[https://ikoyama.com/img/725680400R\(2\).png](https://ikoyama.com/img/725680400R(2).png)



<https://ikoyama.com/img/725680400L.png>

CHEVROLET SPIN 18/UP

AMORTIGUADOR DEL RH A57100

725680400L

[https://ikoyama.com/img/725680400L\(2\).png](https://ikoyama.com/img/725680400L(2).png)



<https://ikoyama.com/img/727780083L.png>

CHEVROLET TRACKER 10/UP

AMORTIGUADOR DEL LH LCHT56

727780083L



[https://ikoyama.com/img/727780083L\(2\).png](https://ikoyama.com/img/727780083L(2).png)



<https://ikoyama.com/img/727780083R.png>

CHEVROLET TRACKER 10/UP

AMORTIGUADOR DEL RH LCHT55

727780083R

[https://ikoyama.com/img/727780083R\(2\).png](https://ikoyama.com/img/727780083R(2).png)



<https://ikoyama.com/img/726780166L.png>

CHEVROLET VIVAN 06/14

AMORTIGUADOR DEL LH 96286840

726780166L



[https://ikoyama.com/img/726780166L\(2\).png](https://ikoyama.com/img/726780166L(2).png)



<https://ikoyama.com/img/726780166R.png>

CHEVROLET VIVAN 06/14

AMORTIGUADOR DEL RH 96286839

726780166R

[https://ikoyama.com/img/726780166R\(2\).png](https://ikoyama.com/img/726780166R(2).png)



<https://ikoyama.com/img/96392790.png>
CHEVROLET VIVANT 06/14

[https://ikoyama.com/img/96392790\(2\).png](https://ikoyama.com/img/96392790(2).png)

AMORTIGUADOR POST RH LH 553339

96392790



<https://ikoyama.com/img/9678808180.png>
CITROËN C-ELYSEE 12/20

[https://ikoyama.com/img/9678808180\(2\).png](https://ikoyama.com/img/9678808180(2).png)

AMORTIGUADOR DEL LH 3338001

9678808180



<https://ikoyama.com/img/9678808280.png>
CITROËN C-ELYSEE 12/20

[https://ikoyama.com/img/9678808280\(2\).png](https://ikoyama.com/img/9678808280(2).png)

AMORTIGUADOR DEL RH 3338000

9678808280



<https://ikoyama.com/img/9802909980.png>
CITROËN C-ELYSEE 12/20

[https://ikoyama.com/img/9802909980\(2\).png](https://ikoyama.com/img/9802909980(2).png)

AMORTIGUADOR POST RH LH 3438000

9802909980



<https://ikoyama.com/img/94583379.png>
DAEWOO DAMAS 85/UP

[https://ikoyama.com/img/94583379\(2\).png](https://ikoyama.com/img/94583379(2).png)

AMORTIGUADOR DEL LH

94583379



<https://ikoyama.com/img/94583376.png>
DAEWOO DAMAS 85/UP

[https://ikoyama.com/img/94583376\(2\).png](https://ikoyama.com/img/94583376(2).png)

AMORTIGUADOR DEL RH

94583376



<https://ikoyama.com/img/96207646.png>
DAEWOO LEGANZA 97/04

[https://ikoyama.com/img/96207646\(2\).png](https://ikoyama.com/img/96207646(2).png)

AMORTIGUADOR DEL LH 634096

96207646



<https://ikoyama.com/img/96207647.png>
DAEWOO LEGANZA 97/04

[https://ikoyama.com/img/96207647\(2\).png](https://ikoyama.com/img/96207647(2).png)

AMORTIGUADOR DEL RH 634095

96207647



<https://ikoyama.com/img/96244008.png>

DAEWOO LEGANZA 97/04

AMORTIGUADOR POST LH 634098



[https://ikoyama.com/img/96244008\(2\).png](https://ikoyama.com/img/96244008(2).png)

96244008



<https://ikoyama.com/img/96244009.png>

DAEWOO LEGANZA 97/04

AMORTIGUADOR POST RH 634097



[https://ikoyama.com/img/96244009\(2\).png](https://ikoyama.com/img/96244009(2).png)

96244009



<https://ikoyama.com/img/96187438.png>

DAEWOO RACER LEMANS CIELO ESPERO 94/UP

AMORTIGUADOR DEL RH LH 365025

[https://ikoyama.com/img/96187438\(2\).png](https://ikoyama.com/img/96187438(2).png)

96187438



<https://ikoyama.com/img/90373164.png>

DAEWOO RACER LEMANS CIELO ESPERO 94/UP

AMORTIGUADOR POST RH LH 443134

[https://ikoyama.com/img/90373164\(2\).png](https://ikoyama.com/img/90373164(2).png)

90373164



<https://ikoyama.com/img/41602A78B01.png>

DAEWOO TICO HIDRAULICO 91/UP

AMORTIGUADOR DEL LH 632094

[https://ikoyama.com/img/41602A78B01\(2\).png](https://ikoyama.com/img/41602A78B01(2).png)

41602A78B01



<https://ikoyama.com/img/41601A78B01.png>

DAEWOO TICO HIDRAULICO 91/UP

AMORTIGUADOR DEL RH 632093

[https://ikoyama.com/img/41601A78B01\(2\).png](https://ikoyama.com/img/41601A78B01(2).png)

41601A78B01



<https://ikoyama.com/img/41700-63010.png>

DAEWOO TICO O/O LARGO 91/UP NS AD WAGON MOD 89/UP

AMORTIGUADOR POST RH LH 443194

[https://ikoyama.com/img/41700-63010\(2\).png](https://ikoyama.com/img/41700-63010(2).png)

41700-63010

<https://ikoyama.com/img/443194.png>

DAEWOO TICO O/O LARGO 91/UP NS AD WAGON MOD 89/UP

AMORTIGUADOR HIDRAULICO POST RH LH

[https://ikoyama.com/img/443194\(2\).png](https://ikoyama.com/img/443194(2).png)

443194



<https://ikoyama.com/img/41800A78B00.png>
DAEWOO TICO ORIGINAL 91/UP

[https://ikoyama.com/img/41800A78B00\(2\).png](https://ikoyama.com/img/41800A78B00(2).png)

AMORTIGUADOR POST RH LH 342020

41800A78B00



<https://ikoyama.com/img/4852087401.png>

[https://ikoyama.com/img/4852087401\(2\).png](https://ikoyama.com/img/4852087401(2).png)

DAIHATSU/ZOTYE TERIOS HUNTER 97/06

AMORTIGUADOR DEL LH 634111

4852087401



<https://ikoyama.com/img/4851087401.png>

[https://ikoyama.com/img/4851087401\(2\).png](https://ikoyama.com/img/4851087401(2).png)

DAIHATSU/ZOTYE TERIOS HUNTER 97/06

AMORTIGUADOR DEL RH 634110

4851087401



<https://ikoyama.com/img/2915100-SA01.png>

[https://ikoyama.com/img/2915100-SA01\(2\).png](https://ikoyama.com/img/2915100-SA01(2).png)

DFSK GLORY 580 18/UP

AMORTIGUADOR POST RH LH 349104

2915100-SA01



<https://ikoyama.com/img/726680398L.png>

[https://ikoyama.com/img/726680398L\(2\).png](https://ikoyama.com/img/726680398L(2).png)

DONGFENG DFSK GLORY 580 18/UP

AMORTIGUADOR DEL LH 903340104

726680398L



<https://ikoyama.com/img/726680398R.png>

[https://ikoyama.com/img/726680398R\(2\).png](https://ikoyama.com/img/726680398R(2).png)

DONGFENG DFSK GLORY 580 18/UP

AMORTIGUADOR DEL RH 903340103

726680398R

<https://ikoyama.com/img/9261206.png>

[https://ikoyama.com/img/9261206\(2\).png](https://ikoyama.com/img/9261206(2).png)

FORD ECOSPORT 13/21

AMORTIGUADOR DEL LH CN1518K001A2D

9261206

<https://ikoyama.com/img/9261205.png>

[https://ikoyama.com/img/9261205\(2\).png](https://ikoyama.com/img/9261205(2).png)

FORD ECOSPORT 13/21

AMORTIGUADOR DEL RH CN1518045A2B

9261205

<https://ikoyama.com/img/9130712.png>

FORD ECOSPORT 13/21

AMORTIGUADOR POST RH LH CN1518097AB

[https://ikoyama.com/img/9130712\(2\).png](https://ikoyama.com/img/9130712(2).png)

9130712



<https://ikoyama.com/img/AB3118045E.png>

FORD RANGER 12/UP MAZDA BT50 12/UP

AMORTIGUADOR DEL RH LH 340124

[https://ikoyama.com/img/AB3118045E\(2\).png](https://ikoyama.com/img/AB3118045E(2).png)

AB3118045E




<https://ikoyama.com/img/AB3118080D.png>

FORD RANGER 12/UP MAZDA BT50 12/UP

AMORTIGUADOR POST RH LH 345101

[https://ikoyama.com/img/AB3118080D\(2\).png](https://ikoyama.com/img/AB3118080D(2).png)

AB3118080D



<https://ikoyama.com/img/9250466.png>

GEELY CK 05/14

AMORTIGUADOR DEL LH 1400516180



[https://ikoyama.com/img/9250466\(2\).png](https://ikoyama.com/img/9250466(2).png)

9250466

<https://ikoyama.com/img/9250465.png>

GEELY CK 05/14

AMORTIGUADOR DEL RH 1400518180

[https://ikoyama.com/img/9250465\(2\).png](https://ikoyama.com/img/9250465(2).png)

9250465



<https://ikoyama.com/img/9250468.png>

GEELY CK 05/14

AMORTIGUADOR POST LH 1400616180



[https://ikoyama.com/img/9250468\(2\).png](https://ikoyama.com/img/9250468(2).png)

9250468



<https://ikoyama.com/img/9250467.png>

GEELY CK 05/14

AMORTIGUADOR POST RH 1400618180



[https://ikoyama.com/img/9250467\(2\).png](https://ikoyama.com/img/9250467(2).png)

9250467

<https://ikoyama.com/img/4013078100.png>

GEELY COOLRAY 19/23

AMORTIGUADOR DEL LH 4013049500

[https://ikoyama.com/img/4013078100\(2\).png](https://ikoyama.com/img/4013078100(2).png)

4013078100



<https://ikoyama.com/img/4013078300.png>

GEELY COOLRAY 19/23

AMORTIGUADOR DEL RH 4013048100

[https://ikoyama.com/img/4013078300\(2\).png](https://ikoyama.com/img/4013078300(2).png)

4013078300

<https://ikoyama.com/img/0a.png>

GEELY COOLRAY 19/23

AMORTIGUADOR POST RH LH 4020029200

[https://ikoyama.com/img/0a\(2\).png](https://ikoyama.com/img/0a(2).png)

0a

<https://ikoyama.com/img/9261508.png>

GREAT WALL M4 14/21

AMORTIGUADOR DEL LH 2905110XG83XA

[https://ikoyama.com/img/9261508\(2\).png](https://ikoyama.com/img/9261508(2).png)

9261508

<https://ikoyama.com/img/9261507.png>

GREAT WALL M4 14/21

AMORTIGUADOR DEL RH 2905220XG83XA

[https://ikoyama.com/img/9261507\(2\).png](https://ikoyama.com/img/9261507(2).png)

9261507

<https://ikoyama.com/img/2905100XPW01A.png>

GREAT WALL POER 19/UP

AMORTIGUADOR DEL RH LH 2905100XPW01A

[https://ikoyama.com/img/2905100XPW01A\(2\).p](https://ikoyama.com/img/2905100XPW01A(2).p)

2905100XPW01A

<https://ikoyama.com/img/J082905100.png>

GREAT WALL VOLEEX C30 12/UP

AMORTIGUADOR DEL LH J082905100

[https://ikoyama.com/img/J082905100\(2\).png](https://ikoyama.com/img/J082905100(2).png)

J082905100

<https://ikoyama.com/img/J082905200.png>

GREAT WALL VOLEEX C30 12/UP

AMORTIGUADOR DEL RH J082905200

[https://ikoyama.com/img/J082905200\(2\).png](https://ikoyama.com/img/J082905200(2).png)

J082905200

<https://ikoyama.com/img/2915100XJ34XA.png>

GREAT WALL VOLEEX C30 12/UP M4 14/21

AMORTIGUADOR POST RH LH 9130306 485300D301

[https://ikoyama.com/img/2915100XJ34XA\(2\).pn](https://ikoyama.com/img/2915100XJ34XA(2).pn)

2915100XJ34XA



<https://ikoyama.com/img/624380212.png>

[https://ikoyama.com/img/624380212\(2\).png](https://ikoyama.com/img/624380212(2).png)

GREAT WALL WINGLE 10/UP

624380212

AMORTIGUADOR DEL RH LH 9450073



<https://ikoyama.com/img/SA0034900M.png>

[https://ikoyama.com/img/SA0034900M\(2\).png](https://ikoyama.com/img/SA0034900M(2).png)

HAIMA 10/UP

SA0034900M

AMORTIGUADOR DEL LH



<https://ikoyama.com/img/SA0034700M.png>

[https://ikoyama.com/img/SA0034700M\(2\).png](https://ikoyama.com/img/SA0034700M(2).png)

HAIMA 10/UP

SA0034700M

AMORTIGUADOR DEL RH



<https://ikoyama.com/img/E11228700D.png>

[https://ikoyama.com/img/E11228700D\(2\).png](https://ikoyama.com/img/E11228700D(2).png)

HAIMA 10/UP

E11228700D

AMORTIGUADOR POST RH LH



<https://ikoyama.com/img/51606-SNA-A130.png>

[https://ikoyama.com/img/51606-SNA-A130\(2\).p](https://ikoyama.com/img/51606-SNA-A130(2).p)

HONDA CIVIC 06/11

51606-SNA-A130

AMORTIGUADOR DEL LH 339036



<https://ikoyama.com/img/51605-SNA-A130.png>

[https://ikoyama.com/img/51605-SNA-A130\(2\).p](https://ikoyama.com/img/51605-SNA-A130(2).p)

HONDA CIVIC 06/11

51605-SNA-A130

AMORTIGUADOR DEL RH 339035



<https://ikoyama.com/img/52610-SNA-A03.png>

[https://ikoyama.com/img/52610-SNA-A03\(2\).pn](https://ikoyama.com/img/52610-SNA-A03(2).pn)

HONDA CIVIC 06/11

52610-SNA-A03

AMORTIGUADOR POST RH LH 343460



<https://ikoyama.com/img/51621TROA220M2.png>

[https://ikoyama.com/img/51621TROA220M2\(2\).](https://ikoyama.com/img/51621TROA220M2(2).)

HONDA CIVIC 11/16

51621TROA220M2

AMORTIGUADOR DEL LH 339278



<https://ikoyama.com/img/51611TROA220M2.png> [https://ikoyama.com/img/51611TROA220M2\(2\).png](https://ikoyama.com/img/51611TROA220M2(2).png)
HONDA CIVIC 11/16

AMORTIGUADOR DEL RH 339277

51611TROA220M2

<https://ikoyama.com/img/52610TR7A020M1.png> [https://ikoyama.com/img/52610TR7A020M1\(2\).png](https://ikoyama.com/img/52610TR7A020M1(2).png)
HONDA CIVIC 11/16

AMORTIGUADOR POST RH LH 348066

52610TR7A020M1

<https://ikoyama.com/img/51620TBAA051.png> [https://ikoyama.com/img/51620TBAA051\(2\).png](https://ikoyama.com/img/51620TBAA051(2).png)
HONDA CIVIC 17/21

AMORTIGUADOR DEL LH 3340145

51620TBAA051

<https://ikoyama.com/img/51610TBAA051.png> [https://ikoyama.com/img/51610TBAA051\(2\).png](https://ikoyama.com/img/51610TBAA051(2).png)
HONDA CIVIC 17/21

AMORTIGUADOR DEL RH 3340144

51610TBAA051

<https://ikoyama.com/img/52610TEAT020.png> [https://ikoyama.com/img/52610TEAT020\(2\).png](https://ikoyama.com/img/52610TEAT020(2).png)
HONDA CIVIC 17/21

AMORTIGUADOR POST RH LH 3430036

52610TEAT020

<https://ikoyama.com/img/341139.png> [https://ikoyama.com/img/341139\(2\).png](https://ikoyama.com/img/341139(2).png)
HONDA CIVIC 91/95

AMORTIGUADOR DEL LH 341139

341139

<https://ikoyama.com/img/341138.png> [https://ikoyama.com/img/341138\(2\).png](https://ikoyama.com/img/341138(2).png)
HONDA CIVIC 91/95

AMORTIGUADOR DEL RH 341138

341138

<https://ikoyama.com/img/341193.png> [https://ikoyama.com/img/341193\(2\).png](https://ikoyama.com/img/341193(2).png)
HONDA CIVIC 91/95

AMORTIGUADOR POST RH LH 341193

341193



<https://ikoyama.com/img/341198.png>

HONDA CIVIC CON UÑA 95/01

AMORTIGUADOR POST RH LH 341198

[https://ikoyama.com/img/341198\(2\).png](https://ikoyama.com/img/341198(2).png)

341198



<https://ikoyama.com/img/331011.png>

HONDA CIVIC SEDAN 00/05

AMORTIGUADOR DEL LH 331011

[https://ikoyama.com/img/331011\(2\).png](https://ikoyama.com/img/331011(2).png)

331011



<https://ikoyama.com/img/331010.png>

HONDA CIVIC SEDAN 00/05

AMORTIGUADOR DEL RH 331010

[https://ikoyama.com/img/331010\(2\).png](https://ikoyama.com/img/331010(2).png)

331010



<https://ikoyama.com/img/341311.png>

HONDA CIVIC SEDAN 00/05

AMORTIGUADOR POST RH LH 341311

[https://ikoyama.com/img/341311\(2\).png](https://ikoyama.com/img/341311(2).png)

341311



<https://ikoyama.com/img/341203.png>

HONDA CIVIC/PARTNER 95/01

AMORTIGUADOR DEL RH LH 341203

[https://ikoyama.com/img/341203\(2\).png](https://ikoyama.com/img/341203(2).png)

341203

<https://ikoyama.com/img/51621T0TH01.png>

HONDA CR-V 11/16

AMORTIGUADOR DEL LH 339366

[https://ikoyama.com/img/51621T0TH01\(2\).png](https://ikoyama.com/img/51621T0TH01(2).png)

51621T0TH01



<https://ikoyama.com/img/51611T0TH01.png>

HONDA CR-V 11/16

AMORTIGUADOR DEL RH 339365

[https://ikoyama.com/img/51611T0TH01\(2\).png](https://ikoyama.com/img/51611T0TH01(2).png)

51611T0TH01



<https://ikoyama.com/img/52611T0TH01.png>

HONDA CR-V 11/16

AMORTIGUADOR POST RH LH 340115

[https://ikoyama.com/img/52611T0TH01\(2\).png](https://ikoyama.com/img/52611T0TH01(2).png)

52611T0TH01



<https://ikoyama.com/img/51621T7JH02.png>


HONDA HR-V 16/22

AMORTIGUADOR DEL LH 3340143



[https://ikoyama.com/img/51621T7JH02\(2\).png](https://ikoyama.com/img/51621T7JH02(2).png)

51621T7JH02



<https://ikoyama.com/img/51611T7JH02.png>

HONDA HR-V 16/22

AMORTIGUADOR DEL RH 3340142



[https://ikoyama.com/img/51611T7JH02\(2\).png](https://ikoyama.com/img/51611T7JH02(2).png)

51611T7JH02



<https://ikoyama.com/img/52611T7MH02.png>

HONDA HR-V 16/22

AMORTIGUADOR POST RH LH 3440039

[https://ikoyama.com/img/52611T7MH02\(2\).png](https://ikoyama.com/img/52611T7MH02(2).png)

52611T7MH02



<https://ikoyama.com/img/51606SZAA02.png>

HONDA PILOT 09/15

AMORTIGUADOR DEL LH 339362



[https://ikoyama.com/img/51606SZAA02\(2\).png](https://ikoyama.com/img/51606SZAA02(2).png)

51606SZAA02



<https://ikoyama.com/img/51605SZAA02.png>

HONDA PILOT 09/15

AMORTIGUADOR DEL RH 339361



[https://ikoyama.com/img/51605SZAA02\(2\).png](https://ikoyama.com/img/51605SZAA02(2).png)


51605SZAA02



<https://ikoyama.com/img/52610SZAA04.png>

HONDA PILOT 09/15

AMORTIGUADOR POST RH LH 349151



[https://ikoyama.com/img/52610SZAA04\(2\).png](https://ikoyama.com/img/52610SZAA04(2).png)

52610SZAA04



<https://ikoyama.com/img/54651-22000.png>

HYUNDAI ACCENT 94/05

AMORTIGUADOR DEL LH 633178



[https://ikoyama.com/img/54651-22000\(2\).png](https://ikoyama.com/img/54651-22000(2).png)

54651-22000



<https://ikoyama.com/img/54661-22000.png>

HYUNDAI ACCENT 94/05

AMORTIGUADOR DEL RH 633177



[https://ikoyama.com/img/54661-22000\(2\).png](https://ikoyama.com/img/54661-22000(2).png)

54661-22000



<https://ikoyama.com/img/55351-22100.png>

HYUNDAI ACCENT PLATO CHICO 94/97

AMORTIGUADOR POST LH 632104



[https://ikoyama.com/img/55351-22100\(2\).png](https://ikoyama.com/img/55351-22100(2).png)

55351-22100



<https://ikoyama.com/img/55361-22100.png>

HYUNDAI ACCENT PLATO CHICO 94/97

AMORTIGUADOR POST RH 632103



[https://ikoyama.com/img/55361-22100\(2\).png](https://ikoyama.com/img/55361-22100(2).png)

55361-22100

<https://ikoyama.com/img/632104.png>

HYUNDAI ACCENT PLATO CHICO 94/97

AMORTIGUADOR HIDRAULICO POST LH

632104

[https://ikoyama.com/img/632104\(2\).png](https://ikoyama.com/img/632104(2).png)

<https://ikoyama.com/img/632103.png>

HYUNDAI ACCENT PLATO CHICO 94/97

AMORTIGUADOR HIDRAULICO POST RH

632103

[https://ikoyama.com/img/632103\(2\).png](https://ikoyama.com/img/632103(2).png)



<https://ikoyama.com/img/55360-25050.png>

HYUNDAI ACCENT PLATO GRANDE 94/05

AMORTIGUADOR POST LH 332109



[https://ikoyama.com/img/55360-25050\(2\).png](https://ikoyama.com/img/55360-25050(2).png)

55360-25050



<https://ikoyama.com/img/55350-25050.png>

HYUNDAI ACCENT PLATO GRANDE 94/05

AMORTIGUADOR POST RH 332108

[https://ikoyama.com/img/55350-25050\(2\).png](https://ikoyama.com/img/55350-25050(2).png)

55350-25050



<https://ikoyama.com/img/54651-A0100.png>

HYUNDAI CRETA 13/UP

AMORTIGUADOR DEL LH



[https://ikoyama.com/img/54651-A0100\(2\).png](https://ikoyama.com/img/54651-A0100(2).png)

54651-A0100



<https://ikoyama.com/img/54661-A0100.png>

HYUNDAI CRETA 13/UP

AMORTIGUADOR DEL RH

[https://ikoyama.com/img/54661-A0100\(2\).png](https://ikoyama.com/img/54661-A0100(2).png)

54661-A0100


<https://ikoyama.com/img/55310-A0000.png>
[https://ikoyama.com/img/55310-A0000\(2\).png](https://ikoyama.com/img/55310-A0000(2).png)

HYUNDAI CRETA 13/UP

55310-A0000

AMORTIGUADOR POST RH LH 3440071


<https://ikoyama.com/img/553512D000.png>
[https://ikoyama.com/img/553512D000\(2\).png](https://ikoyama.com/img/553512D000(2).png)

HYUNDAI ELANTRA 00/05

553512D000

AMORTIGUADOR POST LH 333501


<https://ikoyama.com/img/553612D000.png>
[https://ikoyama.com/img/553612D000\(2\).png](https://ikoyama.com/img/553612D000(2).png)

HYUNDAI ELANTRA 00/05

553612D000

AMORTIGUADOR POST RH 333500


<https://ikoyama.com/img/54651-2H000.png>
[https://ikoyama.com/img/54651-2H000\(2\).png](https://ikoyama.com/img/54651-2H000(2).png)

HYUNDAI ELANTRA 06/11

54651-2H000

AMORTIGUADOR DEL LH 338023


<https://ikoyama.com/img/54661-2H000.png>
[https://ikoyama.com/img/54661-2H000\(2\).png](https://ikoyama.com/img/54661-2H000(2).png)

HYUNDAI ELANTRA 06/11

54661-2H000

AMORTIGUADOR DEL RH 338022


<https://ikoyama.com/img/55311-2H000.png>
[https://ikoyama.com/img/55311-2H000\(2\).png](https://ikoyama.com/img/55311-2H000(2).png)

HYUNDAI ELANTRA 06/11

55311-2H000

AMORTIGUADOR POST RH LH 349085


<https://ikoyama.com/img/54651-3X250.png>
[https://ikoyama.com/img/54651-3X250\(2\).png](https://ikoyama.com/img/54651-3X250(2).png)

HYUNDAI ELANTRA 11/UP

54651-3X250

AMORTIGUADOR DEL LH 54651-3X250


<https://ikoyama.com/img/54661-3X250.png>
[https://ikoyama.com/img/54661-3X250\(2\).png](https://ikoyama.com/img/54661-3X250(2).png)

HYUNDAI ELANTRA 11/UP

54661-3X250

AMORTIGUADOR DEL RH 54661-3X250


<https://ikoyama.com/img/55300-3X100.png>
[https://ikoyama.com/img/55300-3X100\(2\).png](https://ikoyama.com/img/55300-3X100(2).png)

HYUNDAI ELANTRA 11/UP

55300-3X100

AMORTIGUADOR POST RH LH 55300-3X100


<https://ikoyama.com/img/546512D000.png>
[https://ikoyama.com/img/546512D000\(2\).png](https://ikoyama.com/img/546512D000(2).png)

HYUNDAI ELANTRA 96/05

546512D000

AMORTIGUADOR DEL LH 333206


<https://ikoyama.com/img/546612D000.png>
[https://ikoyama.com/img/546612D000\(2\).png](https://ikoyama.com/img/546612D000(2).png)

HYUNDAI ELANTRA 96/05

546612D000

AMORTIGUADOR DEL RH 333205


<https://ikoyama.com/img/54650-4N000.png>
[https://ikoyama.com/img/54650-4N000\(2\).png](https://ikoyama.com/img/54650-4N000(2).png)

HYUNDAI EON

54650-4N000

AMORTIGUADOR DEL RH LH 54650-4N000


<https://ikoyama.com/img/54650-24120.png>
[https://ikoyama.com/img/54650-24120\(2\).png](https://ikoyama.com/img/54650-24120(2).png)

HYUNDAI EXCEL SCOUPE 89/UP

54650-24120

AMORTIGUADOR DEL RH LH 633150


<https://ikoyama.com/img/55310-21010.png>
[https://ikoyama.com/img/55310-21010\(2\).png](https://ikoyama.com/img/55310-21010(2).png)

HYUNDAI EXCEL SCOUPE 89/UP

55310-21010

AMORTIGUADOR POST RH LH 443269

<https://ikoyama.com/img/633150.png>
[https://ikoyama.com/img/633150\(2\).png](https://ikoyama.com/img/633150(2).png)

HYUNDAI EXCEL SCOUPE 89/UP

633150

AMORTIGUADOR HIDRAULICO DEL RH LH

<https://ikoyama.com/img/443269.png>
[https://ikoyama.com/img/443269\(2\).png](https://ikoyama.com/img/443269(2).png)

HYUNDAI EXCEL SCOUPE 89/UP

443269

AMORTIGUADOR HIDRAULICO POST RH LH



<https://ikoyama.com/img/54650-B4000.png>

HYUNDAI GRAND i10 14/UP

AMORTIGUADOR DEL LH



[https://ikoyama.com/img/54650-B4000\(2\).png](https://ikoyama.com/img/54650-B4000(2).png)

54650-B4000



<https://ikoyama.com/img/54660-B4000.png>

HYUNDAI GRAND i10 14/UP

AMORTIGUADOR DEL RH



[https://ikoyama.com/img/54660-B4000\(2\).png](https://ikoyama.com/img/54660-B4000(2).png)

54660-B4000



<https://ikoyama.com/img/55310-B4050.png>

HYUNDAI GRAND i10 14/UP

AMORTIGUADOR POST RH LH 3430039

55310-B4050



<https://ikoyama.com/img/54660-4H600.png>

HYUNDAI H-1 07/14

AMORTIGUADOR DEL LH 54660-4H600

54660-4H600



[https://ikoyama.com/img/54660-4H600\(2\).png](https://ikoyama.com/img/54660-4H600(2).png)



<https://ikoyama.com/img/54650-4H600.png>

HYUNDAI H-1 07/14

AMORTIGUADOR DEL RH 54650-4H600

54650-4H600



[https://ikoyama.com/img/54650-4H600\(2\).png](https://ikoyama.com/img/54650-4H600(2).png)



<https://ikoyama.com/img/55300-4H600.png>

HYUNDAI H-1 07/14

AMORTIGUADOR POST RH LH 55300-4H600

55300-4H600

[https://ikoyama.com/img/55300-4H600\(2\).png](https://ikoyama.com/img/55300-4H600(2).png)




<https://ikoyama.com/img/54300-4F000.png>

HYUNDAI H-100 05/UP

AMORTIGUADOR DEL RH LH 444128

54300-4F000



<https://ikoyama.com/img/55300-4F700.png>

HYUNDAI H-100 05/UP

AMORTIGUADOR POST RH LH 444340

55300-4F700

[https://ikoyama.com/img/55300-4F700\(2\).png](https://ikoyama.com/img/55300-4F700(2).png)


<https://ikoyama.com/img/48511-29606.png>

HYUNDAI H100 PORTER

AMORTIGUADOR DEL RH LH 444093

48511-29606
[https://ikoyama.com/img/48511-29606\(2\).png](https://ikoyama.com/img/48511-29606(2).png)

<https://ikoyama.com/img/54650-C7200.png>

HYUNDAI I20 I30 14/UP

AMORTIGUADOR DEL LH

54650-C7200
[https://ikoyama.com/img/54650-C7200\(2\).png](https://ikoyama.com/img/54650-C7200(2).png)

<https://ikoyama.com/img/54660-C7200.png>

HYUNDAI I20 I30 14/UP

AMORTIGUADOR DEL RH

54660-C7200
[https://ikoyama.com/img/54660-C7200\(2\).png](https://ikoyama.com/img/54660-C7200(2).png)

<https://ikoyama.com/img/55310-C7200.png>

HYUNDAI I20 I30 14/UP

AMORTIGUADOR POST RH LH

55310-C7200
[https://ikoyama.com/img/55310-C7200\(2\).png](https://ikoyama.com/img/55310-C7200(2).png)

<https://ikoyama.com/img/5465007100.png>

HYUNDAI KIA i10 08/UP PICANTO 04/11


AMORTIGUADOR DEL LH 332501

5465007100
[https://ikoyama.com/img/5465007100\(2\).png](https://ikoyama.com/img/5465007100(2).png)

<https://ikoyama.com/img/5466007100.png>

HYUNDAI KIA i10 PICANTO 04/11 08/UP

AMORTIGUADOR DEL RH 332500

5466007100
[https://ikoyama.com/img/5466007100\(2\).png](https://ikoyama.com/img/5466007100(2).png)

<https://ikoyama.com/img/EX54651S1002.png>

HYUNDAI KIA SANTA FE 18/UP

AMORTIGUADOR DEL LH EX54651S1002

EX54651S1002
[https://ikoyama.com/img/EX54651S1002\(2\).png](https://ikoyama.com/img/EX54651S1002(2).png)

<https://ikoyama.com/img/EX54651S1001.png>

HYUNDAI KIA SANTA FE 18/UP

AMORTIGUADOR DEL RH EX54651S1001

EX54651S1001
[https://ikoyama.com/img/EX54651S1001\(2\).png](https://ikoyama.com/img/EX54651S1001(2).png)



<https://ikoyama.com/img/EX55307S1000.png>

[https://ikoyama.com/img/EX55307S1000\(2\).png](https://ikoyama.com/img/EX55307S1000(2).png)

HYUNDAI KIA SANTA FE 18/UP

EX55307S1000

AMORTIGUADOR POST RH LH EX55307S



<https://ikoyama.com/img/54650-2P000.png>

[https://ikoyama.com/img/54650-2P000\(2\).png](https://ikoyama.com/img/54650-2P000(2).png)

HYUNDAI KIA SANTA FE SORENTO 09/12

54650-2P000

AMORTIGUADOR DEL LH



<https://ikoyama.com/img/54611-38550.png>

[https://ikoyama.com/img/54611-38550\(2\).png](https://ikoyama.com/img/54611-38550(2).png)

HYUNDAI KIA SONATA OPTIMA 99/UP

54611-38550

AMORTIGUADOR DEL RH LH 341280



<https://ikoyama.com/img/54651-D3000.png>

[https://ikoyama.com/img/54651-D3000\(2\).png](https://ikoyama.com/img/54651-D3000(2).png)

HYUNDAI TUCSON/KIA SPORTAGE 15/UP

54651-D3000

AMORTIGUADOR DEL LH



<https://ikoyama.com/img/54661-D3000.png>

[https://ikoyama.com/img/54661-D3000\(2\).png](https://ikoyama.com/img/54661-D3000(2).png)

HYUNDAI TUCSON/KIA SPORTAGE 15/UP

54661-D3000

AMORTIGUADOR DEL RH



<https://ikoyama.com/img/55311-D3000.png>

[https://ikoyama.com/img/55311-D3000\(2\).png](https://ikoyama.com/img/55311-D3000(2).png)

HYUNDAI TUCSON/KIA SPORTAGE 15/UP

55311-D3000

AMORTIGUADOR POST RH LH



<https://ikoyama.com/img/54660-1E200.png>

[https://ikoyama.com/img/54660-1E200\(2\).png](https://ikoyama.com/img/54660-1E200(2).png)

HYUNDAI/KIA ACCENT/RIO 06/10

54660-1E200

AMORTIGUADOR DEL LH 333516



<https://ikoyama.com/img/54650-1E200.png>

[https://ikoyama.com/img/54650-1E200\(2\).png](https://ikoyama.com/img/54650-1E200(2).png)

HYUNDAI/KIA ACCENT/RIO 06/10

54650-1E200

AMORTIGUADOR DEL RH 333517



<https://ikoyama.com/img/55310-1G010.png>
 HYUNDAI/KIA ACCENT/RIO 06/10

[https://ikoyama.com/img/55310-1G010\(2\).png](https://ikoyama.com/img/55310-1G010(2).png)

AMORTIGUADOR POST RH LH 348002

55310-1G010



<https://ikoyama.com/img/54650-1R001.png>
 HYUNDAI/KIA ACCENT/RIO 11/UP

[https://ikoyama.com/img/54650-1R001\(2\).png](https://ikoyama.com/img/54650-1R001(2).png)

AMORTIGUADOR DEL LH 54650-1R001

54650-1R001



<https://ikoyama.com/img/54660-1R001.png>
 HYUNDAI/KIA ACCENT/RIO 11/UP

[https://ikoyama.com/img/54660-1R001\(2\).png](https://ikoyama.com/img/54660-1R001(2).png)

AMORTIGUADOR DEL RH 54660-1R001

54660-1R001



<https://ikoyama.com/img/55300-1M300.png>
 HYUNDAI/KIA ACCENT/RIO 11/UP

[https://ikoyama.com/img/55300-1M300\(2\).png](https://ikoyama.com/img/55300-1M300(2).png)

AMORTIGUADOR POST RH LH 55300-1M300

55300-1M300



<https://ikoyama.com/img/54650-H9200.png>
 HYUNDAI/KIA ACCENT/RIO 17/UP

[https://ikoyama.com/img/54650-H9200\(2\).png](https://ikoyama.com/img/54650-H9200(2).png)

AMORTIGUADOR DEL LH

54650-H9200



<https://ikoyama.com/img/54660-H9200.png>
 HYUNDAI/KIA ACCENT/RIO 17/UP

[https://ikoyama.com/img/54660-H9200\(2\).png](https://ikoyama.com/img/54660-H9200(2).png)

AMORTIGUADOR DEL RH

54660-H9200



<https://ikoyama.com/img/553000X100.png>
 HYUNDAI/KIA i10/PICANTO 04/11 ALT 08/UP

[https://ikoyama.com/img/553000X100\(2\).png](https://ikoyama.com/img/553000X100(2).png)

AMORTIGUADOR POST RH LH 349087

553000X100



<https://ikoyama.com/img/55300X100.png>
 HYUNDAI/KIA i10/PICANTO 04/11 ORI 08/UP

[https://ikoyama.com/img/55300X100\(2\).png](https://ikoyama.com/img/55300X100(2).png)

AMORTIGUADOR POST RH LH 349087M

55300X100



<https://ikoyama.com/img/54660-2P000.png> [https://ikoyama.com/img/54660-2P000\(2\).png](https://ikoyama.com/img/54660-2P000(2).png)

HYUNDAI/KIA SANTA FE/SORENTO 09/12

AMORTIGUADOR DEL RH

54660-2P000



<https://ikoyama.com/img/55310-2P000.png> [https://ikoyama.com/img/55310-2P000\(2\).png](https://ikoyama.com/img/55310-2P000(2).png)

HYUNDAI/KIA SANTA FE/SORENTO 09/12

AMORTIGUADOR POST RH LH

55310-2P000



<https://ikoyama.com/img/54660-2W100.png> [https://ikoyama.com/img/54660-2W100\(2\).png](https://ikoyama.com/img/54660-2W100(2).png)

HYUNDAI/KIA SANTA FE/SORENTO 12/UP

AMORTIGUADOR DEL LH 54660-2W100

54660-2W100



<https://ikoyama.com/img/54650-2W100.png> [https://ikoyama.com/img/54650-2W100\(2\).png](https://ikoyama.com/img/54650-2W100(2).png)

HYUNDAI/KIA SANTA FE/SORENTO 12/UP

AMORTIGUADOR DEL RH 54650-2W100

54650-2W100



<https://ikoyama.com/img/55310-2W100.png> [https://ikoyama.com/img/55310-2W100\(2\).png](https://ikoyama.com/img/55310-2W100(2).png)

HYUNDAI/KIA SANTA FE/SORENTO 12/UP

AMORTIGUADOR POST RH LH 55310-2W100

55310-2W100



<https://ikoyama.com/img/55310-C5000.png> [https://ikoyama.com/img/55310-C5000\(2\).png](https://ikoyama.com/img/55310-C5000(2).png)

HYUNDAI/KIA SANTA FE/SORENTO 15/UP

AMORTIGUADOR POST RH LH

55310-C5000



<https://ikoyama.com/img/55311-38601.png> [https://ikoyama.com/img/55311-38601\(2\).png](https://ikoyama.com/img/55311-38601(2).png)

HYUNDAI/KIA SONATA/OPTIMA 99/UP

AMORTIGUADOR POST RH LH 341281

55311-38601



<https://ikoyama.com/img/55351-2E501.png> [https://ikoyama.com/img/55351-2E501\(2\).png](https://ikoyama.com/img/55351-2E501(2).png)

HYUNDAI/KIA TUCSON/SPORTAGE 04/10

AMORTIGUADOR POST LH 334505

55351-2E501


<https://ikoyama.com/img/55361-2E501.png>

HYUNDAI/KIA TUCSON/SPORTAGE 04/10

AMORTIGUADOR POST RH 334504


[https://ikoyama.com/img/55361-2E501\(2\).png](https://ikoyama.com/img/55361-2E501(2).png)
55361-2E501

<https://ikoyama.com/img/54651-2E500.png>

HYUNDAI/KIA TUCSON/SPORTAGE 05/10

AMORTIGUADOR DEL LH 334503

[https://ikoyama.com/img/54651-2E500\(2\).png](https://ikoyama.com/img/54651-2E500(2).png)
54651-2E500

<https://ikoyama.com/img/54661-2E500.png>

HYUNDAI/KIA TUCSON/SPORTAGE 05/10

AMORTIGUADOR DEL RH 334502


[https://ikoyama.com/img/54661-2E500\(2\).png](https://ikoyama.com/img/54661-2E500(2).png)
54661-2E500

<https://ikoyama.com/img/55311-2S400.png>

HYUNDAI/KIA TUCSON/SPORTAGE 11/15

AMORTIGUADOR POST RH LH

[https://ikoyama.com/img/55311-2S400\(2\).png](https://ikoyama.com/img/55311-2S400(2).png)
55311-2S400

<https://ikoyama.com/img/54651-2S000.png>

HYUNDAI/KIA TUCSON/SPORTAGE 11/UP

AMORTIGUADOR DEL LH 339401


[https://ikoyama.com/img/54651-2S000\(2\).png](https://ikoyama.com/img/54651-2S000(2).png)
54651-2S000

<https://ikoyama.com/img/54661-2S000.png>

HYUNDAI/KIA TUCSON/SPORTAGE 11/UP

AMORTIGUADOR DEL RH 339400

[https://ikoyama.com/img/54661-2S000\(2\).png](https://ikoyama.com/img/54661-2S000(2).png)
54661-2S000

<https://ikoyama.com/img/55311-2S000.png>

HYUNDAI/KIA TUCSON/SPORTAGE 11/UP

AMORTIGUADOR POST RH LH 349243

[https://ikoyama.com/img/55311-2S000\(2\).png](https://ikoyama.com/img/55311-2S000(2).png)
55311-2S000

<https://ikoyama.com/img/2901310U8010.png>

JAC A-CLASS

AMORTIGUADOR DEL LH


[https://ikoyama.com/img/2901310U8010\(2\).png](https://ikoyama.com/img/2901310U8010(2).png)
2901310U8010



<https://ikoyama.com/img/2901410U8010.png>

[https://ikoyama.com/img/2901410U8010\(2\).png](https://ikoyama.com/img/2901410U8010(2).png)

JAC A-CLASS

2901410U8010

AMORTIGUADOR DEL RH

<https://ikoyama.com/img/9263798.png>

[https://ikoyama.com/img/9263798\(2\).png](https://ikoyama.com/img/9263798(2).png)

JAC S2 16/UP

9263798

AMORTIGUADOR DEL LH 9263798

<https://ikoyama.com/img/9263797.png>

[https://ikoyama.com/img/9263797\(2\).png](https://ikoyama.com/img/9263797(2).png)

JAC S2 16/UP

9263797

AMORTIGUADOR DEL RH 9263797



<https://ikoyama.com/img/9131610.png>

[https://ikoyama.com/img/9131610\(2\).png](https://ikoyama.com/img/9131610(2).png)

JAC S2 16/UP

9131610

AMORTIGUADOR POST RH LH 9131610

<https://ikoyama.com/img/9251102.png>

[https://ikoyama.com/img/9251102\(2\).png](https://ikoyama.com/img/9251102(2).png)

JAC S3 16/20 JS3 20/UP

9251102

AMORTIGUADOR DEL LH 9251102



<https://ikoyama.com/img/9251101.png>

[https://ikoyama.com/img/9251101\(2\).png](https://ikoyama.com/img/9251101(2).png)

JAC S3 16/20 JS3 20/UP

9251101

AMORTIGUADOR DEL RH 9251101



<https://ikoyama.com/img/9130782.png>

[https://ikoyama.com/img/9130782\(2\).png](https://ikoyama.com/img/9130782(2).png)

JAC S3 16/20 JS3 20/UP

9130782

AMORTIGUADOR POST RH LH 9130782

<https://ikoyama.com/img/F012901010.png>

[https://ikoyama.com/img/F012901010\(2\).png](https://ikoyama.com/img/F012901010(2).png)

JETOUR X70 18/UP

F012901010

AMORTIGUADOR DEL LH F012901010

<https://ikoyama.com/img/F012901020.png>
[https://ikoyama.com/img/F012901020\(2\).png](https://ikoyama.com/img/F012901020(2).png)

JETOUR X70 18/UP

AMORTIGUADOR DEL RH F012901020

F012901020
<https://ikoyama.com/img/F012915010.png>
[https://ikoyama.com/img/F012915010\(2\).png](https://ikoyama.com/img/F012915010(2).png)

JETOUR X70 18/UP

AMORTIGUADOR POST RH LH F012915010

F012915010
<https://ikoyama.com/img/54651-A7400.png>
[https://ikoyama.com/img/54651-A7400\(2\).png](https://ikoyama.com/img/54651-A7400(2).png)

KIA CERATO 13/16

AMORTIGUADOR DEL LH

54651-A7400
<https://ikoyama.com/img/54661-A7400.png>
[https://ikoyama.com/img/54661-A7400\(2\).png](https://ikoyama.com/img/54661-A7400(2).png)

KIA CERATO 13/16

AMORTIGUADOR DEL RH

54661-A7400
<https://ikoyama.com/img/55300-A7200.png>
[https://ikoyama.com/img/55300-A7200\(2\).png](https://ikoyama.com/img/55300-A7200(2).png)

KIA CERATO 13/16

AMORTIGUADOR POST RH LH

55300-A7200
<https://ikoyama.com/img/54651-F2000.png>
[https://ikoyama.com/img/54651-F2000\(2\).png](https://ikoyama.com/img/54651-F2000(2).png)

KIA CERATO HYUNDAI ELANTRA 2017/UP

AMORTIGUADOR DEL LH

54651-F2000
<https://ikoyama.com/img/54661-F2000.png>
[https://ikoyama.com/img/54661-F2000\(2\).png](https://ikoyama.com/img/54661-F2000(2).png)

KIA CERATO HYUNDAI ELANTRA 2017/UP

AMORTIGUADOR DEL RH

54661-F2000
<https://ikoyama.com/img/54300-4E100.png>
[https://ikoyama.com/img/54300-4E100\(2\).png](https://ikoyama.com/img/54300-4E100(2).png)

KIA K2500 K2700 K2900 08/UP

AMORTIGUADOR DEL RH LH 3440046

54300-4E100


<https://ikoyama.com/img/55300-4E100.png>
[https://ikoyama.com/img/55300-4E100\(2\).png](https://ikoyama.com/img/55300-4E100(2).png)

KIA K2500 K2700 K2900 08/UP

AMORTIGUADOR POST RH LH 3440031

55300-4E100
<https://ikoyama.com/img/54650-D4000.png>
[https://ikoyama.com/img/54650-D4000\(2\).png](https://ikoyama.com/img/54650-D4000(2).png)

KIA K5/OPTIMA 12/17

AMORTIGUADOR DEL LH

54650-D4000
<https://ikoyama.com/img/54660-D4000.png>
[https://ikoyama.com/img/54660-D4000\(2\).png](https://ikoyama.com/img/54660-D4000(2).png)

KIA K5/OPTIMA 12/17

AMORTIGUADOR DEL RH

54660-D4000
<https://ikoyama.com/img/55311-D4200.png>
[https://ikoyama.com/img/55311-D4200\(2\).png](https://ikoyama.com/img/55311-D4200(2).png)

KIA K5/OPTIMA 12/17

AMORTIGUADOR POST RH LH

55311-D4200
<https://ikoyama.com/img/5531007100.png>
[https://ikoyama.com/img/5531007100\(2\).png](https://ikoyama.com/img/5531007100(2).png)

KIA PICANTO 04/UP

AMORTIGUADOR POST RH LH 343405

5531007100
<https://ikoyama.com/img/54650-G6250.png>
[https://ikoyama.com/img/54650-G6250\(2\).png](https://ikoyama.com/img/54650-G6250(2).png)

KIA PICANTO 18/UP

AMORTIGUADOR DEL LH

54650-G6250
<https://ikoyama.com/img/54660-G6250.png>
[https://ikoyama.com/img/54660-G6250\(2\).png](https://ikoyama.com/img/54660-G6250(2).png)

KIA PICANTO 18/UP

AMORTIGUADOR DEL RH

54660-G6250
<https://ikoyama.com/img/55310-G6200.png>
[https://ikoyama.com/img/55310-G6200\(2\).png](https://ikoyama.com/img/55310-G6200(2).png)

KIA PICANTO 18/UP

AMORTIGUADOR POST RH LH

55310-G6200



<https://ikoyama.com/img/54650-1Y200.png>

KIA PICANTO MODERNO 12/UP

AMORTIGUADOR DEL LH 54650-1Y200



[https://ikoyama.com/img/54660-1Y200\(2\).png](https://ikoyama.com/img/54660-1Y200(2).png)

54650-1Y200



<https://ikoyama.com/img/54660-1Y200.png>

KIA PICANTO MODERNO 12/UP

AMORTIGUADOR DEL RH 54660-1Y200

[https://ikoyama.com/img/54660-1Y200\(2\).png](https://ikoyama.com/img/54660-1Y200(2).png)

54660-1Y200



<https://ikoyama.com/img/55310-H9200.png>

KIA RIO HYUNDAI ACCENT 17/UP

AMORTIGUADOR POST RH LH

[https://ikoyama.com/img/55310-H9200\(2\).png](https://ikoyama.com/img/55310-H9200(2).png)

55310-H9200



<https://ikoyama.com/img/54650-H7100.png>

KIA SOLUTO 19/UP

AMORTIGUADOR DEL LH



[https://ikoyama.com/img/54650-H7100\(2\).png](https://ikoyama.com/img/54650-H7100(2).png)

54650-H7100



<https://ikoyama.com/img/54660-H7100.png>

KIA SOLUTO 19/UP

AMORTIGUADOR DEL RH

[https://ikoyama.com/img/54660-H7100\(2\).png](https://ikoyama.com/img/54660-H7100(2).png)

54660-H7100



<https://ikoyama.com/img/55300-H7100.png>

KIA SOLUTO 19/UP

AMORTIGUADOR POST LH RH

[https://ikoyama.com/img/55300-H7100\(2\).png](https://ikoyama.com/img/55300-H7100(2).png)

55300-H7100



<https://ikoyama.com/img/54651-C5000.png>

KIA SORENTO 15/UP

AMORTIGUADOR DEL LH



[https://ikoyama.com/img/54651-C5000\(2\).png](https://ikoyama.com/img/54651-C5000(2).png)

54651-C5000



<https://ikoyama.com/img/54661-C5000.png>

KIA SORENTO 15/UP

AMORTIGUADOR DEL RH



[https://ikoyama.com/img/54661-C5000\(2\).png](https://ikoyama.com/img/54661-C5000(2).png)

54661-C5000


<https://ikoyama.com/img/54650-2K000.png>

KIA SOUL 12/UP

AMORTIGUADOR DEL LH


[https://ikoyama.com/img/54650-2K000\(2\).png](https://ikoyama.com/img/54650-2K000(2).png)
54650-2K000
<https://ikoyama.com/img/54660-2K000.png>

KIA SOUL 12/UP

AMORTIGUADOR DEL RH


[https://ikoyama.com/img/54660-2K000\(2\).png](https://ikoyama.com/img/54660-2K000(2).png)
54660-2K000
<https://ikoyama.com/img/55300-2K000.png>

KIA SOUL 12/UP

AMORTIGUADOR POST RH LH

[https://ikoyama.com/img/55300-2K000\(2\).png](https://ikoyama.com/img/55300-2K000(2).png)
55300-2K000
<https://ikoyama.com/img/54650-B2100.png>

KIA SOUL 15/UP

AMORTIGUADOR DEL LH


[https://ikoyama.com/img/54650-B2100\(2\).png](https://ikoyama.com/img/54650-B2100(2).png)
54650-B2100
<https://ikoyama.com/img/54660-B2100.png>

KIA SOUL 15/UP

AMORTIGUADOR DEL RH


[https://ikoyama.com/img/54660-B2100\(2\).png](https://ikoyama.com/img/54660-B2100(2).png)
54660-B2100
<https://ikoyama.com/img/KY01-34-900A.png>

KIA/FORD PRIDE/FESTIVA 91/UP

AMORTIGUADOR DEL LH KY01-34-900A

[https://ikoyama.com/img/KY01-34-900A\(2\).png](https://ikoyama.com/img/KY01-34-900A(2).png)
KY01-34-900A
<https://ikoyama.com/img/KY01-34-700A.png>

KIA/FORD PRIDE/FESTIVA 91/UP

AMORTIGUADOR DEL RH KY01-34-700A

[https://ikoyama.com/img/KY01-34-700A\(2\).png](https://ikoyama.com/img/KY01-34-700A(2).png)
KY01-34-700A
<https://ikoyama.com/img/B45A34900.png>

MAZDA 3 SEDAN HB 13/16

AMORTIGUADOR DEL LH 338088


[https://ikoyama.com/img/B45A34900\(2\).png](https://ikoyama.com/img/B45A34900(2).png)
B45A34900


<https://ikoyama.com/img/B45A34700.png>

MAZDA 3 SEDAN HB 13/16

AMORTIGUADOR DEL RH 338087

[https://ikoyama.com/img/B45A34700\(2\).png](https://ikoyama.com/img/B45A34700(2).png)
B45A34700
<https://ikoyama.com/img/AB3118045D.png>


MAZDA BT50 12/UP

AMORTIGUADOR DEL RH LH 340124

[https://ikoyama.com/img/AB3118045D\(2\).png](https://ikoyama.com/img/AB3118045D(2).png)
AB3118045D
<https://ikoyama.com/img/DD1V-34-900B.png>

MAZDA CX-3 16/UP

AMORTIGUADOR DEL LH 3340139

[https://ikoyama.com/img/DD1V-34-900B\(2\).png](https://ikoyama.com/img/DD1V-34-900B(2).png)
DD1V-34-900B
<https://ikoyama.com/img/DD1V-34-700B.png>


MAZDA CX-3 16/UP

AMORTIGUADOR DEL RH 3340138

[https://ikoyama.com/img/DD1V-34-700B\(2\).png](https://ikoyama.com/img/DD1V-34-700B(2).png)
DD1V-34-700B
<https://ikoyama.com/img/DD1V-28-700D.png>


MAZDA CX-3 16/UP

AMORTIGUADOR POST RH LH 3430037

[https://ikoyama.com/img/DD1V-28-700D\(2\).png](https://ikoyama.com/img/DD1V-28-700D(2).png)
DD1V-28-700D
<https://ikoyama.com/img/KD4534900A.png>

MAZDA CX-5 12/16

AMORTIGUADOR DEL LH 339337

[https://ikoyama.com/img/KD4534900A\(2\).png](https://ikoyama.com/img/KD4534900A(2).png)
KD4534900A
<https://ikoyama.com/img/KD4534700A.png>

MAZDA CX-5 12/16

AMORTIGUADOR DEL RH 339336

[https://ikoyama.com/img/KD4534700A\(2\).png](https://ikoyama.com/img/KD4534700A(2).png)
KD4534700A
<https://ikoyama.com/img/K07028910A.png>

MAZDA CX-5 12/16

AMORTIGUADOR POST RH LH 3440013

[https://ikoyama.com/img/K07028910A\(2\).png](https://ikoyama.com/img/K07028910A(2).png)
K07028910A

<https://ikoyama.com/img/K12834900A.png>
[https://ikoyama.com/img/K12834900A\(2\).png](https://ikoyama.com/img/K12834900A(2).png)

MAZDA CX-5 17/UP

AMORTIGUADOR DEL LH

K12834900A
<https://ikoyama.com/img/K12834700A.png>
[https://ikoyama.com/img/K12834700A\(2\).png](https://ikoyama.com/img/K12834700A(2).png)

MAZDA CX-5 17/UP

AMORTIGUADOR DEL RH

K12834700A
<https://ikoyama.com/img/KL2G28700.png>
[https://ikoyama.com/img/KL2G28700\(2\).png](https://ikoyama.com/img/KL2G28700(2).png)

MAZDA CX-5 17/UP MAZDA6 12/17

AMORTIGUADOR POST RH LH 3440014

KL2G28700
<https://ikoyama.com/img/D04A34900C.png>
[https://ikoyama.com/img/D04A34900C\(2\).png](https://ikoyama.com/img/D04A34900C(2).png)

MAZDA MAZDA 2 DEMIO 08/14

AMORTIGUADOR DEL LH

D04A34900C
<https://ikoyama.com/img/D04A34700C.png>
[https://ikoyama.com/img/D04A34700C\(2\).png](https://ikoyama.com/img/D04A34700C(2).png)

MAZDA MAZDA 2 DEMIO 08/14

AMORTIGUADOR DEL RH

D04A34700C
<https://ikoyama.com/img/DF712870XB.png>
[https://ikoyama.com/img/DF712870XB\(2\).png](https://ikoyama.com/img/DF712870XB(2).png)

MAZDA MAZDA 2 DEMIO 08/14

AMORTIGUADOR POST RH LH

DF712870XB
<https://ikoyama.com/img/D00128-700C.png>
[https://ikoyama.com/img/D00128-700C\(2\).png](https://ikoyama.com/img/D00128-700C(2).png)

MAZDA MAZDA 2 DEMIO 98/00

AMORTIGUADOR POST RH LH 441099

D00128-700C
<https://ikoyama.com/img/B45L34900.png>
[https://ikoyama.com/img/B45L34900\(2\).png](https://ikoyama.com/img/B45L34900(2).png)

MAZDA MAZDA 3 13/18

AMORTIGUADOR DEL LH 338088

B45L34900

<https://ikoyama.com/img/B45L34700.png>

MAZDA MAZDA 3 13/18

AMORTIGUADOR DEL RH 338087

[https://ikoyama.com/img/B45L34700\(2\).png](https://ikoyama.com/img/B45L34700(2).png)

B45L34700

<https://ikoyama.com/img/B45L28700A.png>

MAZDA MAZDA 3 13/18

AMORTIGUADOR POST RH LH 3430041

[https://ikoyama.com/img/B45L28700A\(2\).png](https://ikoyama.com/img/B45L28700A(2).png)

B45L28700A



<https://ikoyama.com/img/B32T34900C.png>

MAZDA MAZDA 3 MAZDA 5 03/13

AMORTIGUADOR DEL LH 334701

[https://ikoyama.com/img/B32T34900C\(2\).png](https://ikoyama.com/img/B32T34900C(2).png)

B32T34900C



<https://ikoyama.com/img/B32T34700C.png>

MAZDA MAZDA 3 MAZDA 5 03/13

AMORTIGUADOR DEL RH 334700

[https://ikoyama.com/img/B32T34700C\(2\).png](https://ikoyama.com/img/B32T34700C(2).png)

B32T34700C



<https://ikoyama.com/img/BP4K28910D.png>

MAZDA MAZDA 3 MAZDA 5 03/13

AMORTIGUADOR POST RH LH 343412

[https://ikoyama.com/img/BP4K28910D\(2\).png](https://ikoyama.com/img/BP4K28910D(2).png)

BP4K28910D



<https://ikoyama.com/img/331702.png>

MERCEDES BENZ SPRINTER

AMORTIGUADOR DEL LH 331702

[https://ikoyama.com/img/331702\(2\).png](https://ikoyama.com/img/331702(2).png)

331702



<https://ikoyama.com/img/331701.png>

MERCEDES BENZ SPRINTER

AMORTIGUADOR DEL RH 331701



[https://ikoyama.com/img/331701\(2\).png](https://ikoyama.com/img/331701(2).png)

331701



<https://ikoyama.com/img/30009866.png>

MG 3 08/UP

AMORTIGUADOR DEL LH 10039821



[https://ikoyama.com/img/30009866\(2\).png](https://ikoyama.com/img/30009866(2).png)

30009866

<https://ikoyama.com/img/30003602.png>

[https://ikoyama.com/img/30003602\(2\).png](https://ikoyama.com/img/30003602(2).png)

MG 3 08/UP

30003602

AMORTIGUADOR DEL RH 10039824



<https://ikoyama.com/img/30003617.png>

[https://ikoyama.com/img/30003617\(2\).png](https://ikoyama.com/img/30003617(2).png)

MG 3 08/UP

30003617

AMORTIGUADOR POST RH LH 10039880

<https://ikoyama.com/img/50016035D.png>

[https://ikoyama.com/img/50016035D\(2\).png](https://ikoyama.com/img/50016035D(2).png)

MG 5 12/18 MG 350 10/14

50016035D

AMORTIGUADOR DEL LH 10037910

<https://ikoyama.com/img/50016055D.png>

[https://ikoyama.com/img/50016055D\(2\).png](https://ikoyama.com/img/50016055D(2).png)

MG 5 12/18 MG 350 10/14

50016055D

AMORTIGUADOR DEL RH 10037911



<https://ikoyama.com/img/50016195D.png>

[https://ikoyama.com/img/50016195D\(2\).png](https://ikoyama.com/img/50016195D(2).png)

MG 5 12/18 MG 350 10/14

50016195D

AMORTIGUADOR POST RH LH 10035491

<https://ikoyama.com/img/10667178.png>

[https://ikoyama.com/img/10667178\(2\).png](https://ikoyama.com/img/10667178(2).png)

MG 5 21/UP

10667178

AMORTIGUADOR DEL LH 10667178



<https://ikoyama.com/img/10667179.png>

[https://ikoyama.com/img/10667179\(2\).png](https://ikoyama.com/img/10667179(2).png)

MG 5 21/UP

10667179

AMORTIGUADOR DEL RH 10667179

<https://ikoyama.com/img/10667182.png>

[https://ikoyama.com/img/10667182\(2\).png](https://ikoyama.com/img/10667182(2).png)

MG 5 21/UP

10667182

AMORTIGUADOR POST RH LH 10667182



<https://ikoyama.com/img/10481745.png>

[https://ikoyama.com/img/10481745\(2\).png](https://ikoyama.com/img/10481745(2).png)

MG GT 15/19

10481745

AMORTIGUADOR DEL LH 10481745



<https://ikoyama.com/img/10481746.png>

[https://ikoyama.com/img/10481746\(2\).png](https://ikoyama.com/img/10481746(2).png)

MG GT 15/19

10481746

AMORTIGUADOR DEL RH 10481746



<https://ikoyama.com/img/10231905.png>

[https://ikoyama.com/img/10231905\(2\).png](https://ikoyama.com/img/10231905(2).png)

MG GT 15/19

10231905

AMORTIGUADOR POST RH LH 10231905



<https://ikoyama.com/img/10242085.png>

[https://ikoyama.com/img/10242085\(2\).png](https://ikoyama.com/img/10242085(2).png)

MG ZS 18/21 MG ZX 21/UP

10242085

AMORTIGUADOR DEL LH 10242085



<https://ikoyama.com/img/10242405.png>

[https://ikoyama.com/img/10242405\(2\).png](https://ikoyama.com/img/10242405(2).png)

MG ZS 18/21 MG ZX 21/UP

10242405

AMORTIGUADOR DEL RH 10242405



<https://ikoyama.com/img/10242400.png>

[https://ikoyama.com/img/10242400\(2\).png](https://ikoyama.com/img/10242400(2).png)

MG ZS 18/21 MG ZX 21/UP

10242400

AMORTIGUADOR POST RH LH 10242400



<https://ikoyama.com/img/4060A575.png>

[https://ikoyama.com/img/4060A575\(2\).png](https://ikoyama.com/img/4060A575(2).png)

MISUBISHI XPANDER 17/21 XPANDER CROSS 21/UP

4060A575

AMORTIGUADOR DEL LH 3340252 B3555



<https://ikoyama.com/img/4060A576.png>

[https://ikoyama.com/img/4060A576\(2\).png](https://ikoyama.com/img/4060A576(2).png)

MISUBISHI XPANDER 17/21 XPANDER CROSS 21/UP

4060A576

AMORTIGUADOR DEL RH 3340251 B3554


<https://ikoyama.com/img/4162A409.png>
[https://ikoyama.com/img/4162A409\(2\).png](https://ikoyama.com/img/4162A409(2).png)

MITSUBISHI XPANDER 17/21 XPANDER CROSS 21/UP

4162A409

AMORTIGUADOR POST RH LH 3430077 E20142


<https://ikoyama.com/img/MR519614.png>
[https://ikoyama.com/img/MR519614\(2\).png](https://ikoyama.com/img/MR519614(2).png)

MITSUBISHI CEDIA PLATO BAJO 01/05

MR519614

AMORTIGUADOR DEL RH LH 333381


<https://ikoyama.com/img/MR491430.png>
[https://ikoyama.com/img/MR491430\(2\).png](https://ikoyama.com/img/MR491430(2).png)

MITSUBISHI CEDIA PLATO BAJO 01/05

MR491430

AMORTIGUADOR DEL RH LH 333882


<https://ikoyama.com/img/MR-992632.png>
[https://ikoyama.com/img/MR-992632\(2\).png](https://ikoyama.com/img/MR-992632(2).png)

MITSUBISHI L200 06/UP

MR-992632

AMORTIGUADOR POST RH LH 443258


<https://ikoyama.com/img/MR-992321.png>
[https://ikoyama.com/img/MR-992321\(2\).png](https://ikoyama.com/img/MR-992321(2).png)

MITSUBISHI L200 07/15

MR-992321

AMORTIGUADOR DEL RH LH 340033


<https://ikoyama.com/img/MR-151235.png>
[https://ikoyama.com/img/MR-151235\(2\).png](https://ikoyama.com/img/MR-151235(2).png)

MITSUBISHI L200 96/05

MR-151235

AMORTIGUADOR POST RH LH 443290


<https://ikoyama.com/img/MR-151227.png>
[https://ikoyama.com/img/MR-151227\(2\).png](https://ikoyama.com/img/MR-151227(2).png)

MITSUBISHI L200 96/UP

MR-151227

AMORTIGUADOR DEL RH LH 444150


<https://ikoyama.com/img/MR-244218.png>
[https://ikoyama.com/img/MR-244218\(2\).png](https://ikoyama.com/img/MR-244218(2).png)

MITSUBISHI LANCER / MIRAGE

MR-244218

AMORTIGUADOR POST RH LH 441112


<https://ikoyama.com/img/633148.png>

MITSUBISHI LANCER / MIRAGE / LIBERO R 92/03

AMORTIGUADOR DEL LH 633148

633148

[https://ikoyama.com/img/633148\(2\).png](https://ikoyama.com/img/633148(2).png)

<https://ikoyama.com/img/633147.png>

MITSUBISHI LANCER / MIRAGE / LIBERO R 92/03

AMORTIGUADOR DEL RH 633147

633147

[https://ikoyama.com/img/633147\(2\).png](https://ikoyama.com/img/633147(2).png)

<https://ikoyama.com/img/4060A065.png>

MITSUBISHI LANCER 07/13

AMORTIGUADOR DEL LH 339105

4060A065

[https://ikoyama.com/img/4060A065\(2\).png](https://ikoyama.com/img/4060A065(2).png)

<https://ikoyama.com/img/4060A066.png>

MITSUBISHI LANCER 07/13

AMORTIGUADOR DEL RH 339104

4060A066

[https://ikoyama.com/img/4060A066\(2\).png](https://ikoyama.com/img/4060A066(2).png)

<https://ikoyama.com/img/4162A130.png>

MITSUBISHI LANCER 07/13

AMORTIGUADOR POST RH LH 341455

4162A130
[https://ikoyama.com/img/4162A130\(2\).png](https://ikoyama.com/img/4162A130(2).png)

<https://ikoyama.com/img/MR197433.png>

MITSUBISHI LANCER 96/00

AMORTIGUADOR DEL LH 332113

MR197433

[https://ikoyama.com/img/MR197433\(2\).png](https://ikoyama.com/img/MR197433(2).png)

<https://ikoyama.com/img/MR197434.png>

MITSUBISHI LANCER 96/00

AMORTIGUADOR DEL RH 332112

MR197434
[https://ikoyama.com/img/MR197434\(2\).png](https://ikoyama.com/img/MR197434(2).png)

<https://ikoyama.com/img/4060A397.png>

MITSUBISHI MIRAGE 13/UP

AMORTIGUADOR DEL RH LH

4060A397

[https://ikoyama.com/img/4060A397\(2\).png](https://ikoyama.com/img/4060A397(2).png)


<https://ikoyama.com/img/348083.png>
[https://ikoyama.com/img/348083\(2\).png](https://ikoyama.com/img/348083(2).png)

MITSUBISHI MIRAGE 13/UP

AMORTIGUADOR POST RH LH 348083

348083

<https://ikoyama.com/img/MB-025381.png>
[https://ikoyama.com/img/MB-025381\(2\).png](https://ikoyama.com/img/MB-025381(2).png)

MITSUBISHI ROSA CANTER FUSO HYUNDAI PORTER 85/UP

AMORTIGUADOR DEL RH LH 444197

MB-025381

<https://ikoyama.com/img/54303-70N00.png>
[https://ikoyama.com/img/54303-70N00\(2\).png](https://ikoyama.com/img/54303-70N00(2).png)

NISSAN AVENIR 94/UP PRIMERA WAGON 90/98

AMORTIGUADOR DEL LH 632060

54303-70N00

<https://ikoyama.com/img/54302-70N00.png>
[https://ikoyama.com/img/54302-70N00\(2\).png](https://ikoyama.com/img/54302-70N00(2).png)

NISSAN AVENIR 94/UP PRIMERA WAGON 90/98

AMORTIGUADOR DEL RH 632059

54302-70N00
<https://ikoyama.com/img/632060.png>
[https://ikoyama.com/img/632060\(2\).png](https://ikoyama.com/img/632060(2).png)

NISSAN AVENIR 94/UP PRIMERA WAGON 90/98

AMORTIGUADOR HIDRAULICO DEL LH

632060
<https://ikoyama.com/img/632059.png>
[https://ikoyama.com/img/632059\(2\).png](https://ikoyama.com/img/632059(2).png)

NISSAN AVENIR 94/UP PRIMERA WAGON 90/98

AMORTIGUADOR HIDRAULICO DEL RH

632059

<https://ikoyama.com/img/5611076000.png>
[https://ikoyama.com/img/5611076000\(2\).png](https://ikoyama.com/img/5611076000(2).png)

NISSAN AVENIR AD WAGON 96/02

AMORTIGUADOR POST RH LH 444024

5611076000

<https://ikoyama.com/img/56211-WF126.png>
[https://ikoyama.com/img/56211-WF126\(2\).png](https://ikoyama.com/img/56211-WF126(2).png)

NISSAN AVENIR AD WAGON LIBERTY 4X4 94/UP

AMORTIGUADOR POST LH 341358

56211-WF126



<https://ikoyama.com/img/56210-WF126.png> [https://ikoyama.com/img/56210-WF126\(2\).png](https://ikoyama.com/img/56210-WF126(2).png)

NISSAN AVENIR AD WAGON LIBERTY 4X4 94/UP

AMORTIGUADOR POST RH 341357

56210-WF126



<https://ikoyama.com/img/56110-VW002.png> [https://ikoyama.com/img/56110-VW002\(2\).png](https://ikoyama.com/img/56110-VW002(2).png)

NISSAN CARAVAN HOMOY URVAN 98/11

AMORTIGUADOR DEL RH LH 344463

56110-VW002



<https://ikoyama.com/img/56210-VW001.png> [https://ikoyama.com/img/56210-VW001\(2\).png](https://ikoyama.com/img/56210-VW001(2).png)

NISSAN CARAVAN HOMOY URVAN 98/11

AMORTIGUADOR POST RH LH 343425

56210-VW001



<https://ikoyama.com/img/56110-S9026.png> [https://ikoyama.com/img/56110-S9026\(2\).png](https://ikoyama.com/img/56110-S9026(2).png)

NISSAN CIVILIAN 86/UP

AMORTIGUADOR DEL RH LH 444202

56110-S9026



<https://ikoyama.com/img/56210-S9026.png> [https://ikoyama.com/img/56210-S9026\(2\).png](https://ikoyama.com/img/56210-S9026(2).png)

NISSAN CIVILIAN 86/UP

AMORTIGUADOR POST RH LH 444228

56210-S9026

<https://ikoyama.com/img/E6110-EB71A.png> [https://ikoyama.com/img/E6110-EB71A\(2\).png](https://ikoyama.com/img/E6110-EB71A(2).png)

NISSAN NAVARA 05/14

AMORTIGUADOR DEL RH LH

E6110-EB71A



<https://ikoyama.com/img/E6200-EB71A.png> [https://ikoyama.com/img/E6200-EB71A\(2\).png](https://ikoyama.com/img/E6200-EB71A(2).png)

NISSAN NAVARA 05/14

AMORTIGUADOR POST RH LH

E6200-EB71A



<https://ikoyama.com/img/48531-36100.png> [https://ikoyama.com/img/48531-36100\(2\).png](https://ikoyama.com/img/48531-36100(2).png)

NISSAN NAVARA 81/UP COASTER 82/92 URVAN HOMOY 05/UP

AMORTIGUADOR POST RH LH 444169

48531-36100


<https://ikoyama.com/img/56110-25G00.png>
[https://ikoyama.com/img/56110-25G00\(2\).png](https://ikoyama.com/img/56110-25G00(2).png)

NISSAN NAVARA FRONTIER CARAVAN 86/UP PORTER 81/UP

56110-25G00

AMORTIGUADOR DEL RH LH 443238


<https://ikoyama.com/img/56210-86425.png>
[https://ikoyama.com/img/56210-86425\(2\).png](https://ikoyama.com/img/56210-86425(2).png)

NISSAN NAVARA FRONTIER CARAVAN 86/UP PORTER 81/UP

56210-86425

AMORTIGUADOR POST RH LH 444023


<https://ikoyama.com/img/924380210.png>
[https://ikoyama.com/img/924380210\(2\).png](https://ikoyama.com/img/924380210(2).png)

NISSAN NP300 12/UP

924380210

AMORTIGUADOR POST RH LH 349911


<https://ikoyama.com/img/561103J200.png>
[https://ikoyama.com/img/561103J200\(2\).png](https://ikoyama.com/img/561103J200(2).png)

NISSAN PRIMERA 96/02

561103J200

AMORTIGUADOR DEL RH LH 341120


<https://ikoyama.com/img/333605.png>
[https://ikoyama.com/img/333605\(2\).png](https://ikoyama.com/img/333605(2).png)

NISSAN SENTRA 2.0 07/UP

333605

AMORTIGUADOR DEL LH 333605


<https://ikoyama.com/img/333604.png>
[https://ikoyama.com/img/333604\(2\).png](https://ikoyama.com/img/333604(2).png)

NISSAN SENTRA 2.0 07/UP

333604

AMORTIGUADOR DEL RH 333604


<https://ikoyama.com/img/54303-01A00.png>
[https://ikoyama.com/img/54303-01A00\(2\).png](https://ikoyama.com/img/54303-01A00(2).png)

NISSAN SENTRA B11 SUNNY 82/88

54303-01A00

AMORTIGUADOR DEL LH 632009


<https://ikoyama.com/img/54302-01A00.png>
[https://ikoyama.com/img/54302-01A00\(2\).png](https://ikoyama.com/img/54302-01A00(2).png)

NISSAN SENTRA B11 SUNNY 82/88

54302-01A00

AMORTIGUADOR DEL RH 632008

<https://ikoyama.com/img/632009.png>
[https://ikoyama.com/img/632009\(2\).png](https://ikoyama.com/img/632009(2).png)

NISSAN SENTRA B11 SUNNY 82/88

632009

AMORTIGUADOR DEL LH 54303-01A00

<https://ikoyama.com/img/632008.png>
[https://ikoyama.com/img/632008\(2\).png](https://ikoyama.com/img/632008(2).png)

NISSAN SENTRA B11 SUNNY 82/88

632008

AMORTIGUADOR DEL RH 54302-01A00


<https://ikoyama.com/img/48531-20111.png>
[https://ikoyama.com/img/48531-20111\(2\).png](https://ikoyama.com/img/48531-20111(2).png)

NISSAN SENTRA B11 SUNNY 82/88 TOYOTA CALDINA 95/UP

48531-20111

AMORTIGUADOR POST RH LH 443073

<https://ikoyama.com/img/54303-50A00.png>
[https://ikoyama.com/img/54303-50A00\(2\).png](https://ikoyama.com/img/54303-50A00(2).png)

NISSAN SENTRA B12 AD WAGON 89/99 OJO CHINO 87/91

54303-50A00

AMORTIGUADOR DEL LH 632041

<https://ikoyama.com/img/54302-50A00.png>
[https://ikoyama.com/img/54302-50A00\(2\).png](https://ikoyama.com/img/54302-50A00(2).png)

NISSAN SENTRA B12 AD WAGON 89/99 OJO CHINO 87/91

54302-50A00

AMORTIGUADOR DEL RH 632040

<https://ikoyama.com/img/55303-51Y00.png>
[https://ikoyama.com/img/55303-51Y00\(2\).png](https://ikoyama.com/img/55303-51Y00(2).png)

NISSAN SENTRA B12 B13 87/UPV16 CLASICO 92/UP

55303-51Y00

AMORTIGUADOR POST LH 632073

<https://ikoyama.com/img/55302-51Y00.png>
[https://ikoyama.com/img/55302-51Y00\(2\).png](https://ikoyama.com/img/55302-51Y00(2).png)

NISSAN SENTRA B12 B13 87/UPV16 CLASICO 92/UP

55302-51Y00

AMORTIGUADOR POST RH 632072

<https://ikoyama.com/img/54303-54Y00.png>
[https://ikoyama.com/img/54303-54Y00\(2\).png](https://ikoyama.com/img/54303-54Y00(2).png)

NISSAN SENTRA B13 V16 CLASICO 92/UP

54303-54Y00


AMORTIGUADOR DEL LH 633116


<https://ikoyama.com/img/54302-54Y00.png>
[https://ikoyama.com/img/54302-54Y00\(2\).png](https://ikoyama.com/img/54302-54Y00(2).png)

NISSAN SENTRA B13 V16 CLASICO 92/UP

54302-54Y00

AMORTIGUADOR DEL RH 633115


<https://ikoyama.com/img/633116.png>
[https://ikoyama.com/img/633116\(2\).png](https://ikoyama.com/img/633116(2).png)

NISSAN SENTRA B13 V16 CLASICO 92/UP

633116

AMORTIGUADOR HIDRAULICO DEL LH


<https://ikoyama.com/img/54303-1N310.png>
[https://ikoyama.com/img/54303-1N310\(2\).png](https://ikoyama.com/img/54303-1N310(2).png)

NISSAN SENTRA B14 SUNNY ALMERA 97/02

54303-1N310

AMORTIGUADOR DEL LH 333239

<https://ikoyama.com/img/633115.png>
[https://ikoyama.com/img/633115\(2\).png](https://ikoyama.com/img/633115(2).png)

NISSAN SENTRA B13 V16 CLASICO 92/UP

633115

AMORTIGUADOR HIDRAULICO DEL RH


<https://ikoyama.com/img/54302-1N310.png>
[https://ikoyama.com/img/54302-1N310\(2\).png](https://ikoyama.com/img/54302-1N310(2).png)

NISSAN SENTRA B14 SUNNY ALMERA 97/02

54302-1N310

AMORTIGUADOR DEL RH 333238


<https://ikoyama.com/img/56210-0M011.png>
[https://ikoyama.com/img/56210-0M011\(2\).png](https://ikoyama.com/img/56210-0M011(2).png)

NISSAN SENTRA B14 SUNNY ALMERA 97/02

56210-0M011

AMORTIGUADOR POST RH LH 341194

<https://ikoyama.com/img/56210-4M400.png>
[https://ikoyama.com/img/56210-4M400\(2\).png](https://ikoyama.com/img/56210-4M400(2).png)

NISSAN SENTRA B15 ALMERA 00/UP

56210-4M400

AMORTIGUADOR POST RH LH 341279


<https://ikoyama.com/img/54303-5M400.png>
[https://ikoyama.com/img/54303-5M400\(2\).png](https://ikoyama.com/img/54303-5M400(2).png)

NISSAN SENTRA B15 ALMERA AD WAGON MODERNO 00/UP

54303-5M400

AMORTIGUADOR DEL LH 332117


<https://ikoyama.com/img/54302-5M400.png>
[https://ikoyama.com/img/54302-5M400\(2\).png](https://ikoyama.com/img/54302-5M400(2).png)

NISSAN SENTRA B15 ALMERA AD WAGON MODERNO 00/UP

54302-5M400

AMORTIGUADOR DEL RH 332116


<https://ikoyama.com/img/56210-9M900.png>
[https://ikoyama.com/img/56210-9M900\(2\).png](https://ikoyama.com/img/56210-9M900(2).png)

NISSAN SENTRA B16

56210-9M900

AMORTIGUADOR POST RH LH

<https://ikoyama.com/img/E4303-9AN1A.png>
[https://ikoyama.com/img/E4303-9AN1A\(2\).png](https://ikoyama.com/img/E4303-9AN1A(2).png)

NISSAN SENTRA B17 13/20

E4303-9AN1A

AMORTIGUADOR DEL LH 339328

<https://ikoyama.com/img/E4302-9AM1A.png>
[https://ikoyama.com/img/E4302-9AM1A\(2\).png](https://ikoyama.com/img/E4302-9AM1A(2).png)

NISSAN SENTRA B17 13/20

E4302-9AM1A

AMORTIGUADOR DEL RH 339327

<https://ikoyama.com/img/E6210-9AN0A.png>
[https://ikoyama.com/img/E6210-9AN0A\(2\).png](https://ikoyama.com/img/E6210-9AN0A(2).png)

NISSAN SENTRA B17 13/20

E6210-9AN0A

AMORTIGUADOR POS RH LH 349212


<https://ikoyama.com/img/54303-ED002.png>
[https://ikoyama.com/img/54303-ED002\(2\).png](https://ikoyama.com/img/54303-ED002(2).png)

NISSAN TIIDA 05/UP

54303-ED002

AMORTIGUADOR DEL LH 333391


<https://ikoyama.com/img/54302-ED002.png>
[https://ikoyama.com/img/54302-ED002\(2\).png](https://ikoyama.com/img/54302-ED002(2).png)

NISSAN TIIDA 05/UP

54302-ED002

AMORTIGUADOR DEL RH 333390


<https://ikoyama.com/img/56210-EL00A.png>
[https://ikoyama.com/img/56210-EL00A\(2\).png](https://ikoyama.com/img/56210-EL00A(2).png)

NISSAN TIIDA 05/UP

56210-EL00A

AMORTIGUADOR POST RH LH 343458



<https://ikoyama.com/img/56200-AX602.png>
NISSAN TIIDA 14/UP

[https://ikoyama.com/img/56200-AX602\(2\).png](https://ikoyama.com/img/56200-AX602(2).png)

AMORTIGUADOR POST RH LH

E4303-5EE0B



<https://ikoyama.com/img/E6210-9KM0A.png>
NISSAN VERSA 12/UP

[https://ikoyama.com/img/E6210-9KM0A\(2\).png](https://ikoyama.com/img/E6210-9KM0A(2).png)

AMORTIGUADOR POST

E6210-9KM0A

<https://ikoyama.com/img/E4303-5EE0B.png>
NISSAN VERSA 19/UP

[https://ikoyama.com/img/E4303-5EE0B\(2\).png](https://ikoyama.com/img/E4303-5EE0B(2).png)

AMORTIGUADOR DEL LH

E4303-5EE0B



<https://ikoyama.com/img/E4302-5EE0B.png>
NISSAN VERSA 19/UP



[https://ikoyama.com/img/E4302-5EE0B\(2\).png](https://ikoyama.com/img/E4302-5EE0B(2).png)

AMORTIGUADOR DEL RH

E4302-5EE0B



<https://ikoyama.com/img/E6210-5EE0B.png>
NISSAN VERSA 19/UP

[https://ikoyama.com/img/E6210-5EE0B\(2\).png](https://ikoyama.com/img/E6210-5EE0B(2).png)

AMORTIGUADOR POST RH LH

E6210-5EE0B



<https://ikoyama.com/img/332153.png>
NISSAN VERSA MARCH 12/UP



[https://ikoyama.com/img/332153\(2\).png](https://ikoyama.com/img/332153(2).png)

AMORTIGUADOR DEL LH 332153

332153



<https://ikoyama.com/img/332152.png>
NISSAN VERSA MARCH 12/UP



[https://ikoyama.com/img/332152\(2\).png](https://ikoyama.com/img/332152(2).png)

AMORTIGUADOR DEL RH 332152

332152



<https://ikoyama.com/img/54303-JG000.png>
NISSAN X-TRAIL QASHQAI 07/14 KOLEOS 07/16



[https://ikoyama.com/img/54303-JG000\(2\).png](https://ikoyama.com/img/54303-JG000(2).png)

AMORTIGUADOR DEL LH 339199

54303-JG000



<https://ikoyama.com/img/54302-JG000.png>

NISSAN XTRAIL QASHQAI 07/14 KOLEOS 07/16

AMORTIGUADOR DEL RH 339198



[https://ikoyama.com/img/54302-JG000\(2\).png](https://ikoyama.com/img/54302-JG000(2).png)

54302-JG000



<https://ikoyama.com/img/56210-JG000.png>

NISSAN XTRAIL QASHQAI 07/UP

AMORTIGUADOR POST RH LH 349078

[https://ikoyama.com/img/56210-JG000\(2\).png](https://ikoyama.com/img/56210-JG000(2).png)

56210-JG000



<https://ikoyama.com/img/E4303-5HA3A.png>

NISSAN XTRAIL QASHQAI 14/UP

AMORTIGUADOR DEL LH 3340159

[https://ikoyama.com/img/E4303-5HA3A\(2\).png](https://ikoyama.com/img/E4303-5HA3A(2).png)

E4303-5HA3A



<https://ikoyama.com/img/54302-5HA3A.png>

NISSAN XTRAIL QASHQAI 14/UP

AMORTIGUADOR DEL RH 3340158

[https://ikoyama.com/img/54302-5HA3A\(2\).png](https://ikoyama.com/img/54302-5HA3A(2).png)

54302-5HA3A



<https://ikoyama.com/img/543038H600.png>

NISSAN X-TRAIL T30 01/07

AMORTIGUADOR DEL LH

[https://ikoyama.com/img/543038H600\(2\).png](https://ikoyama.com/img/543038H600(2).png)

543038H600



<https://ikoyama.com/img/543028H600.png>

NISSAN X-TRAIL T30 01/07

AMORTIGUADOR DEL RH

[https://ikoyama.com/img/543028H600\(2\).png](https://ikoyama.com/img/543028H600(2).png)

543028H600



<https://ikoyama.com/img/553038H304.png>

NISSAN X-TRAIL T30 01/07

AMORTIGUADOR POST LH

[https://ikoyama.com/img/553038H304\(2\).png](https://ikoyama.com/img/553038H304(2).png)

553038H304



<https://ikoyama.com/img/553028H304.png>

NISSAN X-TRAIL T30 01/07

AMORTIGUADOR POST RH

[https://ikoyama.com/img/553028H304\(2\).png](https://ikoyama.com/img/553028H304(2).png)

553028H304



<https://ikoyama.com/img/333839.png> [https://ikoyama.com/img/333839\(2\).png](https://ikoyama.com/img/333839(2).png)

PEUGEOT/CITROEN 306 520 PARTNER BERLINGO 09/UP

AMORTIGUADOR DEL LH 333839

333839



<https://ikoyama.com/img/333838.png> [https://ikoyama.com/img/333838\(2\).png](https://ikoyama.com/img/333838(2).png)

PEUGEOT/CITROEN 306 520 PARTNER BERLINGO 09/UP

AMORTIGUADOR DEL RH 333838

333838



<https://ikoyama.com/img/341166.png> [https://ikoyama.com/img/341166\(2\).png](https://ikoyama.com/img/341166(2).png)

PEUGEOT/CITROEN 306 520 PARTNER BERLINGO 09/UP

AMORTIGUADOR POST RH LH 341166

341166

<https://ikoyama.com/img/338737.png> [https://ikoyama.com/img/338737\(2\).png](https://ikoyama.com/img/338737(2).png)

RENAUL DUSTER 4x2 16/UP

AMORTIGUADOR DEL RH LH 338737

338737



<https://ikoyama.com/img/623380218.png> [https://ikoyama.com/img/623380218\(2\).png](https://ikoyama.com/img/623380218(2).png)

RENAUL DUSTER 4x2 12/UP

AMORTIGUADOR POST RH LH YPRT1563

623380218



<https://ikoyama.com/img/8200811407.png> [https://ikoyama.com/img/8200811407\(2\).png](https://ikoyama.com/img/8200811407(2).png)

RENAUL DUSTER 4x4 12/22

AMORTIGUADOR POST RH LH 338738

8200811407



<https://ikoyama.com/img/543020634R.png> [https://ikoyama.com/img/543020634R\(2\).png](https://ikoyama.com/img/543020634R(2).png)

RENAUL FLUENCE 11/16

AMORTIGUADOR DEL RH LH

543020634R



<https://ikoyama.com/img/543020322R.png> [https://ikoyama.com/img/543020322R\(2\).png](https://ikoyama.com/img/543020322R(2).png)

RENAUL LOGAN 14/16

AMORTIGUADOR DEL RH LH

543020322R


<https://ikoyama.com/img/562106313R.png>
[https://ikoyama.com/img/562106313R\(2\).png](https://ikoyama.com/img/562106313R(2).png)

RENAULT LOGAN 14/16

562106313R

AMORTIGUADOR POST RH LH


<https://ikoyama.com/img/333741.png>
[https://ikoyama.com/img/333741\(2\).png](https://ikoyama.com/img/333741(2).png)

RENAULT LOGAN SANDERO STEPWAY 09/UP

333741

AMORTIGUADOR DEL RH LH 333741


<https://ikoyama.com/img/343418.png>
[https://ikoyama.com/img/343418\(2\).png](https://ikoyama.com/img/343418(2).png)

RENAULT LOGAN SANDERO STEPWAY 09/UP

343418

AMORTIGUADOR POST RH LH 343418


<https://ikoyama.com/img/543029774R.png>
[https://ikoyama.com/img/543029774R\(2\).png](https://ikoyama.com/img/543029774R(2).png)

RENAULT MASTER III 10/UP

543029774R

AMORTIGUADOR DEL RH LH 335835


<https://ikoyama.com/img/562100015R.png>
[https://ikoyama.com/img/562100015R\(2\).png](https://ikoyama.com/img/562100015R(2).png)

RENAULT MASTER III 10/UP

562100015R

AMORTIGUADOR POST RH LH 345702

<https://ikoyama.com/img/543026655R.png>
[https://ikoyama.com/img/543026655R\(2\).png](https://ikoyama.com/img/543026655R(2).png)

RENAULT OROCH 15/22

543026655R

AMORTIGUADOR DEL RH LH 543026655R


<https://ikoyama.com/img/562100449R.png>
[https://ikoyama.com/img/562100449R\(2\).png](https://ikoyama.com/img/562100449R(2).png)

RENAULT OROCH 15/22

562100449R

AMORTIGUADOR POST RH LH 562100449R


<https://ikoyama.com/img/44301-34003.png>
[https://ikoyama.com/img/44301-34003\(2\).png](https://ikoyama.com/img/44301-34003(2).png)

SSANGYONG KORANDO 11/18

44301-34003

AMORTIGUADOR DEL LH 44301-34003

<https://ikoyama.com/img/44302-34003.png>
SSANGYONG KORANDO 11/18

[https://ikoyama.com/img/44302-34003\(2\).png](https://ikoyama.com/img/44302-34003(2).png)

AMORTIGUADOR DEL RH 44302-34003

44302-34003



<https://ikoyama.com/img/45301-34100.png>

[https://ikoyama.com/img/45301-34100\(2\).png](https://ikoyama.com/img/45301-34100(2).png)

SSANGYONG KORANDO 11/18

AMORTIGUADOR POST RH LH 45301-34100

45301-34100

<https://ikoyama.com/img/44310-08C60.png>
SSANGYONG REXTON 12/UP

[https://ikoyama.com/img/44310-08C60\(2\).png](https://ikoyama.com/img/44310-08C60(2).png)

AMORTIGUADOR DEL RH LH

44310-08C60



<https://ikoyama.com/img/45310-08301.png>

[https://ikoyama.com/img/45310-08301\(2\).png](https://ikoyama.com/img/45310-08301(2).png)

SSANGYONG REXTON 12/UP

AMORTIGUADOR POST RH LH

45310-08301



<https://ikoyama.com/img/20360SA010.png>

SUBARU FORESTER SG 02/08

AMORTIGUADOR POST LH 334345

20360SA010



[https://ikoyama.com/img/20360SA010\(2\).png](https://ikoyama.com/img/20360SA010(2).png)



<https://ikoyama.com/img/20360SA000.png>

SUBARU FORESTER SG 02/08

AMORTIGUADOR POST RH 334344

20360SA000



[https://ikoyama.com/img/20360SA000\(2\).png](https://ikoyama.com/img/20360SA000(2).png)



<https://ikoyama.com/img/20310SA110.png>

SUBARU FORESTER SG 2.0 02/08

AMORTIGUADOR DEL LH 334343

20310SA110



[https://ikoyama.com/img/20310SA110\(2\).png](https://ikoyama.com/img/20310SA110(2).png)



<https://ikoyama.com/img/20310SA100.png>

SUBARU FORESTER SG 2.0 02/08

AMORTIGUADOR DEL RH 334342

20310SA100



[https://ikoyama.com/img/20310SA100\(2\).png](https://ikoyama.com/img/20310SA100(2).png)



[https://ikoyama.com/img/20310SA051\(2\).png](https://ikoyama.com/img/20310SA051(2).png)

<https://ikoyama.com/img/20310SA051.png>

SUBARU FORESTER SG 2.5 02/08

AMORTIGUADOR DEL LH 334371

20310SA051



<https://ikoyama.com/img/20310SA041.png>

SUBARU FORESTER SG 2.5 02/08

AMORTIGUADOR DEL RH 334370

20310SA041



[https://ikoyama.com/img/20310SA041\(2\).png](https://ikoyama.com/img/20310SA041(2).png)



<https://ikoyama.com/img/20310SC070.png>

SUBARU FORESTER SH 08/13

AMORTIGUADOR DEL LH 339170

20310SC070



[https://ikoyama.com/img/20310SC070\(2\).png](https://ikoyama.com/img/20310SC070(2).png)



<https://ikoyama.com/img/20310SC060.png>

SUBARU FORESTER SH 08/13

AMORTIGUADOR DEL RH 339169

20310SC060



[https://ikoyama.com/img/20310SC060\(2\).png](https://ikoyama.com/img/20310SC060(2).png)




<https://ikoyama.com/img/20365SG100.png>

SUBARU FORESTER SH SJ 08/18

AMORTIGUADOR POST RH LH 341486 20365SC000

20365SG100



[https://ikoyama.com/img/20365SG100\(2\).png](https://ikoyama.com/img/20365SG100(2).png)



<https://ikoyama.com/img/20310SG011.png>

SUBARU FORESTER SJ 13/18 XV 12/17

AMORTIGUADOR DEL LH 339386 20310-FJ091

20310SG011



[https://ikoyama.com/img/20310SG011\(2\).png](https://ikoyama.com/img/20310SG011(2).png)



<https://ikoyama.com/img/20310SG020.png>


SUBARU FORESTER SJ 13/18 XV 12/17

AMORTIGUADOR DEL RH 339385 20310-FJ081

20310SG020



[https://ikoyama.com/img/20310SG020\(2\).png](https://ikoyama.com/img/20310SG020(2).png)



<https://ikoyama.com/img/20310SJ030.png>

SUBARU FORESTER SK 19/24

AMORTIGUADOR DEL LH 20310SJ030

20310SJ030



[https://ikoyama.com/img/20310SJ030\(2\).png](https://ikoyama.com/img/20310SJ030(2).png)



<https://ikoyama.com/img/20310SJ020.png>
SUBARU FORESTER SK 19/24

AMORTIGUADOR DEL RH 20310SJ020



[https://ikoyama.com/img/20310SJ020\(2\).png](https://ikoyama.com/img/20310SJ020(2).png)

20310SJ020



<https://ikoyama.com/img/20365SJ010.png>

SUBARU FORESTER SK 19/24

AMORTIGUADOR POST RH LH 20365SJ010

[https://ikoyama.com/img/20365SJ010\(2\).png](https://ikoyama.com/img/20365SJ010(2).png)

20365SJ010



<https://ikoyama.com/img/334471.png>
SUBARU IMPREZA 04/09

AMORTIGUADOR DEL LH 334471



[https://ikoyama.com/img/334471\(2\).png](https://ikoyama.com/img/334471(2).png)

334471



<https://ikoyama.com/img/334470.png>

SUBARU IMPREZA 04/09

AMORTIGUADOR DEL RH 334470



[https://ikoyama.com/img/334470\(2\).png](https://ikoyama.com/img/334470(2).png)

334470



<https://ikoyama.com/img/20313AA110.png>
SUBARU IMPREZA LEGACY 90/99

AMORTIGUADOR DEL LH 634084



[https://ikoyama.com/img/20313AA110\(2\).png](https://ikoyama.com/img/20313AA110(2).png)

20313AA110



<https://ikoyama.com/img/20313AA100.png>

SUBARU IMPREZA LEGACY 90/99

AMORTIGUADOR DEL RH 634083



[https://ikoyama.com/img/20313AA100\(2\).png](https://ikoyama.com/img/20313AA100(2).png)

20313AA100



<https://ikoyama.com/img/20360FA050.png>
SUBARU IMPREZA LEGACY 90/99

AMORTIGUADOR POST LH 634079



[https://ikoyama.com/img/20360FA050\(2\).png](https://ikoyama.com/img/20360FA050(2).png)

20360FA050



<https://ikoyama.com/img/20360FA040.png>

SUBARU IMPREZA LEGACY 90/99

AMORTIGUADOR POST RH 634078



[https://ikoyama.com/img/20360FA040\(2\).png](https://ikoyama.com/img/20360FA040(2).png)

20360FA040

<https://ikoyama.com/img/634084.png>
[https://ikoyama.com/img/634084\(2\).png](https://ikoyama.com/img/634084(2).png)

SUBARU IMPREZA LEGACY 90/99

634084

AMORTIGUADOR HIDRAULICO DEL LH

<https://ikoyama.com/img/634083.png>
[https://ikoyama.com/img/634083\(2\).png](https://ikoyama.com/img/634083(2).png)

SUBARU IMPREZA LEGACY 90/99

634083

AMORTIGUADOR HIDRAULICO DEL RH


<https://ikoyama.com/img/20365-FJ080.png>
[https://ikoyama.com/img/20365-FJ080\(2\).png](https://ikoyama.com/img/20365-FJ080(2).png)

SUBARU XV 12/17

20365-FJ080

AMORTIGUADOR POST RH LH 340118


<https://ikoyama.com/img/20310-FL090.png>
[https://ikoyama.com/img/20310-FL090\(2\).png](https://ikoyama.com/img/20310-FL090(2).png)

SUBARU XV 18/22

20310-FL090

AMORTIGUADOR DEL LH 20310FL090


<https://ikoyama.com/img/20310-FL080.png>
[https://ikoyama.com/img/20310-FL080\(2\).png](https://ikoyama.com/img/20310-FL080(2).png)

SUBARU XV 18/22

20310-FL080

AMORTIGUADOR DEL RH 20310FL080


<https://ikoyama.com/img/20365-FL110.png>
[https://ikoyama.com/img/20365-FL110\(2\).png](https://ikoyama.com/img/20365-FL110(2).png)

SUBARU XV 18/22

20365-FL110

AMORTIGUADOR POST RH LH 3410090


<https://ikoyama.com/img/41602-59J10.png>
[https://ikoyama.com/img/41602-59J10\(2\).png](https://ikoyama.com/img/41602-59J10(2).png)

SUZUKI AERIO 00/08 LIANA BALENO CLESENT 95/02

41602-59J10

AMORTIGUADOR DEL LH 333432


<https://ikoyama.com/img/41601-59J10.png>
[https://ikoyama.com/img/41601-59J10\(2\).png](https://ikoyama.com/img/41601-59J10(2).png)

SUZUKI AERIO 00/08 LIANA BALENO CLESENT 95/02

41601-59J10

AMORTIGUADOR DEL RH 333431



<https://ikoyama.com/img/41802-59J10.png>

SUZUKI AERIO LIANA 00/08

AMORTIGUADOR POST LH 333357



[https://ikoyama.com/img/41802-59J10\(2\).png](https://ikoyama.com/img/41802-59J10(2).png)

41802-59J10



<https://ikoyama.com/img/41801-59J10.png>

SUZUKI AERIO LIANA 00/08

AMORTIGUADOR POST RH 333356



[https://ikoyama.com/img/41801-59J10\(2\).png](https://ikoyama.com/img/41801-59J10(2).png)

41801-59J10

<https://ikoyama.com/img/41602M79G80.png>

SUZUKI ALTO 02/UP

AMORTIGUADOR DEL LH 632141

[https://ikoyama.com/img/41602M79G80\(2\).png](https://ikoyama.com/img/41602M79G80(2).png)

41602M79G80

<https://ikoyama.com/img/41601M79G80.png>

SUZUKI ALTO 02/UP

AMORTIGUADOR DEL RH 632140

[https://ikoyama.com/img/41601M79G80\(2\).png](https://ikoyama.com/img/41601M79G80(2).png)

41601M79G80



<https://ikoyama.com/img/96316781.png>

SUZUKI ALTO 10/UP

AMORTIGUADOR POST RH LH 343304

[https://ikoyama.com/img/96316781\(2\).png](https://ikoyama.com/img/96316781(2).png)

96316781

<https://ikoyama.com/img/41601-76G00.png>

SUZUKI ALTO 98/2004

AMORTIGUADOR DEL RH(8)

[https://ikoyama.com/img/41601-76G00\(2\).png](https://ikoyama.com/img/41601-76G00(2).png)

41601-76G00



<https://ikoyama.com/img/4106961J00.png>

SUZUKI APV 07/UP

AMORTIGUADOR DEL LH 338097



[https://ikoyama.com/img/4106961J00\(2\).png](https://ikoyama.com/img/4106961J00(2).png)

4106961J00



<https://ikoyama.com/img/4106861J00.png>

SUZUKI APV 07/UP

AMORTIGUADOR DEL RH 338096

[https://ikoyama.com/img/4106861J00\(2\).png](https://ikoyama.com/img/4106861J00(2).png)

4106861J00


<https://ikoyama.com/img/4170060K00.png>
[https://ikoyama.com/img/4170060K00\(2\).png](https://ikoyama.com/img/4170060K00(2).png)

SUZUKI APV 07/UP

AMORTIGUADOR POST RH LH 348033

4170060K00
<https://ikoyama.com/img/41602-M68K01.png>
[https://ikoyama.com/img/41602-M68K01\(2\).png](https://ikoyama.com/img/41602-M68K01(2).png)

SUZUKI CELERIO 10/UP

AMORTIGUADOR DEL LH 41602-M68K01

41602-M68K01
<https://ikoyama.com/img/41601-M68K01.png>
[https://ikoyama.com/img/41601-M68K01\(2\).png](https://ikoyama.com/img/41601-M68K01(2).png)

SUZUKI CELERIO 10/UP

AMORTIGUADOR DEL RH 41601-M68K01

41601-M68K01
<https://ikoyama.com/img/41800-M68K00.png>
[https://ikoyama.com/img/41800-M68K00\(2\).png](https://ikoyama.com/img/41800-M68K00(2).png)

SUZUKI CELERIO 10/UP

AMORTIGUADOR POST RH LH 41800-M68K00

41800-M68K00
<https://ikoyama.com/img/41810-84M00.png>
[https://ikoyama.com/img/41810-84M00\(2\).png](https://ikoyama.com/img/41810-84M00(2).png)

SUZUKI CELERIO 15/UP

AMORTIGUADOR POST RH LH 3430032

41810-84M00
<https://ikoyama.com/img/41602-71L20.png>
[https://ikoyama.com/img/41602-71L20\(2\).png](https://ikoyama.com/img/41602-71L20(2).png)

SUZUKI ERTIGA 10/UP

AMORTIGUADOR DEL LH

41602-71L20
<https://ikoyama.com/img/41601-71L20.png>
[https://ikoyama.com/img/41601-71L20\(2\).png](https://ikoyama.com/img/41601-71L20(2).png)

SUZUKI ERTIGA 10/UP

AMORTIGUADOR DEL RH

41601-71L20
<https://ikoyama.com/img/41800-M60M00.png>
[https://ikoyama.com/img/41800-M60M00\(2\).png](https://ikoyama.com/img/41800-M60M00(2).png)

SUZUKI ERTIGA 10/UP

AMORTIGUADOR POST RH LH 3430031

41800-M60M00



<https://ikoyama.com/img/726780343L.png>

SUZUKI GRAN VITARA 96/04

AMORTIGUADOR DEL LH UPSZ135102



[https://ikoyama.com/img/726780343L\(2\).png](https://ikoyama.com/img/726780343L(2).png)

726780343L



<https://ikoyama.com/img/726780343R.png>

SUZUKI GRAN VITARA 96/04

AMORTIGUADOR DEL RH UPSZ135101



[https://ikoyama.com/img/726780343R\(2\).png](https://ikoyama.com/img/726780343R(2).png)

726780343R



<https://ikoyama.com/img/344440.png>

SUZUKI GRAN VITARA 96/04

AMORTIGUADOR POST RH LH 344440

[https://ikoyama.com/img/344440\(2\).png](https://ikoyama.com/img/344440(2).png)

344440



<https://ikoyama.com/img/41602-64J00.png>

SUZUKI GRAND NOMADE GRAND VITARA 07/UP

AMORTIGUADOR DEL LH 334465



[https://ikoyama.com/img/41602-64J00\(2\).png](https://ikoyama.com/img/41602-64J00(2).png)

41602-64J00



<https://ikoyama.com/img/41601-64J00.png>

SUZUKI GRAND NOMADE GRAND VITARA 07/UP

AMORTIGUADOR DEL RH 334464



[https://ikoyama.com/img/41601-64J00\(2\).png](https://ikoyama.com/img/41601-64J00(2).png)

41601-64J00



<https://ikoyama.com/img/41700-65J00.png>

SUZUKI GRAND NOMADE GRAND VITARA 07/UP

AMORTIGUADOR POST RH LH 343435



[https://ikoyama.com/img/41700-65J00\(2\).png](https://ikoyama.com/img/41700-65J00(2).png)

41700-65J00



<https://ikoyama.com/img/333426.png>

SUZUKI SUZUKI SWIFT III MZ EZ 05/11

AMORTIGUADOR DEL LH 333426



[https://ikoyama.com/img/333426\(2\).png](https://ikoyama.com/img/333426(2).png)

333426



<https://ikoyama.com/img/339338.png>

SUZUKI SUZUKI SX4 09/14

AMORTIGUADOR DEL LH 339338



[https://ikoyama.com/img/339338\(2\).png](https://ikoyama.com/img/339338(2).png)

339338



<https://ikoyama.com/img/339339.png>

SUZUKI SUZUKI SX4 09/14

AMORTIGUADOR DEL RH 339339

339339



[https://ikoyama.com/img/343493\(2\).png](https://ikoyama.com/img/343493(2).png)

<https://ikoyama.com/img/343493.png>

SUZUKI SUZUKI SX4 09/14

AMORTIGUADOR POST RH LH 343493

343493



<https://ikoyama.com/img/41602-58M00.png>

SUZUKI SWIFT 11/UP

AMORTIGUADOR DEL LH 338095

41602-58M00



[https://ikoyama.com/img/41601-58M00\(2\).png](https://ikoyama.com/img/41601-58M00(2).png)

<https://ikoyama.com/img/41601-58M00.png>

SUZUKI SWIFT 11/UP

AMORTIGUADOR DEL RH 338094

41601-58M00



<https://ikoyama.com/img/41810-58M00.png>

SUZUKI SWIFT 11/UP

AMORTIGUADOR POST RH LH 348084

41810-58M00



<https://ikoyama.com/img/333425.png>

SUZUKI SWIFT III MZ EZ 05/11

AMORTIGUADOR DEL RH 333425

333425



[https://ikoyama.com/img/333425\(2\).png](https://ikoyama.com/img/333425(2).png)

<https://ikoyama.com/img/41800-63J00.png>

[https://ikoyama.com/img/41800-63J00\(2\).png](https://ikoyama.com/img/41800-63J00(2).png)

SUZUKI SWIFT III MZ EZ 05/11

AMORTIGUADOR POST RH LH 343464

41800-63J00



<https://ikoyama.com/img/41602-54P00.png>

SUZUKI VITARA 15/22 SX-4 15/21

AMORTIGUADOR DEL LH 3358008

41602-54P00



[https://ikoyama.com/img/41602-54P00\(2\).png](https://ikoyama.com/img/41602-54P00(2).png)



<https://ikoyama.com/img/41601-54P00.png>
SUZUKI VITARA 15/22 SX-4 15/21

AMORTIGUADOR DEL RH 3358007



[https://ikoyama.com/img/41601-54P00\(2\).png](https://ikoyama.com/img/41601-54P00(2).png)

41601-54P00



<https://ikoyama.com/img/41800-54P01.png>
SUZUKI VITARA 15/22 SX-4 15/21

AMORTIGUADOR POST RH LH 3438005

[https://ikoyama.com/img/41800-54P01\(2\).png](https://ikoyama.com/img/41800-54P01(2).png)

41800-54P01

<https://ikoyama.com/img/48531-35190.png>
TOYOTA 2KD 1KD VIGO FORTUNER 01/ON

AMORTIGUADOR POST RH LH 443241(10)

[https://ikoyama.com/img/48531-35190\(2\).png](https://ikoyama.com/img/48531-35190(2).png)

48531-35190

<https://ikoyama.com/img/48500-29055.png>
TOYOTA 4A CORONA 18R 73/79

AMORTIGUADOR DEL 443071(10)

[https://ikoyama.com/img/48500-29055\(2\).png](https://ikoyama.com/img/48500-29055(2).png)

48500-29055

<https://ikoyama.com/img/3320029.png>
TOYOTA AGYA 18/UP

AMORTIGUADOR DEL LH 48510BZ710

[https://ikoyama.com/img/3320029\(2\).png](https://ikoyama.com/img/3320029(2).png)

3320029

<https://ikoyama.com/img/3320028.png>
TOYOTA AGYA 18/UP

AMORTIGUADOR DEL RH 48510BZ710

[https://ikoyama.com/img/3320028\(2\).png](https://ikoyama.com/img/3320028(2).png)

3320028



<https://ikoyama.com/img/48531-BZ530.png>
TOYOTA AGYA 18/UP

AMORTIGUADOR POST RH LH 3430034

[https://ikoyama.com/img/48531-BZ530\(2\).png](https://ikoyama.com/img/48531-BZ530(2).png)

48531-BZ530



<https://ikoyama.com/img/48531-BZ490.png>
TOYOTA AVANZA 08/14

AMORTIGUADOR POST LH RH 3430058

[https://ikoyama.com/img/48531-BZ490\(2\).png](https://ikoyama.com/img/48531-BZ490(2).png)

48531-BZ490



<https://ikoyama.com/img/48520-BZ750.png>

TOYOTA AVANZA 08/UP

AMORTIGUADOR DEL LH B2354

48520-BZ750

[https://ikoyama.com/img/48520-BZ750\(2\).png](https://ikoyama.com/img/48520-BZ750(2).png)



<https://ikoyama.com/img/48510-BZ750.png>

TOYOTA AVANZA 08/UP

AMORTIGUADOR DEL RH B2353

48510-BZ750

[https://ikoyama.com/img/48510-BZ750\(2\).png](https://ikoyama.com/img/48510-BZ750(2).png)



<https://ikoyama.com/img/724680016L.png>

TOYOTA AVANZA 15/UP

AMORTIGUADOR DEL LH 99701026

724680016L

[https://ikoyama.com/img/724680016L\(2\).png](https://ikoyama.com/img/724680016L(2).png)



<https://ikoyama.com/img/724680016R.png>

TOYOTA AVANZA 15/UP

AMORTIGUADOR DEL RH 99701025

724680016R

[https://ikoyama.com/img/724680016R\(2\).png](https://ikoyama.com/img/724680016R(2).png)

<https://ikoyama.com/img/48520-BZA80.png>

TOYOTA AVANZA 21/UP

AMORTIGUADOR DEL LH

48520-BZA80

[https://ikoyama.com/img/48520-BZA80\(2\).png](https://ikoyama.com/img/48520-BZA80(2).png)

<https://ikoyama.com/img/48510-BZE50.png>

TOYOTA AVANZA 21/UP

AMORTIGUADOR DEL RH

48510-BZE50

[https://ikoyama.com/img/48510-BZE50\(2\).png](https://ikoyama.com/img/48510-BZE50(2).png)



<https://ikoyama.com/img/48531-BZB10.png>

TOYOTA AVANZA 21/UP

AMORTIGUADOR POST LH RH

48531-BZB10

[https://ikoyama.com/img/48531-BZB10\(2\).png](https://ikoyama.com/img/48531-BZB10(2).png)

<https://ikoyama.com/img/48531-B4010.png>

TOYOTA AVANZA E2990 07/UP

AMORTIGUADOR POST RH LH

48531-B4010

[https://ikoyama.com/img/48531-B4010\(2\).png](https://ikoyama.com/img/48531-B4010(2).png)

<https://ikoyama.com/img/444169.png>

[https://ikoyama.com/img/444169\(2\).png](https://ikoyama.com/img/444169(2).png)

TOYOTA COASTER 82/93 B20 B30

444169

AMORTIGUADOR HIDRAULICO POST RH LH



<https://ikoyama.com/img/48511-36110.png>

[https://ikoyama.com/img/48511-36110\(2\).png](https://ikoyama.com/img/48511-36110(2).png)

TOYOTA COASTER 82/UP

48511-36110

AMORTIGUADOR DEL RH LH 445063



<https://ikoyama.com/img/624380211.png>

[https://ikoyama.com/img/624380211\(2\).png](https://ikoyama.com/img/624380211(2).png)

TOYOTA COROLLA 07/UP

624380211

AMORTIGUADOR POST RH LH 48530-026



<https://ikoyama.com/img/332012.png>

[https://ikoyama.com/img/332012\(2\).png](https://ikoyama.com/img/332012(2).png)

TOYOTA COROLLA 89/UP

332012

AMORTIGUADOR POST LH 332012



<https://ikoyama.com/img/332011.png>

[https://ikoyama.com/img/332011\(2\).png](https://ikoyama.com/img/332011(2).png)

TOYOTA COROLLA 89/UP

332011

AMORTIGUADOR POST RH 332011



<https://ikoyama.com/img/48510-12550.png>

[https://ikoyama.com/img/48510-12550\(2\).png](https://ikoyama.com/img/48510-12550(2).png)

TOYOTA COROLLA DIESEL CARTUCHO 91/99

48510-12550

AMORTIGUADOR DEL RH LH 365064



<https://ikoyama.com/img/3410014.png>

[https://ikoyama.com/img/3410014\(2\).png](https://ikoyama.com/img/3410014(2).png)

TOYOTA COROLLA MODERNO 15/ON

3410014

AMORTIGUADOR POST RH LH 3410014



<https://ikoyama.com/img/3410014A.png>

[https://ikoyama.com/img/3410014A\(2\).png](https://ikoyama.com/img/3410014A(2).png)

TOYOTA COROLLA MODERNO 15/ON

3410014A

AMORTIGUADOR POST RH LH 3410014 (largo)


<https://ikoyama.com/img/3340048.png>

TOYOTA COROLLA MODERNO 15/UP

AMORTIGUADOR DEL LH 3340048


[https://ikoyama.com/img/3340048\(2\).png](https://ikoyama.com/img/3340048(2).png)
3340048

<https://ikoyama.com/img/3340047.png>

TOYOTA COROLLA MODERNO 15/UP

AMORTIGUADOR DEL RH 3340047


[https://ikoyama.com/img/3340047\(2\).png](https://ikoyama.com/img/3340047(2).png)
3340047

<https://ikoyama.com/img/48540-02120.png>

TOYOTA COROLLA SEDAN 90/99

AMORTIGUADOR POST LH 333117


[https://ikoyama.com/img/48540-02120\(2\).png](https://ikoyama.com/img/48540-02120(2).png)
48540-02120

<https://ikoyama.com/img/48530-02130.png>

TOYOTA COROLLA SEDAN 90/99

AMORTIGUADOR POST RH 333116


[https://ikoyama.com/img/48530-02130\(2\).png](https://ikoyama.com/img/48530-02130(2).png)
48530-02130

<https://ikoyama.com/img/48520-02150.png>

TOYOTA COROLLA SEDAN MODERNO 01/08 COROLLON

AMORTIGUADOR DEL LH 334324

[https://ikoyama.com/img/48520-02150\(2\).png](https://ikoyama.com/img/48520-02150(2).png)
48520-02150

<https://ikoyama.com/img/48510-02150.png>

TOYOTA COROLLA SEDAN MODERNO 01/08 COROLLON

AMORTIGUADOR DEL RH 334323


[https://ikoyama.com/img/48510-02150\(2\).png](https://ikoyama.com/img/48510-02150(2).png)
48510-02150

<https://ikoyama.com/img/48530-02180.png>

TOYOTA COROLLA SEDAN MODERNO 01/UP

AMORTIGUADOR POST RH LH 341322

[https://ikoyama.com/img/48530-02180\(2\).png](https://ikoyama.com/img/48530-02180(2).png)
48530-02180

<https://ikoyama.com/img/48520-12C20.png>

TOYOTA COROLLA SEDAN MODERNO COROLLON 08/13

AMORTIGUADOR DEL LH 339131


[https://ikoyama.com/img/48520-12C20\(2\).png](https://ikoyama.com/img/48520-12C20(2).png)
48520-12C20


<https://ikoyama.com/img/48510-12D20.png>
[https://ikoyama.com/img/48510-12D20\(2\).png](https://ikoyama.com/img/48510-12D20(2).png)

TOYOTA COROLLA SEDAN MODERNO COROLLON 08/13

48510-12D20

AMORTIGUADOR DEL RH 339130


<https://ikoyama.com/img/4853002700.png>
[https://ikoyama.com/img/4853002700\(2\).png](https://ikoyama.com/img/4853002700(2).png)

TOYOTA COROLLA SEDAN MODERNO COROLLON 08/13

4853002700

AMORTIGUADOR POST RH LH 341363


<https://ikoyama.com/img/48520-12610-L.png>
[https://ikoyama.com/img/48520-12610-L\(2\).png](https://ikoyama.com/img/48520-12610-L(2).png)

TOYOTA COROLLA SEDAN REF SPRINTER C/ ROSCA 90/99

48520-12610-L

AMORTIGUADOR DEL LH 333115-RE


<https://ikoyama.com/img/48510-12750-R.png>
[https://ikoyama.com/img/48510-12750-R\(2\).png](https://ikoyama.com/img/48510-12750-R(2).png)

TOYOTA COROLLA SEDAN REF SPRINTER C/ ROSCA 90/99

48510-12750-R

AMORTIGUADOR DEL RH 333114-RE


<https://ikoyama.com/img/48520-12610.png>
[https://ikoyama.com/img/48520-12610\(2\).png](https://ikoyama.com/img/48520-12610(2).png)

TOYOTA COROLLA SEDAN SPRINTER EJE NORMAL 90/99

48520-12610

AMORTIGUADOR DEL LH 333115


<https://ikoyama.com/img/48510-12750.png>
[https://ikoyama.com/img/48510-12750\(2\).png](https://ikoyama.com/img/48510-12750(2).png)

TOYOTA COROLLA SEDAN SPRINTER EJE NORMAL 90/99

48510-12750

AMORTIGUADOR DEL RH 333114


<https://ikoyama.com/img/48530-19805.png>
[https://ikoyama.com/img/48530-19805\(2\).png](https://ikoyama.com/img/48530-19805(2).png)

TOYOTA COROLLA SPRINTER 90/99

48530-19805

AMORTIGUADOR POST RH LH 443102


<https://ikoyama.com/img/48511-12320.png>
[https://ikoyama.com/img/48511-12320\(2\).png](https://ikoyama.com/img/48511-12320(2).png)

TOYOTA COROLLA SW C/ROSCA 87/92

48511-12320

AMORTIGUADOR DEL LH 333119




<https://ikoyama.com/img/48510-12530.png>

TOYOTA COROLLA SW C/ROSCA 87/92

AMORTIGUADOR DEL RH 333118


[https://ikoyama.com/img/48510-12530\(2\).png](https://ikoyama.com/img/48510-12530(2).png)
48510-12530
<https://ikoyama.com/img/48510-20010.png>

TOYOTA CORONA 2T 3T CARTUCHO 80/89

AMORTIGUADOR DEL RH LH 665021

[https://ikoyama.com/img/48510-20010\(2\).png](https://ikoyama.com/img/48510-20010(2).png)
48510-20010
<https://ikoyama.com/img/48520-29285.png>

TOYOTA CORONA CARINA CALDINA AT190 ST191 CT190 96/UP

AMORTIGUADOR DEL LH 334138


[https://ikoyama.com/img/48520-29285\(2\).png](https://ikoyama.com/img/48520-29285(2).png)
48520-29285
<https://ikoyama.com/img/48510-29277.png>

TOYOTA CORONA CARINA CALDINA AT190 ST191 CT190 96/UP

AMORTIGUADOR DEL RH 334137


[https://ikoyama.com/img/48510-29277\(2\).png](https://ikoyama.com/img/48510-29277(2).png)
48510-29277
<https://ikoyama.com/img/48540-20820.png>

TOYOTA CORONA CARINA CALDINA AT190 ST191 CT190 96/UP

AMORTIGUADOR POST LH 334062


[https://ikoyama.com/img/48540-20820\(2\).png](https://ikoyama.com/img/48540-20820(2).png)
48540-20820
<https://ikoyama.com/img/48530-20820.png>

TOYOTA CORONA CARINA CALDINA AT190 ST191 CT190 96/UP

AMORTIGUADOR POST RH 334061


[https://ikoyama.com/img/48530-20820\(2\).png](https://ikoyama.com/img/48530-20820(2).png)
48530-20820
<https://ikoyama.com/img/485100D851.png>

TOYOTA ETIOS 18/UP

AMORTIGUADOR DEL RH LH

[https://ikoyama.com/img/485100D851\(2\).png](https://ikoyama.com/img/485100D851(2).png)
485100D851
<https://ikoyama.com/img/485300D330.png>

TOYOTA ETIOS 18/UP

AMORTIGUADOR POST RH LH


[https://ikoyama.com/img/485300D330\(2\).png](https://ikoyama.com/img/485300D330(2).png)
485300D330


<https://ikoyama.com/img/4853109450.png>
[https://ikoyama.com/img/4853109450\(2\).png](https://ikoyama.com/img/4853109450(2).png)

TOYOTA FORTUNER 05/15

AMORTIGUADOR POST RH LH 349017

4853109450
<https://ikoyama.com/img/4853109450REF.png>
[https://ikoyama.com/img/4853109450REF\(2\).png](https://ikoyama.com/img/4853109450REF(2).png)

TOYOTA FORTUNER 05/15

AMORTIGUADOR POST RH LH 349017

4853109450REF
<https://ikoyama.com/img/56110-01N00.png>
[https://ikoyama.com/img/56110-01N00\(2\).png](https://ikoyama.com/img/56110-01N00(2).png)

TOYOTA HIACE 3Y 4Y 2L 3L 86/UP

AMORTIGUADOR DEL RH LH 444132

56110-01N00
<https://ikoyama.com/img/48511-29526.png>
[https://ikoyama.com/img/48511-29526\(2\).png](https://ikoyama.com/img/48511-29526(2).png)

TOYOTA HIACE 5L

AMORTIGUADOR DEL RH LH 444104

48511-29526
<https://ikoyama.com/img/48511-80107.png>
[https://ikoyama.com/img/48511-80107\(2\).png](https://ikoyama.com/img/48511-80107(2).png)

TOYOTA HIACE 5L 2KD 05/19

AMORTIGUADOR DEL RH LH 344493

48511-80107
<https://ikoyama.com/img/48531-80736.png>
[https://ikoyama.com/img/48531-80736\(2\).png](https://ikoyama.com/img/48531-80736(2).png)

TOYOTA HIACE 5L 2KD 05/19

AMORTIGUADOR POST RH LH 344204

48531-80736
<https://ikoyama.com/img/48520-80646.png>
[https://ikoyama.com/img/48520-80646\(2\).png](https://ikoyama.com/img/48520-80646(2).png)

TOYOTA HIACE GDH300 19/UP

AMORTIGUADOR DEL LH 3310007

48520-80646
<https://ikoyama.com/img/48510-80A86.png>
[https://ikoyama.com/img/48510-80A86\(2\).png](https://ikoyama.com/img/48510-80A86(2).png)

TOYOTA HIACE GDH300 19/UP

AMORTIGUADOR DEL RH 3310006

48510-80A86


<https://ikoyama.com/img/48531-26A30A.png>
[https://ikoyama.com/img/48531-26A30A\(2\).png](https://ikoyama.com/img/48531-26A30A(2).png)

TOYOTA HIACE GDH300 19/UP

AMORTIGUADOR POST RH LH 3450021

48531-26A30A
<https://ikoyama.com/img/48531-26360.png>
[https://ikoyama.com/img/48531-26360\(2\).png](https://ikoyama.com/img/48531-26360(2).png)

TOYOTA HIACE LH102 103 110 113 115 89/95

AMORTIGUADOR POST RH LH 444123

48531-26360
<https://ikoyama.com/img/48531-26220.png>
[https://ikoyama.com/img/48531-26220\(2\).png](https://ikoyama.com/img/48531-26220(2).png)

TOYOTA HIACE LH108 109 118 119 86/UP

AMORTIGUADOR POST RH LH 444105

48531-26220
<https://ikoyama.com/img/444139.png>
[https://ikoyama.com/img/444139\(2\).png](https://ikoyama.com/img/444139(2).png)

TOYOTA HIACE NISSAN URVAN

AMORTIGUADOR DEL RH LH 444139

444139
<https://ikoyama.com/img/48510-8Z205REF.png>
[https://ikoyama.com/img/48510-8Z205REF\(2\).p](https://ikoyama.com/img/48510-8Z205REF(2).p)

TOYOTA HILUX 1GD 2GD REVO REF 15/UP

AMORTIGUADOR DEL RH LH

48510-8Z205REF
<https://ikoyama.com/img/48541-09210.png>
[https://ikoyama.com/img/48541-09210\(2\).png](https://ikoyama.com/img/48541-09210(2).png)

TOYOTA HILUX 1GD 2GD REVO REF 15/UP

AMORTIGUADOR POST LH

48541-09210
<https://ikoyama.com/img/48541-09210REF.png>
[https://ikoyama.com/img/48541-09210REF\(2\).p](https://ikoyama.com/img/48541-09210REF(2).p)

TOYOTA HILUX 1GD 2GD REVO REF 15/UP

AMORTIGUADOR POST LH

48541-09210REF
<https://ikoyama.com/img/48531-09840.png>
[https://ikoyama.com/img/48531-09840\(2\).png](https://ikoyama.com/img/48531-09840(2).png)

TOYOTA HILUX 1GD 2GD REVO REF 15/UP

AMORTIGUADOR POST RH

48531-09840



<https://ikoyama.com/img/48531-09840REF.png> [https://ikoyama.com/img/48531-09840REF\(2\).p](https://ikoyama.com/img/48531-09840REF(2).p)

TOYOTA HILUX 1GD 2GD REVO REF 15/UP

AMORTIGUADOR POST RH

48531-09840REF



<https://ikoyama.com/img/48511-39687.png> [https://ikoyama.com/img/48511-39687\(2\).png](https://ikoyama.com/img/48511-39687(2).png)

TOYOTA HILUX 3L 4X2 P/C 83/UP

AMORTIGUADOR DEL RH LH 443214

48511-39687



<https://ikoyama.com/img/MB-242115.png> [https://ikoyama.com/img/MB-242115\(2\).png](https://ikoyama.com/img/MB-242115(2).png)

TOYOTA HILUX 4X2 NISSAN CARAVAN 86/ON MIT MONTERO

AMORTIGUADOR POST 443198(10)

MB-242115



<https://ikoyama.com/img/48511-35280.png> [https://ikoyama.com/img/48511-35280\(2\).png](https://ikoyama.com/img/48511-35280(2).png)

TOYOTA HILUX 4X4 BARRA TORSION P/B 94/UP

AMORTIGUADOR DEL RH LH 444103

48511-35280



<https://ikoyama.com/img/48511-35360.png> [https://ikoyama.com/img/48511-35360\(2\).png](https://ikoyama.com/img/48511-35360(2).png)

TOYOTA HILUX 4X4 CON MUELLE P/B 86/UP

AMORTIGUADOR DEL RH LH 443106

48511-35360



<https://ikoyama.com/img/48531-60100.png> [https://ikoyama.com/img/48531-60100\(2\).png](https://ikoyama.com/img/48531-60100(2).png)

TOYOTA HILUX KD L200 PROBOX STRONGER

AMORTIGUADOR POST RH LH 444092

48531-60100




<https://ikoyama.com/img/56210-01N00.png> [https://ikoyama.com/img/56210-01N00\(2\).png](https://ikoyama.com/img/56210-01N00(2).png)

TOYOTA HILUX PROBOX OJO+ 443198 83/UP

AMORTIGUADOR POST RH LH 444055

56210-01N00



<https://ikoyama.com/img/48531-36160.png> [https://ikoyama.com/img/48531-36160\(2\).png](https://ikoyama.com/img/48531-36160(2).png)

TOYOTA HILUX REF OJO ANCHO COASTER 93/UP 86/14

AMORTIGUADOR POST RH LH 444178

48531-36160



<https://ikoyama.com/img/48510-09K60REF.png> [https://ikoyama.com/img/48510-09K60REF\(2\).p](https://ikoyama.com/img/48510-09K60REF(2).p)

TOYOTA HILUX VIGO 1KD 2KD FORTUNER REF 01/14

48510-09K60REF

AMORTIGUADOR DEL RH LH 341372



<https://ikoyama.com/img/48531-35190REF.png> [https://ikoyama.com/img/48531-35190REF\(2\).p](https://ikoyama.com/img/48531-35190REF(2).p)

TOYOTA HILUX VIGO 1KD 2KD FORTUNER REF 86/14

48531-35190REF

AMORTIGUADOR POST RH LH 443241



<https://ikoyama.com/img/48530-52440.png> [https://ikoyama.com/img/48530-52440\(2\).png](https://ikoyama.com/img/48530-52440(2).png)

TOYOTA PROBOX REFORZADO 99/UP

48530-52440

AMORTIGUADOR POST RH LH 343434



<https://ikoyama.com/img/4852009M80.png> [https://ikoyama.com/img/4852009M80\(2\).png](https://ikoyama.com/img/4852009M80(2).png)

TOYOTA RAV4 06/13

4852009M80

AMORTIGUADOR DEL LH 339032



<https://ikoyama.com/img/4851009U70.png> [https://ikoyama.com/img/4851009U70\(2\).png](https://ikoyama.com/img/4851009U70(2).png)

TOYOTA RAV4 06/13

4851009U70

AMORTIGUADOR DEL RH 339031



<https://ikoyama.com/img/485310R010.png> [https://ikoyama.com/img/485310R010\(2\).png](https://ikoyama.com/img/485310R010(2).png)

TOYOTA RAV4 06/13

485310R010

AMORTIGUADOR POST RH LH 349024



<https://ikoyama.com/img/48520-0R110.png> [https://ikoyama.com/img/48520-0R110\(2\).png](https://ikoyama.com/img/48520-0R110(2).png)

TOYOTA RAV4 13/19

48520-0R110

AMORTIGUADOR DEL LH 3350001



<https://ikoyama.com/img/48520-0R110.png> [https://ikoyama.com/img/48520-0R110\(2\).png](https://ikoyama.com/img/48520-0R110(2).png)

TOYOTA RAV4 13/19

48520-0R110

AMORTIGUADOR DEL LH 3350001



<https://ikoyama.com/img/48510-0R110.png> [https://ikoyama.com/img/48510-0R110\(2\).png](https://ikoyama.com/img/48510-0R110(2).png)

TOYOTA RAV4 13/19

48510-0R110

AMORTIGUADOR DEL RH 3350000



<https://ikoyama.com/img/48510-0R110.png> [https://ikoyama.com/img/48510-0R110\(2\).png](https://ikoyama.com/img/48510-0R110(2).png)

TOYOTA RAV4 13/19

48510-0R110

AMORTIGUADOR DEL RH 3350000



<https://ikoyama.com/img/48520-0R330.png>

TOYOTA RAV4 19/UP

AMORTIGUADOR DEL LH 3350045



[https://ikoyama.com/img/48520-0R330\(2\).png](https://ikoyama.com/img/48520-0R330(2).png)

48520-0R330



<https://ikoyama.com/img/48510-0R330.png>

TOYOTA RAV4 19/UP

AMORTIGUADOR DEL RH 3350044



[https://ikoyama.com/img/48510-0R330\(2\).png](https://ikoyama.com/img/48510-0R330(2).png)

48510-0R330

<https://ikoyama.com/img/48530-80895.png>

TOYOTA RAV4 19/UP

AMORTIGUADOR POS LH RH 3440083

[https://ikoyama.com/img/48530-80895\(2\).png](https://ikoyama.com/img/48530-80895(2).png)

48530-80895



<https://ikoyama.com/img/4852042080.png>

TOYOTA RAV4 CHERY TIGGO 00/05

AMORTIGUADOR DEL LH 335040

[https://ikoyama.com/img/4852042080\(2\).png](https://ikoyama.com/img/4852042080(2).png)

4852042080



<https://ikoyama.com/img/4851042080.png>

TOYOTA RAV4 CHERY TIGGO 00/05

AMORTIGUADOR DEL RH 335041



[https://ikoyama.com/img/4851042080\(2\).png](https://ikoyama.com/img/4851042080(2).png)

4851042080



<https://ikoyama.com/img/726680404L.png>

TOYOTA RUSH 18/UP

AMORTIGUADOR DEL LH SA1417



[https://ikoyama.com/img/726680404L\(2\).png](https://ikoyama.com/img/726680404L(2).png)

726680404L



<https://ikoyama.com/img/726680404R.png>

TOYOTA RUSH 18/UP

AMORTIGUADOR DEL RH SA1416



[https://ikoyama.com/img/726680404R\(2\).png](https://ikoyama.com/img/726680404R(2).png)

726680404R



<https://ikoyama.com/img/922380213.png>

TOYOTA RUSH 18/UP

AMORTIGUADOR POST RH LH SA1418

[https://ikoyama.com/img/922380213\(2\).png](https://ikoyama.com/img/922380213(2).png)

922380213

<https://ikoyama.com/img/48520-16070.png>

[https://ikoyama.com/img/48520-16070\(2\).png](https://ikoyama.com/img/48520-16070(2).png)

TOYOTA TERCEL EL40 90/94

48520-16070

AMORTIGUADOR DEL LH 333068



<https://ikoyama.com/img/48510-16290.png>

[https://ikoyama.com/img/48510-16290\(2\).png](https://ikoyama.com/img/48510-16290(2).png)

TOYOTA TERCEL EL40 90/94

48510-16290

AMORTIGUADOR DEL RH 333067



<https://ikoyama.com/img/48530-19265.png>

[https://ikoyama.com/img/48530-19265\(2\).png](https://ikoyama.com/img/48530-19265(2).png)

TOYOTA TERCEL EL40 90/94

48530-19265

AMORTIGUADOR POST RH LH 341125



<https://ikoyama.com/img/48520-19075.png>

[https://ikoyama.com/img/48520-19075\(2\).png](https://ikoyama.com/img/48520-19075(2).png)

TOYOTA TERCEL EL50 95/99

48520-19075

AMORTIGUADOR DEL LH 333210



<https://ikoyama.com/img/48510-19355.png>

[https://ikoyama.com/img/48510-19355\(2\).png](https://ikoyama.com/img/48510-19355(2).png)

TOYOTA TERCEL EL50 95/99

48510-19355

AMORTIGUADOR DEL RH 333209

<https://ikoyama.com/img/48530-16380.png>

[https://ikoyama.com/img/48530-16380\(2\).png](https://ikoyama.com/img/48530-16380(2).png)

TOYOTA TERCEL EL50 95/99

48530-16380

AMORTIGUADOR POST RH LH 341191



<https://ikoyama.com/img/48520-52010.png>

[https://ikoyama.com/img/48520-52010\(2\).png](https://ikoyama.com/img/48520-52010(2).png)

TOYOTA YARIS 05/13

48520-52010

AMORTIGUADOR DEL LH 334473



<https://ikoyama.com/img/48510-52790.png>

[https://ikoyama.com/img/48510-52790\(2\).png](https://ikoyama.com/img/48510-52790(2).png)

TOYOTA YARIS 05/13

48510-52790

AMORTIGUADOR DEL RH 334472


<https://ikoyama.com/img/48530-52B00.png>
[https://ikoyama.com/img/48530-52B00\(2\).png](https://ikoyama.com/img/48530-52B00(2).png)

TOYOTA YARIS 05/13

AMORTIGUADOR POST RH LH 343442

48530-52B00
<https://ikoyama.com/img/3330084.png>
[https://ikoyama.com/img/3330084\(2\).png](https://ikoyama.com/img/3330084(2).png)

TOYOTA YARIS 18/UP

AMORTIGUADOR DEL LH 3330084

3330084
<https://ikoyama.com/img/3330083.png>
[https://ikoyama.com/img/3330083\(2\).png](https://ikoyama.com/img/3330083(2).png)

TOYOTA YARIS 18/UP

AMORTIGUADOR DEL RH 3330083

3330083
<https://ikoyama.com/img/48530-52051.png>
[https://ikoyama.com/img/48530-52051\(2\).png](https://ikoyama.com/img/48530-52051(2).png)

TOYOTA YARIS 99/05

AMORTIGUADOR POST RH LH 343295

48530-52051
<https://ikoyama.com/img/48510-52031.png>
[https://ikoyama.com/img/48510-52031\(2\).png](https://ikoyama.com/img/48510-52031(2).png)

TOYOTA YARIS 99/UP PROBOX 99/05

AMORTIGUADOR DEL RH LH 333258

48510-52031
<https://ikoyama.com/img/48510-0D591.png>
[https://ikoyama.com/img/48510-0D591\(2\).png](https://ikoyama.com/img/48510-0D591(2).png)

TOYOTA YARIS ENVIDIA 14/UP

AMORTIGUADOR DEL RH LH B2350

48510-0D591
<https://ikoyama.com/img/48540-0D570.png>
[https://ikoyama.com/img/48540-0D570\(2\).png](https://ikoyama.com/img/48540-0D570(2).png)

TOYOTA YARIS ENVIDIA 14/UP

AMORTIGUADOR POST RH LH E20045

48540-0D570
<https://ikoyama.com/img/2H0413031G.png>
[https://ikoyama.com/img/2H0413031G\(2\).png](https://ikoyama.com/img/2H0413031G(2).png)

VW AMAROK 11/UP

AMORTIGUADOR DEL RH LH 315229

2H0413031G


<https://ikoyama.com/img/2H0513029J.png>
[https://ikoyama.com/img/2H0513029J\(2\).png](https://ikoyama.com/img/2H0513029J(2).png)

VW AMAROK 11/UP

AMORTIGUADOR POST RH LH 349144

2H0513029J
<https://ikoyama.com/img/377412503.png>
[https://ikoyama.com/img/377412503\(2\).png](https://ikoyama.com/img/377412503(2).png)

VW GOL METROPOLITANO 04/ON

AMORTIGUADOR DEL RH LH 377412503

377412503
<https://ikoyama.com/img/377513029.png>
[https://ikoyama.com/img/377513029\(2\).png](https://ikoyama.com/img/377513029(2).png)

VW GOL METROPOLITANO 04/ON

AMORTIGUADOR POST RH LH 377513029

377513029
<https://ikoyama.com/img/5U0513025E.png>
[https://ikoyama.com/img/5U0513025E\(2\).png](https://ikoyama.com/img/5U0513025E(2).png)

VW GOL VOYAGE SEDAN 08/22

AMORTIGUADOR POST RH LH 5U0513025E

5U0513025E
<https://ikoyama.com/img/5U0413031.png>
[https://ikoyama.com/img/5U0413031\(2\).png](https://ikoyama.com/img/5U0413031(2).png)

VW GOL VOYAGE SEDAN 13/UP

AMORTIGUADOR DEL RH LH 5U0413031


5U0413031

Especialistas en:

RESORTES



KOYAMA
SUSPENSION PARTS



<https://ikoyama.com/img/CG001.png>

[https://ikoyama.com/img/CG001\(2\).png](https://ikoyama.com/img/CG001(2).png)

CHANGUE COOLCAR 1400 10/UP

CG001

RESORTE DEL ORI 12X133X260X5 1/2 15631



<https://ikoyama.com/img/CG002.png>

[https://ikoyama.com/img/CG002\(2\).png](https://ikoyama.com/img/CG002(2).png)

CHANGUE COOLCAR 1400 10/UP

CG002

RESORTE POST ORI 12.5X106X305X6 7/8 11449



<https://ikoyama.com/img/CG004.png>

[https://ikoyama.com/img/CG004\(2\).png](https://ikoyama.com/img/CG004(2).png)

CHANGUE FREEDON 1100 10/13

CG004

RESORTE DEL ORI 12X130X310X8 1/2 11680



<https://ikoyama.com/img/CG003.png>

[https://ikoyama.com/img/CG003\(2\).png](https://ikoyama.com/img/CG003(2).png)

CHANGUE FREEDON 1100 10/13

CG003

RESORTE POST ORI 12X107X320X7 7/8 11679




<https://ikoyama.com/img/CH001.png>

[https://ikoyama.com/img/CH001\(2\).png](https://ikoyama.com/img/CH001(2).png)

CHEVROLET AVEO SAIL 06/UP

CH001

RESORTE DEL REF 13X144X340X6 1/4 8752



<https://ikoyama.com/img/CH002.png>

[https://ikoyama.com/img/CH002\(2\).png](https://ikoyama.com/img/CH002(2).png)

CHEVROLET AVEO SAIL 06/UP

CH002

RESORTE POST GNV 12.2X122X370X7 7/8 6241



<https://ikoyama.com/img/CH004.png>

[https://ikoyama.com/img/CH004\(2\).png](https://ikoyama.com/img/CH004(2).png)

CHEVROLET CORSA CHEVY TAXI 92/09

CH004

RESORTE DEL REF 12,2X131X320X6 1/2 10464



<https://ikoyama.com/img/CH005.png>

[https://ikoyama.com/img/CH005\(2\).png](https://ikoyama.com/img/CH005(2).png)

CHEVROLET CORSA CHEVY TAXI 92/09

CH005

RESORTE POST GNV 13.2X138X250X6 1/2 5255

<https://ikoyama.com/img/CH012.png>

[https://ikoyama.com/img/CH012\(2\).png](https://ikoyama.com/img/CH012(2).png)

CHEVROLET CRUZE 10/UP

CH012

RESORTE DEL ORI 13.5X158X395X 6 1/4 13702

<https://ikoyama.com/img/DG001.png>

[https://ikoyama.com/img/DG001\(2\).png](https://ikoyama.com/img/DG001(2).png)

CHEVROLET N200 DONGFENG MINI

DG001

RESORTE DEL ORI 11.7X131X315X8 3/4 9315

<https://ikoyama.com/img/CH008.png>

[https://ikoyama.com/img/CH008\(2\).png](https://ikoyama.com/img/CH008(2).png)

CHEVROLET N300 10/UP

CH008

RESORTE DEL ORI 12.7X133X315X8 5/8 10418

<https://ikoyama.com/img/CH013.png>

[https://ikoyama.com/img/CH013\(2\).png](https://ikoyama.com/img/CH013(2).png)

CHEVROLET OPTRA 09/13

CH013

RESORTE DEL ORI 13.5X154X350X5 1/2 11784

<https://ikoyama.com/img/CH011.png>

[https://ikoyama.com/img/CH011\(2\).png](https://ikoyama.com/img/CH011(2).png)

CHEVROLET SAIL 16/UP

CH011

RESORTE POST GNV 11.5X79X320X7 17471

<https://ikoyama.com/img/CH009.png>

[https://ikoyama.com/img/CH009\(2\).png](https://ikoyama.com/img/CH009(2).png)

CHEVROLET SPARK DAEWOO MATIZ 3 07/UP

CH009

RESORTE DEL REF 12.2X144X333X5 3/8 8250

<https://ikoyama.com/img/CH010.png>

[https://ikoyama.com/img/CH010\(2\).png](https://ikoyama.com/img/CH010(2).png)

CHEVROLET SPARK DAEWOO MATIZ 3 07/UP

CH010

RESORTE POST REF 12.2X122X280X5 5/8

<https://ikoyama.com/img/CH014.png>

[https://ikoyama.com/img/CH014\(2\).png](https://ikoyama.com/img/CH014(2).png)

CHEVROLET TRACKER 12/UP

CH014

RESORTE DEL ORI 13X138X340X 6 1/2



<https://ikoyama.com/img/CH006.png>
CHEVROLET VIVANT 03/UP

[https://ikoyama.com/img/CH006\(2\).png](https://ikoyama.com/img/CH006(2).png)

RESORTE DEL ORI 13.7X149X405X7 12540

CH006



<https://ikoyama.com/img/CH007.png>
CHEVROLET VIVANT 03/UP



[https://ikoyama.com/img/CH007\(2\).png](https://ikoyama.com/img/CH007(2).png)

RESORTE POST REF 14.2X146X322X5 7/8 12541

CH007




<https://ikoyama.com/img/D007.png>
DAEWU DAMAS 92/UP

[https://ikoyama.com/img/D007\(2\).png](https://ikoyama.com/img/D007(2).png)

RESORTE DEL 11X92X275X9

D007



<https://ikoyama.com/img/D008.png>
DAEWU NUBIRA 97/02

[https://ikoyama.com/img/D008\(2\).png](https://ikoyama.com/img/D008(2).png)

RESORTE DEL 12.5X143X415X7 1/2 13872

D008



<https://ikoyama.com/img/D003.png>
DAEWU RACER CIELO ESPERO 94/UP

[https://ikoyama.com/img/D003\(2\).png](https://ikoyama.com/img/D003(2).png)

RESORTE DEL REF 12.7X139X310X6 1/4 66

D003



<https://ikoyama.com/img/D004.png>
DAEWU RACER CIELO ESPERO 94/UP



[https://ikoyama.com/img/D004\(2\).png](https://ikoyama.com/img/D004(2).png)

RESORTE POST REF 13.7X162X270X7 1/4 65

D004



<https://ikoyama.com/img/D001.png>
DAEWU TICO 91/UP

[https://ikoyama.com/img/D001\(2\).png](https://ikoyama.com/img/D001(2).png)

RESORTE DEL REF 10.5X101X330X7 7/8 67

D001



<https://ikoyama.com/img/D006.png>
DAIHATSU TERIOS HUNTER NOMADE ZOTYE



[https://ikoyama.com/img/D006\(2\).png](https://ikoyama.com/img/D006(2).png)

RESORTE DEL REF 13.2X136X275X5 3/8 10505

D006



<https://ikoyama.com/img/D005.png>

[https://ikoyama.com/img/D005\(2\).png](https://ikoyama.com/img/D005(2).png)

DAIHATSU/ZOTYE TERIOS HUNTER NOMADE

RESORTE POST REF 12.7X131X300X6 1/4 9052

D005



<https://ikoyama.com/img/DF01.png>

[https://ikoyama.com/img/DF01\(2\).png](https://ikoyama.com/img/DF01(2).png)

DONG FENG MINI 06/12

RESORTE DEL ORI 11.5X131X315X8 1/2

DF01

<https://ikoyama.com/img/DS001.png>

[https://ikoyama.com/img/DS001\(2\).png](https://ikoyama.com/img/DS001(2).png)

DONGFENG DFSK GLORY 330 12/UP

RESORTE POST 14X82X295X6

DS001

<https://ikoyama.com/img/GE001.png>

[https://ikoyama.com/img/GE001\(2\).png](https://ikoyama.com/img/GE001(2).png)

GEELY CK MK 05/15

RESORTE POST GNV 12.5X162X455X9 1/4 1259APG

GE001

<https://ikoyama.com/img/GW001.png>

[https://ikoyama.com/img/GW001\(2\).png](https://ikoyama.com/img/GW001(2).png)

GREAT WALL GW HAVAL H3 10/UP

RESORTE POST REF 13X132X395X6 3/4 13102

GW001

<https://ikoyama.com/img/C002.png>

[https://ikoyama.com/img/C002\(2\).png](https://ikoyama.com/img/C002(2).png)

HONDA CIVIC 90/99

RESORTE POST ORI 11.2X101X378X10 1/2 74

C002

<https://ikoyama.com/img/C001.png>

[https://ikoyama.com/img/C001\(2\).png](https://ikoyama.com/img/C001(2).png)

HONDA CIVIC PARTNER 90/99

RESORTE DEL ORI 12.2X98X375X11 1/2 73

C001

<https://ikoyama.com/img/C005.png>

[https://ikoyama.com/img/C005\(2\).png](https://ikoyama.com/img/C005(2).png)

HONDA CRV 02/05

RESORTE DEL REF 15X169X330X5 1104

C005



<https://ikoyama.com/img/C006.png>

[https://ikoyama.com/img/C006\(2\).png](https://ikoyama.com/img/C006(2).png)

HONDA CRV 02/05

RESORTE POST 14.5X96X280X6

C006



<https://ikoyama.com/img/C004.png>

[https://ikoyama.com/img/C004\(2\).png](https://ikoyama.com/img/C004(2).png)

HONDA CRV 06/09

RESORTE POST REF 14.7X122X280X5 3/4 5624

C004



<https://ikoyama.com/img/C007.png>

[https://ikoyama.com/img/C007\(2\).png](https://ikoyama.com/img/C007(2).png)

HONDA CRV 06/14

RESORTE POST REF 15X96X280X6

C007



<https://ikoyama.com/img/C003.png>

[https://ikoyama.com/img/C003\(2\).png](https://ikoyama.com/img/C003(2).png)

HONDA CRV 2002/2006

RESORTE DEL ORI 15.2X169X330X4 7950

C003



<https://ikoyama.com/img/HY052.png>

[https://ikoyama.com/img/HY052\(2\).png](https://ikoyama.com/img/HY052(2).png)

HYUNDAI ELANTRA 07/10

RESORTE DEL ORI 14.5X176X330X5 15365

HY052



<https://ikoyama.com/img/HY029.png>

[https://ikoyama.com/img/HY029\(2\).png](https://ikoyama.com/img/HY029(2).png)

HYUNDAI ELANTRA 06/09

RESORTE POST GNV 11.7X101X370X9 1/2 533

HY029



<https://ikoyama.com/img/HY040.png>

[https://ikoyama.com/img/HY040\(2\).png](https://ikoyama.com/img/HY040(2).png)

HYUNDAI EON 09/UP

RESORTE POST GNV 10X101X280X7 11350

HY040



<https://ikoyama.com/img/HY051.png>

[https://ikoyama.com/img/HY051\(2\).png](https://ikoyama.com/img/HY051(2).png)

HYUNDAI EON 10/UP

RESORTE DEL REF 12X142X290X4 1/2

HY051



<https://ikoyama.com/img/HY041.png>

[https://ikoyama.com/img/HY041\(2\).png](https://ikoyama.com/img/HY041(2).png)

HYUNDAI GRAND i10 HATCHBACK 13/UP

HY041

RESORTE DEL ORI 12X116X330X6 1/2 16342



<https://ikoyama.com/img/HY042.png>

[https://ikoyama.com/img/HY042\(2\).png](https://ikoyama.com/img/HY042(2).png)

HYUNDAI GRAND i10 SEDAN 13/UP

HY042

RESORTE DEL ORI 11.5X115X340X6 1/8 11903



<https://ikoyama.com/img/HY053.png>

[https://ikoyama.com/img/HY053\(2\).png](https://ikoyama.com/img/HY053(2).png)

HYUNDAI GRAND i10 SEDAN 13/UP

HY053

RESORTE POST GNV 12X112X293X6 7/8 14201



<https://ikoyama.com/img/HY035.png>

[https://ikoyama.com/img/HY035\(2\).png](https://ikoyama.com/img/HY035(2).png)

HYUNDAI H-1 06/21

HY035

RESORTE DEL ORI 17.7X201X355X4 6400



<https://ikoyama.com/img/HY039.png>

[https://ikoyama.com/img/HY039\(2\).png](https://ikoyama.com/img/HY039(2).png)

HYUNDAI H-1 06/21

HY039

RESORTE DEL REF 19.2X203X325X4 3/4 4771




<https://ikoyama.com/img/HY047.png>

[https://ikoyama.com/img/HY047\(2\).png](https://ikoyama.com/img/HY047(2).png)

HYUNDAI H-1 06/21

HY047

RESORTE POST ORI 18.8X162X340X6 6335



<https://ikoyama.com/img/HY036.png>

[https://ikoyama.com/img/HY036\(2\).png](https://ikoyama.com/img/HY036(2).png)

HYUNDAI H-1 06/21

HY036

RESORTE POST REF 19.5X162X340X6 5797



<https://ikoyama.com/img/HY037.png>

[https://ikoyama.com/img/HY037\(2\).png](https://ikoyama.com/img/HY037(2).png)

HYUNDAI i10 07/13

HY037

RESORTE DEL ORI 12.7X144X345X5 1/2 13706


<https://ikoyama.com/img/HY038.png>
[https://ikoyama.com/img/HY038\(2\).png](https://ikoyama.com/img/HY038(2).png)

HYUNDAI i10 07/13

HY038

RESORTE POST REF 11.7X122X300X6 3/4 9787


<https://ikoyama.com/img/HY043.png>
[https://ikoyama.com/img/HY043\(2\).png](https://ikoyama.com/img/HY043(2).png)

HYUNDAI NEW ELANTRA 16/UP

HY043

RESORTE DEL ORI 13X126X325X5 1/2 14475


<https://ikoyama.com/img/HY044.png>
[https://ikoyama.com/img/HY044\(2\).png](https://ikoyama.com/img/HY044(2).png)

HYUNDAI NEW ELANTRA 16/UP

HY044

RESORTE POST GNV 12.5X79X340X8 1/2 15157


<https://ikoyama.com/img/HY048.png>
[https://ikoyama.com/img/HY048\(2\).png](https://ikoyama.com/img/HY048(2).png)

HYUNDAI SANTA FE PATRULLERO REF 11/14

HY048

RESORTE POST ORI 16X145X320X5 1/2


<https://ikoyama.com/img/N023.png>
[https://ikoyama.com/img/N023\(2\).png](https://ikoyama.com/img/N023(2).png)

HYUNDAI SONATA 4 00/05 NISSAN SUNNY B11 83/89 (DEL)

N023

RESORTE POST 11x122x390x6 7/8 488


<https://ikoyama.com/img/HY054.png>
[https://ikoyama.com/img/HY054\(2\).png](https://ikoyama.com/img/HY054(2).png)

HYUNDAI SONATA N20

HY054

RESORTE DEL REF 14.5X131X370X8 12841


<https://ikoyama.com/img/HY056.png>
[https://ikoyama.com/img/HY056\(2\).png](https://ikoyama.com/img/HY056(2).png)

HYUNDAI TUCSON 15/UP

HY056

RESORTE POST GLP 13.5X113X355X8 1/8 13732


<https://ikoyama.com/img/K010.png>
[https://ikoyama.com/img/K010\(2\).png](https://ikoyama.com/img/K010(2).png)

HYUNDAI/KIA SANTA FE/SORENTO 09/13

K010

RESORTE DEL REF 15X157X335X5 1/4 13136



<https://ikoyama.com/img/HY003.png>

[https://ikoyama.com/img/HY003\(2\).png](https://ikoyama.com/img/HY003(2).png)

HYUNDAI/KIA ACCENT/RIO 06/10

HY003

RESORTE DEL ORI 13.7X166X330X5 6180



<https://ikoyama.com/img/HY004.png>

[https://ikoyama.com/img/HY004\(2\).png](https://ikoyama.com/img/HY004(2).png)

HYUNDAI/KIA ACCENT/RIO 06/10

HY004

RESORTE POST REF 12.5X124X335X7 3322



<https://ikoyama.com/img/HY008.png>

[https://ikoyama.com/img/HY008\(2\).png](https://ikoyama.com/img/HY008(2).png)

HYUNDAI/KIA ACCENT/RIO 11/UP

HY008

RESORTE DEL REF 12.7X140X335X5 3/4 9542



<https://ikoyama.com/img/HY009.png>

[https://ikoyama.com/img/HY009\(2\).png](https://ikoyama.com/img/HY009(2).png)

HYUNDAI/KIA ACCENT/RIO 11/UP SOLUTO 19/UP

HY009

RESORTE POST GNV 12.2X124X332X7 8493



<https://ikoyama.com/img/HY045.png>

[https://ikoyama.com/img/HY045\(2\).png](https://ikoyama.com/img/HY045(2).png)

HYUNDAI/KIA ACCENT/RIO 17/UP

HY045

RESORTE POST GNV 11.5X77X320X8 17218



<https://ikoyama.com/img/HY030.png>

[https://ikoyama.com/img/HY030\(2\).png](https://ikoyama.com/img/HY030(2).png)

HYUNDAI/KIA ELANTRA BLUEBIRD 90/00

HY030

RESORTE DEL ORI 13.4X172X388X5



<https://ikoyama.com/img/HY026.png>

[https://ikoyama.com/img/HY026\(2\).png](https://ikoyama.com/img/HY026(2).png)

HYUNDAI/KIA ELANTRA/CERATO 11/UP

HY026

RESORTE DEL REF 13.2X142X315X5 1/4 10781



<https://ikoyama.com/img/HY027.png>

[https://ikoyama.com/img/HY027\(2\).png](https://ikoyama.com/img/HY027(2).png)

HYUNDAI/KIA ELANTRA/CERATO 11/UP

HY027

RESORTE POST REF 12.7X123X325X7 3/8 10550



<https://ikoyama.com/img/HY050.png>
HYUNDAI/KIA SANTA FE 06/09

[https://ikoyama.com/img/HY050\(2\).png](https://ikoyama.com/img/HY050(2).png)

RESORTE POST ORI 15X145X320X5 1/2 11145

HY050



<https://ikoyama.com/img/HY049.png>
HYUNDAI/KIA SANTA FE 12/UP



[https://ikoyama.com/img/HY049\(2\).png](https://ikoyama.com/img/HY049(2).png)

RESORTE POST REF 16X147X285X5 16590

HY049



<https://ikoyama.com/img/HY046.png>
HYUNDAI/KIA SANTA FE/SORENTO 10/12

[https://ikoyama.com/img/HY046\(2\).png](https://ikoyama.com/img/HY046(2).png)

RESORTE POST REF 16.8X144X325X6 1/8 1703NPG

HY046



<https://ikoyama.com/img/K009.png>
HYUNDAI/KIA SANTA FE/SORENTO 15/UP

[https://ikoyama.com/img/K009\(2\).png](https://ikoyama.com/img/K009(2).png)

RESORTE POST GLP 15X116X320X 7 1/2 17308

K009



<https://ikoyama.com/img/HY016.png>
HYUNDAI/KIA SONATA 00/05 OPTIMA 00/05

[https://ikoyama.com/img/HY016\(2\).png](https://ikoyama.com/img/HY016(2).png)

RESORTE DEL REF 14.2X126X390X8 3/4 5727

HY016



<https://ikoyama.com/img/HY017.png>
HYUNDAI/KIA SONATA/OPTIMA

[https://ikoyama.com/img/HY017\(2\).png](https://ikoyama.com/img/HY017(2).png)

RESORTE POST REF 12.2X118X383X8 92

HY017



<https://ikoyama.com/img/HY028.png>
HYUNDAI/KIA SONATA/OPTIMA 94/99

[https://ikoyama.com/img/HY028\(2\).png](https://ikoyama.com/img/HY028(2).png)

RESORTE DEL ORI 13.7X160X375X5 1/2 87

HY028



<https://ikoyama.com/img/HY031.png>
HYUNDAI/KIA TUCSON/SPORTAGE 02/10

[https://ikoyama.com/img/HY031\(2\).png](https://ikoyama.com/img/HY031(2).png)

RESORTE POST ORI 14.2X186X370X6 1/2 10324

HY031


<https://ikoyama.com/img/HY033.png>
[https://ikoyama.com/img/HY033\(2\).png](https://ikoyama.com/img/HY033(2).png)

HYUNDAI/KIA TUCSON/SPORTAGE 10/UP

HY033

RESORTE DEL REF 14.7X166X305X4 3/4 12586


<https://ikoyama.com/img/HY023.png>
[https://ikoyama.com/img/HY023\(2\).png](https://ikoyama.com/img/HY023(2).png)

HYUNDAI/KIA TUCSON/SPORTAGE 10/UP

HY023

RESORTE POST GLP 12.7X102X345X9 9281


<https://ikoyama.com/img/HY032.png>
[https://ikoyama.com/img/HY032\(2\).png](https://ikoyama.com/img/HY032(2).png)

HYUNDAI/KIA TUCSON/SPORTAGE 10/UP

HY032

RESORTE POST REF 13.2X103X345X9 1/2 9471

<https://ikoyama.com/img/HY055.png>
[https://ikoyama.com/img/HY055\(2\).png](https://ikoyama.com/img/HY055(2).png)

HYUNDAI/KIA TUCSON/SPORTAGE 15/UP

HY055

RESORTE DEL ORI 14X124X365X5 19111


<https://ikoyama.com/img/J001.png>
[https://ikoyama.com/img/J001\(2\).png](https://ikoyama.com/img/J001(2).png)

JAC JAC CLASS 06/UP

J001

RESORTE DEL ORI 13X143X355X6 7963


<https://ikoyama.com/img/J002.png>
[https://ikoyama.com/img/J002\(2\).png](https://ikoyama.com/img/J002(2).png)

JAC JAC CLASS 06/UP

J002

RESORTE POST REF 13.5X163X345X7 7850


<https://ikoyama.com/img/JP001.png>
[https://ikoyama.com/img/JP001\(2\).png](https://ikoyama.com/img/JP001(2).png)

JEEP GRAND CHEROKEE 01/06

JP001

RESORTE DEL 14X124X395X9 1/2


<https://ikoyama.com/img/JP002.png>
[https://ikoyama.com/img/JP002\(2\).png](https://ikoyama.com/img/JP002(2).png)

JEEP GRAND CHEROKEE 05/10

JP002

RESORTE POST REF 16X123X340X6 1/2 14243



<https://ikoyama.com/img/K007.png>

[https://ikoyama.com/img/K007\(2\).png](https://ikoyama.com/img/K007(2).png)

KIA CARENS 06/10

K007

RESORTE DEL REF 15X179X345X5 1622



<https://ikoyama.com/img/K008.png>

[https://ikoyama.com/img/K008\(2\).png](https://ikoyama.com/img/K008(2).png)

KIA CARENS 13/UP

K008

RESORTE POST REF 13.5X96X325X8 1219 12999



<https://ikoyama.com/img/HY034.png>

[https://ikoyama.com/img/HY034\(2\).png](https://ikoyama.com/img/HY034(2).png)

KIA CERATO 07/12

HY034

RESORTE DEL ORI 14.2X171X350X5 12721



<https://ikoyama.com/img/K006.png>

[https://ikoyama.com/img/K006\(2\).png](https://ikoyama.com/img/K006(2).png)

KIA CERATO 13/UP

K006

RESORTE DEL ORI 13.5X130X305X5 14264



<https://ikoyama.com/img/K005.png>

[https://ikoyama.com/img/K005\(2\).png](https://ikoyama.com/img/K005(2).png)

KIA CERATO 13/UP

K005

RESORTE POST GNV 4 13X124X340X8 16469




<https://ikoyama.com/img/K003.png>

[https://ikoyama.com/img/K003\(2\).png](https://ikoyama.com/img/K003(2).png)

KIA PICANTO 11/17

K003

RESORTE POST ORI 11.7X114X295X7 3/8 9841



<https://ikoyama.com/img/K004.png>

[https://ikoyama.com/img/K004\(2\).png](https://ikoyama.com/img/K004(2).png)

KIA PICANTO 11/UP

K004

RESORTE DEL ORI 11X114X365X5 5/8 1104DD



<https://ikoyama.com/img/K002.png>

[https://ikoyama.com/img/K002\(2\).png](https://ikoyama.com/img/K002(2).png)

KIA/FORD PRIDE/FESTIVA 92/97

K002

RESORTE POST REF 11.2X98X345X7 7/8 91



<https://ikoyama.com/img/L001.png>

LIFAN 520 00/UP

RESORTE DEL 13X160X410X6 1/2

[https://ikoyama.com/img/L001\(2\).png](https://ikoyama.com/img/L001(2).png)

L001



<https://ikoyama.com/img/L002.png>

LIFAN MINIVAN 10/UP

RESORTE DEL REF 13X88X265X7 9307

[https://ikoyama.com/img/L002\(2\).png](https://ikoyama.com/img/L002(2).png)

L002



<https://ikoyama.com/img/MZ001.png>

MAZDA 3 02/13

RESORTE DEL ORI 13.2X159X355X5 1/4 11691

[https://ikoyama.com/img/MZ001\(2\).png](https://ikoyama.com/img/MZ001(2).png)

MZ001



<https://ikoyama.com/img/MZ002.png>

MAZDA 3 02/13

RESORTE POST ORI 11.7X111X360X7 1/2 11420

[https://ikoyama.com/img/MZ002\(2\).png](https://ikoyama.com/img/MZ002(2).png)

MZ002



<https://ikoyama.com/img/MZ004.png>

MAZDA 5 2.0 10/UP

RESORTE DEL ORI 14X159X340X5 1/2 16155

[https://ikoyama.com/img/MZ004\(2\).png](https://ikoyama.com/img/MZ004(2).png)

MZ004



<https://ikoyama.com/img/MZ005.png>

MAZDA 5 2.0 10/UP

RESORTE POST ORI 14X112X355X9 16441

[https://ikoyama.com/img/MZ005\(2\).png](https://ikoyama.com/img/MZ005(2).png)

MZ005



<https://ikoyama.com/img/MZ003.png>

MAZDA DEMIO 04/08

RESORTE POST ORI 10X74X305X7 1/2 3411

[https://ikoyama.com/img/MZ003\(2\).png](https://ikoyama.com/img/MZ003(2).png)

MZ003



<https://ikoyama.com/img/MG001.png>

MG 3 HB 1.5 11/15

RESORTE DEL REF 12.5X108X325X5 16288

[https://ikoyama.com/img/MG001\(2\).png](https://ikoyama.com/img/MG001(2).png)

MG001



<https://ikoyama.com/img/MI004.png>

mitsubishi L200 10/UP

RESORTE DEL REF 17.7X128X315X6 5/8 13457



[https://ikoyama.com/img/MI004\(2\).png](https://ikoyama.com/img/MI004(2).png)

MI004



<https://ikoyama.com/img/MI003.png>

mitsubishi L200 DAKAR AVISPA TIBURON 06/11

RESORTE DEL ORI 17.2X127X338X6 3/4 5737



[https://ikoyama.com/img/MI003\(2\).png](https://ikoyama.com/img/MI003(2).png)

MI003

<https://ikoyama.com/img/MI005.png>

mitsubishi LANCER 12/17

RESORTE POST GLP 10X74X335X7 1/2 2315

[https://ikoyama.com/img/MI005\(2\).png](https://ikoyama.com/img/MI005(2).png)

MI005



<https://ikoyama.com/img/MI001.png>

mitsubishi LANCER CEDIA 90/05

RESORTE POST REF 11.7X101X355X8 1/2 518

[https://ikoyama.com/img/MI001\(2\).png](https://ikoyama.com/img/MI001(2).png)

MI001

<https://ikoyama.com/img/MI002.png>

mitsubishi LANCER LIBERO 90/05

RESORTE DEL ORI 12.7X151X360X5 1/2 8941

[https://ikoyama.com/img/MI002\(2\).png](https://ikoyama.com/img/MI002(2).png)

MI002



<https://ikoyama.com/img/MI006.png>

mitsubishi LIBERO 4X4 95/99

RESORTE POST 15X116X310X8 1/2 516

[https://ikoyama.com/img/MI006\(2\).png](https://ikoyama.com/img/MI006(2).png)

MI006



<https://ikoyama.com/img/MI007.png>

mitsubishi MONTERO 3P 94/99

RESORTE POST REF 15X178X420X6 1/2 515

[https://ikoyama.com/img/MI007\(2\).png](https://ikoyama.com/img/MI007(2).png)

MI007



<https://ikoyama.com/img/MI008.png>

mitsubishi SW LANCER 02/06

RESORTE POST GNV 13X107X355 9 7/8

[https://ikoyama.com/img/MI008\(2\).png](https://ikoyama.com/img/MI008(2).png)

MI008



<https://ikoyama.com/img/N022.png>

[https://ikoyama.com/img/N022\(2\).png](https://ikoyama.com/img/N022(2).png)

NISSAN AD DX 4X4 00/06

N022

RESORTE POST GLP 14X117X295X6 1/2 10392



<https://ikoyama.com/img/N011.png>

[https://ikoyama.com/img/N011\(2\).png](https://ikoyama.com/img/N011(2).png)

NISSAN AD WAGON 06/UP

N011

RESORTE DEL ORI 13.2X140X310X5 1/2 9511



<https://ikoyama.com/img/N012.png>

[https://ikoyama.com/img/N012\(2\).png](https://ikoyama.com/img/N012(2).png)

NISSAN AD WAGON 4X4 00/07

N012

RESORTE POST GNV 15.2X118X300X6 1/2 667



<https://ikoyama.com/img/N002.png>

[https://ikoyama.com/img/N002\(2\).png](https://ikoyama.com/img/N002(2).png)

NISSAN AD WAGON 90/06

N002

RESORTE POST REF 13.7X131X380X8 1/4 483



<https://ikoyama.com/img/N017.png>

[https://ikoyama.com/img/N017\(2\).png](https://ikoyama.com/img/N017(2).png)

NISSAN AVENIR MM CD20 CD17 90/00

N017

RESORTE DEL REF 12.5X141X380X6 5/8 499



<https://ikoyama.com/img/N015.png>

[https://ikoyama.com/img/N015\(2\).png](https://ikoyama.com/img/N015(2).png)

NISSAN NAVARA 04/13

N015

RESORTE DEL ORI 16.7X111X365X5 1/2 6829



<https://ikoyama.com/img/N021.png>

[https://ikoyama.com/img/N021\(2\).png](https://ikoyama.com/img/N021(2).png)

NISSAN PATHFINDER 86/95

N021

RESORTE POST REF 15X136X445X8 1/2 2425



<https://ikoyama.com/img/N080.png>

[https://ikoyama.com/img/N080\(2\).png](https://ikoyama.com/img/N080(2).png)

NISSAN PATHFINDER 96/05

N080

RESORTE DEL REF 16X150X395X7 668 2422



<https://ikoyama.com/img/N024.png>

[https://ikoyama.com/img/N024\(2\).png](https://ikoyama.com/img/N024(2).png)

NISSAN PRIMERA 95/00

N024

RESORTE DEL 12X152X385X7 1/8 2421



<https://ikoyama.com/img/N006.png>

[https://ikoyama.com/img/N006\(2\).png](https://ikoyama.com/img/N006(2).png)

NISSAN SENTRA B12 B13 V16 CLAS 87/94

N006

RESORTE POST REF 12.2X140X340X6 493



<https://ikoyama.com/img/N005.png>

[https://ikoyama.com/img/N005\(2\).png](https://ikoyama.com/img/N005(2).png)

NISSAN SENTRA B12 B13 V16 CLAS AD 87/13

N005

RESORTE DEL ORI 12.2X141X365X6 491



<https://ikoyama.com/img/N008.png>

[https://ikoyama.com/img/N008\(2\).png](https://ikoyama.com/img/N008(2).png)

NISSAN SENTRA B14 PRIMERA 95/99

N008

RESORTE POST REF 11.7X108X330X6 7/8 495



<https://ikoyama.com/img/N009.png>

[https://ikoyama.com/img/N009\(2\).png](https://ikoyama.com/img/N009(2).png)

NISSAN SENTRA B15 ALMERA 00/06

N009

RESORTE DEL ORI 12.8X153X355X5 1/4 496



<https://ikoyama.com/img/N010.png>

[https://ikoyama.com/img/N010\(2\).png](https://ikoyama.com/img/N010(2).png)

NISSAN SENTRA B15 ALMERA 00/06

N010

RESORTE POST GNV 13.2X111X295X6 7/8 662



<https://ikoyama.com/img/N025.png>

[https://ikoyama.com/img/N025\(2\).png](https://ikoyama.com/img/N025(2).png)

NISSAN SENTRA B15 ALMERA 00/06

N025

RESORTE POST REF 12X111X295X6 4/5 498



<https://ikoyama.com/img/N013.png>

[https://ikoyama.com/img/N013\(2\).png](https://ikoyama.com/img/N013(2).png)

NISSAN TIIDA WINGROAD 06/UP 05/13

N013

RESORTE DEL ORI 12.2X134X345X5 1/2 8783


<https://ikoyama.com/img/N014.png>
[https://ikoyama.com/img/N014\(2\).png](https://ikoyama.com/img/N014(2).png)

NISSAN TIIDA WINGROAD 06/UP 05/13

RESORTE POST GNV 13.2X89X270X5 1/2 5358

N014
<https://ikoyama.com/img/N018.png>
[https://ikoyama.com/img/N018\(2\).png](https://ikoyama.com/img/N018(2).png)

NISSAN VERSA 11/19

RESORTE DEL ORI 11.5X112X340X7 1/2 12755

N018
<https://ikoyama.com/img/N019.png>
[https://ikoyama.com/img/N019\(2\).png](https://ikoyama.com/img/N019(2).png)

NISSAN VERSA 11/19

RESORTE POST GLP 13.5X132X315X5 3/8 11446

N019
<https://ikoyama.com/img/N016.png>
[https://ikoyama.com/img/N016\(2\).png](https://ikoyama.com/img/N016(2).png)

NISSAN VERSA 11/19

RESORTE POST REF 14.7X135X315X5 1/4 11925

N016
<https://ikoyama.com/img/N020.png>
[https://ikoyama.com/img/N020\(2\).png](https://ikoyama.com/img/N020(2).png)

NISSAN XTRAIL 00/06

RESORTE DEL ORIG 14X164X330X4 1/4

N020
<https://ikoyama.com/img/F001.png>
[https://ikoyama.com/img/F001\(2\).png](https://ikoyama.com/img/F001(2).png)

NISSAN XTRAIL 00/06 FORD ESCORT 90/94

RESORTE POST ORI 13.7X174X320X4 5/8 2280

F001
<https://ikoyama.com/img/RE003.png>
[https://ikoyama.com/img/RE003\(2\).png](https://ikoyama.com/img/RE003(2).png)

RENAULT DUSTER 4X4 10/14

RESORTE POST GLP 13.5x137x350x6 3/8 16653

RE003
<https://ikoyama.com/img/RE001.png>
[https://ikoyama.com/img/RE001\(2\).png](https://ikoyama.com/img/RE001(2).png)

RENAULT LOGAN 07/UP

RESORTE DEL ORI 13.2X140X325X5 1/4 13128

RE001


<https://ikoyama.com/img/RE002.png>
[https://ikoyama.com/img/RE002\(2\).png](https://ikoyama.com/img/RE002(2).png)

RENAULT LOGAN 07/UP

RE002

RESORTE POST REF 13.2X103X320X9 13715


<https://ikoyama.com/img/SS01.png>
[https://ikoyama.com/img/SS01\(2\).png](https://ikoyama.com/img/SS01(2).png)

SSANGYONG REXTON 00/UP

SS01

RESORTE POST ORI 14X144X392X6 1/2 12179


<https://ikoyama.com/img/SS02.png>
[https://ikoyama.com/img/SS02\(2\).png](https://ikoyama.com/img/SS02(2).png)

SSANGYONG REXTON 12/UP

SS02

RESORTE DEL 15X89X390X9

<https://ikoyama.com/img/SB005.png>
[https://ikoyama.com/img/SB005\(2\).png](https://ikoyama.com/img/SB005(2).png)

SUBARU FORESTER 00/UP

SB005

RESORTE DEL REF 14X151X373X5 1/2 3309


<https://ikoyama.com/img/SB003.png>
[https://ikoyama.com/img/SB003\(2\).png](https://ikoyama.com/img/SB003(2).png)

SUBARU FORESTER 98/04

SB003

RESORTE POST ORI 14.2X157X385X5 5/8 525


<https://ikoyama.com/img/SB004.png>
[https://ikoyama.com/img/SB004\(2\).png](https://ikoyama.com/img/SB004(2).png)

SUBARU IMPREZA 00/09

SB004

RESORTE POST ORI 12.5X110X330X7


<https://ikoyama.com/img/SB002.png>
[https://ikoyama.com/img/SB002\(2\).png](https://ikoyama.com/img/SB002(2).png)

SUBARU IMPREZA LEGACY 90/99

SB002

RESORTE POST REF 13.7X165X320X4 1/4 3436


<https://ikoyama.com/img/SB001.png>
[https://ikoyama.com/img/SB001\(2\).png](https://ikoyama.com/img/SB001(2).png)

SUBARU IMPREZA LEGACY 91/96

SB001

RESORTE DEL REF 13.7X170X345X4 1/2 507



<https://ikoyama.com/img/SK010.png> [https://ikoyama.com/img/SK010\(2\).png](https://ikoyama.com/img/SK010(2).png)

SUBARU IMPREZA LEGACY SUZUKI AERIO 90/99

RESORTE DEL REF 13.2X165X317X4 1/4 3436

SK010



<https://ikoyama.com/img/SK012.png> [https://ikoyama.com/img/SK012\(2\).png](https://ikoyama.com/img/SK012(2).png)

SUZUKI AERIO BALENO

RESORTE POST REF 13.2X147X330X5 5/8 9465

SK012



<https://ikoyama.com/img/SK011.png> [https://ikoyama.com/img/SK011\(2\).png](https://ikoyama.com/img/SK011(2).png)

SUZUKI AERIO STATION WAGON

RESORTE DEL REF 13.7X166X325X4 3/8 11440

SK011



<https://ikoyama.com/img/SK008.png> [https://ikoyama.com/img/SK008\(2\).png](https://ikoyama.com/img/SK008(2).png)

SUZUKI ALTO CHERY QQ

RESORTE DEL REF 10.7X107X325X8 9842

SK008



<https://ikoyama.com/img/SK009.png> [https://ikoyama.com/img/SK009\(2\).png](https://ikoyama.com/img/SK009(2).png)

SUZUKI ALTO CHERY QQ

RESORTE POST REF 11.2X101X295X6 3/4 5121

SK009



<https://ikoyama.com/img/SK005.png> [https://ikoyama.com/img/SK005\(2\).png](https://ikoyama.com/img/SK005(2).png)

SUZUKI APV 09/UP

RESORTE DEL ORI 11.7X100X320X8 3/4 7305

SK005




<https://ikoyama.com/img/SK006.png> [https://ikoyama.com/img/SK006\(2\).png](https://ikoyama.com/img/SK006(2).png)

SUZUKI APV 09/UP

RESORTE POST GNV 13.7X109X340X8 5/8 7802

SK006



<https://ikoyama.com/img/SK020.png> [https://ikoyama.com/img/SK020\(2\).png](https://ikoyama.com/img/SK020(2).png)

SUZUKI BALENO 94/02

RESORTE DEL ORI 13X148X325X4 1/2 3409 10947

SK020

<https://ikoyama.com/img/SK022.png>

[https://ikoyama.com/img/SK022\(2\).png](https://ikoyama.com/img/SK022(2).png)

SUZUKI CIAZ 15/21

SK022

RESORTE DEL ORI 11.5X 16103

<https://ikoyama.com/img/SK023.png>

[https://ikoyama.com/img/SK023\(2\).png](https://ikoyama.com/img/SK023(2).png)

SUZUKI CIAZ 15/21

SK023

RESORTE POST GNV 11.5X113X315X6 5/8 12181



<https://ikoyama.com/img/SK021.png>

[https://ikoyama.com/img/SK021\(2\).png](https://ikoyama.com/img/SK021(2).png)

SUZUKI ERTIGA 12/18

SK021

RESORTE DEL REF 12X129X350X6 18848



<https://ikoyama.com/img/SK015.png>

[https://ikoyama.com/img/SK015\(2\).png](https://ikoyama.com/img/SK015(2).png)

SUZUKI ERTIGA 12/18

SK015

RESORTE POST GNV 5 13.5X83X305X6 1/2 13987



<https://ikoyama.com/img/SK013.png>

[https://ikoyama.com/img/SK013\(2\).png](https://ikoyama.com/img/SK013(2).png)

SUZUKI GRAND NOMADE 07/17 GRAND VITARA 07/17

SK013

RESORTE DEL ORI 13.7X156X375X5 1/2 3541



<https://ikoyama.com/img/SK014.png>

[https://ikoyama.com/img/SK014\(2\).png](https://ikoyama.com/img/SK014(2).png)

SUZUKI GRAND NOMADE 07/17 GRAND VITARA 07/17

SK014

RESORTE POST ORI 16.2X104X329X8 1/4 3542



<https://ikoyama.com/img/SK017.png>

[https://ikoyama.com/img/SK017\(2\).png](https://ikoyama.com/img/SK017(2).png)

SUZUKI SWIFT HATCHBACK 04/14

SK017

RESORTE DEL ORI 12.5X156X370X6 1/4 13415



<https://ikoyama.com/img/SK016.png>

[https://ikoyama.com/img/SK016\(2\).png](https://ikoyama.com/img/SK016(2).png)

SUZUKI SWIFT HATCHBACK 04/14

SK016

RESORTE POST REF 11.5X80X315X7 11513DP



<https://ikoyama.com/img/SK019.png>
SUZUKI SX4 08/UP

RESORTE DEL ORI 12.5X156X365X6 12546

SK019



<https://ikoyama.com/img/SK018.png>
SUZUKI SX4 08/UP

RESORTE POST GLP 12.5X79X290X6 1/4 13116

SK018



[https://ikoyama.com/img/SK018\(2\).png](https://ikoyama.com/img/SK018(2).png)



<https://ikoyama.com/img/T022.png>
TOYOTA AVANZA 11/UP

RESORTE DEL ORI 13.5X133X290X5 1/2 1352MD

T022



[https://ikoyama.com/img/T022\(2\).png](https://ikoyama.com/img/T022(2).png)



<https://ikoyama.com/img/T023.png>
TOYOTA AVANZA 11/UP

RESORTE POST GNV 15X84X275X6 1/4 11760

T023



[https://ikoyama.com/img/T023\(2\).png](https://ikoyama.com/img/T023(2).png)



<https://ikoyama.com/img/T035.png>
TOYOTA CALDINA DIESEL 90/02

RESORTE DEL REF 13X150X385X6

T035



[https://ikoyama.com/img/T035\(2\).png](https://ikoyama.com/img/T035(2).png)



<https://ikoyama.com/img/T039.png>
TOYOTA COROLLA 00/UP

RESORTE DEL ORI 13X121X360X8 1/4

T039




[https://ikoyama.com/img/T039\(2\).png](https://ikoyama.com/img/T039(2).png)



<https://ikoyama.com/img/T036.png>
TOYOTA COROLLA 14/19

RESORTE DEL ORI 13X133X340X5 18394

T036



[https://ikoyama.com/img/T036\(2\).png](https://ikoyama.com/img/T036(2).png)



<https://ikoyama.com/img/T018.png>
TOYOTA COROLLA 14/19

RESORTE POST GNV 12.2X107X340X8 3/4 11079

T018



[https://ikoyama.com/img/T018\(2\).png](https://ikoyama.com/img/T018(2).png)



<https://ikoyama.com/img/T005.png>

[https://ikoyama.com/img/T005\(2\).png](https://ikoyama.com/img/T005(2).png)

TOYOTA COROLLA 92/00

T005

RESORTE POST REF 12.2X151X350X5 7/8 449



<https://ikoyama.com/img/T006.png>

[https://ikoyama.com/img/T006\(2\).png](https://ikoyama.com/img/T006(2).png)

TOYOTA COROLLA COROLON 01/13 BYD F3 05/20

T006

RESORTE DEL REF 13.2X162X340X4 1/4 8751



<https://ikoyama.com/img/T007.png>

[https://ikoyama.com/img/T007\(2\).png](https://ikoyama.com/img/T007(2).png)

TOYOTA COROLLA COROLON 01/13 BYD F3 05/20

T007

RESORTE POST GNV 11.7X105X368X8 1/2 6331



<https://ikoyama.com/img/T029.png>

[https://ikoyama.com/img/T029\(2\).png](https://ikoyama.com/img/T029(2).png)

TOYOTA COROLLA COROLON 06/13

T029

RESORTE POST GLP 11.5X85X368X8 1/2 6331



<https://ikoyama.com/img/T003.png>

[https://ikoyama.com/img/T003\(2\).png](https://ikoyama.com/img/T003(2).png)

TOYOTA COROLLA DIESEL 92/00

T003

RESORTE DEL REF 13X155X385X5 3/4 447



<https://ikoyama.com/img/T004.png>

[https://ikoyama.com/img/T004\(2\).png](https://ikoyama.com/img/T004(2).png)

TOYOTA COROLLA GASOLINERO 90/00

T004

RESORTE DEL ORI 13X151X350X4 5/8 10222



<https://ikoyama.com/img/T017.png>

[https://ikoyama.com/img/T017\(2\).png](https://ikoyama.com/img/T017(2).png)

TOYOTA CORONA 70/79

T017

RESORTE DEL ORI 14.2X114X380X10 452



<https://ikoyama.com/img/T002.png>

[https://ikoyama.com/img/T002\(2\).png](https://ikoyama.com/img/T002(2).png)

TOYOTA CORONA CALDINA 92/97

T002

RESORTE POST REF 12.2X141X370X6 1/2 460



<https://ikoyama.com/img/T026.png>

[https://ikoyama.com/img/T026\(2\).png](https://ikoyama.com/img/T026(2).png)

TOYOTA CORONA CALDINA CONICO S 92/97

T026

RESORTE POST ORI 11.5X141X370X6 1/2 460



<https://ikoyama.com/img/T030.png>

[https://ikoyama.com/img/T030\(2\).png](https://ikoyama.com/img/T030(2).png)

TOYOTA FIELDER 00/UP

T030

RESORTE DEL 13.5X132X340X4 1/2



<https://ikoyama.com/img/T031.png>

[https://ikoyama.com/img/T031\(2\).png](https://ikoyama.com/img/T031(2).png)

TOYOTA FIELDER 01/05

T031

RESORTE POST GNV 11.5X77X365X8 679



<https://ikoyama.com/img/T032.png>

[https://ikoyama.com/img/T032\(2\).png](https://ikoyama.com/img/T032(2).png)

TOYOTA FORTUNER 05/15

T032

RESORTE POST REF 15X118X445X8 1/2 13420



<https://ikoyama.com/img/T021.png>

[https://ikoyama.com/img/T021\(2\).png](https://ikoyama.com/img/T021(2).png)

TOYOTA HILUX 1KD 2KD 1GD 05/UP

T021

RESORTE DEL ORI 16.7X110X365X9 1/2 5592



<https://ikoyama.com/img/T016.png>

[https://ikoyama.com/img/T016\(2\).png](https://ikoyama.com/img/T016(2).png)

TOYOTA HILUX 1KD 2KD 1GD REF 05/UP

T016

RESORTE DEL REF 17.2X111X365X9 3/8 9670



<https://ikoyama.com/img/T033.png>

[https://ikoyama.com/img/T033\(2\).png](https://ikoyama.com/img/T033(2).png)

TOYOTA LAND CRUISER PRADO 09/UP

T033

RESORTE POST REF 16X119X400X6 3/4 12870



<https://ikoyama.com/img/T037.png>

[https://ikoyama.com/img/T037\(2\).png](https://ikoyama.com/img/T037(2).png)

TOYOTA PRADO 09/UP

T037

RESORTE POST REF 16X162X395X7 12870



<https://ikoyama.com/img/T008.png>

[https://ikoyama.com/img/T008\(2\).png](https://ikoyama.com/img/T008(2).png)

TOYOTA PROBOX 03/07

T008

RESORTE DEL REF 13.2X151X335X5 1/4 3437



<https://ikoyama.com/img/T025.png>

[https://ikoyama.com/img/T025\(2\).png](https://ikoyama.com/img/T025(2).png)

TOYOTA PROBOX 03/07

T025

RESORTE POST ORI 14.5X83X295X6 13158



<https://ikoyama.com/img/T009.png>

[https://ikoyama.com/img/T009\(2\).png](https://ikoyama.com/img/T009(2).png)

TOYOTA PROBOX 03/07

T009

RESORTE POST REF 15.2X144X295X6 3262



<https://ikoyama.com/img/T040.png>

[https://ikoyama.com/img/T040\(2\).png](https://ikoyama.com/img/T040(2).png)

TOYOTA RAV4 00/05 CHERY TIGGO 3 05/UP

T040

RESORTE POST REF 14.5X145X280X5 3531



<https://ikoyama.com/img/T019.png>

[https://ikoyama.com/img/T019\(2\).png](https://ikoyama.com/img/T019(2).png)

TOYOTA RAV4 06/14

T019

RESORTE DEL REF 15.2X177X340X5 9077



<https://ikoyama.com/img/T020.png>

[https://ikoyama.com/img/T020\(2\).png](https://ikoyama.com/img/T020(2).png)

TOYOTA RAV4 06/14

T020

RESORTE POST REF 15X107X320X6 1/2 9079



<https://ikoyama.com/img/T010.png>

[https://ikoyama.com/img/T010\(2\).png](https://ikoyama.com/img/T010(2).png)

TOYOTA TERCEL EL50 EL40 90/99 STARLET EP82 EP91 90/99

T010

RESORTE DEL REF 11.7X142X330X5 3/8 465



<https://ikoyama.com/img/T011.png>

[https://ikoyama.com/img/T011\(2\).png](https://ikoyama.com/img/T011(2).png)

TOYOTA TERCEL EL50 EL40 90/99 STARLET EP82 EP91 90/99

T011

RESORTE POST REF 11.2X95X335X8 7/8 467



<https://ikoyama.com/img/T024.png>

TOYOTA YARIS 00/05

RESORTE DEL REF 12.5X150X335X5 1/2 8505

T024



[https://ikoyama.com/img/T024\(2\).png](https://ikoyama.com/img/T024(2).png)



<https://ikoyama.com/img/T014.png>

TOYOTA YARIS 06/13

RESORTE DEL REF 12.2X144X390X5 3/4 9160

T014



[https://ikoyama.com/img/T014\(2\).png](https://ikoyama.com/img/T014(2).png)



<https://ikoyama.com/img/T041.png>

TOYOTA YARIS 06/13

RESORTE POST GNV 13X120X333X8 3518

T041

[https://ikoyama.com/img/T041\(2\).png](https://ikoyama.com/img/T041(2).png)



<https://ikoyama.com/img/T015.png>

TOYOTA YARIS 06/13

RESORTE POST REF 12.7X120X333X8 3590

T015



[https://ikoyama.com/img/T015\(2\).png](https://ikoyama.com/img/T015(2).png)



<https://ikoyama.com/img/T027.png>

TOYOTA YARIS ENVIDIA 14/21

RESORTE DEL ORI 11X127X395X6 3/8 9814

T027

[https://ikoyama.com/img/T027\(2\).png](https://ikoyama.com/img/T027(2).png)



<https://ikoyama.com/img/T038.png>

TOYOTA YARIS ENVIDIA 14/21

RESORTE DEL REF 11.5X129X395X6 1/2 9814

T038

[https://ikoyama.com/img/T038\(2\).png](https://ikoyama.com/img/T038(2).png)



<https://ikoyama.com/img/T012.png>

TOYOTA YARIS ENVIDIA 14/21

RESORTE DEL REF GNV 11.7X127X395X6 3/8 14913

T012

[https://ikoyama.com/img/T012\(2\).png](https://ikoyama.com/img/T012(2).png)



<https://ikoyama.com/img/T028.png>

TOYOTA YARIS ENVIDIA 14/21

RESORTE POST ORI 12X127X315X6 3/8 10364

T028

[https://ikoyama.com/img/T028\(2\).png](https://ikoyama.com/img/T028(2).png)




<https://ikoyama.com/img/T013.png> [https://ikoyama.com/img/T013\(2\).png](https://ikoyama.com/img/T013(2).png)

TOYOTA YARIS ENVIDIA 14/21

RESORTE POST REF 12.7X98X315X6 3/8 10364

T013






<https://ikoyama.com/img/V003.png> [https://ikoyama.com/img/V003\(2\).png](https://ikoyama.com/img/V003(2).png)

VW AMAROK 10/ON

RESORTE DEL REF 16.8X123X310X7 1/2 6503

V003

<https://ikoyama.com/img/V004.png> [https://ikoyama.com/img/V004\(2\).png](https://ikoyama.com/img/V004(2).png)

VW GOL 08/22 VOYAGE 13/21 SAVEIRO 13/UP CROSSFOX 08/22

RESORTE DEL REF 12.5X106.5X340X6 1807

V004




<https://ikoyama.com/img/V001.png> [https://ikoyama.com/img/V001\(2\).png](https://ikoyama.com/img/V001(2).png)

VW GOL METROPOLITANO 04/ON

RESORTE DEL REF 12.7X144X345X5 8297

V001




<https://ikoyama.com/img/V002.png> [https://ikoyama.com/img/V002\(2\).png](https://ikoyama.com/img/V002(2).png)

VW GOL METROPOLITANO 04/ON

RESORTE POST REF 11.7X101X360X11 7/8 64

V002

Especialistas en:

PALIERES



KOYAMA
SUSPENSION PARTS



<https://ikoyama.com/img/MI-940L.png>

[https://ikoyama.com/img/MI-940L\(2\).png](https://ikoyama.com/img/MI-940L(2).png)

mitsubishi L200 08/UP

MI-940L

PALIER COMPLETO DEL LH MI-5-6389A



<https://ikoyama.com/img/MI-940R.png>

[https://ikoyama.com/img/MI-940R\(2\).png](https://ikoyama.com/img/MI-940R(2).png)

mitsubishi L200 08/UP

MI-940R

PALIER COMPLETO DEL RH MI-5-6385A



<https://ikoyama.com/img/NI-924.png>

[https://ikoyama.com/img/NI-924\(2\).png](https://ikoyama.com/img/NI-924(2).png)

NISSAN FRONTIER 09/UP

NI-924

PALIER COMPLETO A121156



<https://ikoyama.com/img/NI-981.png>

[https://ikoyama.com/img/NI-981\(2\).png](https://ikoyama.com/img/NI-981(2).png)

NISSAN NAVARA 08/UP

NI-981

PALIER COMPLETO A09365



<https://ikoyama.com/img/ATO-002.png>

[https://ikoyama.com/img/ATO-002\(2\).png](https://ikoyama.com/img/ATO-002(2).png)

TOYOTA HILUX REVO 1GD 2GD 15/UP

ATO-002

PALIER COMPLETO 30X30X63



<https://ikoyama.com/img/ATO-001.png>

[https://ikoyama.com/img/ATO-001\(2\).png](https://ikoyama.com/img/ATO-001(2).png)

TOYOTA HILUX VIGO 1KD 2KD 04/UP

ATO-001

PALIER COMPLETO 30X30X63.5



<https://ikoyama.com/img/OP-707.png>

CHEVROLET CHEVY TAXI

OP-707

COPA DE PALIER 22X28X34.95



[https://ikoyama.com/img/OP-707\(2\).png](https://ikoyama.com/img/OP-707(2).png)



<https://ikoyama.com/img/OP-705.png>

CHEVROLET CHEVY TAXI

OP-705

COPA DE PALIER 22X28X35 CORTO



[https://ikoyama.com/img/OP-705\(2\).png](https://ikoyama.com/img/OP-705(2).png)



<https://ikoyama.com/img/OP-701.png>

[https://ikoyama.com/img/OP-701\(2\).png](https://ikoyama.com/img/OP-701(2).png)

DAEWOO RACER CIELO

OP-701

COPA DE PALIER 34X22X35



<https://ikoyama.com/img/OP-501.png>

[https://ikoyama.com/img/OP-501\(2\).png](https://ikoyama.com/img/OP-501(2).png)

DAEWOO TICO

OP-501

COPA DE PALIER 22X19X35



<https://ikoyama.com/img/MI-501.png>

[https://ikoyama.com/img/MI-501\(2\).png](https://ikoyama.com/img/MI-501(2).png)

HYUNDAI EXCEL

MI-501

COPA DE PALIER 25X22X35



<https://ikoyama.com/img/MI-720.png>

[https://ikoyama.com/img/MI-720\(2\).png](https://ikoyama.com/img/MI-720(2).png)

HYUNDAI SONATA IV 02/06

MI-720

COPA DE PALIER 25X25X35



<https://ikoyama.com/img/NI-721.png>

[https://ikoyama.com/img/NI-721\(2\).png](https://ikoyama.com/img/NI-721(2).png)

NISSAN AD NEW 00/06

NI-721

COPA DE PALIER 25X23X40



<https://ikoyama.com/img/NI-720.png>

[https://ikoyama.com/img/NI-720\(2\).png](https://ikoyama.com/img/NI-720(2).png)

NISSAN CD17 SUNNY 92/97

NI-720

COPA DE PALIER 24X23X40



<https://ikoyama.com/img/NI-546.png>

[https://ikoyama.com/img/NI-546\(2\).png](https://ikoyama.com/img/NI-546(2).png)

NISSAN SENTRA B12

NI-546

COPA DE PALIER 24X24X40



<https://ikoyama.com/img/NI-7508.png>

[https://ikoyama.com/img/NI-7508\(2\).png](https://ikoyama.com/img/NI-7508(2).png)

NISSAN SENTRA B12 87/90

NI-7508

COPA DE PALIER 24X23X40



<https://ikoyama.com/img/NI-545.png>

[https://ikoyama.com/img/NI-545\(2\).png](https://ikoyama.com/img/NI-545(2).png)

NISSAN SENTRA B13

NI-545

COPA DE PALIER 25X24X40



<https://ikoyama.com/img/NI-7327.png>

[https://ikoyama.com/img/NI-7327\(2\).png](https://ikoyama.com/img/NI-7327(2).png)

NISSAN TIIDA

NI-7327

COPA DE PALIER 26X23X40



<https://ikoyama.com/img/TO-720.png>

[https://ikoyama.com/img/TO-720\(2\).png](https://ikoyama.com/img/TO-720(2).png)

TOYOTA 2C COROLLA 92/02

TO-720

COPA DE PALIER 20X23X35 CORTA



<https://ikoyama.com/img/TO-721.png>

[https://ikoyama.com/img/TO-721\(2\).png](https://ikoyama.com/img/TO-721(2).png)

TOYOTA 2C COROLLA 92/02

TO-721

COPA DE PALIER 20X23X35 LARGA



<https://ikoyama.com/img/TO-502.png>

[https://ikoyama.com/img/TO-502\(2\).png](https://ikoyama.com/img/TO-502(2).png)

TOYOTA COROLLA 92/01

TO-502

COPA DE PALIER 23X23X34



<https://ikoyama.com/img/TO-722.png>

[https://ikoyama.com/img/TO-722\(2\).png](https://ikoyama.com/img/TO-722(2).png)

TOYOTA HILUX REVO 16/20

TO-722

COPA DE PALIER 30X28X47



<https://ikoyama.com/img/TO-731B.png>

[https://ikoyama.com/img/TO-731B\(2\).png](https://ikoyama.com/img/TO-731B(2).png)

TOYOTA HILUX VIGO

TO-731B

COPA DE PALIER 30X29X47 TO-03



<https://ikoyama.com/img/TO-721A.png>

[https://ikoyama.com/img/TO-721A\(2\).png](https://ikoyama.com/img/TO-721A(2).png)

TOYOTA PROBOX 02/12

TO-721A

COPA DE PALIER 23X23X34 CV-1004



<https://ikoyama.com/img/TO-723.png>

[https://ikoyama.com/img/TO-723\(2\).png](https://ikoyama.com/img/TO-723(2).png)

TOYOTA YARIS 06/13

TO-723

COPA DE PALIER 23X22X34 TY-107



<https://ikoyama.com/img/TO-7391.png>

[https://ikoyama.com/img/TO-7391\(2\).png](https://ikoyama.com/img/TO-7391(2).png)

TOYOTA YARIS ENVIDIA 14/17

TO-7391

COPA DE PALIER 23X31X34



<https://ikoyama.com/img/BR-001.png>

[https://ikoyama.com/img/BR-001\(2\).png](https://ikoyama.com/img/BR-001(2).png)

BRILLIANCE CARROS CHINOS

BR-001

PALIER 36X21X55



<https://ikoyama.com/img/BY-002.png>

[https://ikoyama.com/img/BY-002\(2\).png](https://ikoyama.com/img/BY-002(2).png)

BYD F3 CHERY TIGGO

BY-002

PALIER 26X30X55.4 C/ABS VW-078A48T



<https://ikoyama.com/img/BY-001.png>

[https://ikoyama.com/img/BY-001\(2\).png](https://ikoyama.com/img/BY-001(2).png)

BYD F3 LIFAN 620

BY-001

PALIER 26X32X55.4 C/ABS TO-257A48T



<https://ikoyama.com/img/CH-005.png>

[https://ikoyama.com/img/CH-005\(2\).png](https://ikoyama.com/img/CH-005(2).png)

CHERY QQ 08/UP

CH-005

PALIER 22X19X51 40/ABS S/EXT SK-824A40T



<https://ikoyama.com/img/CH-004.png>

[https://ikoyama.com/img/CH-004\(2\).png](https://ikoyama.com/img/CH-004(2).png)

CHERY QQ 08/UP

CH-004

PALIER 22X19X51 40/ABS S/INT SK-824F2A40T



<https://ikoyama.com/img/SK-611.png>

[https://ikoyama.com/img/SK-611\(2\).png](https://ikoyama.com/img/SK-611(2).png)

CHERY S22 10/UP

SK-611

PALIER 23X29X51 43/ABS S/INT SK-829A



<https://ikoyama.com/img/OP-002F3.png>

[https://ikoyama.com/img/OP-002F3\(2\).png](https://ikoyama.com/img/OP-002F3(2).png)

CHEVROLET AVEO 02/UP

OP-002F3

PALIER 22X22X52 C/ANILLO OP-002F3



<https://ikoyama.com/img/OP-100.png>

[https://ikoyama.com/img/OP-100\(2\).png](https://ikoyama.com/img/OP-100(2).png)

CHEVROLET AVEO 08/14

OP-100

PALIER 22X22X52 29/ABS S/INT



<https://ikoyama.com/img/OP-620.png>

[https://ikoyama.com/img/OP-620\(2\).png](https://ikoyama.com/img/OP-620(2).png)

CHEVROLET AVEO 12/UP

OP-620

PALIER 22X22X52 S/EXT CH-002



<https://ikoyama.com/img/OP-001.png>

[https://ikoyama.com/img/OP-001\(2\).png](https://ikoyama.com/img/OP-001(2).png)

CHEVROLET AVEO SAIL 02/UP SEGURO EXTERIOR

OP-001

PALIER 22X22X52 S/EXT



<https://ikoyama.com/img/OP-630.png>

[https://ikoyama.com/img/OP-630\(2\).png](https://ikoyama.com/img/OP-630(2).png)

CHEVROLET AVEO SAIL S/EXT 08/12

OP-630

PALIER 22X22X52



<https://ikoyama.com/img/OP-004.png>

[https://ikoyama.com/img/OP-004\(2\).png](https://ikoyama.com/img/OP-004(2).png)

CHEVROLET CORSA CHEVY TAXI 07/UP

OP-004

PALIER 22X28X52.2 C/ANILLO



<https://ikoyama.com/img/OP-013.png>

[https://ikoyama.com/img/OP-013\(2\).png](https://ikoyama.com/img/OP-013(2).png)

CHEVROLET NEW SAIL 16/UP

OP-013

PALIER 22X22X52 C/ABS TORRE ALTA



<https://ikoyama.com/img/GM-631.png>

[https://ikoyama.com/img/GM-631\(2\).png](https://ikoyama.com/img/GM-631(2).png)

CHEVROLET SAIL 16/18

GM-631

PALIER 33X23X56



<https://ikoyama.com/img/OP-621.png>

[https://ikoyama.com/img/OP-621\(2\).png](https://ikoyama.com/img/OP-621(2).png)

CHEVROLET SAIL 16/UP

OP-621

PALIER 33X23X56 C/ABS 47T CH-106A



<https://ikoyama.com/img/OP-011.png>

[https://ikoyama.com/img/OP-011\(2\).png](https://ikoyama.com/img/OP-011(2).png)

CHEVROLET SPARK 95/UP DAEWOO MATIZ 06/09

OP-011

PALIER 23X19X46 S/EXT OP-2011



<https://ikoyama.com/img/CH-006.png>

[https://ikoyama.com/img/CH-006\(2\).png](https://ikoyama.com/img/CH-006(2).png)

CHEVROLET SPARK GT 02/UP

CH-006

PALIER 22X20X52 C/ANILLO CH-203A47T



<https://ikoyama.com/img/OP-806.png>

[https://ikoyama.com/img/OP-806\(2\).png](https://ikoyama.com/img/OP-806(2).png)

DAEWOO NUBIRA

OP-806

PALIER 33X22X52



<https://ikoyama.com/img/OP-006.png>

[https://ikoyama.com/img/OP-006\(2\).png](https://ikoyama.com/img/OP-006(2).png)

DAEWOO RACER LANOS CIELO 89/UP

OP-006

PALIER 22X29X52 C/ANILLO



<https://ikoyama.com/img/OP-012.png>

[https://ikoyama.com/img/OP-012\(2\).png](https://ikoyama.com/img/OP-012(2).png)

DAEWOO RACER LANOS LEMANS 11/UP

OP-012

PALIER 22X29X52 C/ANILLO



<https://ikoyama.com/img/OP-010.png>

[https://ikoyama.com/img/OP-010\(2\).png](https://ikoyama.com/img/OP-010(2).png)

DAEWOO TICO 91/UP

OP-010

PALIER 23X19X44 S/EXT OP-2010



<https://ikoyama.com/img/DA-014.png>

[https://ikoyama.com/img/DA-014\(2\).png](https://ikoyama.com/img/DA-014(2).png)

DAIHATSU CHARADE G102

DA-014

PALIER 24X21X54



<https://ikoyama.com/img/DF-001.png>

[https://ikoyama.com/img/DF-001\(2\).png](https://ikoyama.com/img/DF-001(2).png)

DONGFENG DFSK GLORY 12/UP

DF-001

PALIER 27X24X62.2



<https://ikoyama.com/img/FI-807.png>

[https://ikoyama.com/img/FI-807\(2\).png](https://ikoyama.com/img/FI-807(2).png)

FIAT FIORINO SIENA PALIO 93/ON

FI-807

PALIER 22X20X52 817017(10)

<https://ikoyama.com/img/FI-857.png>

[https://ikoyama.com/img/FI-857\(2\).png](https://ikoyama.com/img/FI-857(2).png)

FORD ECO SPORT 2.0L 4X4

FI-857

PALIER 25X24X51 FI-825(10)

<https://ikoyama.com/img/FD-005.png>

[https://ikoyama.com/img/FD-005\(2\).png](https://ikoyama.com/img/FD-005(2).png)

FORD ESCORT

FD-005

PALIER 24X30X46



<https://ikoyama.com/img/FD-106.png>

[https://ikoyama.com/img/FD-106\(2\).png](https://ikoyama.com/img/FD-106(2).png)

FORD ESCORT

FD-106

PALIER 26X28X56



<https://ikoyama.com/img/FO-003.png>

[https://ikoyama.com/img/FO-003\(2\).png](https://ikoyama.com/img/FO-003(2).png)

FOTON VARIOS

FO-003

PALIER 25X22X54.8 CT-001



<https://ikoyama.com/img/GE-007.png>

[https://ikoyama.com/img/GE-007\(2\).png](https://ikoyama.com/img/GE-007(2).png)

GEELY CK 08/11

GE-007

PALIER 24X23X54 NI-234



<https://ikoyama.com/img/GE-008.png>

[https://ikoyama.com/img/GE-008\(2\).png](https://ikoyama.com/img/GE-008(2).png)

GEELY FAW 00/14

GE-008

PALIER 24X21X56 TO-258



<https://ikoyama.com/img/HO-016.png>

[https://ikoyama.com/img/HO-016\(2\).png](https://ikoyama.com/img/HO-016(2).png)

HONDA ACCORD

HO-016

PALIER 26X32X49



<https://ikoyama.com/img/HO-019.png>

[https://ikoyama.com/img/HO-019\(2\).png](https://ikoyama.com/img/HO-019(2).png)

HONDA ACCORD

HO-019

PALIER 28X32X60



<https://ikoyama.com/img/HO-020.png>

[https://ikoyama.com/img/HO-020\(2\).png](https://ikoyama.com/img/HO-020(2).png)

HONDA ACCORD 93/02

HO-020

PALIER 26X32X55



<https://ikoyama.com/img/HO-003.png>

[https://ikoyama.com/img/HO-003\(2\).png](https://ikoyama.com/img/HO-003(2).png)

HONDA CIVIC

HO-003

PALIER 23X22X45



<https://ikoyama.com/img/HO-013.png>

[https://ikoyama.com/img/HO-013\(2\).png](https://ikoyama.com/img/HO-013(2).png)

HONDA CIVIC

HO-013

PALIER 23X30X45



<https://ikoyama.com/img/HO-009.png>

[https://ikoyama.com/img/HO-009\(2\).png](https://ikoyama.com/img/HO-009(2).png)

HONDA CIVIC

HO-009

PALIER 23X30X49



<https://ikoyama.com/img/HO-054.png>

[https://ikoyama.com/img/HO-054\(2\).png](https://ikoyama.com/img/HO-054(2).png)

HONDA CIVIC

HO-054

PALIER 26X22X58



<https://ikoyama.com/img/HO-017.png>

[https://ikoyama.com/img/HO-017\(2\).png](https://ikoyama.com/img/HO-017(2).png)

HONDA CIVIC

HO-017

PALIER 26X30X49



<https://ikoyama.com/img/HO-5025.png>

[https://ikoyama.com/img/HO-5025\(2\).png](https://ikoyama.com/img/HO-5025(2).png)

HONDA CIVIC 91/95

HO-5025

PALIER 26X30X55 HO-025



<https://ikoyama.com/img/HO-046.png>

[https://ikoyama.com/img/HO-046\(2\).png](https://ikoyama.com/img/HO-046(2).png)

HONDA CIVIC PARTNER 96/00

HO-046

PALIER 26X28X55



<https://ikoyama.com/img/HO-5046.png>

[https://ikoyama.com/img/HO-5046\(2\).png](https://ikoyama.com/img/HO-5046(2).png)

HONDA CIVIC PARTNER 96/00

HO-5046

PALIER 26X58X55 HO-046



<https://ikoyama.com/img/MI-801.png>

[https://ikoyama.com/img/MI-801\(2\).png](https://ikoyama.com/img/MI-801(2).png)

HYUNDAI ACCENT

MI-801

PALIER 25X29X54



<https://ikoyama.com/img/MI-013A.png>

[https://ikoyama.com/img/MI-013A\(2\).png](https://ikoyama.com/img/MI-013A(2).png)

HYUNDAI ELANTRA 00/08 SONATA

MI-013A

PALIER 25X30X50

<https://ikoyama.com/img/HY-62026.png>

[https://ikoyama.com/img/HY-62026\(2\).png](https://ikoyama.com/img/HY-62026(2).png)

HYUNDAI ACCENT 12/15

HY-62026

PALIER 25X22X55.4 KA-102A



<https://ikoyama.com/img/HY-013.png>

[https://ikoyama.com/img/HY-013\(2\).png](https://ikoyama.com/img/HY-013(2).png)

HYUNDAI ELANTRA 08/15 ACCENT G4FG 11/15

HY-013

PALIER 27X22X60 S/INT

<https://ikoyama.com/img/MI-5005.png>

[https://ikoyama.com/img/MI-5005\(2\).png](https://ikoyama.com/img/MI-5005(2).png)

HYUNDAI ELANTRA 1.8 SONATA 88/91 MT GALANT 85/88

MI-5005

PALIER 25X23X50 C/ANILLO



<https://ikoyama.com/img/HY-630.png>

[https://ikoyama.com/img/HY-630\(2\).png](https://ikoyama.com/img/HY-630(2).png)

HYUNDAI ELANTRA 17/20

HY-630

PALIER 27X23X60 SEG. MEDIO 18-R-059A



<https://ikoyama.com/img/HY-010.png>

[https://ikoyama.com/img/HY-010\(2\).png](https://ikoyama.com/img/HY-010(2).png)

HYUNDAI EON 10/10

HY-010

PALIER 24X19X52.5 S/MED HY-231



<https://ikoyama.com/img/MI-2351A.png>

[https://ikoyama.com/img/MI-2351A\(2\).png](https://ikoyama.com/img/MI-2351A(2).png)

HYUNDAI EON i10

MI-2351A

PALIER 24X20X52.5 C/ABS



<https://ikoyama.com/img/HY-009.png>

[https://ikoyama.com/img/HY-009\(2\).png](https://ikoyama.com/img/HY-009(2).png)

HYUNDAI GRAND i10 13/UP

HY-009

PALIER 25X21X52.5 C/ANILLO HY-230



<https://ikoyama.com/img/HY-014.png>

[https://ikoyama.com/img/HY-014\(2\).png](https://ikoyama.com/img/HY-014(2).png)

HYUNDAI i20 i30 16/UP

HY-014

PALIER 27X30X60 C/ABS



<https://ikoyama.com/img/HY-012.png>

[https://ikoyama.com/img/HY-012\(2\).png](https://ikoyama.com/img/HY-012(2).png)

HYUNDAI SANTA FE G4KE 08/15

HY-012

PALIER 30X36X72.8 52/ABS S/INT



<https://ikoyama.com/img/HY-823.png>

[https://ikoyama.com/img/HY-823\(2\).png](https://ikoyama.com/img/HY-823(2).png)

HYUNDAI SANTA FE JAC REIN

HY-823

PALIER 27X25X60 C/ABS



<https://ikoyama.com/img/HY-824.png>

[https://ikoyama.com/img/HY-824\(2\).png](https://ikoyama.com/img/HY-824(2).png)

HYUNDAI SANTA FE PATRULLERO}

HY-824

PALIER 30X35X73 S/INT ABS/52



<https://ikoyama.com/img/MI-004.png>

[https://ikoyama.com/img/MI-004\(2\).png](https://ikoyama.com/img/MI-004(2).png)

HYUNDAI SONATA 85/93

MI-004

PALIER 25X25X50



<https://ikoyama.com/img/MI-641.png>

[https://ikoyama.com/img/MI-641\(2\).png](https://ikoyama.com/img/MI-641(2).png)

HYUNDAI TUCSON 12/UP

MI-641

PALIER 27X24X62.2 48/ABS S/MED



<https://ikoyama.com/img/MI-002.png>

[https://ikoyama.com/img/MI-002\(2\).png](https://ikoyama.com/img/MI-002(2).png)

HYUNDAI/KIA ACCENT/RIO EXCEL 86/11

MI-002

PALIER 25X22X50 C/ANILLO



<https://ikoyama.com/img/HY-011.png>

[https://ikoyama.com/img/HY-011\(2\).png](https://ikoyama.com/img/HY-011(2).png)

HYUNDAI/KIA i10 KIA PICANTO 07/13

HY-011

PALIER 24X20X52.5 C/ANILLO HY-232



<https://ikoyama.com/img/HY-640.png>

[https://ikoyama.com/img/HY-640\(2\).png](https://ikoyama.com/img/HY-640(2).png)

HYUNDAI/KIA SANTA FE 13/18 SORENTO 16/20

HY-640

PALIER 30X25X73



<https://ikoyama.com/img/HY-803.png>

[https://ikoyama.com/img/HY-803\(2\).png](https://ikoyama.com/img/HY-803(2).png)

HYUNDAI/KIA SONATA/OPTIMA 01/09

HY-803

PALIER 27X26X60 C/ANILLO



<https://ikoyama.com/img/HY-820.png>

[https://ikoyama.com/img/HY-820\(2\).png](https://ikoyama.com/img/HY-820(2).png)

HYUNDAI/KIA TUCSON/SPORTAGE

HY-820

PALIER 27X23X62.2 MI-205



<https://ikoyama.com/img/HY-822.png>

[https://ikoyama.com/img/HY-822\(2\).png](https://ikoyama.com/img/HY-822(2).png)

HYUNDAI/KIA TUCSON/SPORTAGE

HY-822

PALIER 27X25X62.2 HY-825



<https://ikoyama.com/img/MI-620.png>

[https://ikoyama.com/img/MI-620\(2\).png](https://ikoyama.com/img/MI-620(2).png)

JAC CLASS 10/13

MI-620

PALIER 25X29X52.5 ABS/44 S/INT



<https://ikoyama.com/img/MI-621.png>

[https://ikoyama.com/img/MI-621\(2\).png](https://ikoyama.com/img/MI-621(2).png)

JAC CLASS 10/UP

MI-621

PALIER 25X29X52.5 ABS/44 S/MED JA-101A



<https://ikoyama.com/img/MZ-2812A.png>

[https://ikoyama.com/img/MZ-2812A\(2\).png](https://ikoyama.com/img/MZ-2812A(2).png)

KIA CARENS

MZ-2812A

PALIER 28X24X56 C/ABS



<https://ikoyama.com/img/KI-001.png>

[https://ikoyama.com/img/KI-001\(2\).png](https://ikoyama.com/img/KI-001(2).png)

KIA CERATO G4FG 12/UP

KI-001

PALIER 27X22X60 46/ABS S/MED

<https://ikoyama.com/img/JX-002A.png>

[https://ikoyama.com/img/JX-002A\(2\).png](https://ikoyama.com/img/JX-002A(2).png)

KIA PICANTO 1.2

JX-002A

PALIER 24X21X52.5 C/ABS



<https://ikoyama.com/img/HY-610.png>

[https://ikoyama.com/img/HY-610\(2\).png](https://ikoyama.com/img/HY-610(2).png)

KIA RIO 12/15

HY-610

PALIER 25X20X50



<https://ikoyama.com/img/KI-003.png>

[https://ikoyama.com/img/KI-003\(2\).png](https://ikoyama.com/img/KI-003(2).png)

KIA RIO 15/UP HYUNDAI ATOS

KI-003

PALIER 25X20X50 MI-810



<https://ikoyama.com/img/HY-620A.png>

[https://ikoyama.com/img/HY-620A\(2\).png](https://ikoyama.com/img/HY-620A(2).png)

KIA RIO 18/UP

HY-620A

PALIER 25X22X52.5 KA-104A



<https://ikoyama.com/img/KI-002.png>

[https://ikoyama.com/img/KI-002\(2\).png](https://ikoyama.com/img/KI-002(2).png)

KIA RIO G4FA 11/UP

KI-002

PALIER 25X22X52.5 48/ABS S/INT



<https://ikoyama.com/img/KA-103.png>

[https://ikoyama.com/img/KA-103\(2\).png](https://ikoyama.com/img/KA-103(2).png)

KIA SEPHIA

KA-103

PALIER 26X22X56



<https://ikoyama.com/img/MZ-023.png>

[https://ikoyama.com/img/MZ-023\(2\).png](https://ikoyama.com/img/MZ-023(2).png)

KIA/FORD PRIDE/FESTIVA 90/93

MZ-023

PALIER 24X20X52



<https://ikoyama.com/img/MZ-012.png>

[https://ikoyama.com/img/MZ-012\(2\).png](https://ikoyama.com/img/MZ-012(2).png)

KIA/FORD PRIDE/FESTIVA 94/95

MZ-012

PALIER 24X19X52 MZ-2012



<https://ikoyama.com/img/HY-620.png>

[https://ikoyama.com/img/HY-620\(2\).png](https://ikoyama.com/img/HY-620(2).png)

KIO RIO HYUNDAI ACCENT 12/15

HY-620

PALIER 25X22X52.5



<https://ikoyama.com/img/LI-012.png>

[https://ikoyama.com/img/LI-012\(2\).png](https://ikoyama.com/img/LI-012(2).png)

LIFAN 520

LI-012

PALIER 25X30X58 FK-801



<https://ikoyama.com/img/MZ-001.png>

[https://ikoyama.com/img/MZ-001\(2\).png](https://ikoyama.com/img/MZ-001(2).png)

MAZDA 2 DEMIO 07/UP

MZ-001

PALIER 25X29X53.8



<https://ikoyama.com/img/MZ-39.png>

[https://ikoyama.com/img/MZ-39\(2\).png](https://ikoyama.com/img/MZ-39(2).png)

MAZDA 3 05/09

MZ-39

PALIER 28X23X56 S/INT MZ-830



<https://ikoyama.com/img/MZ-001A.png>

[https://ikoyama.com/img/MZ-001A\(2\).png](https://ikoyama.com/img/MZ-001A(2).png)

MAZDA 323

MZ-001A

PALIER 24X22X52



<https://ikoyama.com/img/MZ-009.png>

[https://ikoyama.com/img/MZ-009\(2\).png](https://ikoyama.com/img/MZ-009(2).png)

MAZDA 323

MZ-009

PALIER 26X21X56



<https://ikoyama.com/img/MZ-008.png>

[https://ikoyama.com/img/MZ-008\(2\).png](https://ikoyama.com/img/MZ-008(2).png)

MAZDA 323

MZ-008

PALIER 26X22X56



<https://ikoyama.com/img/MZ-016.png>

[https://ikoyama.com/img/MZ-016\(2\).png](https://ikoyama.com/img/MZ-016(2).png)

MAZDA 626

MZ-016

PALIER 28X23X56



<https://ikoyama.com/img/MZ-037A.png>

[https://ikoyama.com/img/MZ-037A\(2\).png](https://ikoyama.com/img/MZ-037A(2).png)

MAZDA FAMILIA 323 95/98

MZ-037A

PALIER 26X29X56 C/ABS



<https://ikoyama.com/img/MZ-024F2.png>

[https://ikoyama.com/img/MZ-024F2\(2\).png](https://ikoyama.com/img/MZ-024F2(2).png)

MAZDA/KIA DEMIO/PRIDE 94/UP

MZ-024F2

PALIER 24X19X52 S/EXT



<https://ikoyama.com/img/MI-015.png>

[https://ikoyama.com/img/MI-015\(2\).png](https://ikoyama.com/img/MI-015(2).png)

MITSUBISHI GALANT 94/97

MI-015

PALIER 25X24X54

<https://ikoyama.com/img/MI-5016F2.png> [https://ikoyama.com/img/MI-5016F2\(2\).png](https://ikoyama.com/img/MI-5016F2(2).png)

MITSUBISHI GALANT ECLIPSE LANCER MIRAGE 91/96

PALIER 25X30X54 C/ANILLO MI-016

MI-5016F2

<https://ikoyama.com/img/MI-013.png> [https://ikoyama.com/img/MI-013\(2\).png](https://ikoyama.com/img/MI-013(2).png)

MITSUBISHI L200 04/14 15/UP

PALIER 30X35X69 C/ABS MI-318

MI-013

<https://ikoyama.com/img/MI-014.png> [https://ikoyama.com/img/MI-014\(2\).png](https://ikoyama.com/img/MI-014(2).png)

MITSUBISHI L200 08/UP

PALIER 30X33X69 C/ABS

MI-014

<https://ikoyama.com/img/MI-025.png> [https://ikoyama.com/img/MI-025\(2\).png](https://ikoyama.com/img/MI-025(2).png)

MITSUBISHI LANCER

PALIER 25X23X54

MI-025

<https://ikoyama.com/img/MI-620A.png> [https://ikoyama.com/img/MI-620A\(2\).png](https://ikoyama.com/img/MI-620A(2).png)

MITSUBISHI LANCER 00/UP

PALIER 25x22x54 S/INT MI-017

MI-620A

<https://ikoyama.com/img/MI-012.png> [https://ikoyama.com/img/MI-012\(2\).png](https://ikoyama.com/img/MI-012(2).png)

MITSUBISHI LANCER MIRAGE LIBERO 4WD 96/UP

PALIER 25X23X54 C/ANILLO

MI-012

<https://ikoyama.com/img/MI-016.png> [https://ikoyama.com/img/MI-016\(2\).png](https://ikoyama.com/img/MI-016(2).png)

MITSUBISHI MIRAGE

PALIER 24X29X47

MI-016

<https://ikoyama.com/img/CV-18.png> [https://ikoyama.com/img/CV-18\(2\).png](https://ikoyama.com/img/CV-18(2).png)

NISSAN AD WAGON CD20 WINGROAD SUNNY 90/ON

PALIER 25X23X55 NI-022FS DIENTES REDONDOS

CV-18



<https://ikoyama.com/img/NI-022F3.png>

[https://ikoyama.com/img/NI-022F3\(2\).png](https://ikoyama.com/img/NI-022F3(2).png)

NISSAN AD WAGON CD20 WINGROAD SUNNY 90/UP

NI-022F3

PALIER 25X23X55 S/INT NI-2022F3



<https://ikoyama.com/img/NI-029.png>

[https://ikoyama.com/img/NI-029\(2\).png](https://ikoyama.com/img/NI-029(2).png)

NISSAN BLUEBIRD

NI-029

PALIER 27X25X56



<https://ikoyama.com/img/NI-041A.png>

[https://ikoyama.com/img/NI-041A\(2\).png](https://ikoyama.com/img/NI-041A(2).png)

NISSAN BLUEBIRD

NI-041A

PALIER 29X25X56 C/ABS



<https://ikoyama.com/img/NI-009.png>

[https://ikoyama.com/img/NI-009\(2\).png](https://ikoyama.com/img/NI-009(2).png)

NISSAN BLUEBIRD PREIRE 83/97

NI-009

PALIER 27X23X56 C/ANILLO NI-2009



<https://ikoyama.com/img/NI-007.png>

[https://ikoyama.com/img/NI-007\(2\).png](https://ikoyama.com/img/NI-007(2).png)

NISSAN BLUEBIRD U12

NI-007

PALIER 27X23X56

<https://ikoyama.com/img/NI-043.png>

[https://ikoyama.com/img/NI-043\(2\).png](https://ikoyama.com/img/NI-043(2).png)

NISSAN FRONTIER D22 05/06

NI-043

PALIER 28X27X50(10)



<https://ikoyama.com/img/NI-045.png>

[https://ikoyama.com/img/NI-045\(2\).png](https://ikoyama.com/img/NI-045(2).png)

NISSAN FRONTIER D22 CD32 KA24 06/UP

NI-045

PALIER 28X25X50 C/ANILLO

<https://ikoyama.com/img/NI-036.png>

[https://ikoyama.com/img/NI-036\(2\).png](https://ikoyama.com/img/NI-036(2).png)

NISSAN GA15D ADWAGON Y10

NI-036

PALIER 24X23X52(10)



<https://ikoyama.com/img/CV-27.png>

[https://ikoyama.com/img/CV-27\(2\).png](https://ikoyama.com/img/CV-27(2).png)

NISSAN MARCH

CV-27

PALIER 23X19X48



<https://ikoyama.com/img/NI-046.png>

[https://ikoyama.com/img/NI-046\(2\).png](https://ikoyama.com/img/NI-046(2).png)

NISSAN NAVARA YD25 14/UP

NI-046

PALIER 29X36X67.2 C/ANILLO



<https://ikoyama.com/img/NI-5052.png>

[https://ikoyama.com/img/NI-5052\(2\).png](https://ikoyama.com/img/NI-5052(2).png)

NISSAN SENTRA 2.0

NI-5052

PALIER 25X32X55 C/ANILLO NI-052



<https://ikoyama.com/img/NI-020.png>

[https://ikoyama.com/img/NI-020\(2\).png](https://ikoyama.com/img/NI-020(2).png)

NISSAN SENTRA AVENIR SUNNY AD CD17 CD20 90/UP

NI-020

PALIER 25X22X55 S/INT NI-2020



<https://ikoyama.com/img/NI-003.png>

[https://ikoyama.com/img/NI-003\(2\).png](https://ikoyama.com/img/NI-003(2).png)

NISSAN SENTRA B11 SUNNY 82/86

NI-003

PALIER 24X22X52 C/ANILLO NI-2003



<https://ikoyama.com/img/NI-011.png>

[https://ikoyama.com/img/NI-011\(2\).png](https://ikoyama.com/img/NI-011(2).png)

NISSAN SENTRA B12

NI-011

PALIER 25X22X52.2



<https://ikoyama.com/img/NI-006.png>

[https://ikoyama.com/img/NI-006\(2\).png](https://ikoyama.com/img/NI-006(2).png)

NISSAN SENTRA B12

NI-006

PALIER 25X23X52.2



<https://ikoyama.com/img/NI-028.png>

[https://ikoyama.com/img/NI-028\(2\).png](https://ikoyama.com/img/NI-028(2).png)

NISSAN SENTRA B12 MEX 90/ON

NI-028

PALIER 25X24X52.2 S/INT



<https://ikoyama.com/img/NI-021.png>

[https://ikoyama.com/img/NI-021\(2\).png](https://ikoyama.com/img/NI-021(2).png)

NISSAN SENTRA B13

NI-021

PALIER 25X25X52.2 NI-2021 (10)



<https://ikoyama.com/img/NI-032.png>

[https://ikoyama.com/img/NI-032\(2\).png](https://ikoyama.com/img/NI-032(2).png)

NISSAN SENTRA B13 GA16 SUNNY 93/ON

NI-032

PALIER 25X24X55 S/INT NI-2032



<https://ikoyama.com/img/CV-15.png>

[https://ikoyama.com/img/CV-15\(2\).png](https://ikoyama.com/img/CV-15(2).png)

NISSAN SENTRA B13 MEXICO SUNNY 90/UP

CV-15

PALIER 25X23X55 S/INT NI-214



<https://ikoyama.com/img/NI-052.png>

[https://ikoyama.com/img/NI-052\(2\).png](https://ikoyama.com/img/NI-052(2).png)

NISSAN SENTRA B14

NI-052

PALIER 25X32X55 S/INT



<https://ikoyama.com/img/NI-047.png>

[https://ikoyama.com/img/NI-047\(2\).png](https://ikoyama.com/img/NI-047(2).png)

NISSAN SENTRA B16 13/UP

NI-047

PALIER 29X23X56.2



<https://ikoyama.com/img/NI-048.png>

[https://ikoyama.com/img/NI-048\(2\).png](https://ikoyama.com/img/NI-048(2).png)

NISSAN SENTRA TIIDA 07/UP LAFESTA

NI-048

PALIER 29X24X56



<https://ikoyama.com/img/NI-026.png>

[https://ikoyama.com/img/NI-026\(2\).png](https://ikoyama.com/img/NI-026(2).png)

NISSAN STANZA T11

NI-026

PALIER 27X25X56



<https://ikoyama.com/img/NI-620.png>

[https://ikoyama.com/img/NI-620\(2\).png](https://ikoyama.com/img/NI-620(2).png)

NISSAN SUNNY 84/UP

NI-620

PALIER 21X22X48 S/INT NI-004



<https://ikoyama.com/img/NI-080.png>

[https://ikoyama.com/img/NI-080\(2\).png](https://ikoyama.com/img/NI-080(2).png)

NISSAN TIIDA 04/11

NI-080

PALIER 25X21X49 S/INT NI-231



<https://ikoyama.com/img/NI-012.png>

[https://ikoyama.com/img/NI-012\(2\).png](https://ikoyama.com/img/NI-012(2).png)

NISSAN TIIDA 04/11 VERSA 1.6 MARCH 1.6 11/UP

NI-012

PALIER 25X22X49 S/MED NI-232



<https://ikoyama.com/img/NI-049.png>

[https://ikoyama.com/img/NI-049\(2\).png](https://ikoyama.com/img/NI-049(2).png)

NISSAN VERSA 15/UP SUNNY N17 MARCH 10/15

NI-049

PALIER 25X29X49 S/ABS



<https://ikoyama.com/img/NI-044.png>

[https://ikoyama.com/img/NI-044\(2\).png](https://ikoyama.com/img/NI-044(2).png)

NISSAN X-TRAIL 06/UP

NI-044

PALIER 29X25X56 C/ABS



<https://ikoyama.com/img/NI-640.png>

[https://ikoyama.com/img/NI-640\(2\).png](https://ikoyama.com/img/NI-640(2).png)

NISSAN X-TRAIL 08/15

NI-640

PALIER 29x35x56 NI-102



<https://ikoyama.com/img/RE-015.png>

[https://ikoyama.com/img/RE-015\(2\).png](https://ikoyama.com/img/RE-015(2).png)

RENAULT MASTER II 98/04

RE-015

PALIER 28X36X65 ME-201(10)



<https://ikoyama.com/img/RN-811A.png>

[https://ikoyama.com/img/RN-811A\(2\).png](https://ikoyama.com/img/RN-811A(2).png)

RENAULT CLIO MEGANE 96/00

RN-811A

PALIER 21X22X51.3 C/ABS



<https://ikoyama.com/img/RE-014.png>

[https://ikoyama.com/img/RE-014\(2\).png](https://ikoyama.com/img/RE-014(2).png)

RENAULT LOGAN 07/13 CLIO

RE-014

PALIER 23X21X56 RN-212



<https://ikoyama.com/img/RE-017.png>

[https://ikoyama.com/img/RE-017\(2\).png](https://ikoyama.com/img/RE-017(2).png)

RENAULT LOGAN CLIO

PALIER 23X30X57.3 C/ABS

RE-017



<https://ikoyama.com/img/RN-671.png>

[https://ikoyama.com/img/RN-671\(2\).png](https://ikoyama.com/img/RN-671(2).png)

RENAULT MASTER II 08/12

PALIER 28X36X64.5 RM-102

RN-671



<https://ikoyama.com/img/RE-010.png>

[https://ikoyama.com/img/RE-010\(2\).png](https://ikoyama.com/img/RE-010(2).png)

RENAULT MASTER III 04/UP

PALIER 28X27X67.2 C/ABS

RE-010



<https://ikoyama.com/img/RE-016.png>

[https://ikoyama.com/img/RE-016\(2\).png](https://ikoyama.com/img/RE-016(2).png)

RENAULT MASTER III 04/UP

PALIER 31X36X70 S/INT ME-200

RE-016



<https://ikoyama.com/img/RN-671A.png>

[https://ikoyama.com/img/RN-671A\(2\).png](https://ikoyama.com/img/RN-671A(2).png)

RENAULT MASTER III 12/18

PALIER 31X36X70 RM-101

RN-671A



<https://ikoyama.com/img/SB-010.png>

[https://ikoyama.com/img/SB-010\(2\).png](https://ikoyama.com/img/SB-010(2).png)

SUBARU IMPREZA 1.8 LEGACY 89/90

PALIER 27X30X56 C/ANILLO

SB-010



<https://ikoyama.com/img/SB-022.png>

[https://ikoyama.com/img/SB-022\(2\).png](https://ikoyama.com/img/SB-022(2).png)

SUBARU IMPREZA FORESTER LEGACY 94/04

PALIER 27X30X56 C/ANILLO

SB-022

<https://ikoyama.com/img/SB-008.png>

[https://ikoyama.com/img/SB-008\(2\).png](https://ikoyama.com/img/SB-008(2).png)

SUBARU LEGACY 2WD

PALIER 27X25X56

SB-008



<https://ikoyama.com/img/SB-012.png>

[https://ikoyama.com/img/SB-012\(2\).png](https://ikoyama.com/img/SB-012(2).png)

SUBARU LEGACY 4WD

SB-012

PALIER 27X22X56



<https://ikoyama.com/img/SK-823A.png>

[https://ikoyama.com/img/SK-823A\(2\).png](https://ikoyama.com/img/SK-823A(2).png)

SUZUKI AERIO LIANA BALENO CLESENT 95/02

SK-823A

PALIER 25X29X49 C/ANILLO SK-823A



<https://ikoyama.com/img/SK-017.png>

[https://ikoyama.com/img/SK-017\(2\).png](https://ikoyama.com/img/SK-017(2).png)

SUZUKI ALTO 05/13

SK-017

PALIER 23X19X49 S/INT SK-024



<https://ikoyama.com/img/SK-1043.png>

[https://ikoyama.com/img/SK-1043\(2\).png](https://ikoyama.com/img/SK-1043(2).png)

SUZUKI ALTO A23 B18 C49 06/09

SK-1043

PALIER 23X18X49 S/INT SK-202



<https://ikoyama.com/img/SK-610.png>

[https://ikoyama.com/img/SK-610\(2\).png](https://ikoyama.com/img/SK-610(2).png)

SUZUKI ALTO CELERIO 10/15

SK-610

PALIER 23X19X49 S/INT SK-811



<https://ikoyama.com/img/SK-130.png>

[https://ikoyama.com/img/SK-130\(2\).png](https://ikoyama.com/img/SK-130(2).png)

SUZUKI ALTO K10

SK-130

PALIER 23X20X49 C/ABS



<https://ikoyama.com/img/SK-801.png>

[https://ikoyama.com/img/SK-801\(2\).png](https://ikoyama.com/img/SK-801(2).png)

SUZUKI BALENO

SK-801

PALIER 25X21X49



<https://ikoyama.com/img/SK-610A.png>

[https://ikoyama.com/img/SK-610A\(2\).png](https://ikoyama.com/img/SK-610A(2).png)

SUZUKI CELERIO 10/UP

SK-610A

PALIER 23x19x49 S/INT SK-811



<https://ikoyama.com/img/SK-110.png>

SUZUKI ERTIGA

PALIER 28X28X61

SK-110



[https://ikoyama.com/img/SK-110\(2\).png](https://ikoyama.com/img/SK-110(2).png)



<https://ikoyama.com/img/TJSK04.png>

SUZUKI ERTIGA

TRICERA DE PALIER 28DX35X11.5

TJSK04



[https://ikoyama.com/img/TJSK04\(2\).png](https://ikoyama.com/img/TJSK04(2).png)



<https://ikoyama.com/img/SK-901.png>

SUZUKI ERTIGA LH 14/18

PALIER 28X28X68

SK-901



[https://ikoyama.com/img/SK-901\(2\).png](https://ikoyama.com/img/SK-901(2).png)



<https://ikoyama.com/img/SK-026.png>

SUZUKI MARUTTI

PALIER 23X18X44

SK-026



[https://ikoyama.com/img/SK-026\(2\).png](https://ikoyama.com/img/SK-026(2).png)



<https://ikoyama.com/img/SK-621.png>

SUZUKI SWIFT 12/UP

PALIER 25X28X49 SZ-101

SK-621



[https://ikoyama.com/img/SK-621\(2\).png](https://ikoyama.com/img/SK-621(2).png)



<https://ikoyama.com/img/SK-120.png>

SUZUKI SX4

PALIER 28X29X58 S/INT

SK-120



[https://ikoyama.com/img/SK-120\(2\).png](https://ikoyama.com/img/SK-120(2).png)



<https://ikoyama.com/img/TO-640.png>

TOYOTA 4RUNNER 98/05 LANDCRUISER 98/05

PALIER 30X27X33.5 TO-003

TO-640



[https://ikoyama.com/img/TO-640\(2\).png](https://ikoyama.com/img/TO-640(2).png)



<https://ikoyama.com/img/TO-022.png>

TOYOTA CARINA DIESEL 91/ON

PALIER 26X27X56 TO-2022(10)

TO-022



[https://ikoyama.com/img/TO-022\(2\).png](https://ikoyama.com/img/TO-022(2).png)



<https://ikoyama.com/img/TO-839.png>

[https://ikoyama.com/img/TO-839\(2\).png](https://ikoyama.com/img/TO-839(2).png)

TOYOTA COROLLA 08/13 COROLLON

TO-839

PALIER 26X23X58 S/MED



<https://ikoyama.com/img/TO-843.png>

[https://ikoyama.com/img/TO-843\(2\).png](https://ikoyama.com/img/TO-843(2).png)

TOYOTA COROLLA 18/UP

TO-843

PALIER 26X32X58 C/ABS



<https://ikoyama.com/img/TO-015.png>

[https://ikoyama.com/img/TO-015\(2\).png](https://ikoyama.com/img/TO-015(2).png)

TOYOTA COROLLA 1C 2C DIESEL 91/99 COROLLON

TO-015

PALIER 26X24X56 S/INT TO-2015



<https://ikoyama.com/img/TO-014F2.png>

[https://ikoyama.com/img/TO-014F2\(2\).png](https://ikoyama.com/img/TO-014F2(2).png)

TOYOTA COROLLA 2E 3E 4A TERCEL 84/99

TO-014F2

PALIER 26X23X56 S/INT TO-2014F2



<https://ikoyama.com/img/TO-813.png>

[https://ikoyama.com/img/TO-813\(2\).png](https://ikoyama.com/img/TO-813(2).png)

TOYOTA COROLLA ZZE120 02/UP

TO-813

PALIER 26X24X58 S/INT



<https://ikoyama.com/img/TO-844.png>

[https://ikoyama.com/img/TO-844\(2\).png](https://ikoyama.com/img/TO-844(2).png)

TOYOTA ETIOS 16/UP YARIS 18/22

TO-844

PALIER 26X22X55.5 S/MED



<https://ikoyama.com/img/TO-842.png>

[https://ikoyama.com/img/TO-842\(2\).png](https://ikoyama.com/img/TO-842(2).png)

TOYOTA ETIOS MOTOR 2NR 16/UP BYD F3

TO-842

PALIER 26X21X55.5 C/ANILLO S/ABS



<https://ikoyama.com/img/TO-838.png>

[https://ikoyama.com/img/TO-838\(2\).png](https://ikoyama.com/img/TO-838(2).png)

TOYOTA HILUX 2KD 4X4 ARGENTINO

TO-838

PALIER 26X34X60(10)



<https://ikoyama.com/img/TO-025.png>

[https://ikoyama.com/img/TO-025\(2\).png](https://ikoyama.com/img/TO-025(2).png)

TOYOTA HILUX 4WD 97/05 HIACE 3L 90/04

TO-025

PALIER 26X27X60 TO-2025(10) 43460-35070



<https://ikoyama.com/img/TO-841.png>

[https://ikoyama.com/img/TO-841\(2\).png](https://ikoyama.com/img/TO-841(2).png)

TOYOTA HILUX REVO 1GD 2GD 15/UP

TO-841

PALIER 30X29X70 S/MED



<https://ikoyama.com/img/TO-2880.png>

[https://ikoyama.com/img/TO-2880\(2\).png](https://ikoyama.com/img/TO-2880(2).png)

TOYOTA HILUX VIGO 1KD 2KD 04/UP

TO-2880

PALIER 30X29X72.5 S/MED TO-210



<https://ikoyama.com/img/TO-023.png>

[https://ikoyama.com/img/TO-023\(2\).png](https://ikoyama.com/img/TO-023(2).png)

TOYOTA STARLET

TO-023

PALIER 23X21X56



<https://ikoyama.com/img/TO-007.png>

[https://ikoyama.com/img/TO-007\(2\).png](https://ikoyama.com/img/TO-007(2).png)

TOYOTA STARLET 1N EP70 83/88

TO-007

PALIER 23X23X56 C/ANILLO TO-2007



<https://ikoyama.com/img/TO-027.png>

[https://ikoyama.com/img/TO-027\(2\).png](https://ikoyama.com/img/TO-027(2).png)

TOYOTA TERCEL EL40 91/94

TO-027

PALIER 26X22X56 C/ANILLO



<https://ikoyama.com/img/TO-029.png>

[https://ikoyama.com/img/TO-029\(2\).png](https://ikoyama.com/img/TO-029(2).png)

TOYOTA TERCEL EL50 95/UP

TO-029

PALIER 26X22X56 TO-2029



<https://ikoyama.com/img/TO-826.png>

[https://ikoyama.com/img/TO-826\(2\).png](https://ikoyama.com/img/TO-826(2).png)

TOYOTA YARIS 1NZ 06/13

TO-826

PALIER 26X23X55.6 S/INT



<https://ikoyama.com/img/TO-926.png>

[https://ikoyama.com/img/TO-926\(2\).png](https://ikoyama.com/img/TO-926(2).png)

TOYOTA YARIS 1NZ 06/13

TO-926

PALIER 26X23X55.6 S/INT FD2329-K



<https://ikoyama.com/img/TO-834.png>

[https://ikoyama.com/img/TO-834\(2\).png](https://ikoyama.com/img/TO-834(2).png)

TOYOTA YARIS 99/06

TO-834

PALIER 24X23X56 TO-2834(10)



<https://ikoyama.com/img/TO-808.png>

[https://ikoyama.com/img/TO-808\(2\).png](https://ikoyama.com/img/TO-808(2).png)

TOYOTA YARIS 99/07

TO-808

PALIER 24X22X56 C/ANILLO TO-2808



<https://ikoyama.com/img/TO-2435.png>

[https://ikoyama.com/img/TO-2435\(2\).png](https://ikoyama.com/img/TO-2435(2).png)

TOYOTA YARIS ENVIDIA 14/17

TO-2435

PALIER 26X31X55.6 S/INT TO-200



<https://ikoyama.com/img/TO-836.png>

[https://ikoyama.com/img/TO-836\(2\).png](https://ikoyama.com/img/TO-836(2).png)

TOYOTA YARIS PROBOX

TO-836

PALIER 24X22X58 TO-2836(10)



<https://ikoyama.com/img/TO-840.png>

[https://ikoyama.com/img/TO-840\(2\).png](https://ikoyama.com/img/TO-840(2).png)

TOYOTA YARIS PROBOX 1.3 1.5 99/03

TO-840

PALIER 24X23X58 S/ABS



<https://ikoyama.com/img/AD-2307.png>

[https://ikoyama.com/img/AD-2307\(2\).png](https://ikoyama.com/img/AD-2307(2).png)

VW AMAROK 10/UP

AD-2307

PALIER 28X27X64.8



<https://ikoyama.com/img/VW-802.png>

[https://ikoyama.com/img/VW-802\(2\).png](https://ikoyama.com/img/VW-802(2).png)

VW GOL JETTA VENTO 98/04

VW-802

PALIER 22X30X51



<https://ikoyama.com/img/VW-005.png>

[https://ikoyama.com/img/VW-005\(2\).png](https://ikoyama.com/img/VW-005(2).png)

VW GOL METROPOLITANO 04/ON

VW-005

PALIER 22X30X50



<https://ikoyama.com/img/VW-020.png>

[https://ikoyama.com/img/VW-020\(2\).png](https://ikoyama.com/img/VW-020(2).png)

VW GOLF JETTA 93/95

VW-020

PALIER 22X30X51 S/INT



<https://ikoyama.com/img/VW-010.png>

[https://ikoyama.com/img/VW-010\(2\).png](https://ikoyama.com/img/VW-010(2).png)

VW VENTO GOLF

VW-010

PALIER 22X30X51



<https://ikoyama.com/img/VW-011.png>

[https://ikoyama.com/img/VW-011\(2\).png](https://ikoyama.com/img/VW-011(2).png)

VW VENTO JETTA

VW-011

PALIER 22X30X51 ANCHO

Especialistas en:

TRICETAS



KOYAMA
SUSPENSION PARTS



<https://ikoyama.com/img/TJBYD03.png>
BYD F3 , LIFAN 520 , 620

[https://ikoyama.com/img/TJBYD03\(2\).png](https://ikoyama.com/img/TJBYD03(2).png)

TRICETA DE PALIER 30DX32X11

TJBYD03



<https://ikoyama.com/img/TJBYD02.png>

[https://ikoyama.com/img/TJBYD02\(2\).png](https://ikoyama.com/img/TJBYD02(2).png)

CHERY ARRIZO 3 17/22 , LIFAN 520

TRICETA DE PALIER 29DX32X11

TJBYD02



<https://ikoyama.com/img/TJCH03.png>
CHEVROLET AVEO 10/14

[https://ikoyama.com/img/TJCH03\(2\).png](https://ikoyama.com/img/TJCH03(2).png)

TRICETA DE PALIER 29DX33.5X10

TJCH03



<https://ikoyama.com/img/TJCH01.png>

[https://ikoyama.com/img/TJCH01\(2\).png](https://ikoyama.com/img/TJCH01(2).png)

CHEVROLET CHEVY TAXI 07/09

TRICETA DE PALIER 28DX30X11.9

TJCH01



<https://ikoyama.com/img/TJCH02.png>
CHEVROLET SAIL 11/15

[https://ikoyama.com/img/TJCH02\(2\).png](https://ikoyama.com/img/TJCH02(2).png)

TRICETA DE PALIER 22DX32X10.7

TJCH02



<https://ikoyama.com/img/TJCH04.png>

[https://ikoyama.com/img/TJCH04\(2\).png](https://ikoyama.com/img/TJCH04(2).png)

CHEVROLET SPARK GT 14/16

TRICETA DE PALIER 20DX27.5X9

TJCH04



<https://ikoyama.com/img/TJDW01.png>
DAEWOO TICO/MATIZ 95/00 CHEVROLET SPARK

[https://ikoyama.com/img/TJDW01\(2\).png](https://ikoyama.com/img/TJDW01(2).png)

TRICETA DE PALIER 19DX28X9.4

TJDW01



<https://ikoyama.com/img/TJFT01.png>

[https://ikoyama.com/img/TJFT01\(2\).png](https://ikoyama.com/img/TJFT01(2).png)

FIAT FIORINO 92/02

TRICETA DE PALIER 20DX32X10.8

TJFT01



<https://ikoyama.com/img/TJFD01.png>

[https://ikoyama.com/img/TJFD01\(2\).png](https://ikoyama.com/img/TJFD01(2).png)

FORD RANGER 12/UP MAZDA BT-50 12/UP

TRICETA DE PALIER 27DX47X15.5

TJFD01



<https://ikoyama.com/img/TJGW01.png>

[https://ikoyama.com/img/TJGW01\(2\).png](https://ikoyama.com/img/TJGW01(2).png)

GREAT WALL VOLEEX C30

TRICETA DE PALIER 29DX32X11

TJGW01



<https://ikoyama.com/img/TJHN01.png>

[https://ikoyama.com/img/TJHN01\(2\).png](https://ikoyama.com/img/TJHN01(2).png)

HONDA CIVIC 95/02

TRICETA DE PALIER 32DX38X9.5

TJHN01



<https://ikoyama.com/img/TJHN02.png>

[https://ikoyama.com/img/TJHN02\(2\).png](https://ikoyama.com/img/TJHN02(2).png)

HONDA CR-V 02/07

TRICETA DE PALIER 32DX38X9.5

TJHN02



<https://ikoyama.com/img/TJHY02.png>

[https://ikoyama.com/img/TJHY02\(2\).png](https://ikoyama.com/img/TJHY02(2).png)

HYUNDAI ELANTRA 08/12 ACCENT 11/17 KIA CERATO 11/UP RIO 11/17

TRICETA DE PALIER 22DX32.5X11

TJHY02



<https://ikoyama.com/img/TJHY03.png>

[https://ikoyama.com/img/TJHY03\(2\).png](https://ikoyama.com/img/TJHY03(2).png)

HYUNDAI ELANTRA 11/15 SONATA 10/15

TRICETA DE PALIER 30DX38X11

TJHY03



<https://ikoyama.com/img/TJHY05.png>

[https://ikoyama.com/img/TJHY05\(2\).png](https://ikoyama.com/img/TJHY05(2).png)

HYUNDAI EON 14/17

TRICETA DE PALIER 19DX32X10.5

TJHY05



<https://ikoyama.com/img/TJHY06.png>

[https://ikoyama.com/img/TJHY06\(2\).png](https://ikoyama.com/img/TJHY06(2).png)

HYUNDAI EON 14/17

TRICETA DE PALIER 21DX31X10

TJHY06



<https://ikoyama.com/img/TJHY07.png>

[https://ikoyama.com/img/TJHY07\(2\).png](https://ikoyama.com/img/TJHY07(2).png)

HYUNDAI EXCEL 92/97

TJHY07

TRICETA DE PALIER 22DX30X12



<https://ikoyama.com/img/TJHY10.png>

[https://ikoyama.com/img/TJHY10\(2\).png](https://ikoyama.com/img/TJHY10(2).png)

HYUNDAI SANTAFE 10/15 KIA SORENTO 10/15

TJHY10

TRICETA DE PALIER 33DX44X15



<https://ikoyama.com/img/TJHY09.png>

[https://ikoyama.com/img/TJHY09\(2\).png](https://ikoyama.com/img/TJHY09(2).png)

HYUNDAI SONATA 02/06

TJHY09

TRICETA DE PALIER 25DX36.5X



<https://ikoyama.com/img/TJKI01.png>

[https://ikoyama.com/img/TJKI01\(2\).png](https://ikoyama.com/img/TJKI01(2).png)

KIA PICANTO 12/15 , HYUNDAI I10

TJKI01

TRICETA DE PALIER 20DX27.7X 9.4



<https://ikoyama.com/img/TJKI07.png>

[https://ikoyama.com/img/TJKI07\(2\).png](https://ikoyama.com/img/TJKI07(2).png)

KIA PRIDE

TJKI07

TRICETA DE PALIER 20DX29X10



<https://ikoyama.com/img/TJKI05.png>

[https://ikoyama.com/img/TJKI05\(2\).png](https://ikoyama.com/img/TJKI05(2).png)

KIA RIO HATCHBACK 1.2L 16/21 HYUNDAI GRAND I10 16/21

TJKI05

TRICETA DE PALIER 20DX30X10.3



<https://ikoyama.com/img/TJKI06.png>

[https://ikoyama.com/img/TJKI06\(2\).png](https://ikoyama.com/img/TJKI06(2).png)

KIA SPORTAGE 11/15 HYUNDAI TUCSON 11/15 KIA CARENS

TJKI06

TRICETA DE PALIER 24DX42X14



<https://ikoyama.com/img/TJMI02.png>

[https://ikoyama.com/img/TJMI02\(2\).png](https://ikoyama.com/img/TJMI02(2).png)

MITSUBISHI LIBERO

TJMI02

TRICETA DE PALIER 30DX34X11



<https://ikoyama.com/img/TJMI01.png>

[https://ikoyama.com/img/TJMI01\(2\).png](https://ikoyama.com/img/TJMI01(2).png)

mitsubishi mirage mitsubishi lancer

TJMI01

TRICETA DE PALIER 23DX33X13



<https://ikoyama.com/img/TJNIO1.png>

[https://ikoyama.com/img/TJNIO1\(2\).png](https://ikoyama.com/img/TJNIO1(2).png)

NISSAN AD NEW 02/06 , WINGROAD 96/UP

TJNIO1

TRICETA DE PALIER 23DX36X12



<https://ikoyama.com/img/TJNIO2.png>

[https://ikoyama.com/img/TJNIO2\(2\).png](https://ikoyama.com/img/TJNIO2(2).png)

NISSAN AD WAGON Y10 92/97

TJNIO2

TRICETA DE PALIER 23DX39X15



<https://ikoyama.com/img/TJNIO3.png>

[https://ikoyama.com/img/TJNIO3\(2\).png](https://ikoyama.com/img/TJNIO3(2).png)

NISSAN SENTRA AD WAGON Y10 , CD17 92/97

TJNIO3

TRICETA DE PALIER 23DX33X13



<https://ikoyama.com/img/TJNIO5.png>

[https://ikoyama.com/img/TJNIO5\(2\).png](https://ikoyama.com/img/TJNIO5(2).png)

NISSAN SENTRA B13 92/97 MEXICANO

TJNIO5

TRICETA DE PALIER 24DX30X11.8



<https://ikoyama.com/img/TJNIO6.png>

[https://ikoyama.com/img/TJNIO6\(2\).png](https://ikoyama.com/img/TJNIO6(2).png)

NISSAN SENTRA B14 98/00

TJNIO6

TRICETA DE PALIER 32DX37X12



<https://ikoyama.com/img/TJNIO7.png>

[https://ikoyama.com/img/TJNIO7\(2\).png](https://ikoyama.com/img/TJNIO7(2).png)

NISSAN SENTRA V16 10/14 , MR18 , MR20 , COROLLON 06/13

TJNIO7

TRICETA DE PALIER 23DX34X12



<https://ikoyama.com/img/TJNIO11.png>

[https://ikoyama.com/img/TJNIO11\(2\).png](https://ikoyama.com/img/TJNIO11(2).png)

NISSAN SUNNY B11 CD17 92/97

TJNIO11

TRICETA DE PALIER 23DX32X11



<https://ikoyama.com/img/TJN109.png>

[https://ikoyama.com/img/TJN109\(2\).png](https://ikoyama.com/img/TJN109(2).png)

NISSAN TIIDA 12/15 NISSAN VERSA 15/21

TJN109

TRICETA DE PALIER 21DX30X10.5



<https://ikoyama.com/img/TJSK03.png>

[https://ikoyama.com/img/TJSK03\(2\).png](https://ikoyama.com/img/TJSK03(2).png)

SUZUKI SWIFT 05/12

TJSK03

TRICETA DE PALIER 28DX32.5X9



<https://ikoyama.com/img/TJSK02.png>

[https://ikoyama.com/img/TJSK02\(2\).png](https://ikoyama.com/img/TJSK02(2).png)

SUZUKI SWIFT 12/16 , ERTIGA 15/18

TJSK02

TRICETA DE PALIER 28DX32X11.5



<https://ikoyama.com/img/TJTY01.png>

[https://ikoyama.com/img/TJTY01\(2\).png](https://ikoyama.com/img/TJTY01(2).png)

TOYOTA COROLLA 4E , COROLLA AE100 92/02

TJTY01

TRICETA DE PALIER 23DX30X11.5



<https://ikoyama.com/img/TJTY02.png>

[https://ikoyama.com/img/TJTY02\(2\).png](https://ikoyama.com/img/TJTY02(2).png)

TOYOTA COROLLA AE100 92/02

TJTY02

TRICETA DE PALIER 24DX34X14



<https://ikoyama.com/img/TJTY03.png>

[https://ikoyama.com/img/TJTY03\(2\).png](https://ikoyama.com/img/TJTY03(2).png)

TOYOTA COROLLA AE100 92/02 , MOTOR 2C

TJTY03

TRICETA DE PALIER 23DX38X12



<https://ikoyama.com/img/TJTY05.png>

[https://ikoyama.com/img/TJTY05\(2\).png](https://ikoyama.com/img/TJTY05(2).png)

TOYOTA ETIOS 18/20

TJTY05

TRICETA DE PALIER 21DX30.4X11



<https://ikoyama.com/img/TJTY17.png>

[https://ikoyama.com/img/TJTY17\(2\).png](https://ikoyama.com/img/TJTY17(2).png)

TOYOTA HILUX 1KD 2KD 2/15

TJTY17

TRICETA DE PALIER 29DX48X17



<https://ikoyama.com/img/TJTY09.png>

[https://ikoyama.com/img/TJTY09\(2\).png](https://ikoyama.com/img/TJTY09(2).png)

TOYOTA HILUX REVO 1GD , 2GD 16/20

TJTY09

TRICETA DE PALIER 28DX48.2X17



<https://ikoyama.com/img/TJTY18.png>

[https://ikoyama.com/img/TJTY18\(2\).png](https://ikoyama.com/img/TJTY18(2).png)

TOYOTA PROBOX

TJTY18

TRICETA DE PALIER 23DX30X11



<https://ikoyama.com/img/TJTY13.png>

[https://ikoyama.com/img/TJTY13\(2\).png](https://ikoyama.com/img/TJTY13(2).png)

TOYOTA PROBOX 00/06 COROLLA 90/00 TERCEL 90/94

TJTY13

TRICETA DE PALIER 23DX32X11



<https://ikoyama.com/img/TJTY07.png>

[https://ikoyama.com/img/TJTY07\(2\).png](https://ikoyama.com/img/TJTY07(2).png)

TOYOTA RAV4 08/19

TJTY07

TRICETA DE PALIER 27DX43X14.5



<https://ikoyama.com/img/TJTY14.png>

[https://ikoyama.com/img/TJTY14\(2\).png](https://ikoyama.com/img/TJTY14(2).png)

TOYOTA TERCEL EL50 95/98

TJTY14

TRICETA DE PALIER 22DX29X10



<https://ikoyama.com/img/TJTY15.png>

[https://ikoyama.com/img/TJTY15\(2\).png](https://ikoyama.com/img/TJTY15(2).png)

TOYOTA YARIS 08/13

TJTY15

TRICETA DE PALIER 22DX29X11



<https://ikoyama.com/img/TJTY16.png>

[https://ikoyama.com/img/TJTY16\(2\).png](https://ikoyama.com/img/TJTY16(2).png)

TOYOTA YARIS ENVIDIA 14/17

TJTY16

TRICETA DE PALIER 31DX37X10



<https://ikoyama.com/img/TJVW01.png>

[https://ikoyama.com/img/TJVW01\(2\).png](https://ikoyama.com/img/TJVW01(2).png)

VOLKSWAGEN GOL STATION

TJVW01

TRICETA DE PALIER 30DX39X13

Especialistas en:

BOCAMAZAS



KOYAMA
SUSPENSION PARTS



<https://ikoyama.com/img/BCG002.png>

[https://ikoyama.com/img/BCG002\(2\).png](https://ikoyama.com/img/BCG002(2).png)

CHANGAN GRAND SUPERVAN 19/UP

BOCAMAZA DEL 5P DACF281345

BCG002



<https://ikoyama.com/img/BCG001.png>

[https://ikoyama.com/img/BCG001\(2\).png](https://ikoyama.com/img/BCG001(2).png)

CHANGAN HONOR 20/UP

BOCAMAZA DEL 4P C/ABS 3501130-T01

BCG001



<https://ikoyama.com/img/BCH001.png>

[https://ikoyama.com/img/BCH001\(2\).png](https://ikoyama.com/img/BCH001(2).png)

CHEVROLET CHEVY DAEWOO RACER 92/98

BOCAMAZA DEL BRIDA 34mm 96176252

BCH001



<https://ikoyama.com/img/BCH002.png>

[https://ikoyama.com/img/BCH002\(2\).png](https://ikoyama.com/img/BCH002(2).png)

CHEVROLET N300 MINI VAN 07/14

BOCAMAZA DEL BASE INT 30mm 4P 24510383

BCH002



<https://ikoyama.com/img/BCH005.png>

[https://ikoyama.com/img/BCH005\(2\).png](https://ikoyama.com/img/BCH005(2).png)

CHEVROLET N400 21/UP

BOCAMAZA DEL 5P C/ABS 23858012

BCH005



<https://ikoyama.com/img/BCH009.png>

[https://ikoyama.com/img/BCH009\(2\).png](https://ikoyama.com/img/BCH009(2).png)

CHEVROLET SAIL 11/16 AVEO 07/12

BOCAMAZA POST S/ABS 96471776

BCH009



<https://ikoyama.com/img/BCH008.png>

[https://ikoyama.com/img/BCH008\(2\).png](https://ikoyama.com/img/BCH008(2).png)

CHEVROLET SAIL 16/20

BOCAMAZA POST C/ABS 09064172

BCH008



<https://ikoyama.com/img/BCH003.png>

[https://ikoyama.com/img/BCH003\(2\).png](https://ikoyama.com/img/BCH003(2).png)

CHEVROLET SAIL AVEO OPTRA 03/08

BOCAMAZA DEL BRIDA 34mm 4P 96535041

BCH003



<https://ikoyama.com/img/BCH004.png>

[https://ikoyama.com/img/BCH004\(2\).png](https://ikoyama.com/img/BCH004(2).png)

CHEVROLET SPARK M200 MATIZ 04/10

BCH004

BOCAMAZA DEL BRIDA 35mm 96316757



<https://ikoyama.com/img/BCH006.png>

[https://ikoyama.com/img/BCH006\(2\).png](https://ikoyama.com/img/BCH006(2).png)

CHEVROLET SPIN 13/UP

BCH006

BOCAMAZA DEL 13513413



<https://ikoyama.com/img/BCH007.png>

[https://ikoyama.com/img/BCH007\(2\).png](https://ikoyama.com/img/BCH007(2).png)

CHEVROLET SPIN 13/UP

BCH007

BOCAMAZA POST 13593156



<https://ikoyama.com/img/BDW001.png>

[https://ikoyama.com/img/BDW001\(2\).png](https://ikoyama.com/img/BDW001(2).png)

DAEWOO TICO 92/98

BDW001

BOCAMAZA DEL BRIDA 4H 3421A70B0100



<https://ikoyama.com/img/BDF001.png>

[https://ikoyama.com/img/BDF001\(2\).png](https://ikoyama.com/img/BDF001(2).png)

DFSK C31 ,C35, C37 20/UP

BDF001

BOCAMAZA DEL BRIDA 5P 3501610-CA01



<https://ikoyama.com/img/BDF002.png>

[https://ikoyama.com/img/BDF002\(2\).png](https://ikoyama.com/img/BDF002(2).png)

DFSK GLORY 330 20/UP

BDF002

BOCAMAZA POST 5P 15007039



<https://ikoyama.com/img/BDF003.png>

[https://ikoyama.com/img/BDF003\(2\).png](https://ikoyama.com/img/BDF003(2).png)

DFSK GLORY 580 20/UP

BDF003

BOCAMAZA DEL 5P 3H 10115525



<https://ikoyama.com/img/BDF004.png>

[https://ikoyama.com/img/BDF004\(2\).png](https://ikoyama.com/img/BDF004(2).png)

DFSK GLORY 580 20/UP

BDF004

BOCAMAZA POST 5P 4H 1712010-SA01



<https://ikoyama.com/img/BHY022.png>

[https://ikoyama.com/img/BHY022\(2\).png](https://ikoyama.com/img/BHY022(2).png)

HYUNDAI ACCENT 00/04

BOCAMAZA POST 4P C/RODAJE 52710-25000

BHY022



<https://ikoyama.com/img/BHY009.png>

[https://ikoyama.com/img/BHY009\(2\).png](https://ikoyama.com/img/BHY009(2).png)

HYUNDAI ELANTRA 17/UP

BOCAMAZA DEL 51750-F2000

BHY009



<https://ikoyama.com/img/BHY006.png>

[https://ikoyama.com/img/BHY006\(2\).png](https://ikoyama.com/img/BHY006(2).png)

HYUNDAI H-1 GRAND STAREX 07/17

BOCAMAZA DEL BASE 45mm 6P C/ABS 51750-4H000

BHY006



<https://ikoyama.com/img/BHY013.png>

[https://ikoyama.com/img/BHY013\(2\).png](https://ikoyama.com/img/BHY013(2).png)

HYUNDAI H-1 GRAND STAREX 07/18

BOCAMAZA DEL BRIDA 45mm 6P S/ABS 51750-4H000

BHY013



<https://ikoyama.com/img/BHY012.png>

[https://ikoyama.com/img/BHY012\(2\).png](https://ikoyama.com/img/BHY012(2).png)

HYUNDAI i10 13/17

BOCAMAZA POST 52750-B9000

BHY012



<https://ikoyama.com/img/BHY010.png>

[https://ikoyama.com/img/BHY010\(2\).png](https://ikoyama.com/img/BHY010(2).png)

HYUNDAI SONATA VII TUCSON i30 i40/KIA

BOCAMAZA DEL 51750-C1000

BHY010



<https://ikoyama.com/img/BHY001.png>

[https://ikoyama.com/img/BHY001\(2\).png](https://ikoyama.com/img/BHY001(2).png)

HYUNDAI/KIA ACCENT/RIO 05/10

BOCAMAZA DEL BRIDA 38mm 4P 51750-25001

BHY001



<https://ikoyama.com/img/BHY002.png>

[https://ikoyama.com/img/BHY002\(2\).png](https://ikoyama.com/img/BHY002(2).png)

HYUNDAI/KIA ACCENT/RIO 05/10

BOCAMAZA POST BASE 4P S/ABS 52750-1G000

BHY002



<https://ikoyama.com/img/BHY011.png>

[https://ikoyama.com/img/BHY011\(2\).png](https://ikoyama.com/img/BHY011(2).png)

HYUNDAI/KIA ACCENT/RIO 05/10

BHY011

BOCAMAZA POST BASE 4P C/ABS 52750-1G000



<https://ikoyama.com/img/BHY003.png>

[https://ikoyama.com/img/BHY003\(2\).png](https://ikoyama.com/img/BHY003(2).png)

HYUNDAI/KIA ACCENT/RIO 11/14

BHY003

BOCAMAZA DEL BRIDA 37mm 4P 51750-1J000



<https://ikoyama.com/img/BHY004.png>

[https://ikoyama.com/img/BHY004\(2\).png](https://ikoyama.com/img/BHY004(2).png)

HYUNDAI/KIA ACCENT/RIO 11/14

BHY004

BOCAMAZA POST BASE 4H 4P 52750-0U000



<https://ikoyama.com/img/BHY005.png>

[https://ikoyama.com/img/BHY005\(2\).png](https://ikoyama.com/img/BHY005(2).png)

HYUNDAI/KIA ACCENT/RIO 11/14

BHY005

BOCAMAZA POST BASE 4H 4P 52750-1R000



<https://ikoyama.com/img/BHY015.png>

[https://ikoyama.com/img/BHY015\(2\).png](https://ikoyama.com/img/BHY015(2).png)

HYUNDAI/KIA ELANTRA 10/21

BHY015

BOCAMAZA POST 52710-3X000



<https://ikoyama.com/img/BHY014.png>

[https://ikoyama.com/img/BHY014\(2\).png](https://ikoyama.com/img/BHY014(2).png)

HYUNDAI/KIA ELANTRA 16/21

BHY014

BOCAMAZA DEL 51750-F0000



<https://ikoyama.com/img/BHY021.png>

[https://ikoyama.com/img/BHY021\(2\).png](https://ikoyama.com/img/BHY021(2).png)

HYUNDAI/KIA SANTAFE 07/12 SORENTO 09/14

BHY021

BOCAMAZA POST5P 4H C/ABS 2WD 52750-2B100



<https://ikoyama.com/img/BHY016.png>

[https://ikoyama.com/img/BHY016\(2\).png](https://ikoyama.com/img/BHY016(2).png)

HYUNDAI/KIA SANTAFE 12/18 SORENTO 14/20

BHY016

BOCAMAZA DEL 5P 4H 51750-2B000



<https://ikoyama.com/img/BHY020.png> [https://ikoyama.com/img/BHY020\(2\).png](https://ikoyama.com/img/BHY020(2).png)

HYUNDAI/KIA SANTAFE 12/18 SORENTO 14/20

BOCAMAZA POST 5P 4H C/ABS 2WD 51750-C5000

BHY020



<https://ikoyama.com/img/BHY007.png> [https://ikoyama.com/img/BHY007\(2\).png](https://ikoyama.com/img/BHY007(2).png)

HYUNDAI/KIA SONATA/OPTIMA 01/05

BOCAMAZA DEL BRIDA 45mm 4P 51750-3D000

BHY007



<https://ikoyama.com/img/BHY008.png> [https://ikoyama.com/img/BHY008\(2\).png](https://ikoyama.com/img/BHY008(2).png)

HYUNDAI/KIA SONATA/OPTIMA 01/05

BOCAMAZA POST BASE 4H 4P S/ABS 52730-38000

BHY008



<https://ikoyama.com/img/BHY018.png> [https://ikoyama.com/img/BHY018\(2\).png](https://ikoyama.com/img/BHY018(2).png)

HYUNDAI/KIA TUCSON 04/09 SPORTAGE 05/10

BOCAMAZA POST 5P C/ABS C/RODAJE 2WD 52710-2E100

BHY018



<https://ikoyama.com/img/BHY017.png> [https://ikoyama.com/img/BHY017\(2\).png](https://ikoyama.com/img/BHY017(2).png)

HYUNDAI/KIA TUCSON 09/15 SPORTAGE 11/16

BOCAMAZA POST 5P C/ABS C/RODAJE 2WD 52730-1D400

BHY017



<https://ikoyama.com/img/BHY019.png> [https://ikoyama.com/img/BHY019\(2\).png](https://ikoyama.com/img/BHY019(2).png)

HYUNDAI/KIA TUCSON 15/21 SPORTAGE 17/22

BOCAMAZA POST 5P 4H C/ABS 2WD 52730-C1100

BHY019

<https://ikoyama.com/img/BKI001.png>

KIA PICANTO

BOCAMAZA DEL 51750-0X000

BKI001



<https://ikoyama.com/img/BKI002.png>

KIA PICANTO 07/14

BOCAMAZA POST 52750-1C100

BKI002



<https://ikoyama.com/img/BKI004.png>

[https://ikoyama.com/img/BKI004\(2\).png](https://ikoyama.com/img/BKI004(2).png)

KIA PICANTO 17/21

BKI004

BOCAMAZA POST 52750-G6000



<https://ikoyama.com/img/BMZ003.png>

[https://ikoyama.com/img/BMZ003\(2\).png](https://ikoyama.com/img/BMZ003(2).png)

MAZDA 2 07/14

BMZ003

BOCAMAZA DEL HJ1025K/518510



<https://ikoyama.com/img/BMZ004.png>

[https://ikoyama.com/img/BMZ004\(2\).png](https://ikoyama.com/img/BMZ004(2).png)

MAZDA 2 07/14

BMZ004

BOCAMAZA POST 512468



<https://ikoyama.com/img/BMZ006.png>

[https://ikoyama.com/img/BMZ006\(2\).png](https://ikoyama.com/img/BMZ006(2).png)

MAZDA 2 15/UP

BMZ006

BOCAMAZA POST D09H-26-15X



<https://ikoyama.com/img/BMZ001.png>

[https://ikoyama.com/img/BMZ001\(2\).png](https://ikoyama.com/img/BMZ001(2).png)

MAZDA 3, 5 13/UP

BMZ001

BOCAMAZA DEL B45A3304X



<https://ikoyama.com/img/BMZ002.png>

[https://ikoyama.com/img/BMZ002\(2\).png](https://ikoyama.com/img/BMZ002(2).png)

MAZDA 3, 5 13/UP

BMZ002

BOCAMAZA POST B45A2615X



<https://ikoyama.com/img/BMI001.png>

[https://ikoyama.com/img/BMI001\(2\).png](https://ikoyama.com/img/BMI001(2).png)

MITSUBISHI L200 DKR KATANA 04/15

BMI001

BOCAMAZA DEL BASE 4H 6P MR992374



<https://ikoyama.com/img/BMI003.png>

[https://ikoyama.com/img/BMI003\(2\).png](https://ikoyama.com/img/BMI003(2).png)

MITSUBISHI LANCER/LIBERO 92/99

BMI003

BOCAMAZA POST 4P C/RODAJE S/ABS DACF1050B



<https://ikoyama.com/img/BMI004.png>

[https://ikoyama.com/img/BMI004\(2\).png](https://ikoyama.com/img/BMI004(2).png)

mitsubishi MIRAGE 12/21

BMI004

BOCAMAZA DEL 3880A056



<https://ikoyama.com/img/BMI002.png>

[https://ikoyama.com/img/BMI002\(2\).png](https://ikoyama.com/img/BMI002(2).png)

mitsubishi OUTLANDER III ASX PEUGEOT 4008

BMI002

BOCAMAZA DEL 3880A018



<https://ikoyama.com/img/BMI006.png>

[https://ikoyama.com/img/BMI006\(2\).png](https://ikoyama.com/img/BMI006(2).png)

mitsubishi XPANDER 17/UP

BMI006

BOCAMAZA POST 5P C/RODAJE 3785A070



<https://ikoyama.com/img/BNI011.png>

[https://ikoyama.com/img/BNI011\(2\).png](https://ikoyama.com/img/BNI011(2).png)

NISSAN AD

BNI011

BOCAMAZA DEL BRIDA 38mm 4P 40202-50Y00



<https://ikoyama.com/img/BNI001.png>

[https://ikoyama.com/img/BNI001\(2\).png](https://ikoyama.com/img/BNI001(2).png)

NISSAN NAVARA 4WD 08/14

BNI001

BOCAMAZA DEL BASE 4H 6P C/ABS 40202-JR71B



<https://ikoyama.com/img/BNI008.png>

[https://ikoyama.com/img/BNI008\(2\).png](https://ikoyama.com/img/BNI008(2).png)

NISSAN NP300 NAVARA 15/UP D23 14/UP

BNI008

BOCAMAZA DEL 40202-4KH1A



<https://ikoyama.com/img/BNI003.png>

[https://ikoyama.com/img/BNI003\(2\).png](https://ikoyama.com/img/BNI003(2).png)

NISSAN SENTRA B13 90/08

BNI003

BOCAMAZA POST BASE 27mm 4P VKBA-3202-A



<https://ikoyama.com/img/BNI002.png>

[https://ikoyama.com/img/BNI002\(2\).png](https://ikoyama.com/img/BNI002(2).png)

NISSAN SENTRA B13 SUNNY 92/10

BNI002

BOCAMAZA DEL BRIDA 38mm 4P 40202-F4200





<https://ikoyama.com/img/BNI017.png>

[https://ikoyama.com/img/BNI017\(2\).png](https://ikoyama.com/img/BNI017(2).png)

NISSAN URVAN E26 13/20

BOCAMAZA DEL BASE 40210-3XA0A

BNI017



<https://ikoyama.com/img/BNI009.png>

[https://ikoyama.com/img/BNI009\(2\).png](https://ikoyama.com/img/BNI009(2).png)

NISSAN VERSA 15/UP

BOCAMAZA DEL 40202-AX000

BNI009



<https://ikoyama.com/img/BNI010.png>

[https://ikoyama.com/img/BNI010\(2\).png](https://ikoyama.com/img/BNI010(2).png)

NISSAN X-TRAIL

BOCAMAZA DEL BRIDA 40202-2Y010

BNI010



<https://ikoyama.com/img/BNI013.png>

[https://ikoyama.com/img/BNI013\(2\).png](https://ikoyama.com/img/BNI013(2).png)

NISSAN XTRAIL T31 07/18 QASHQAI 06/13 SENTRA 06/20

BOCAMAZA DEL 40202-JE20A C/ABS 29T

BNI013



<https://ikoyama.com/img/BRN001.png>

[https://ikoyama.com/img/BRN001\(2\).png](https://ikoyama.com/img/BRN001(2).png)

RENAULT DUSTER

BOCAMAZA DEL BRIDA 402020016R

BRN001



<https://ikoyama.com/img/BSU001.png>

[https://ikoyama.com/img/BSU001\(2\).png](https://ikoyama.com/img/BSU001(2).png)

SUBARU FORESTER IMPREZA Hatchback/XV

BOCAMAZA DEL HJ3197/28373FG000

BSU001



<https://ikoyama.com/img/BSU002.png>

[https://ikoyama.com/img/BSU002\(2\).png](https://ikoyama.com/img/BSU002(2).png)

SUBARU IMPREZA 00/UP

BOCAMAZA DEL HJ3414/ 28373FG010

BSU002



<https://ikoyama.com/img/BSK004.png>

[https://ikoyama.com/img/BSK004\(2\).png](https://ikoyama.com/img/BSK004(2).png)

SUZUKI ALTO

BOCAMAZA DEL BRIDA 43421-70B01

BSK004



<https://ikoyama.com/img/BSK006.png>

[https://ikoyama.com/img/BSK006\(2\).png](https://ikoyama.com/img/BSK006(2).png)

SUZUKI APV 08/UP

BSK006

BOCAMAZA DEL BRIDA S/ABS 43421-61J01



<https://ikoyama.com/img/BSK001.png>

[https://ikoyama.com/img/BSK001\(2\).png](https://ikoyama.com/img/BSK001(2).png)

SUZUKI CARRY 1.3

BSK001

BOCAMAZA DEL BASE INT 27mm 4P 43202-77A01



<https://ikoyama.com/img/BSK003.png>

[https://ikoyama.com/img/BSK003\(2\).png](https://ikoyama.com/img/BSK003(2).png)

SUZUKI GRAN NOMADE 08/20

BSK003

BOCAMAZA DEL POST HUB271-T5

<https://ikoyama.com/img/BSK002.png>

[https://ikoyama.com/img/BSK002\(2\).png](https://ikoyama.com/img/BSK002(2).png)

SUZUKI SWIFT 11/17

BSK002

BOCAMAZA DEL BRIDA 43420-50853



<https://ikoyama.com/img/BTO001.png>

[https://ikoyama.com/img/BTO001\(2\).png](https://ikoyama.com/img/BTO001(2).png)

TOYOTA COROLLA AE100 93/01

BTO001

BOCAMAZA DEL BRIDA 38mm 4P 43502-12090



<https://ikoyama.com/img/BTO002.png>

[https://ikoyama.com/img/BTO002\(2\).png](https://ikoyama.com/img/BTO002(2).png)

TOYOTA COROLLA BR 01/08

BTO002

BOCAMAZA POST BASE 4H 4P C/ABS 42410-02100



<https://ikoyama.com/img/BTO003.png>

[https://ikoyama.com/img/BTO003\(2\).png](https://ikoyama.com/img/BTO003(2).png)

TOYOTA HIACE 5L 05/12

BTO003

BOCAMAZA DEL BASE 4H RODAJE 43560-26010



<https://ikoyama.com/img/BTO016.png>

[https://ikoyama.com/img/BTO016\(2\).png](https://ikoyama.com/img/BTO016(2).png)

TOYOTA HILUX 1GD 2GD 15/UP

BTO016

BOCAMAZA DEL BASE 6P 43502-KK010



<https://ikoyama.com/img/BTO014.png>

[https://ikoyama.com/img/BTO014\(2\).png](https://ikoyama.com/img/BTO014(2).png)

TOYOTA YARIS 14/UP

BTO014

BOCAMAZA DEL 3H 4P S/ABS 43550-0D070



<https://ikoyama.com/img/BTO012.png>

[https://ikoyama.com/img/BTO012\(2\).png](https://ikoyama.com/img/BTO012(2).png)

TOYOTA YARIS 14/UP

BTO012

BOCAMAZA DEL LH 3H C/ABS 43560-0D050



<https://ikoyama.com/img/BTO013.png>

[https://ikoyama.com/img/BTO013\(2\).png](https://ikoyama.com/img/BTO013(2).png)

TOYOTA YARIS 14/UP

BTO013

BOCAMAZA DEL RH 3H C/ABS 43550-0D050



<https://ikoyama.com/img/BTO015.png>

[https://ikoyama.com/img/BTO015\(2\).png](https://ikoyama.com/img/BTO015(2).png)

TOYOTA YARIS 14/UP

BTO015

BOCAMAZA POST BASE 4H 4P C/ABS 42450-0D120



<https://ikoyama.com/img/BTO008.png>

[https://ikoyama.com/img/BTO008\(2\).png](https://ikoyama.com/img/BTO008(2).png)

TOYOTA YARIS 99/05 NCP 10/12

BTO008

BOCAMAZA POST BASE 4H 4P C/ABS 42450-52020



<https://ikoyama.com/img/BTO010.png>

[https://ikoyama.com/img/BTO010\(2\).png](https://ikoyama.com/img/BTO010(2).png)

TOYOTA YARIS NCP93 06/13

BTO010

BOCAMAZA POST BASE 4H 4P C/ABS 3DACF026-20



<https://ikoyama.com/img/BTO011.png>

[https://ikoyama.com/img/BTO011\(2\).png](https://ikoyama.com/img/BTO011(2).png)

TOYOTA YARIS NCP93 06/13

BTO011

BOCAMAZA POST BASE 4H 4P S/ABS 3DACF026-8A



<https://ikoyama.com/img/BTO007.png>

[https://ikoyama.com/img/BTO007\(2\).png](https://ikoyama.com/img/BTO007(2).png)

TOYOTA YARIS PROBOX 99/05

BTO007

BOCAMAZA DEL BRIDA 38mm 4P 43502-52010



<https://ikoyama.com/img/BTO009.png>

[https://ikoyama.com/img/BTO009\(2\).png](https://ikoyama.com/img/BTO009(2).png)

TOYOTA YARIS VITZ 06/13

BOCAMAZA DEL BRIDA 40mm 4P S/ROD 43502-52030

BTO009



<https://ikoyama.com/img/BTO004.png>

[https://ikoyama.com/img/BTO004\(2\).png](https://ikoyama.com/img/BTO004(2).png)

TOYOTA 1KD 2KD 1GD 2GD HILUX 04/ON

BOCAMAZA DEL BASE 4H RODAJE 43570-60010

BTO004



<https://ikoyama.com/img/BTO005.png>

[https://ikoyama.com/img/BTO005\(2\).png](https://ikoyama.com/img/BTO005(2).png)

TOYOTA 1KD 2KD HILUX 04/14

BOCAMAZA DEL BASE 6P 43502-0K030

BTO005

<https://ikoyama.com/img/BTO017.png>

[https://ikoyama.com/img/BTO017\(2\).png](https://ikoyama.com/img/BTO017(2).png)

TOYOTA 1KD 2KD 1GD 2GD HILUX 04/ON

BOCAMAZA DEL BASE 4H RODAJE 43570-60010 MOD

BTO017



<https://ikoyama.com/img/BTO027.png>

[https://ikoyama.com/img/BTO027\(2\).png](https://ikoyama.com/img/BTO027(2).png)

TOYOTA AVANZA

BOCAMAZA DEL BRIDA 43511-BZ090

BTO027

<https://ikoyama.com/img/BOT003.png>

[https://ikoyama.com/img/BOT003\(2\).png](https://ikoyama.com/img/BOT003(2).png)

TOYOTA 5L HIACE 02/12 43560-26010

BOCAMAZA DEL BASE 4H 4P

BTO003



<https://ikoyama.com/img/BTO032.png>

[https://ikoyama.com/img/BTO032\(2\).png](https://ikoyama.com/img/BTO032(2).png)

TOYOTA COROLLA 08/13

BOCAMAZA DE BRIDA 5P 43502-32080

BTO032



<https://ikoyama.com/img/BTO031.png>

[https://ikoyama.com/img/BTO031\(2\).png](https://ikoyama.com/img/BTO031(2).png)

TOYOTA COROLLA 08/13

BOCAMAZA POST 5P 4H S/ABS 42410-02170

BTO031

<https://ikoyama.com/img/BTO019.png>

[https://ikoyama.com/img/BTO019\(2\).png](https://ikoyama.com/img/BTO019(2).png)

TOYOTA COROLLA 09/18

BTO019

BOCAMAZA DEL HJ1080K/ BR930589k

<https://ikoyama.com/img/BTO029.png>

[https://ikoyama.com/img/BTO029\(2\).png](https://ikoyama.com/img/BTO029(2).png)

TOYOTA COROLLA 14/18

BTO029

BOCAMAZA DEL BRIDA 5P 43502-02080

<https://ikoyama.com/img/BTO030.png>

[https://ikoyama.com/img/BTO030\(2\).png](https://ikoyama.com/img/BTO030(2).png)

TOYOTA COROLLA 14/18

BTO030

BOCAMAZA POST 5P 4H 42450-02170

<https://ikoyama.com/img/BTO026.png>

[https://ikoyama.com/img/BTO026\(2\).png](https://ikoyama.com/img/BTO026(2).png)

TOYOTA COROLLA AE90 87/93

BTO026

BOCAMAZA DEL BRIDA 43502-12110

<https://ikoyama.com/img/BOT002.png>

[https://ikoyama.com/img/BOT002\(2\).png](https://ikoyama.com/img/BOT002(2).png)

TOYOTA COROLLA BR 01/08 42410-02100

BOT002

BOCAMAZA POST BASE 4H 4P

<https://ikoyama.com/img/BTO020.png>

[https://ikoyama.com/img/BTO020\(2\).png](https://ikoyama.com/img/BTO020(2).png)

TOYOTA ETIOS 10/UP

BTO020

BOCAMAZA DEL LH 43550-0D010

<https://ikoyama.com/img/BTO021.png>

[https://ikoyama.com/img/BTO021\(2\).png](https://ikoyama.com/img/BTO021(2).png)

TOYOTA ETIOS 10/UP

BTO021

BOCAMAZA DEL RH 43550-0D030

<https://ikoyama.com/img/BTO024.png>

[https://ikoyama.com/img/BTO024\(2\).png](https://ikoyama.com/img/BTO024(2).png)

TOYOTA ETIOS 10/UP

BTO024

BOCAMAZA POST C/ABS 42450-0D100



<https://ikoyama.com/img/BTO022.png> [https://ikoyama.com/img/BTO022\(2\).png](https://ikoyama.com/img/BTO022(2).png)
 TOYOTA RAV4 06/18
 BOCAMAZA DEL 43550-42020 **BTO022**



<https://ikoyama.com/img/BTO023.png> [https://ikoyama.com/img/BTO023\(2\).png](https://ikoyama.com/img/BTO023(2).png)
 TOYOTA RAV4 06/18
 BOCAMAZA POST 42450-42040 **BTO023**



<https://ikoyama.com/img/BTO025.png> [https://ikoyama.com/img/BTO025\(2\).png](https://ikoyama.com/img/BTO025(2).png)
 TOYOTA RAV4 06/18
 BOCAMAZA DEL 43550-42010 D/26 **BTO025**



<https://ikoyama.com/img/BTO028.png> [https://ikoyama.com/img/BTO028\(2\).png](https://ikoyama.com/img/BTO028(2).png)
 TOYOTA RAV4 06/18
 BOCAMAZA POST 4WD 42410-42040 **BTO028**



<https://ikoyama.com/img/BTO006.png> [https://ikoyama.com/img/BTO006\(2\).png](https://ikoyama.com/img/BTO006(2).png)
 TOYOTA TERCEL 90/99
 BOCAMAZA DEL BRIDA 38mm 4P 43502-16040 **BTO006**



<https://ikoyama.com/img/BVW002.png> [https://ikoyama.com/img/BVW002\(2\).png](https://ikoyama.com/img/BVW002(2).png)
 VOLKSWAGEN GOL 09/22
 BOCAMASA DEL BRIDA 5X0 407 615A **BVW002**



<https://ikoyama.com/img/BVW001.png> [https://ikoyama.com/img/BVW001\(2\).png](https://ikoyama.com/img/BVW001(2).png)
 VOLKSWAGEN GOL 09/22
 BOCAMAZA POST C/RODAJE 5U0 501 611 **BVW001**

Especialistas en:

DIRECCION



KOYAMA
SUSPENSION PARTS



<https://ikoyama.com/img/ECH001.png>
CHEVROLET AVEO F14D6

[https://ikoyama.com/img/ECH001\(2\).png](https://ikoyama.com/img/ECH001(2).png)

ESTABILIZADORES DEL RH LH 96391875 CLKD-8

ECH001



<https://ikoyama.com/img/EHY005.png>

[https://ikoyama.com/img/EHY005\(2\).png](https://ikoyama.com/img/EHY005(2).png)

HYUNDAI ACCENT ELANTRA MD i30 KIA RIO 11/16

ESTABILIZADORES DEL RH LH 54830-0U000 CLKH-46

EHY005



<https://ikoyama.com/img/EHY004.png>

[https://ikoyama.com/img/EHY004\(2\).png](https://ikoyama.com/img/EHY004(2).png)

HYUNDAI ACCENT KIA RIO 05/10

ESTABILIZADORES DEL LH 54830-1G000 CLKK-28L

EHY004



<https://ikoyama.com/img/EHY003.png>

[https://ikoyama.com/img/EHY003\(2\).png](https://ikoyama.com/img/EHY003(2).png)

HYUNDAI ACCENT KIA RIO 05/10

ESTABILIZADORES DEL RH 54840-1G000 CLKK-28R

EHY003



<https://ikoyama.com/img/EHY002.png>

[https://ikoyama.com/img/EHY002\(2\).png](https://ikoyama.com/img/EHY002(2).png)

HYUNDAI ACCENT PRIME 00/05

ESTABILIZADORES DEL LH 54830-25010 CLKH-18L

EHY002



<https://ikoyama.com/img/EHY001.png>

[https://ikoyama.com/img/EHY001\(2\).png](https://ikoyama.com/img/EHY001(2).png)

HYUNDAI ACCENT PRIME 00/05

ESTABILIZADORES DEL RH 54830-25020 CLKH-18R

EHY001



<https://ikoyama.com/img/EHY009.png>

[https://ikoyama.com/img/EHY009\(2\).png](https://ikoyama.com/img/EHY009(2).png)

HYUNDAI H-1 08/15

ESTABILIZADORES DEL LH 54830-4H000 CLKH-38L

EHY009



<https://ikoyama.com/img/EHY008.png>

[https://ikoyama.com/img/EHY008\(2\).png](https://ikoyama.com/img/EHY008(2).png)

HYUNDAI H-1 08/15

ESTABILIZADORES DEL RH 54840-4H000 CLKH-38R

EHY008



<https://ikoyama.com/img/EHY007.png>
HYUNDAI i10 08/10

[https://ikoyama.com/img/EHY007\(2\).png](https://ikoyama.com/img/EHY007(2).png)

ESTABILIZADORES DEL LH 54830-0X000 CLKH-42L

EHY007



<https://ikoyama.com/img/EHY006.png>
HYUNDAI i10 08/10

[https://ikoyama.com/img/EHY006\(2\).png](https://ikoyama.com/img/EHY006(2).png)

ESTABILIZADORES DEL RH 54840-0X000 CLKH-42R

EHY006



<https://ikoyama.com/img/EK004.png>
KIA CERATO 01/06

[https://ikoyama.com/img/EK004\(2\).png](https://ikoyama.com/img/EK004(2).png)

ESTABILIZADORES DEL LH 54830-2F000 CLKK-19L

EK004



<https://ikoyama.com/img/EK003.png>
KIA CERATO 01/06

[https://ikoyama.com/img/EK003\(2\).png](https://ikoyama.com/img/EK003(2).png)

ESTABILIZADORES DEL RH 54840-2F000 CLKK-19R

EK003



<https://ikoyama.com/img/EK002.png>
KIA PICANTO 12/15

[https://ikoyama.com/img/EK002\(2\).png](https://ikoyama.com/img/EK002(2).png)

ESTABILIZADORES DEL LH 54830-1J000 CLKH-43L

EK002



<https://ikoyama.com/img/EK001.png>
KIA PICANTO 12/15

[https://ikoyama.com/img/EK001\(2\).png](https://ikoyama.com/img/EK001(2).png)

ESTABILIZADORES DEL RH 54840-1J000 CLKH-43R

EK001




<https://ikoyama.com/img/EK007.png>
KIA PICANTO 17/UP

[https://ikoyama.com/img/EK007\(2\).png](https://ikoyama.com/img/EK007(2).png)

ESTABILIZADORES DEL RH LH 54830-G6000 CL0361

EK007



<https://ikoyama.com/img/EMA001.png>
MAZDA 2

[https://ikoyama.com/img/EMA001\(2\).png](https://ikoyama.com/img/EMA001(2).png)

ESTABILIZADORES DEL RH LH LC62-34-170B SL-1680

EMA001



<https://ikoyama.com/img/EMA002.png> [https://ikoyama.com/img/EMA002\(2\).png](https://ikoyama.com/img/EMA002(2).png)

MAZDA 3

ESTABILIZADORES DEL RH LH BP4K-34-170D SL-1650

EMA002



<https://ikoyama.com/img/EMI001.png> [https://ikoyama.com/img/EMI001\(2\).png](https://ikoyama.com/img/EMI001(2).png)

MITSUBISHI L200 DAKAR TRITON KA4T 07/16

ESTABILIZADORES DEL LH MR992309 CLM-25

EMI001



<https://ikoyama.com/img/EMI002.png> [https://ikoyama.com/img/EMI002\(2\).png](https://ikoyama.com/img/EMI002(2).png)

MITSUBISHI L200 DAKAR TRITON KA4T 07/16

ESTABILIZADORES DEL RH MR992310 CLM-24

EMI002



<https://ikoyama.com/img/ENI003.png> [https://ikoyama.com/img/ENI003\(2\).png](https://ikoyama.com/img/ENI003(2).png)

NISSAN B13 POST 90/UP

ESTABILIZADORES POST RH LH 54618-58Y10 SL-4745

ENI003



<https://ikoyama.com/img/ENI001.png> [https://ikoyama.com/img/ENI001\(2\).png](https://ikoyama.com/img/ENI001(2).png)

NISSAN CD17 GA13 GA15 AD VAN SUNNY SENTRA

ESTABILIZADORES DEL RH LH 54618-50Y00 CLN-1

ENI001

<https://ikoyama.com/img/ENI004.png> [https://ikoyama.com/img/ENI004\(2\).png](https://ikoyama.com/img/ENI004(2).png)

NISSAN NAVARA

ESTABILIZADORES DEL LH 56261-75000 SL-N130L

ENI004



<https://ikoyama.com/img/ENI005.png> [https://ikoyama.com/img/ENI005\(2\).png](https://ikoyama.com/img/ENI005(2).png)

NISSAN NAVARA

ESTABILIZADORES DEL RH 56261-75010 SL-N130R

ENI005



<https://ikoyama.com/img/ENI002.png> [https://ikoyama.com/img/ENI002\(2\).png](https://ikoyama.com/img/ENI002(2).png)

NISSAN TIIDA 1.6L 4PTA MEXICO HR16DE

ESTABILIZADORES DEL RH LH54618-9U00A CLN-54

ENI002



<https://ikoyama.com/img/ENI006.png> [https://ikoyama.com/img/ENI006\(2\).png](https://ikoyama.com/img/ENI006(2).png)

NISSAN URVAN

ESTABILIZADORES DEL RH LH 54617-VW000 SL-4970

ENI006



<https://ikoyama.com/img/ENI007.png> [https://ikoyama.com/img/ENI007\(2\).png](https://ikoyama.com/img/ENI007(2).png)

NISSAN XTRAIL

ESTABILIZADORES DEL LH 54668-JA000 SL-N150L

ENI007



<https://ikoyama.com/img/ENI008.png> [https://ikoyama.com/img/ENI008\(2\).png](https://ikoyama.com/img/ENI008(2).png)

NISSAN XTRAIL

ESTABILIZADORES DEL RH 54618-JA000 SL-N150R

ENI008



<https://ikoyama.com/img/ESU001.png> [https://ikoyama.com/img/ESU001\(2\).png](https://ikoyama.com/img/ESU001(2).png)

SUZUKI APV 07/ON

ESTABILIZADORES DEL RH LH 42420-61J00

ESU001

<https://ikoyama.com/img/ESU002.png> [https://ikoyama.com/img/ESU002\(2\).png](https://ikoyama.com/img/ESU002(2).png)

SUZUKI VITARA NOMADE

ESTABILIZADORES DEL RH LH 42420-59J00 SL-7630

ESU002

<https://ikoyama.com/img/ETY014.png> [https://ikoyama.com/img/ETY014\(2\).png](https://ikoyama.com/img/ETY014(2).png)

TOYOTA AGYA 14/UP

ESTABILIZADOR RH LH 48820-BZ030 SL-T920

ETY014

<https://ikoyama.com/img/ETY015.png> [https://ikoyama.com/img/ETY015\(2\).png](https://ikoyama.com/img/ETY015(2).png)

TOYOTA AVANZA 03/21

ESTABILIZADOR RH LH 48820-B0010 SL-3870

ETY015

<https://ikoyama.com/img/ETY016.png> [https://ikoyama.com/img/ETY016\(2\).png](https://ikoyama.com/img/ETY016(2).png)

TOYOTA AVANZA 22/UP RAIZE 19/UP HONDA PILOT 03/15

ESTABILIZADOR RH LH 48820-BZ130 SL-6400

ETY016



<https://ikoyama.com/img/ETY006.png> [https://ikoyama.com/img/ETY006\(2\).png](https://ikoyama.com/img/ETY006(2).png)

TOYOTA CALDINA 02/07 AVENSIS 03/08

ESTABILIZADORES POS LH 48840-21010 CLT-65

ETY006



<https://ikoyama.com/img/ETY007.png> [https://ikoyama.com/img/ETY007\(2\).png](https://ikoyama.com/img/ETY007(2).png)

TOYOTA CALDINA 02/07 AVENSIS 03/08

ESTABILIZADORES POS RH 48830-21020 CLT-64

ETY007



<https://ikoyama.com/img/ETY004.png> [https://ikoyama.com/img/ETY004\(2\).png](https://ikoyama.com/img/ETY004(2).png)

TOYOTA COROLLA COROLLON ZRE142 AZE141 07/13 ATS

ESTABILIZADORES DEL RH LH 48820-02030 CLT20

ETY004



<https://ikoyama.com/img/ETY009.png> [https://ikoyama.com/img/ETY009\(2\).png](https://ikoyama.com/img/ETY009(2).png)

TOYOTA COROLLA POST 92/01

ESTABILIZADORES POST RH LH 48830-20010 SL-2805

ETY009

<https://ikoyama.com/img/ETY010.png>

[https://ikoyama.com/img/ETY010\(2\).png](https://ikoyama.com/img/ETY010(2).png)

TOYOTA CORONA 92/UP

ESTABILIZADORES DEL RH LH 48810-20020 SL-2990L

ETY010

<https://ikoyama.com/img/ETY011.png>

[https://ikoyama.com/img/ETY011\(2\).png](https://ikoyama.com/img/ETY011(2).png)

TOYOTA CORONA 92/UP

ESTABILIZADORES DEL RH LH 48820-20020 SL-2990R

ETY011



<https://ikoyama.com/img/ETY020.png> [https://ikoyama.com/img/ETY020\(2\).png](https://ikoyama.com/img/ETY020(2).png)

TOYOTA HIACE 1GD 19/UP

ESTABILIZADOR DEL LH 48810-26050 SL-A370L

ETY020



<https://ikoyama.com/img/ETY021.png> [https://ikoyama.com/img/ETY021\(2\).png](https://ikoyama.com/img/ETY021(2).png)

TOYOTA HIACE 1GD 19/UP

ESTABILIZADOR DEL RH 48820-26060 SL-A370R

ETY021



<https://ikoyama.com/img/ETY005.png> [https://ikoyama.com/img/ETY005\(2\).png](https://ikoyama.com/img/ETY005(2).png)

TOYOTA HIACE 5L 05/12

ESTABILIZADORES DEL RH LH 48820-26050 CLT-51

ETY005



<https://ikoyama.com/img/ETY002.png> [https://ikoyama.com/img/ETY002\(2\).png](https://ikoyama.com/img/ETY002(2).png)

TOYOTA HILUX 1KD 2KD 1GD 2GD 4WD 05/ON

ESTABILIZADORES DEL LH 48810-0K010 CLT-46

ETY002



<https://ikoyama.com/img/ETY001.png> [https://ikoyama.com/img/ETY001\(2\).png](https://ikoyama.com/img/ETY001(2).png)

TOYOTA HILUX 1KD 2KD 1GD 2GD 4WD 05/ON

ESTABILIZADORES DEL RH 48820-0K030 CLT-45

ETY001



<https://ikoyama.com/img/ETY008.png> [https://ikoyama.com/img/ETY008\(2\).png](https://ikoyama.com/img/ETY008(2).png)

TOYOTA HILUX KUN 25 2WD 05/12

ESTABILIZADORES DEL RH LH 48820-0K010 CLT-53

ETY008



<https://ikoyama.com/img/ETY003.png> [https://ikoyama.com/img/ETY003\(2\).png](https://ikoyama.com/img/ETY003(2).png)

TOYOTA PROBOX YARIS 06/13 ATS

ESTABILIZADORES DEL RH LH 48820-0D020 CLT-69

ETY003



<https://ikoyama.com/img/ETY012.png> [https://ikoyama.com/img/ETY012\(2\).png](https://ikoyama.com/img/ETY012(2).png)

TOYOTA RAV 4 00/05

ESTABILIZADORES DEL RH LH 48820-42020 SL-3920

ETY012



<https://ikoyama.com/img/ETY013.png> [https://ikoyama.com/img/ETY013\(2\).png](https://ikoyama.com/img/ETY013(2).png)

TOYOTA RAV 4 06/14

ESTABILIZADORES DEL RH LH 48820-42030 SL-T220

ETY013



<https://ikoyama.com/img/ACH001.png> [https://ikoyama.com/img/ACH001\(2\).png](https://ikoyama.com/img/ACH001(2).png)

CHEVROLET AVEO 02/12 DW KALOS 02/05

RACK END DEL RH LH 2602032 CRKD-10R

ACH001

<https://ikoyama.com/img/ACH002.png> [https://ikoyama.com/img/ACH002\(2\).png](https://ikoyama.com/img/ACH002(2).png)

CHEVROLET AVEO 02/12 DW KALOS 02/05

RACK END DEL RH LH 2602032 CRKD-10R

ACH002

<https://ikoyama.com/img/AH0001.png>

HONDA CIVIC 92/99

RACK END DEL RH LH 53010-AR3-010 SR-6190

AH0001

[https://ikoyama.com/img/AH0001\(2\).png](https://ikoyama.com/img/AH0001(2).png)



<https://ikoyama.com/img/AHY001.png>

HYUNDAI ACCENT 06/10

RACK END DEL RH LH 57724-1E000 CRKH-29

AHY001

[https://ikoyama.com/img/AHY001\(2\).png](https://ikoyama.com/img/AHY001(2).png)

<https://ikoyama.com/img/AHY004.png>

HYUNDAI ACCENT KIA RIO JB 05/10

RACK END DEL LH 57724-1G000 CRKK-28L

AHY004

[https://ikoyama.com/img/AHY004\(2\).png](https://ikoyama.com/img/AHY004(2).png)

<https://ikoyama.com/img/AHY003.png>

HYUNDAI ACCENT KIA RIO JB 05/10

RACK END DEL RH 57724-1G100 CRKK-28R

AHY003

[https://ikoyama.com/img/AHY003\(2\).png](https://ikoyama.com/img/AHY003(2).png)

<https://ikoyama.com/img/AHY002.png>

HYUNDAI ACCENT RB KIA RIO 11/ON

RACK END DEL RH LH 56540-0U500 CRKH-40

AHY002

[https://ikoyama.com/img/AHY002\(2\).png](https://ikoyama.com/img/AHY002(2).png)



<https://ikoyama.com/img/AHY005.png>

HYUNDAI ELANTRA 11/16 VELOSTER 12/15 I30 12/15

RACK END DEL RH/LH 56540-3X000 CRKH-44

AHY005

[https://ikoyama.com/img/AHY005\(2\).png](https://ikoyama.com/img/AHY005(2).png)

<https://ikoyama.com/img/AHY006.png>

HYUNDAI ELANTRA KIA CERATO i30 08/11

RACK END DEL RH LH 56540-2H000 CRKH-30

AHY006

[https://ikoyama.com/img/AHY006\(2\).png](https://ikoyama.com/img/AHY006(2).png)



<https://ikoyama.com/img/AHY007.png> [https://ikoyama.com/img/AHY007\(2\).png](https://ikoyama.com/img/AHY007(2).png)

HYUNDAI H-1 07/15 GRAN STAREX 07/ON

RACK END DEL LH 57724-4H000 CRKH-34L

AHY007



<https://ikoyama.com/img/AHY008.png> [https://ikoyama.com/img/AHY008\(2\).png](https://ikoyama.com/img/AHY008(2).png)

HYUNDAI H-1 07/15 GRAN STAREX 07/ON

RACK END DEL RH 57724-4H100 CRKH-34R

AHY008



<https://ikoyama.com/img/AHY009.png> [https://ikoyama.com/img/AHY009\(2\).png](https://ikoyama.com/img/AHY009(2).png)

HYUNDAI i10 10/14 1.1L

RACK END DEL RH LH 57724-0X000 CRKH-48

AHY009




<https://ikoyama.com/img/AHY010.png> [https://ikoyama.com/img/AHY010\(2\).png](https://ikoyama.com/img/AHY010(2).png)

HYUNDAI SONATA EF 99/11 KIA OPTIMA 01/05

RACK END DEL RH LH 57724-38000 CRKK-19

AHY010



<https://ikoyama.com/img/AHY011.png> [https://ikoyama.com/img/AHY011\(2\).png](https://ikoyama.com/img/AHY011(2).png)

HYUNDAI SONATA KIA OPTIMA EF 01/05

RACK END DEL RH/LH 57724-38010 CRKK-19

AHY011



<https://ikoyama.com/img/AHY012.png> [https://ikoyama.com/img/AHY012\(2\).png](https://ikoyama.com/img/AHY012(2).png)

HYUNDAI TUCSON SPORTAGE 11/ON

RACK END DEL 57724-2S000 CRKH-42

AHY012

<https://ikoyama.com/img/AK001.png>

[https://ikoyama.com/img/AK001\(2\).png](https://ikoyama.com/img/AK001(2).png)

KIA SORENTO 09/12

RACK END DEL RH LH 57724-2P000 CRKK-40R

AK001

<https://ikoyama.com/img/AMI002.png>

[https://ikoyama.com/img/AMI002\(2\).png](https://ikoyama.com/img/AMI002(2).png)

MITSUBISHI L200 05/UP

RACK END DEL RH LH 4410A173T SR-7950

AMI002



<https://ikoyama.com/img/AMI001.png>

[https://ikoyama.com/img/AMI001\(2\).png](https://ikoyama.com/img/AMI001(2).png)

mitsubishi L200 DAKAR 07/15

AMI001

RACK END DEL RH LH MR510267 CRM-20



<https://ikoyama.com/img/ANI004.png>

[https://ikoyama.com/img/ANI004\(2\).png](https://ikoyama.com/img/ANI004(2).png)

NISSAN FRONTIER 05/UP

ANI004

RACK END DEL RH LH 48521-EA000 TR-4970/1



<https://ikoyama.com/img/ANI005.png>

[https://ikoyama.com/img/ANI005\(2\).png](https://ikoyama.com/img/ANI005(2).png)

NISSAN NAVARA

ANI005

RACK END DEL RH LH D8521-EB70A SR-N250



<https://ikoyama.com/img/ANI006.png>

[https://ikoyama.com/img/ANI006\(2\).png](https://ikoyama.com/img/ANI006(2).png)

NISSAN SENTRA

ANI006

RACK END DEL RH LH 48521-Q5601 SR-4741



<https://ikoyama.com/img/ANI002.png>

[https://ikoyama.com/img/ANI002\(2\).png](https://ikoyama.com/img/ANI002(2).png)

NISSAN SENTRA B12 B13 B14

ANI002

RACK END DEL RH LH 48521-50Y00 CRN-8



<https://ikoyama.com/img/ANI003.png>

[https://ikoyama.com/img/ANI003\(2\).png](https://ikoyama.com/img/ANI003(2).png)

NISSAN SENTRA B15

ANI003

RACK END DEL RH LH 48521-4M485 CRN-22

<https://ikoyama.com/img/ANI001.png>

[https://ikoyama.com/img/ANI001\(2\).png](https://ikoyama.com/img/ANI001(2).png)

NISSAN TIIDA

ANI001

RACK END DEL 48521-3U025 CRN-41



<https://ikoyama.com/img/ANI007.png>

[https://ikoyama.com/img/ANI007\(2\).png](https://ikoyama.com/img/ANI007(2).png)

NISSAN VERSA 13/16

ANI007

RACK END DEL RH LH 48521-1HK0A

<https://ikoyama.com/img/ASZ001.png>

[https://ikoyama.com/img/ASZ001\(2\).png](https://ikoyama.com/img/ASZ001(2).png)

SUZUKI SWIFT 10/UP

ASZ001

RACK END DEL RH LH 48830-68L00 TR-5010

<https://ikoyama.com/img/ASZ002.png>

[https://ikoyama.com/img/ASZ002\(2\).png](https://ikoyama.com/img/ASZ002(2).png)

SUZUKI VITARA 08/UP

ASZ002

RACK END DEL RH LH 48830-65D00 TR-7590



<https://ikoyama.com/img/ATY001.png>

[https://ikoyama.com/img/ATY001\(2\).png](https://ikoyama.com/img/ATY001(2).png)

TOYOTA AVANZA F652 11/15

ATY001

RACK END DEL RH LH 45503-BZ120 CRT-120



<https://ikoyama.com/img/ATY007.png>

[https://ikoyama.com/img/ATY007\(2\).png](https://ikoyama.com/img/ATY007(2).png)

TOYOTA COROLLA 02/UP

ATY007

RACK END DEL RH LH 45503-12130 SR-3640



<https://ikoyama.com/img/ATY008.png>

[https://ikoyama.com/img/ATY008\(2\).png](https://ikoyama.com/img/ATY008(2).png)

TOYOTA COROLLA 92/99

ATY008

RACK END DEL RH LH 45503-29065 SR-2670



<https://ikoyama.com/img/ATY009.png>

[https://ikoyama.com/img/ATY009\(2\).png](https://ikoyama.com/img/ATY009(2).png)

TOYOTA HIACE 05/14

ATY009

RACK END DEL RH LH 45503-29836 SR-3970



<https://ikoyama.com/img/ATY015.png>

[https://ikoyama.com/img/ATY015\(2\).png](https://ikoyama.com/img/ATY015(2).png)

TOYOTA HIACE 1GD 19/UP

ATY015

RACK END DEL RH LH 45503-26180 SR-A370



<https://ikoyama.com/img/ATY002.png>

[https://ikoyama.com/img/ATY002\(2\).png](https://ikoyama.com/img/ATY002(2).png)

TOYOTA HIACE CONMUTER HILUX L 2L

ATY002

RACK END DEL RH LH 45503-29265 CRT-18



<https://ikoyama.com/img/ATY006.png>

[https://ikoyama.com/img/ATY006\(2\).png](https://ikoyama.com/img/ATY006(2).png)

TOYOTA HILUX 1GD 2GD 15/ON

RACK END DEL RH LH 45503-0K130

ATY006



<https://ikoyama.com/img/ATY005.png>

[https://ikoyama.com/img/ATY005\(2\).png](https://ikoyama.com/img/ATY005(2).png)

TOYOTA HILUX 1KD VIGO 04/14

RACK END DEL RH LH 45503-09321 CRT-89

ATY005

<https://ikoyama.com/img/ATY010.png>

[https://ikoyama.com/img/ATY010\(2\).png](https://ikoyama.com/img/ATY010(2).png)

TOYOTA RAV 4

RACK END DEL RH LH 45503-0R030

ATY010



<https://ikoyama.com/img/ATY011.png>

[https://ikoyama.com/img/ATY011\(2\).png](https://ikoyama.com/img/ATY011(2).png)

TOYOTA RAV 4

RACK END DEL RH LH 45503-42030 SR-T220

ATY011

<https://ikoyama.com/img/ATY012.png>

[https://ikoyama.com/img/ATY012\(2\).png](https://ikoyama.com/img/ATY012(2).png)

TOYOTA TERCEL

RACK END DEL RH LH 45503-19155 SR-2940

ATY012



<https://ikoyama.com/img/ATY013.png>

[https://ikoyama.com/img/ATY013\(2\).png](https://ikoyama.com/img/ATY013(2).png)

TOYOTA YARIS 05/UP

RACK END DEL RH LH 45503-52070 SR-TY020

ATY013

<https://ikoyama.com/img/ATY014.png>

[https://ikoyama.com/img/ATY014\(2\).png](https://ikoyama.com/img/ATY014(2).png)

TOYOTA YARIS 14/UP

RACK END DEL RH LH 45510-0D460 TR-T420

ATY014



<https://ikoyama.com/img/ATY004.png>

[https://ikoyama.com/img/ATY004\(2\).png](https://ikoyama.com/img/ATY004(2).png)

TOYOTA YARIS PROBOX NCP11,55,59 99/05

RACK END DEL RH LH 45503-59045 CRT-47

ATY004

<https://ikoyama.com/img/UR008.png>

[https://ikoyama.com/img/UR008\(2\).png](https://ikoyama.com/img/UR008(2).png)

HONDA CIVIC TERCEL VARIOS

RACK END UNIVERSAL 12X12 HILO FINO

UR008

<https://ikoyama.com/img/UR009.png>

[https://ikoyama.com/img/UR009\(2\).png](https://ikoyama.com/img/UR009(2).png)

TOYOTA HILUX 1KD 3L 5L

RACK END UNIVERSAL 14X15 HILO FINO

UR009

<https://ikoyama.com/img/UR006.png>

[https://ikoyama.com/img/UR006\(2\).png](https://ikoyama.com/img/UR006(2).png)

HYUNDAI ELANTRA 12/16

RACK END UNIVERSAL 16X16 HILO FINO

UR006

<https://ikoyama.com/img/UR005.png>

[https://ikoyama.com/img/UR005\(2\).png](https://ikoyama.com/img/UR005(2).png)

TOYOTA COROLLA

RACK END UNIVERSAL 45503-29065 SR-2670 14X14 HILO CORRIENTE

UR005

<https://ikoyama.com/img/UR004.png>

[https://ikoyama.com/img/UR004\(2\).png](https://ikoyama.com/img/UR004(2).png)

NISSAN TIIDA

RACK END UNIVERSAL 48521-35A00 SR-4510 14X12 HILO CORRIENTE

UR004

<https://ikoyama.com/img/UR002.png>

[https://ikoyama.com/img/UR002\(2\).png](https://ikoyama.com/img/UR002(2).png)

NISSAN SENTRA

RACK END UNIVERSAL 48521-5Y00 SR-4740 16X12 HILO FINO

UR002

<https://ikoyama.com/img/UR001.png>

[https://ikoyama.com/img/UR001\(2\).png](https://ikoyama.com/img/UR001(2).png)

HYUNDAI ACCENT

RACK END UNIVERSAL MB-266152 SR-7230 16X14 HILO CORRIENTE

UR001

<https://ikoyama.com/img/UR003.png>

[https://ikoyama.com/img/UR003\(2\).png](https://ikoyama.com/img/UR003(2).png)

NISSAN SENTRA

RACK END UNIVERSAL SR-4741 LARGO 16X12 HILO CORRIENTE

UR003

<https://ikoyama.com/img/UR007.png>

[https://ikoyama.com/img/UR007\(2\).png](https://ikoyama.com/img/UR007(2).png)

TOYOTA 2L

RACK END UNIVERSAL14X17 HILO FINO

UR007

<https://ikoyama.com/img/RCH001.png>

[https://ikoyama.com/img/RCH001\(2\).png](https://ikoyama.com/img/RCH001(2).png)

CHEVROLET AVEO 06/12 SAIL 12/15

ROTULA DEL INFE RH LH 96535089 CBKD-10

RCH001

<https://ikoyama.com/img/RDA001.png>

[https://ikoyama.com/img/RDA001\(2\).png](https://ikoyama.com/img/RDA001(2).png)

DAEWOO RACER ESPERO LANOS

ROTULA DEL INF RH LH 94788122 CBKD-1

RDA001

<https://ikoyama.com/img/RHO001.png>

[https://ikoyama.com/img/RHO001\(2\).png](https://ikoyama.com/img/RHO001(2).png)

HONDA ACCORD INF 90/00

ROTULA DEL INF RH LH SB-6182

RHO001

<https://ikoyama.com/img/RHO002.png>

[https://ikoyama.com/img/RHO002\(2\).png](https://ikoyama.com/img/RHO002(2).png)

HONDA CIVIC INF 91/00

ROTULA DEL INF RH LH SB-6102

RHO002

<https://ikoyama.com/img/RHO003.png>

[https://ikoyama.com/img/RHO003\(2\).png](https://ikoyama.com/img/RHO003(2).png)

HONDA CIVIC SUP 91/00

ROTULA DEL SUP RH LH SB-6191

RHO003

<https://ikoyama.com/img/RHY001.png>

[https://ikoyama.com/img/RHY001\(2\).png](https://ikoyama.com/img/RHY001(2).png)

HYUNDAI ACCENT 11/16 ELANTRA 11/16 CERATO 13/16

ROTULA DEL INF RH LH 54530-0U000 CBKH-38

RHY001

<https://ikoyama.com/img/RHY002.png>

[https://ikoyama.com/img/RHY002\(2\).png](https://ikoyama.com/img/RHY002(2).png)

HYUNDAI ACCENT KIA RIO 05/10

ROTULA DEL INF RH LH 51760-1G000 CBKK-20

RHY002

<https://ikoyama.com/img/RHY003.png>
HYUNDAI ELANTRA 06/10

[https://ikoyama.com/img/RHY003\(2\).png](https://ikoyama.com/img/RHY003(2).png)

ROTULA DEL INF RH LH 51760-2H000 CBKH-30

RHY003



<https://ikoyama.com/img/RHY004.png>
HYUNDAI EXCEL 89/94

[https://ikoyama.com/img/RHY004\(2\).png](https://ikoyama.com/img/RHY004(2).png)

ROTULA DEL INF RH LH 54530-24000 CBKH-3

RHY004



<https://ikoyama.com/img/RHY005.png>
HYUNDAI H-1 07/16

[https://ikoyama.com/img/RHY005\(2\).png](https://ikoyama.com/img/RHY005(2).png)

ROTULA DEL INF RH LH 54530-3J000 CBKK-22

RHY005



<https://ikoyama.com/img/RHY006.png>
HYUNDAI H100 04/15 PORTER 94/08 GRACE 96/05

[https://ikoyama.com/img/RHY006\(2\).png](https://ikoyama.com/img/RHY006(2).png)

ROTULA DEL INF RH LH 54524-43000 CBKH-10

RHY006



<https://ikoyama.com/img/RHY007.png>
HYUNDAI H100 04/15 PORTER 94/08 GRACE 96/05

[https://ikoyama.com/img/RHY007\(2\).png](https://ikoyama.com/img/RHY007(2).png)

ROTULA DEL SUP RH LH 54417-4A000 CBKH-9

RHY007



<https://ikoyama.com/img/RHY008.png>
HYUNDAI i10 KIA PICANTO 08/14

[https://ikoyama.com/img/RHY008\(2\).png](https://ikoyama.com/img/RHY008(2).png)

ROTULA DEL INF RH LH 54530-07000 CBKK-16

RHY008



<https://ikoyama.com/img/RHY009.png>
HYUNDAI SANTA FE SORENTO 13/16 SONATA YF 10/ON

[https://ikoyama.com/img/RHY009\(2\).png](https://ikoyama.com/img/RHY009(2).png)

ROTULA DEL INF RH LH 54530-3S100 CBKH-40

RHY009

<https://ikoyama.com/img/RHY012.png>
HYUNDAI SONATA OPTIMA 01/ON

[https://ikoyama.com/img/RHY012\(2\).png](https://ikoyama.com/img/RHY012(2).png)

ROTULA DEL INF RH LH 51760-38A00 CBKK-13

RHY012

<https://ikoyama.com/img/RHY011.png> [https://ikoyama.com/img/RHY011\(2\).png](https://ikoyama.com/img/RHY011(2).png)

HYUNDAI SONATA OPTIMA 01/ON

ROTULA DEL SUP RH LH 54403-38A00 CBKH-28

RHY011



<https://ikoyama.com/img/RHY010.png>

[https://ikoyama.com/img/RHY010\(2\).png](https://ikoyama.com/img/RHY010(2).png)

HYUNDAI TUCSON 09/13

ROTULA DEL INF RH LH 54530-3S000 CBKH-39

RHY010

<https://ikoyama.com/img/RHY013.png> [https://ikoyama.com/img/RHY013\(2\).png](https://ikoyama.com/img/RHY013(2).png)

KIA K-2700, BESTA, TOPIC INF 16/UP

ROTULA DEL INF RH LH SB-1412

RHY013

<https://ikoyama.com/img/RHY014.png>

[https://ikoyama.com/img/RHY014\(2\).png](https://ikoyama.com/img/RHY014(2).png)

KIA K-2700, BESTA, TOPIC SUP 16/UP

ROTULA DEL SUP RH LH SB-1411

RHY014



<https://ikoyama.com/img/RKI001.png> [https://ikoyama.com/img/RKI001\(2\).png](https://ikoyama.com/img/RKI001(2).png)

KIA RIO 1.2L KIA PICANTO GRAN i10 SOUL 11/ON

ROTULA DEL INF DEL RH LH 54530-2K000 CBKK-27

RKI001



<https://ikoyama.com/img/RMI001.png>

[https://ikoyama.com/img/RMI001\(2\).png](https://ikoyama.com/img/RMI001(2).png)

MITSUBISHI L200 DAKAR TRITON KA4T 07/14

ROTULA DEL INF RH LH MR-496799 CBM-33

RMI001



<https://ikoyama.com/img/RMI002.png> [https://ikoyama.com/img/RMI002\(2\).png](https://ikoyama.com/img/RMI002(2).png)

MITSUBISHI L200 DAKAR TRITON KA4T 07/14

ROTULA DEL SUP RH LH MR496792 CBM-32

RMI002

<https://ikoyama.com/img/RMI003.png>

[https://ikoyama.com/img/RMI003\(2\).png](https://ikoyama.com/img/RMI003(2).png)

MITSUBISHI LANCER CEDIA 03/13

ROTULA DEL RH LH SB-7872

RMI003



<https://ikoyama.com/img/RNI007.png>

[https://ikoyama.com/img/RNI007\(2\).png](https://ikoyama.com/img/RNI007(2).png)

NISSAN CARAVAN TD27 KA24 TD23 D21 PICKUP

ROTULA DEL SUP RH LH 40110-T3060 CBN-11

RNI007



<https://ikoyama.com/img/RNI001.png>

[https://ikoyama.com/img/RNI001\(2\).png](https://ikoyama.com/img/RNI001(2).png)

NISSAN CARAVAN URVAN E25 01/ON

ROTULA DEL INF RH LH 40160-VW000 CBN-66

RNI001



<https://ikoyama.com/img/RNI002.png>

[https://ikoyama.com/img/RNI002\(2\).png](https://ikoyama.com/img/RNI002(2).png)

NISSAN FIERA 4WD Z24

ROTULA DEL INF RH LH 40160-50W00 CBN-21

RNI002



<https://ikoyama.com/img/RNI008.png>

[https://ikoyama.com/img/RNI008\(2\).png](https://ikoyama.com/img/RNI008(2).png)

NISSAN FIERA CARAVAN D21 PICKUP 85/91

ROTULA DEL INFE RH LH 40160-01N25 CBN-31

RNI008



<https://ikoyama.com/img/RNI003.png>

[https://ikoyama.com/img/RNI003\(2\).png](https://ikoyama.com/img/RNI003(2).png)

NISSAN FRONTIER 2WD 4WD D22 05/ON

ROTULA DEL INF RH LH 40160-2S601 CBN-63

RNI003



<https://ikoyama.com/img/RNI004.png>

[https://ikoyama.com/img/RNI004\(2\).png](https://ikoyama.com/img/RNI004(2).png)

NISSAN FRONTIER 2WD 4WD D22 05/ON

ROTULA DEL SUP RH LH 40110-2S485 CBN-62

RNI004



<https://ikoyama.com/img/RNI005.png>

[https://ikoyama.com/img/RNI005\(2\).png](https://ikoyama.com/img/RNI005(2).png)

NISSAN NAVARA 07/15

ROTULA DEL INF RH LH 40160-EB70A CBN-73

RNI005



<https://ikoyama.com/img/RNI006.png>

[https://ikoyama.com/img/RNI006\(2\).png](https://ikoyama.com/img/RNI006(2).png)

NISSAN NAVARA 07/15

ROTULA DEL SUP RH LH 40110-EB70D CBN-74

RNI006



<https://ikoyama.com/img/RNI009.png> [https://ikoyama.com/img/RNI009\(2\).png](https://ikoyama.com/img/RNI009(2).png)

NISSAN SUNNY SENTRA B12 87/ON 38MM LISA

ROTULA DEL INF RH LH 40160-50A00 CBN-30

RNI009



<https://ikoyama.com/img/RNI010.png> [https://ikoyama.com/img/RNI010\(2\).png](https://ikoyama.com/img/RNI010(2).png)

NISSAN SUNNY SENTRA B13 CD17 90/ON 39MM LISA

ROTULA DEL INF RH LH 40160-50Y10 CBN-36

RNI010



<https://ikoyama.com/img/RNI011.png> [https://ikoyama.com/img/RNI011\(2\).png](https://ikoyama.com/img/RNI011(2).png)

NISSAN TIIDA VERSA 1.6L 11/14 SENTRA B16 06/12

ROTULA DEL INF RH LH 40160-ED00A CBN-70

RNI011



<https://ikoyama.com/img/RTO014.png> [https://ikoyama.com/img/RTO014\(2\).png](https://ikoyama.com/img/RTO014(2).png)

TOYOTA 1KD 2KD 1GD 2GD HILUX 04/ON

ROTULA DEL INF RH LH 43330-09295 CBT-64

RTO014



<https://ikoyama.com/img/RTO015.png> [https://ikoyama.com/img/RTO015\(2\).png](https://ikoyama.com/img/RTO015(2).png)

TOYOTA 1KD 2KD 1GD 2GD HILUX 04/ON

ROTULA DEL SUP RH LH 43310-09015 CBT-63

RTO015



<https://ikoyama.com/img/RTO001.png> [https://ikoyama.com/img/RTO001\(2\).png](https://ikoyama.com/img/RTO001(2).png)

TOYOTA AVANZA 11/12

ROTULA DEL INF RH LH 43330-BZ010 CBT-87

RTO001

<https://ikoyama.com/img/RTO018.png> [https://ikoyama.com/img/RTO018\(2\).png](https://ikoyama.com/img/RTO018(2).png)

TOYOTA COASTER SUP 95/10

ROTULA DEL RH LH SB-3551

RTO018



<https://ikoyama.com/img/RTO002.png> [https://ikoyama.com/img/RTO002\(2\).png](https://ikoyama.com/img/RTO002(2).png)

TOYOTA COROLLA 1C 2C 90/00 3 PERNOS

ROTULA DEL INF RH LH 43330-19095 CBT-40

RTO002



<https://ikoyama.com/img/RT0019.png>
TOYOTA COROLLA COROLLON 08/13
ROTULA DEL RH LH SB-3962

RT0019



<https://ikoyama.com/img/RT0003.png>
TOYOTA COROLLA ZZE12 3ZZ-FE 01/06
ROTULA DEL INF RH LH 43330-19115 CBT-46

RT0003



<https://ikoyama.com/img/RT0004.png>
TOYOTA CORONA 2S 3T 78/87
ROTULA DEL INF RH LH 43308-12030 CBT-9

RT0004



<https://ikoyama.com/img/RT0005.png>
TOYOTA HIACE 2WD 2L 2Y 83/89
ROTULA DEL INF RH LH 43330-29125 CBT-21

RT0005



<https://ikoyama.com/img/RT0006.png>
TOYOTA HIACE 2WD 2L 2Y 83/89
ROTULA DEL SUP RH LH 43360-29076 CBT-20

RT0006



<https://ikoyama.com/img/RT0007.png>
TOYOTA HIACE 4WD 87/ON
ROTULA DEL INF RH LH 43330-39195 CBT-28

RT0007



<https://ikoyama.com/img/RT0008.png>
TOYOTA HIACE CONMUTER 3L 90/95
ROTULA DEL SUP RH LH 43350-29065 CBT-34

RT0008



<https://ikoyama.com/img/RT0009.png>
TOYOTA HIACE CONMUTER 5L 04/13
ROTULA DEL INF RH LH 43330-29565 CBT-68

RT0009



<https://ikoyama.com/img/RT0010.png>

[https://ikoyama.com/img/RT0010\(2\).png](https://ikoyama.com/img/RT0010(2).png)

TOYOTA HILUX 2WD 2L 88/05 3Y 83/88 22R

ROTULA DEL SUP RH LH 43350-39035 CBT-14

RT0010



<https://ikoyama.com/img/RT0011.png>

[https://ikoyama.com/img/RT0011\(2\).png](https://ikoyama.com/img/RT0011(2).png)

TOYOTA HILUX 2WD 4Y 83/ON

ROTULA DEL INF RH LH 43330-39165 CBT-15

RT0011



<https://ikoyama.com/img/RT0012.png>

[https://ikoyama.com/img/RT0012\(2\).png](https://ikoyama.com/img/RT0012(2).png)

TOYOTA HILUX 4WD 22R 4Y 3L 91/ON

ROTULA DEL INF RH LH 43330-39265 CBT-42

RT0012



<https://ikoyama.com/img/RT0013.png>

[https://ikoyama.com/img/RT0013\(2\).png](https://ikoyama.com/img/RT0013(2).png)

TOYOTA HILUX 4WD 22R 4Y 3L 91/ON

ROTULA DEL SUP RH LH 43350-39045 CBT-27

RT0013



<https://ikoyama.com/img/RT0020.png>

[https://ikoyama.com/img/RT0020\(2\).png](https://ikoyama.com/img/RT0020(2).png)

TOYOTA RAV 4 06/13

ROTULA DEL RH LH SB-T222

RT0020



<https://ikoyama.com/img/RT0016.png>

[https://ikoyama.com/img/RT0016\(2\).png](https://ikoyama.com/img/RT0016(2).png)

TOYOTA TERCEL 2E 3E STARLET 1N 90/94

ROTULA DEL INF LH CBT-38L

RT0016

<https://ikoyama.com/img/RT0016R.png>

[https://ikoyama.com/img/RT0016R\(2\).png](https://ikoyama.com/img/RT0016R(2).png)

TOYOTA TERCEL 2E 3E STARLET 1N 90/94

ROTULA DEL INF RH CBT-38R

RT0016R



<https://ikoyama.com/img/RT0017.png>

[https://ikoyama.com/img/RT0017\(2\).png](https://ikoyama.com/img/RT0017(2).png)

TOYOTA YARIS 99/ON PROBOX 02/ON

ROTULA DEL INF RH LH 43308-59035 CBT-56

RT0017

<https://ikoyama.com/img/RTO017A.png> [https://ikoyama.com/img/RTO017A\(2\).png](https://ikoyama.com/img/RTO017A(2).png)

TOYOTA YARIS 99/ON PROBOX 02/ON

ROTULA DEL INF RH LH 43308-59035 CBT-56

RTO017A



<https://ikoyama.com/img/TCH002.png> [https://ikoyama.com/img/TCH002\(2\).png](https://ikoyama.com/img/TCH002(2).png)

CHEVROLET AVEO 02/12 KALOS 02/05

TERMINAL DEL EXT LH 93740722 CEKD-13L

TCH002



<https://ikoyama.com/img/TCH001.png> [https://ikoyama.com/img/TCH001\(2\).png](https://ikoyama.com/img/TCH001(2).png)

CHEVROLET AVEO 02/12 KALOS 02/05

TERMINAL DEL EXT RH 93740723 CEKD-13R

TCH001



<https://ikoyama.com/img/TCH004.png> [https://ikoyama.com/img/TCH004\(2\).png](https://ikoyama.com/img/TCH004(2).png)

CHEVROLET SAIL 1.4 F14D3 10/14

TERMINAL DEL LH 9005917 CEG-11

TCH004



<https://ikoyama.com/img/TCH003.png> [https://ikoyama.com/img/TCH003\(2\).png](https://ikoyama.com/img/TCH003(2).png)

CHEVROLET SAIL 1.4 F14D3 10/14

TERMINAL DEL RH 9005918 CEG-10

TCH003

<https://ikoyama.com/img/TCH005.png> [https://ikoyama.com/img/TCH005\(2\).png](https://ikoyama.com/img/TCH005(2).png)

CHEVROLET SPARK M300 GT 10/15

TERMINAL DEL EXT RH LH 95967285 CEKD-18

TCH005

<https://ikoyama.com/img/TDA003.png> [https://ikoyama.com/img/TDA003\(2\).png](https://ikoyama.com/img/TDA003(2).png)

DAEWOO RACER CIELO LANOS

TERMINAL DEL LH 96275018 CEKD-1L

TDA003

<https://ikoyama.com/img/TDA002.png> [https://ikoyama.com/img/TDA002\(2\).png](https://ikoyama.com/img/TDA002(2).png)

DAEWOO RACER CIELO LANOS

TERMINAL DEL RH 96275019 CEKD-1R

TDA002



<https://ikoyama.com/img/TDA001.png>
DAEWOO TICO 91/01 SPARK 98/ON

[https://ikoyama.com/img/TDA001\(2\).png](https://ikoyama.com/img/TDA001(2).png)

TERMINAL DEL EXT RH LH 93741077 CEKD-5

TDA001



<https://ikoyama.com/img/THO003.png>
HONDA CIVIC 05/UP

[https://ikoyama.com/img/THO003\(2\).png](https://ikoyama.com/img/THO003(2).png)

TERMINAL DEL LH 53560-5NA-A01 SE-6381L

THO003

<https://ikoyama.com/img/THO004.png>
HONDA CIVIC 05/UP

[https://ikoyama.com/img/THO004\(2\).png](https://ikoyama.com/img/THO004(2).png)

TERMINAL DEL RH 53540-5NA-A01 SE-6381R

THO004

<https://ikoyama.com/img/THO001.png>
HONDA CIVIC 90/UP

[https://ikoyama.com/img/THO001\(2\).png](https://ikoyama.com/img/THO001(2).png)

TERMINAL DEL LH 53550-SR3-003 SE-6191L

THO001

<https://ikoyama.com/img/THO002.png>
HONDA CIVIC 90/UP

[https://ikoyama.com/img/THO002\(2\).png](https://ikoyama.com/img/THO002(2).png)

TERMINAL DEL RH 53540-SR3-003 SE-6191R

THO002



<https://ikoyama.com/img/THY002.png>
HYUNDAI ACCENT KIA RIO 05/10

[https://ikoyama.com/img/THY002\(2\).png](https://ikoyama.com/img/THY002(2).png)

TERMINAL DEL EXT LH 56820-1E000 CEKH-36L

THY002



<https://ikoyama.com/img/THY001.png>
HYUNDAI ACCENT KIA RIO 05/10

[https://ikoyama.com/img/THY001\(2\).png](https://ikoyama.com/img/THY001(2).png)

TERMINAL DEL EXT RH 56820-1E900 CEKH-36R

THY001



<https://ikoyama.com/img/THY004.png>
HYUNDAI ACCENT KIA RIO 11/18

[https://ikoyama.com/img/THY004\(2\).png](https://ikoyama.com/img/THY004(2).png)

TERMINAL DEL EXT LH 56820-0U500 CEKH-46L

THY004



<https://ikoyama.com/img/THY003.png> [https://ikoyama.com/img/THY003\(2\).png](https://ikoyama.com/img/THY003(2).png)
HYUNDAI ACCENT KIA RIO 11/18
TERMINAL DEL EXT RH 56820-0U590 CEKH-46R **THY003**



<https://ikoyama.com/img/THY005.png> [https://ikoyama.com/img/THY005\(2\).png](https://ikoyama.com/img/THY005(2).png)
HYUNDAI EXCEL 89/94
TERMINAL DEL EXT RH LH 56820-21000 CEKH-3 **THY005**



<https://ikoyama.com/img/THY007.png> [https://ikoyama.com/img/THY007\(2\).png](https://ikoyama.com/img/THY007(2).png)
HYUNDAI H-1 08/15
TERMINAL DEL EXT LH 56820-4H000 CEKH-43L **THY007**



<https://ikoyama.com/img/THY006.png> [https://ikoyama.com/img/THY006\(2\).png](https://ikoyama.com/img/THY006(2).png)
HYUNDAI H-1 08/15
TERMINAL DEL EXT RH 56820-4H100 CEKH-43R **THY006**




<https://ikoyama.com/img/THY008.png> [https://ikoyama.com/img/THY008\(2\).png](https://ikoyama.com/img/THY008(2).png)
HYUNDAI H100 GRACE PORTER 96/04
TERMINAL DEL EXT RH LH 56872-43010 CEKH-9 **THY008**



<https://ikoyama.com/img/THY009.png> [https://ikoyama.com/img/THY009\(2\).png](https://ikoyama.com/img/THY009(2).png)
HYUNDAI H100 PORTER 04/11
TERMINAL DEL EXT RH LH 56820-47500 CEKH-40 **THY009**



<https://ikoyama.com/img/THY010.png> [https://ikoyama.com/img/THY010\(2\).png](https://ikoyama.com/img/THY010(2).png)
HYUNDAI i10 10/14 PICANTO 08/11 GRAND i 10 14/18
TERMINAL DEL EXT 56820-0X000 CEKK-35 **THY010**



<https://ikoyama.com/img/THY012.png> [https://ikoyama.com/img/THY012\(2\).png](https://ikoyama.com/img/THY012(2).png)
HYUNDAI SANTA FE 13/15 SORENTO 13/15
TERMINAL DEL EXT LH 56820-2W000 CEKH-49L **THY012**

<https://ikoyama.com/img/THY011.png> [https://ikoyama.com/img/THY011\(2\).png](https://ikoyama.com/img/THY011(2).png)

HYUNDAI SANTA FE SORENTO 13/15

TERMINAL DEL EXT RH 56820-2W050 CEKH-49R

THY011

<https://ikoyama.com/img/THY014.png> [https://ikoyama.com/img/THY014\(2\).png](https://ikoyama.com/img/THY014(2).png)

HYUNDAI SONATA OPTIMA 01/ON

TERMINAL DEL EXT LH 56820-38000 CEKH-29

THY014

<https://ikoyama.com/img/THY013.png> [https://ikoyama.com/img/THY013\(2\).png](https://ikoyama.com/img/THY013(2).png)

HYUNDAI SONATA OPTIMA 01/ON

TERMINAL DEL EXT RH 56820-38900 CEKH-28

THY013

<https://ikoyama.com/img/THY016.png> [https://ikoyama.com/img/THY016\(2\).png](https://ikoyama.com/img/THY016(2).png)

HYUNDAI TUCSON JM SPORTAGE 04/10

TERMINAL DEL EXT LH 56820-2E000 CEKH-35L

THY016

<https://ikoyama.com/img/THY015.png> [https://ikoyama.com/img/THY015\(2\).png](https://ikoyama.com/img/THY015(2).png)

HYUNDAI TUCSON JM SPORTAGE 04/10

TERMINAL DEL EXT RH 56820-2E900 CEKH-35R

THY015

<https://ikoyama.com/img/THY018.png> [https://ikoyama.com/img/THY018\(2\).png](https://ikoyama.com/img/THY018(2).png)

HYUNDAI TUCSON SPORTAGE 11/16

TERMINAL DEL EXT LH 56820-2S000 CEKH-45L

THY018

<https://ikoyama.com/img/THY017.png> [https://ikoyama.com/img/THY017\(2\).png](https://ikoyama.com/img/THY017(2).png)

HYUNDAI TUCSON SPORTAGE 11/16

TERMINAL DEL EXT RH 56820-2S050 CEKH-45R

THY017

<https://ikoyama.com/img/TKI002.png> [https://ikoyama.com/img/TKI002\(2\).png](https://ikoyama.com/img/TKI002(2).png)

KIA CERATO KOUP 08/12 ELANTRA 06/10

TERMINAL DEL EXT LH 56820-2H000 CEKH-38L

TKI002



<https://ikoyama.com/img/TKI001.png> [https://ikoyama.com/img/TKI001\(2\).png](https://ikoyama.com/img/TKI001(2).png)
KIA CERATO KROUP 08/12 ELANTRA 06/10
TERMINAL DEL EXT RH 56820-2H090 CEKH-38R **TKI001**



<https://ikoyama.com/img/TKI004.png> [https://ikoyama.com/img/TKI004\(2\).png](https://ikoyama.com/img/TKI004(2).png)
KIA PICANTO 11/16
TERMINAL DEL EXT LH 56820-1Y500 CEKK-37L **TKI004**



<https://ikoyama.com/img/TKI003.png> [https://ikoyama.com/img/TKI003\(2\).png](https://ikoyama.com/img/TKI003(2).png)
KIA PICANTO 11/16
TERMINAL DEL EXT RH 56820-1Y550 CEKK-37R **TKI003**



<https://ikoyama.com/img/TMA002.png> [https://ikoyama.com/img/TMA002\(2\).png](https://ikoyama.com/img/TMA002(2).png)
MAZDA 3 MAZDA 5 03/13
TERMINAL DEL EXT LH BP4L-32-290 CEMZ-46 **TMA002**




<https://ikoyama.com/img/TMA001.png> [https://ikoyama.com/img/TMA001\(2\).png](https://ikoyama.com/img/TMA001(2).png)
MAZDA 3 MAZDA 5 03/13
TERMINAL DEL EXT RH BP4L-32-280 CEMZ-45 **TMA001**



<https://ikoyama.com/img/TMI002.png> [https://ikoyama.com/img/TMI002\(2\).png](https://ikoyama.com/img/TMI002(2).png)
MITSUBISHI L200 DAKAR TRITON KA4T 07/14
TERMINAL DEL EXT LH MR-508135 CEM-51L **TMI002**



<https://ikoyama.com/img/TMI001.png> [https://ikoyama.com/img/TMI001\(2\).png](https://ikoyama.com/img/TMI001(2).png)
MITSUBISHI L200 DAKAR TRITON KA4T 07/14
TERMINAL DEL EXT RH MR-508136 CEM-51R **TMI001**



<https://ikoyama.com/img/TMI003.png> [https://ikoyama.com/img/TMI003\(2\).png](https://ikoyama.com/img/TMI003(2).png)
MITSUBISHI LIBERO
TERMINAL DEL RH LH MB527169 SE-7301 **TMI003**



<https://ikoyama.com/img/TNI001.png>
NISSAN AD VAN SUNNY 00/ON

[https://ikoyama.com/img/TNI001\(2\).png](https://ikoyama.com/img/TNI001(2).png)

TERMINAL DEL EXT RH LH 48520-0M085 CEN-80

TNI001



<https://ikoyama.com/img/TNI014.png>
NISSAN AD WAGON SUNNY

[https://ikoyama.com/img/TNI014\(2\).png](https://ikoyama.com/img/TNI014(2).png)

TERMINAL DEL RH LH 48520-50Y00 SE-4581

TNI014



<https://ikoyama.com/img/TNI003.png>
NISSAN CARAVAN E24 88/ON

[https://ikoyama.com/img/TNI003\(2\).png](https://ikoyama.com/img/TNI003(2).png)

TERMINAL DEL EXT RH LH 48520-27N25 CEN-75

TNI003



<https://ikoyama.com/img/TNI004.png>
NISSAN CARAVAN HOMOY 86/88

[https://ikoyama.com/img/TNI004\(2\).png](https://ikoyama.com/img/TNI004(2).png)

TERMINAL DEL EXT RH LH 48520-01N25 CEN-72

TNI004



<https://ikoyama.com/img/TNI002.png>
NISSAN CARAVAN URVAN E25 01/ON

[https://ikoyama.com/img/TNI002\(2\).png](https://ikoyama.com/img/TNI002(2).png)

TERMINAL DEL EXT RH LH 48520-VW025 CEN-117

TNI002



<https://ikoyama.com/img/TNI006.png>
NISSAN FRONTIER 2WD D22 05/ON

[https://ikoyama.com/img/TNI006\(2\).png](https://ikoyama.com/img/TNI006(2).png)

TERMINAL DEL EXT RH LH 48520-2S485 CEN-95

TNI006



<https://ikoyama.com/img/TNI005.png>
NISSAN FRONTIER 2WD D22 05/ON

[https://ikoyama.com/img/TNI005\(2\).png](https://ikoyama.com/img/TNI005(2).png)

TERMINAL DEL INT RH LH 48521-2S485 CEN-94

TNI005



<https://ikoyama.com/img/TNI008.png>
NISSAN FRONTIER 4WD D22 05/ON

[https://ikoyama.com/img/TNI008\(2\).png](https://ikoyama.com/img/TNI008(2).png)

TERMINAL DEL EXT RH LH 48520-3S525 CEN-98

TNI008



<https://ikoyama.com/img/TNI007.png> [https://ikoyama.com/img/TNI007\(2\).png](https://ikoyama.com/img/TNI007(2).png)
NISSAN FRONTIER 4WD D22 05/ON

TERMINAL DEL INT RH LH 48570-3S525 CEN-99

TNI007



<https://ikoyama.com/img/TNI010.png> [https://ikoyama.com/img/TNI010\(2\).png](https://ikoyama.com/img/TNI010(2).png)
NISSAN NAVARA FRONTIER D40 07/ON

TERMINAL DEL EXT LH D8520-EB70A CEN-144

TNI010



<https://ikoyama.com/img/TNI009.png> [https://ikoyama.com/img/TNI009\(2\).png](https://ikoyama.com/img/TNI009(2).png)
NISSAN NAVARA FRONTIER D40 07/ON

TERMINAL DEL EXT RH D8640-EB70A CEN-143

TNI009



<https://ikoyama.com/img/TNI015.png> [https://ikoyama.com/img/TNI015\(2\).png](https://ikoyama.com/img/TNI015(2).png)
NISSAN SENTRA

TERMINAL DEL RH LH 48520-42025 SE-4901

TNI015



<https://ikoyama.com/img/TNI011.png> [https://ikoyama.com/img/TNI011\(2\).png](https://ikoyama.com/img/TNI011(2).png)
NISSAN SUNNY SENTRA B13 90/95

TERMINAL DEL EXT RH LH 48520-50A26 CEN-47

TNI011



<https://ikoyama.com/img/TNI013.png> [https://ikoyama.com/img/TNI013\(2\).png](https://ikoyama.com/img/TNI013(2).png)
NISSAN TIIDA

TERMINAL DEL EXT LH 48640-3U025 CEN-116

TNI013



<https://ikoyama.com/img/TNI012.png> [https://ikoyama.com/img/TNI012\(2\).png](https://ikoyama.com/img/TNI012(2).png)
NISSAN TIIDA

TERMINAL DEL EXT RH 48520-3U025 CEN-115

TNI012



<https://ikoyama.com/img/TNI016.png> [https://ikoyama.com/img/TNI016\(2\).png](https://ikoyama.com/img/TNI016(2).png)
NISSAN URVAN

TERMINAL DEL RH LH 48520-VW025 SE-4971

TNI016



<https://ikoyama.com/img/TSZ001.png>

[https://ikoyama.com/img/TSZ001\(2\).png](https://ikoyama.com/img/TSZ001(2).png)

SUZUKI ALTO 93/12

TSZ001

TERMINAL DEL RH/LH 48810-84000 CES-12



<https://ikoyama.com/img/TSZ002.png>

[https://ikoyama.com/img/TSZ002\(2\).png](https://ikoyama.com/img/TSZ002(2).png)

SUZUKI APV

TSZ002

TERMINAL DEL RH LH 48810-60810 SE-7561

<https://ikoyama.com/img/TSZ003.png>

[https://ikoyama.com/img/TSZ003\(2\).png](https://ikoyama.com/img/TSZ003(2).png)

SUZUKI BALENO

TSZ003

TERMINAL DEL RH LH 48810-60B00 SE-7461

<https://ikoyama.com/img/TSZ004.png>

[https://ikoyama.com/img/TSZ004\(2\).png](https://ikoyama.com/img/TSZ004(2).png)

SUZUKI GRAN VITARA 07/UP

TSZ004

TERMINAL DEL RH LH 48810-65J00 SE-7641



<https://ikoyama.com/img/TTO002.png>

[https://ikoyama.com/img/TTO002\(2\).png](https://ikoyama.com/img/TTO002(2).png)

TOYOTA AVANZA 11/15

TTO002

TERMINAL DEL EXT LH 45047-BZ120 CET-185



<https://ikoyama.com/img/TTO001.png>

[https://ikoyama.com/img/TTO001\(2\).png](https://ikoyama.com/img/TTO001(2).png)

TOYOTA AVANZA 11/15

TTO001

TERMINAL DEL EXT RH 45046-BZ120 CET-184



<https://ikoyama.com/img/TTO003.png>

[https://ikoyama.com/img/TTO003\(2\).png](https://ikoyama.com/img/TTO003(2).png)

TOYOTA CALDINA CARINA CORONA 92/ON

TTO003

TERMINAL DEL EXT LH 45047-29075 CET-91



<https://ikoyama.com/img/TTO004.png>

[https://ikoyama.com/img/TTO004\(2\).png](https://ikoyama.com/img/TTO004(2).png)

TOYOTA CALDINA CARINA CORONA 92/ON

TTO004

TERMINAL DEL EXT RH 45046-29275 CET-90



<https://ikoyama.com/img/TTO006.png>
TOYOTA COROLLA 1ZZ 3ZZ 03/08

[https://ikoyama.com/img/TTO006\(2\).png](https://ikoyama.com/img/TTO006(2).png)

TERMINAL DEL EXT LH 45047-09080 CET-112L

TTO006



<https://ikoyama.com/img/TTO005.png>
TOYOTA COROLLA 1ZZ 3ZZ 03/08

[https://ikoyama.com/img/TTO005\(2\).png](https://ikoyama.com/img/TTO005(2).png)

TERMINAL DEL EXT RH 45046-09200 CET-112R

TTO005



<https://ikoyama.com/img/TTO007.png>
TOYOTA COROLLA 1ZZ 3ZZ 09/0N

[https://ikoyama.com/img/TTO007\(2\).png](https://ikoyama.com/img/TTO007(2).png)

TERMINAL DEL EXT RH LH 45046-19425 CET-180

TTO007



<https://ikoyama.com/img/TTO008.png>
TOYOTA COROLLA 2C-4AF 92/99

[https://ikoyama.com/img/TTO008\(2\).png](https://ikoyama.com/img/TTO008(2).png)

TERMINAL DEL EXT RH LH 45046-19175 CET-59

TTO008



<https://ikoyama.com/img/TTO009.png>
TOYOTA CORONA 16R 18R 3T 74/87

[https://ikoyama.com/img/TTO009\(2\).png](https://ikoyama.com/img/TTO009(2).png)

TERMINAL DEL EXT RH LH CORTO 45046-29075 CET-23

TTO009

<https://ikoyama.com/img/TTO010.png>
TOYOTA CORONA 16R 18R 3T 74/87

[https://ikoyama.com/img/TTO010\(2\).png](https://ikoyama.com/img/TTO010(2).png)

TERMINAL DEL INT RH LH LARGO 45406-19016 CET-24

TTO010



<https://ikoyama.com/img/TTO037.png>
TOYOTA ETIOS 14/UP

[https://ikoyama.com/img/TTO037\(2\).png](https://ikoyama.com/img/TTO037(2).png)

TERMINAL DEL LH 45047-09360 CE0818L

TTO037



<https://ikoyama.com/img/TTO036.png>
TOYOTA ETIOS 14/UP

[https://ikoyama.com/img/TTO036\(2\).png](https://ikoyama.com/img/TTO036(2).png)

TERMINAL DEL RH 45046-09710 CE0818R

TTO036



<https://ikoyama.com/img/TT0011.png>
TOYOTA HIACE 2L 82/89

[https://ikoyama.com/img/TT0011\(2\).png](https://ikoyama.com/img/TT0011(2).png)

TERMINAL DEL EXT RH LH CORTO 45046-29115 CET-26

TT0011



<https://ikoyama.com/img/TT0012.png>
TOYOTA HIACE 3L 90/ON

[https://ikoyama.com/img/TT0012\(2\).png](https://ikoyama.com/img/TT0012(2).png)

TERMINAL DEL EXT RH LH 45046-29215 CET-70

TT0012



<https://ikoyama.com/img/TT0013.png>
TOYOTA HIACE 3L 95/ON

[https://ikoyama.com/img/TT0013\(2\).png](https://ikoyama.com/img/TT0013(2).png)

TERMINAL DEL EXT RH LH TUBO 45046-29325 CET-114

TT0013



<https://ikoyama.com/img/TT0014.png>
TOYOTA HIACE VAN COMMUTER 5L 04/ON

[https://ikoyama.com/img/TT0014\(2\).png](https://ikoyama.com/img/TT0014(2).png)

TERMINAL DEL EXT RH LH 45046-29456 CET-150

TT0014



<https://ikoyama.com/img/TT0030.png>
TOYOTA HILUX 1GD 2GD 15/ON

[https://ikoyama.com/img/TT0030\(2\).png](https://ikoyama.com/img/TT0030(2).png)

TERMINAL DEL RH LH 45046-09800

TT0030



<https://ikoyama.com/img/TT0022.png>
TOYOTA HILUX 1KD VIGO 04/14

[https://ikoyama.com/img/TT0022\(2\).png](https://ikoyama.com/img/TT0022(2).png)

TERMINAL DEL EXT RH LH 45046-09251 CET-146

TT0022



<https://ikoyama.com/img/TT0021.png>
TOYOTA HILUX 1KD VIGO 04/14

[https://ikoyama.com/img/TT0021\(2\).png](https://ikoyama.com/img/TT0021(2).png)

TERMINAL DEL EXT RH LH 45046-09281 CET-147

TT0021



<https://ikoyama.com/img/TT0015.png>
TOYOTA HILUX 2WD 2L 88/05 3Y 83/88

[https://ikoyama.com/img/TT0015\(2\).png](https://ikoyama.com/img/TT0015(2).png)

TERMINAL DEL INT RH LH 45406-29115 CET-27

TT0015



<https://ikoyama.com/img/TT0020.png>

[https://ikoyama.com/img/TT0020\(2\).png](https://ikoyama.com/img/TT0020(2).png)

TOYOTA HILUX 4WD 22R 4Y 3L 91/04

TT0020

TERMINAL DEL LARGO RH LH 45406-39175 CET-75



<https://ikoyama.com/img/TT0017.png>

[https://ikoyama.com/img/TT0017\(2\).png](https://ikoyama.com/img/TT0017(2).png)

TOYOTA HILUX 4WD 22R 88/90 4Y 3L 90/ON

TT0017

TERMINAL DEL EXT LH 45047-39156 CET-73



<https://ikoyama.com/img/TT0019.png>

[https://ikoyama.com/img/TT0019\(2\).png](https://ikoyama.com/img/TT0019(2).png)

TOYOTA HILUX 4WD 22R 88/90 4Y 3L 90/ON

TT0019

TERMINAL DEL EXT LH CORTO 45047-35050 CET-58



<https://ikoyama.com/img/TT0016.png>

[https://ikoyama.com/img/TT0016\(2\).png](https://ikoyama.com/img/TT0016(2).png)

TOYOTA HILUX 4WD 22R 88/90 4Y 3L 90/ON

TT0016

TERMINAL DEL EXT RH 45046-39256 CET-72



<https://ikoyama.com/img/TT0018.png>

[https://ikoyama.com/img/TT0018\(2\).png](https://ikoyama.com/img/TT0018(2).png)

TOYOTA HILUX 4WD 22R 88/90 4Y 3L 90/ON

TT0018

TERMINAL DEL EXT RH CORTO 45046-35080 CET-57



<https://ikoyama.com/img/TT0031.png>

[https://ikoyama.com/img/TT0031\(2\).png](https://ikoyama.com/img/TT0031(2).png)

TOYOTA RAV 4

TT0031

TERMINAL DEL LH 45047-49135 SE-T221L



<https://ikoyama.com/img/TT0032.png>

[https://ikoyama.com/img/TT0032\(2\).png](https://ikoyama.com/img/TT0032(2).png)

TOYOTA RAV 4

TT0032

TERMINAL DEL RH 45046-49195 SE-T221R



<https://ikoyama.com/img/TT0023.png>

[https://ikoyama.com/img/TT0023\(2\).png](https://ikoyama.com/img/TT0023(2).png)

TOYOTA TERCEL 90/99

TT0023

TERMINAL DEL EXT RH LH 45046-19216 CET-84

<https://ikoyama.com/img/TT0024.png> [https://ikoyama.com/img/TT0024\(2\).png](https://ikoyama.com/img/TT0024(2).png)

TOYOTA YARIS 99/ON PROBOX 02/ON

TERMINAL DEL EXT LH 45047-59026 CET-98

TT0024



<https://ikoyama.com/img/TT0025.png> [https://ikoyama.com/img/TT0025\(2\).png](https://ikoyama.com/img/TT0025(2).png)

TOYOTA YARIS 99/ON PROBOX 02/ON

TERMINAL DEL EXT RH 45046-59026 CET-99

TT0025

<https://ikoyama.com/img/TT0029.png> [https://ikoyama.com/img/TT0029\(2\).png](https://ikoyama.com/img/TT0029(2).png)

TOYOTA YARIS ENVIDIA 06/13

TERMINAL DEL EXT LH 45047-59135 CET-167

TT0029



<https://ikoyama.com/img/TT0028.png> [https://ikoyama.com/img/TT0028\(2\).png](https://ikoyama.com/img/TT0028(2).png)

TOYOTA YARIS ENVIDIA 06/13

TERMINAL DEL EXT RH 45046-59195 CET-166

TT0028

<https://ikoyama.com/img/TT0027.png> [https://ikoyama.com/img/TT0027\(2\).png](https://ikoyama.com/img/TT0027(2).png)

TOYOTA YARIS ENVIDIA 14/ON

TERMINAL DEL EXT LH 45047-09370 CET-201L

TT0027



<https://ikoyama.com/img/TT0026.png> [https://ikoyama.com/img/TT0026\(2\).png](https://ikoyama.com/img/TT0026(2).png)

TOYOTA YARIS ENVIDIA 14/ON

TERMINAL DEL EXT RH 45046-09720 CET-201R

TT0026

Especialistas en:

TRAPECIOS



KOYAMA
SUSPENSION PARTS



<https://ikoyama.com/img/B1016.png>

[https://ikoyama.com/img/B1016\(2\).png](https://ikoyama.com/img/B1016(2).png)

HONDA ODYSSEY 05/10

BOCINA FLOT. TRAPECIO DEL INF 74X14.1X63 51360SHJA03

B1016



<https://ikoyama.com/img/B1011.png>

[https://ikoyama.com/img/B1011\(2\).png](https://ikoyama.com/img/B1011(2).png)

HYUNDAI ELANTRA 04/09 KIA CERATO 04/09

BOCINA FLOT. TRAPECIO DEL INF 63X14.5X55 5458417000

B1011



<https://ikoyama.com/img/B1009.png>

[https://ikoyama.com/img/B1009\(2\).png](https://ikoyama.com/img/B1009(2).png)

HYUNDAI I10 01/08 KIA PICANTO 01/05

BOCINA FLOTANTE TRAPECIO DEL INF 60X12X54.5 5458407000

B1009



<https://ikoyama.com/img/B1015.png>

[https://ikoyama.com/img/B1015\(2\).png](https://ikoyama.com/img/B1015(2).png)

HYUNDAI TUCSON 01/12 KIA SPORTAGE 02/10

BOCINA FLOT. TRAPECIO DEL INF 70X14.4X59.5 54584A6000

B1015



<https://ikoyama.com/img/B1012.png>

[https://ikoyama.com/img/B1012\(2\).png](https://ikoyama.com/img/B1012(2).png)

HYUNDAI TUCSON 04/10 ELANTRA 06/10 KIA SPORTAGE 04/10 CERATO

BOCINA FLOT. TRAPECIO DEL INF 66.3X14.4X60 545842B000

B1012



<https://ikoyama.com/img/B1006.png>

[https://ikoyama.com/img/B1006\(2\).png](https://ikoyama.com/img/B1006(2).png)

HYUNDAI TUCSON 04/10 ELANTRA 06/10 KIA SPORTAGE 04/10 CERATO

BOCINA TRAPECIO DEL INF 38X12.3X55 545001F000

B1006



<https://ikoyama.com/img/B1020.png>

[https://ikoyama.com/img/B1020\(2\).png](https://ikoyama.com/img/B1020(2).png)

MITSUBISHI L200 06/14

BOCINA TRAPECIO DEL INF 62X16.6X66 MR992256

B1020



<https://ikoyama.com/img/B1021.png>

[https://ikoyama.com/img/B1021\(2\).png](https://ikoyama.com/img/B1021(2).png)

NISSAN NAVARA 07/UP

BOCINA TRAPECIO DEL INF 43X14.3X74 54501EB70A

B1021



<https://ikoyama.com/img/B1019.png>

[https://ikoyama.com/img/B1019\(2\).png](https://ikoyama.com/img/B1019(2).png)

NISSAN SENTRA 06/16 XTRAIL T31 07/18 QASHAI 06/13

BOCINA FLOT. TRAPECIO DEL INF 58X12.3X53 54570EN002

B1019



<https://ikoyama.com/img/B1008.png>

[https://ikoyama.com/img/B1008\(2\).png](https://ikoyama.com/img/B1008(2).png)

NISSAN SENTRA B 16 07/12 XTRAIL 08/14

BOCINA FLOT. TRAPECIO DEL INF 59X12.1X53.9 54500JY00A

B1008



<https://ikoyama.com/img/B1013.png>

[https://ikoyama.com/img/B1013\(2\).png](https://ikoyama.com/img/B1013(2).png)

SUZUKI GRAN VITARA 06/14

BOCINA FLOT. TRAPECIO DEL INF 67X14.3X60 4520178K00

B1013



<https://ikoyama.com/img/B1017.png>

[https://ikoyama.com/img/B1017\(2\).png](https://ikoyama.com/img/B1017(2).png)

TOYOTA COROLLA 01/07 BYD F3

BOCINA FLOT. TRAPECIO DEL INF 76X14.2X60 4806812220

B1017



<https://ikoyama.com/img/B1007.png>

[https://ikoyama.com/img/B1007\(2\).png](https://ikoyama.com/img/B1007(2).png)

TOYOTA COROLLA 92/97

BOCINA FLOT. TRAPECIO DEL INF 56X12X58 4865512120

B1007



<https://ikoyama.com/img/B1014.png>

[https://ikoyama.com/img/B1014\(2\).png](https://ikoyama.com/img/B1014(2).png)

TOYOTA COROLLA 97/08

BOCINA FLOT. TRAPECIO DEL INF 68.4X14X59.5 4865512170

B1014



<https://ikoyama.com/img/B1003.png>

[https://ikoyama.com/img/B1003\(2\).png](https://ikoyama.com/img/B1003(2).png)

TOYOTA HILUX 1GD 2GD 15/UP

BOCINA TRAPECIO DEL INF GRANDE 48655-0K080

B1003



<https://ikoyama.com/img/B1004.png>

[https://ikoyama.com/img/B1004\(2\).png](https://ikoyama.com/img/B1004(2).png)

TOYOTA HILUX 1GD 2GD 15/UP

BOCINA TRAPECIO DEL INF PEQUEÑA 48654-0K080

B1004



<https://ikoyama.com/img/B1001.png>
TOYOTA HILUX 1KD 2KD 05/14

[https://ikoyama.com/img/B1001\(2\).png](https://ikoyama.com/img/B1001(2).png)

BOCINA TRAPECIO DEL INF GRANDE 48655-0K040

B1001



<https://ikoyama.com/img/B1002.png>
TOYOTA HILUX 1KD 2KD 05/14

[https://ikoyama.com/img/B1002\(2\).png](https://ikoyama.com/img/B1002(2).png)

BOCINA TRAPECIO DEL INF PEQUEÑA 48654-0K040

B1002



<https://ikoyama.com/img/B1005.png>
TOYOTA HILUX 1KD 2KD 1GD 2GD 05/UP

[https://ikoyama.com/img/B1005\(2\).png](https://ikoyama.com/img/B1005(2).png)

BOCINA TRAPECIO DEL SUP 48632-0K040

B1005



<https://ikoyama.com/img/B1018.png>
TOYOTA RAV4 06/18

[https://ikoyama.com/img/B1018\(2\).png](https://ikoyama.com/img/B1018(2).png)

BOCINA ARTICULADA BRAZO POSTERIOR 35X12.3X43 4877042040

B1018



<https://ikoyama.com/img/B1010.png>
TOYOTA YARIS 99/05

[https://ikoyama.com/img/B1010\(2\).png](https://ikoyama.com/img/B1010(2).png)

BOCINA FLOT. TRAPECIO DEL INF 61X12.1X58 4806859055

B1010



<https://ikoyama.com/img/T1001.png>
CHEVROLET AVEO SAIL 06/14

[https://ikoyama.com/img/T1001\(2\).png](https://ikoyama.com/img/T1001(2).png)

TRAPECIO DEL RH 96535081

T1001



<https://ikoyama.com/img/T1002.png>
CHEVROLET AVEO SAIL 06/15

[https://ikoyama.com/img/T1002\(2\).png](https://ikoyama.com/img/T1002(2).png)

TRAPECIO DEL LH 96535082

T1002



<https://ikoyama.com/img/T1008.png>
CHEVROLET N300 12/20

[https://ikoyama.com/img/T1008\(2\).png](https://ikoyama.com/img/T1008(2).png)

TRAPECIO DEL LH 24552619

T1008



<https://ikoyama.com/img/T1007.png>

[https://ikoyama.com/img/T1007\(2\).png](https://ikoyama.com/img/T1007(2).png)

CHEVROLET N300 12/20

T1007

TRAPECIO DEL RH 24552620



<https://ikoyama.com/img/T1143.png>

[https://ikoyama.com/img/T1143\(2\).png](https://ikoyama.com/img/T1143(2).png)

CHEVROLET NEW SAIL 1.5 16/18

T1143

TRAPECIO DEL LH 9065277



<https://ikoyama.com/img/T1142.png>

[https://ikoyama.com/img/T1142\(2\).png](https://ikoyama.com/img/T1142(2).png)

CHEVROLET NEW SAIL 1.5 16/18

T1142

TRAPECIO DEL RH 9065278



<https://ikoyama.com/img/T1219.png>

[https://ikoyama.com/img/T1219\(2\).png](https://ikoyama.com/img/T1219(2).png)

CHEVROLET OPTRA

T1219

TRAPECIO DEL DER 96415064



<https://ikoyama.com/img/T1218.png>

[https://ikoyama.com/img/T1218\(2\).png](https://ikoyama.com/img/T1218(2).png)

CHEVROLET OPTRA

T1218

TRAPECIO DEL IZQ 96415063



<https://ikoyama.com/img/T1006.png>

[https://ikoyama.com/img/T1006\(2\).png](https://ikoyama.com/img/T1006(2).png)

CHEVROLET SPARK 10/UP

T1006

TRAPECIO DEL LH 95032441



<https://ikoyama.com/img/T1005.png>

[https://ikoyama.com/img/T1005\(2\).png](https://ikoyama.com/img/T1005(2).png)

CHEVROLET SPARK 10/UP

T1005

TRAPECIO DEL RH 95032440



<https://ikoyama.com/img/T1185.png>

[https://ikoyama.com/img/T1185\(2\).png](https://ikoyama.com/img/T1185(2).png)

DAEWOO DAMAS 91/05 SUZUKI CARRY 85/90

T1185

TRAPECIO DEL RH LH 45200-85001 XCQKD-6



<https://ikoyama.com/img/T1145.png>
DAEWOO LANOS RACER 05/09
TRAPECIO DEL LH 96218397

T1145



<https://ikoyama.com/img/T1144.png>
DAEWOO LANOS RACER 05/09
TRAPECIO DEL RH 96218398

T1144



<https://ikoyama.com/img/T7069.png>
DONGFENG DFSK C37 MINIVAN
TRAPECIO DEL RH LH 2904300-CA01

T7069



<https://ikoyama.com/img/T1175.png>
HONDA CIVIC 01/05
TRAPECIO DEL DER 51350-S5A-A03

T1175



<https://ikoyama.com/img/T1174.png>
HONDA CIVIC 01/05
TRAPECIO DEL IZQ 51360-S5A-A03

T1174



<https://ikoyama.com/img/T1229.png>
HONDA CIVIC 11/14
TRAPECIO DEL DER 51360-TR0-A01

T1229



<https://ikoyama.com/img/T1228.png>
HONDA CIVIC 11/14
TRAPECIO DEL IZQ 51350-TR0-A01

T1228



<https://ikoyama.com/img/T1173.png>
HONDA CIVIC 96/00
TRAPECIO DEL INF DER 51350-S04-000

T1173



<https://ikoyama.com/img/T1173L.png>

[https://ikoyama.com/img/T1173L\(2\).png](https://ikoyama.com/img/T1173L(2).png)

HONDA CIVIC 96/00

TRAPECIO DEL INF IZQ 51360-S04-000

T1173L



<https://ikoyama.com/img/T1205.png>

[https://ikoyama.com/img/T1205\(2\).png](https://ikoyama.com/img/T1205(2).png)

HONDA CRV 06/11

TRAPECIO DEL DER 51350-SWA-A01

T1205



<https://ikoyama.com/img/T1204.png>

[https://ikoyama.com/img/T1204\(2\).png](https://ikoyama.com/img/T1204(2).png)

HONDA CRV 06/11

TRAPECIO DEL IZQ 51360-SWA-A01

T1204



<https://ikoyama.com/img/T1191.png>

[https://ikoyama.com/img/T1191\(2\).png](https://ikoyama.com/img/T1191(2).png)

HONDA CRV 11/15

TRAPECIO DEL DER 51350-T0T-H11

T1191



<https://ikoyama.com/img/T1190.png>

[https://ikoyama.com/img/T1190\(2\).png](https://ikoyama.com/img/T1190(2).png)

HONDA CRV 11/15

TRAPECIO DEL IZQ 51360-T0T-H11

T1190



<https://ikoyama.com/img/T1021.png>

[https://ikoyama.com/img/T1021\(2\).png](https://ikoyama.com/img/T1021(2).png)

HYUNDAI H-1 KIA 07/15

TRAPECIO DEL LH 54500-4H000

T1021



<https://ikoyama.com/img/T1022.png>

[https://ikoyama.com/img/T1022\(2\).png](https://ikoyama.com/img/T1022(2).png)

HYUNDAI H-1 KIA 07/15

TRAPECIO DEL RH 54501-4H000

T1022



<https://ikoyama.com/img/T1116.png>

[https://ikoyama.com/img/T1116\(2\).png](https://ikoyama.com/img/T1116(2).png)

HYUNDAI/KIA ACCENT 11/15

TRAPECIO DEL LH 54500-1R000

T1116



<https://ikoyama.com/img/T1117.png>
HYUNDAI/KIA ACCENT 11/15

[https://ikoyama.com/img/T1117\(2\).png](https://ikoyama.com/img/T1117(2).png)

TRAPECIO DEL RH 54501-1R000

T1117



<https://ikoyama.com/img/T1013.png>

[https://ikoyama.com/img/T1013\(2\).png](https://ikoyama.com/img/T1013(2).png)

HYUNDAI/KIA ACCENT/RIO S/ROTULA 06/11

TRAPECIO DEL LH S/ROTULA 54500-1E000

T1013



<https://ikoyama.com/img/T1014.png>

[https://ikoyama.com/img/T1014\(2\).png](https://ikoyama.com/img/T1014(2).png)

HYUNDAI/KIA ACCENT/RIO S/ROTULA 06/11

TRAPECIO DEL RH S/ROTULA 54501-1E000

T1014



<https://ikoyama.com/img/T1134.png>

[https://ikoyama.com/img/T1134\(2\).png](https://ikoyama.com/img/T1134(2).png)

HYUNDAI/KIA ELANTRA G4FG 11/UP i30 12/UP VELOSTER 12/15

TRAPECIO DEL LH 54500-3X000

T1134



<https://ikoyama.com/img/T1135.png>

[https://ikoyama.com/img/T1135\(2\).png](https://ikoyama.com/img/T1135(2).png)

HYUNDAI/KIA ELANTRA G4FG 11/UP i30 12/UP VELOSTER 12/15

TRAPECIO DEL RH 54501-3X000

T1135



<https://ikoyama.com/img/T1131.png>

[https://ikoyama.com/img/T1131\(2\).png](https://ikoyama.com/img/T1131(2).png)

HYUNDAI/KIA EON 11/UP

TRAPECIO DEL LH 54500-4N000

T1131



<https://ikoyama.com/img/T1130.png>

[https://ikoyama.com/img/T1130\(2\).png](https://ikoyama.com/img/T1130(2).png)

HYUNDAI/KIA EON 11/UP

TRAPECIO DEL RH 54501-4N000

T1130



<https://ikoyama.com/img/T1147.png>

[https://ikoyama.com/img/T1147\(2\).png](https://ikoyama.com/img/T1147(2).png)

HYUNDAI/KIA GRAND i10 14/UP

TRAPECIO DEL LH 54500-B4000

T1147



<https://ikoyama.com/img/T1146.png>
HYUNDAI/KIA GRAND i10 14/UP

[https://ikoyama.com/img/T1146\(2\).png](https://ikoyama.com/img/T1146(2).png)

TRAPECIO DEL RH 54501-B4000

T1146



<https://ikoyama.com/img/T1124.png>
HYUNDAI/KIA H100 97/UP PORTER 96/16

[https://ikoyama.com/img/T1124\(2\).png](https://ikoyama.com/img/T1124(2).png)

TRAPECIO DEL LH INF 54510-4B000

T1124



<https://ikoyama.com/img/T1132.png>
HYUNDAI/KIA H100 97/UP PORTER 96/16

[https://ikoyama.com/img/T1132\(2\).png](https://ikoyama.com/img/T1132(2).png)

TRAPECIO DEL LH SUP 54410-4B000

T1132



<https://ikoyama.com/img/T1125.png>
HYUNDAI/KIA H100 97/UP PORTER 96/16

[https://ikoyama.com/img/T1125\(2\).png](https://ikoyama.com/img/T1125(2).png)

TRAPECIO DEL RH INF 54540-4B000

T1125



<https://ikoyama.com/img/T1133.png>
HYUNDAI/KIA H100 97/UP PORTER 96/16

[https://ikoyama.com/img/T1133\(2\).png](https://ikoyama.com/img/T1133(2).png)

TRAPECIO DEL RH SUP 54430-4B000

T1133



<https://ikoyama.com/img/T1149.png>
HYUNDAI/KIA i10 08/10

[https://ikoyama.com/img/T1149\(2\).png](https://ikoyama.com/img/T1149(2).png)

TRAPECIO DEL LH 54500-0X000

T1149



<https://ikoyama.com/img/T1148.png>
HYUNDAI/KIA i10 08/10

[https://ikoyama.com/img/T1148\(2\).png](https://ikoyama.com/img/T1148(2).png)

TRAPECIO DEL RH 54501-0X000

T1148



<https://ikoyama.com/img/T1154.png>
HYUNDAI/KIA NEW ELANTRA 17/19

[https://ikoyama.com/img/T1154\(2\).png](https://ikoyama.com/img/T1154(2).png)

TRAPECIO DEL LH 54500-F3000

T1154



<https://ikoyama.com/img/T1153.png>

[https://ikoyama.com/img/T1153\(2\).png](https://ikoyama.com/img/T1153(2).png)

HYUNDAI/KIA NEW ELANTRA 17/19

TRAPECIO DEL RH 54501-F3000

T1153



<https://ikoyama.com/img/T1128.png>

[https://ikoyama.com/img/T1128\(2\).png](https://ikoyama.com/img/T1128(2).png)

HYUNDAI/KIA SANTA FE 12/UP

TRAPECIO DEL LH 54500-2W000

T1128



<https://ikoyama.com/img/T1129.png>

[https://ikoyama.com/img/T1129\(2\).png](https://ikoyama.com/img/T1129(2).png)

HYUNDAI/KIA SANTA FE 12/UP

TRAPECIO DEL RH 54501-2W000

T1129



<https://ikoyama.com/img/T1122.png>

[https://ikoyama.com/img/T1122\(2\).png](https://ikoyama.com/img/T1122(2).png)

HYUNDAI/KIA SONATA/OPTIMA 99/06

TRAPECIO DEL LH INF S/ROTULA 54500-38000

T1122



<https://ikoyama.com/img/T1123.png>

[https://ikoyama.com/img/T1123\(2\).png](https://ikoyama.com/img/T1123(2).png)

HYUNDAI/KIA SONATA/OPTIMA 99/06

TRAPECIO DEL RH INF S/ROTULA 54501-38000

T1123



<https://ikoyama.com/img/T1120.png>

[https://ikoyama.com/img/T1120\(2\).png](https://ikoyama.com/img/T1120(2).png)

HYUNDAI/KIA SONATA/OPTIMA 99/06

TRAPECIO DEL LH SUP 54410-38000

T1120



<https://ikoyama.com/img/T1121.png>

[https://ikoyama.com/img/T1121\(2\).png](https://ikoyama.com/img/T1121(2).png)

HYUNDAI/KIA SONATA/OPTIMA 99/06

TRAPECIO DEL RH SUP 54420-38000

T1121



<https://ikoyama.com/img/T1215.png>

[https://ikoyama.com/img/T1215\(2\).png](https://ikoyama.com/img/T1215(2).png)

HYUNDAI/KIA TUCSON 05/09 SPORTAGE 05/09

TRAPECIO DEL DER 54501-2E000

T1215



<https://ikoyama.com/img/T1214.png> [https://ikoyama.com/img/T1214\(2\).png](https://ikoyama.com/img/T1214(2).png)
HYUNDAI/KIA TUCSON 05/09 SPORTAGE 05/09

TRAPECIO DEL IZQ 54500-2E000

T1214



<https://ikoyama.com/img/T1042.png> [https://ikoyama.com/img/T1042\(2\).png](https://ikoyama.com/img/T1042(2).png)
HYUNDAI/KIA TUCSON/SPORTAGE 10/15

TRAPECIO DEL LH 54501-2S000

T1042



<https://ikoyama.com/img/T1041.png> [https://ikoyama.com/img/T1041\(2\).png](https://ikoyama.com/img/T1041(2).png)
HYUNDAI/KIA TUCSON/SPORTAGE 10/15

TRAPECIO DEL RH 54500-2S000

T1041



<https://ikoyama.com/img/T1136.png> [https://ikoyama.com/img/T1136\(2\).png](https://ikoyama.com/img/T1136(2).png)
KIA CERATO 13/18

TRAPECIO DEL LH 54500-A7000

T1136



<https://ikoyama.com/img/T1137.png> [https://ikoyama.com/img/T1137\(2\).png](https://ikoyama.com/img/T1137(2).png)
KIA CERATO 13/18

TRAPECIO DEL RH 54501-A7000

T1137



<https://ikoyama.com/img/T1045.png> [https://ikoyama.com/img/T1045\(2\).png](https://ikoyama.com/img/T1045(2).png)
KIA PICANTO 08/11

TRAPECIO DEL LH 54500-07160

T1045



<https://ikoyama.com/img/T1046.png> [https://ikoyama.com/img/T1046\(2\).png](https://ikoyama.com/img/T1046(2).png)
KIA PICANTO 08/11

TRAPECIO DEL RH 54501-07160

T1046



<https://ikoyama.com/img/T1047.png> [https://ikoyama.com/img/T1047\(2\).png](https://ikoyama.com/img/T1047(2).png)
KIA PICANTO 11/15

TRAPECIO DEL LH 54500-1Y000

T1047



<https://ikoyama.com/img/T1048.png>

[https://ikoyama.com/img/T1048\(2\).png](https://ikoyama.com/img/T1048(2).png)

KIA PICANTO 11/15

TRAPECIO DEL RH 54501-1Y000

T1048



<https://ikoyama.com/img/T1223.png>

[https://ikoyama.com/img/T1223\(2\).png](https://ikoyama.com/img/T1223(2).png)

KIA PICANTO 16/19

TRAPECIO DEL DER 54501-G6000

T1223



<https://ikoyama.com/img/T1222.png>

[https://ikoyama.com/img/T1222\(2\).png](https://ikoyama.com/img/T1222(2).png)

KIA PICANTO 16/19

TRAPECIO DEL IZQ 54500-G6000

T1222



<https://ikoyama.com/img/T1118.png>

[https://ikoyama.com/img/T1118\(2\).png](https://ikoyama.com/img/T1118(2).png)

KIA RIO 11/15

TRAPECIO DEL LH 54500-1W000

T1118



<https://ikoyama.com/img/T1119.png>

[https://ikoyama.com/img/T1119\(2\).png](https://ikoyama.com/img/T1119(2).png)

KIA RIO 11/15

TRAPECIO DEL RH 54501-1W000

T1119



<https://ikoyama.com/img/T1126.png>

[https://ikoyama.com/img/T1126\(2\).png](https://ikoyama.com/img/T1126(2).png)

KIA SORENTO 09/14

TRAPECIO DEL LH 54500-2P000

T1126



<https://ikoyama.com/img/T1127.png>

[https://ikoyama.com/img/T1127\(2\).png](https://ikoyama.com/img/T1127(2).png)

KIA SORENTO 09/14

TRAPECIO DEL RH 54501-2P000

T1127



<https://ikoyama.com/img/T1201.png>

[https://ikoyama.com/img/T1201\(2\).png](https://ikoyama.com/img/T1201(2).png)

KIA SORENTO 14/17

TRAPECIO DEL DER 54501-C5000

T1201



<https://ikoyama.com/img/T1200.png>

[https://ikoyama.com/img/T1200\(2\).png](https://ikoyama.com/img/T1200(2).png)

KIA SORENTO 14/17

TRAPECIO DEL IZQ 54500-C5000

T1200



<https://ikoyama.com/img/T1203.png>

[https://ikoyama.com/img/T1203\(2\).png](https://ikoyama.com/img/T1203(2).png)

KIA SOUL 14/18

TRAPECIO DEL DER 54501-B2000

T1203



<https://ikoyama.com/img/T1202.png>

[https://ikoyama.com/img/T1202\(2\).png](https://ikoyama.com/img/T1202(2).png)

KIA SOUL 14/18

TRAPECIO DEL IZQ 54500-B2000

T1202



<https://ikoyama.com/img/T1161.png>

[https://ikoyama.com/img/T1161\(2\).png](https://ikoyama.com/img/T1161(2).png)

MAZDA 2 DEMIO 07/13

TRAPECIO DEL DER D651-34-300

T1161



<https://ikoyama.com/img/T1162.png>

[https://ikoyama.com/img/T1162\(2\).png](https://ikoyama.com/img/T1162(2).png)

MAZDA 2 DEMIO 07/13

TRAPECIO DEL IZQ D651-34-350

T1162



<https://ikoyama.com/img/T1193.png>

[https://ikoyama.com/img/T1193\(2\).png](https://ikoyama.com/img/T1193(2).png)

MAZDA 3 5 13/16

TRAPECIO DEL DER ABRA+ BBM2-34-300

T1193



<https://ikoyama.com/img/T1192.png>

[https://ikoyama.com/img/T1192\(2\).png](https://ikoyama.com/img/T1192(2).png)

MAZDA 3 5 13/16

TRAPECIO DEL IZQ ABRA+ BBM2-34-350

T1192



<https://ikoyama.com/img/T1217.png>

[https://ikoyama.com/img/T1217\(2\).png](https://ikoyama.com/img/T1217(2).png)

MAZDA 3 5 AXELA 03/12

TRAPECIO DEL DER ABRA- B32H-34-300A

T1217



<https://ikoyama.com/img/T1216.png>

[https://ikoyama.com/img/T1216\(2\).png](https://ikoyama.com/img/T1216(2).png)

MAZDA 3 5 AXELA 03/12

TRAPECIO DEL IZQ ABRA- B32H-34-350A

T1216



<https://ikoyama.com/img/T1210.png>

[https://ikoyama.com/img/T1210\(2\).png](https://ikoyama.com/img/T1210(2).png)

MAZDA/ FORD BT50 RANGER 11/16

TRAPECIO DEL LH INF UC25-34-350

T1210



<https://ikoyama.com/img/T1211.png>

[https://ikoyama.com/img/T1211\(2\).png](https://ikoyama.com/img/T1211(2).png)

MAZDA/ FORD BT50 RANGER 11/16

TRAPECIO DEL RH INF UC25-34-300

T1211



<https://ikoyama.com/img/T1208.png>

[https://ikoyama.com/img/T1208\(2\).png](https://ikoyama.com/img/T1208(2).png)

MAZDA/ FORD BT50 RANGER 11/UP

TRAPECIO DEL LH SUP UC3C-34-250D

T1208



<https://ikoyama.com/img/T1209.png>

[https://ikoyama.com/img/T1209\(2\).png](https://ikoyama.com/img/T1209(2).png)

MAZDA/ FORD BT50 RANGER 11/UP

TRAPECIO DEL RH SUP UC3C-34-200D

T1209



<https://ikoyama.com/img/T1197.png>

[https://ikoyama.com/img/T1197\(2\).png](https://ikoyama.com/img/T1197(2).png)

MITSUBISHI L200 06/14

TRAPECIO DEL SUP DER 4010A014

T1197



<https://ikoyama.com/img/T1196.png>

[https://ikoyama.com/img/T1196\(2\).png](https://ikoyama.com/img/T1196(2).png)

MITSUBISHI L200 06/14

TRAPECIO DEL SUP IZQ 4010A013

T1196



<https://ikoyama.com/img/T1195.png>

[https://ikoyama.com/img/T1195\(2\).png](https://ikoyama.com/img/T1195(2).png)

MITSUBISHI L200 4X4 06/14

TRAPECIO DEL INF DER 4013A088

T1195



<https://ikoyama.com/img/T1194.png>

[https://ikoyama.com/img/T1194\(2\).png](https://ikoyama.com/img/T1194(2).png)

MITSUBISHI L200 4X4 06/14

T1194

TRAPECIO DEL INF IZQ 4013A087



<https://ikoyama.com/img/T1172.png>

[https://ikoyama.com/img/T1172\(2\).png](https://ikoyama.com/img/T1172(2).png)

MITSUBISHI L200 4X4 15/19

T1172

TRAPECIO DEL INF DER 4013A472



<https://ikoyama.com/img/T1171.png>

[https://ikoyama.com/img/T1171\(2\).png](https://ikoyama.com/img/T1171(2).png)

MITSUBISHI L200 4X4 15/19

T1171

TRAPECIO DEL INF IZQ 4013A471



<https://ikoyama.com/img/T1170.png>

[https://ikoyama.com/img/T1170\(2\).png](https://ikoyama.com/img/T1170(2).png)

MITSUBISHI L200 4X4 15/19

T1170

TRAPECIO DEL SUP DER 4010A148



<https://ikoyama.com/img/T1169.png>

[https://ikoyama.com/img/T1169\(2\).png](https://ikoyama.com/img/T1169(2).png)

MITSUBISHI L200 4X4 15/19

T1169

TRAPECIO DEL SUP IZQ 4010A147



<https://ikoyama.com/img/T1166.png>

[https://ikoyama.com/img/T1166\(2\).png](https://ikoyama.com/img/T1166(2).png)

MITSUBISHI MIRAGE 12/17

T1166

TRAPECIO DEL DER 4013A310



<https://ikoyama.com/img/T1165.png>

[https://ikoyama.com/img/T1165\(2\).png](https://ikoyama.com/img/T1165(2).png)

MITSUBISHI MIRAGE 12/17

T1165

TRAPECIO DEL IZQ 4013A309



<https://ikoyama.com/img/T1114.png>

[https://ikoyama.com/img/T1114\(2\).png](https://ikoyama.com/img/T1114(2).png)

NISSAN NAVARA 4X4 07/UP

T1114

TRAPECIO DEL LH INF 54501-EB70A



<https://ikoyama.com/img/T1230.png>

[https://ikoyama.com/img/T1230\(2\).png](https://ikoyama.com/img/T1230(2).png)

NISSAN NAVARA 4X4 07/UP

TRAPECIO DEL LH INF 54501-EB70A

T1230



<https://ikoyama.com/img/T1112.png>

[https://ikoyama.com/img/T1112\(2\).png](https://ikoyama.com/img/T1112(2).png)

NISSAN NAVARA 4X4 07/UP

TRAPECIO DEL LH SUP 54525-EB70D

T1112



<https://ikoyama.com/img/T1115.png>

[https://ikoyama.com/img/T1115\(2\).png](https://ikoyama.com/img/T1115(2).png)

NISSAN NAVARA 4X4 07/UP

TRAPECIO DEL RH INF 54500-EB70A

T1115



<https://ikoyama.com/img/T1231.png>

[https://ikoyama.com/img/T1231\(2\).png](https://ikoyama.com/img/T1231(2).png)

NISSAN NAVARA 4X4 07/UP

TRAPECIO DEL RH INF 54500-EB70A

T1231



<https://ikoyama.com/img/T1113.png>

[https://ikoyama.com/img/T1113\(2\).png](https://ikoyama.com/img/T1113(2).png)

NISSAN NAVARA 4X4 07/UP

TRAPECIO DEL RH SUP 54524-E870D

T1113



<https://ikoyama.com/img/T1003.png>

[https://ikoyama.com/img/T1003\(2\).png](https://ikoyama.com/img/T1003(2).png)

NISSAN NV 350 14/UP

TRAPECIO DEL INF LH 545013XA0A

T1003



<https://ikoyama.com/img/T1004.png>

[https://ikoyama.com/img/T1004\(2\).png](https://ikoyama.com/img/T1004(2).png)

NISSAN NV 350 14/UP

TRAPECIO DEL INF RH 545003XA0A

T1004



<https://ikoyama.com/img/T1059.png>

[https://ikoyama.com/img/T1059\(2\).png](https://ikoyama.com/img/T1059(2).png)

NISSAN SENTRA B13 SUNNY 90/95

TRAPECIO DEL LH 54501-52Y10

T1059



<https://ikoyama.com/img/T1060.png>

[https://ikoyama.com/img/T1060\(2\).png](https://ikoyama.com/img/T1060(2).png)

NISSAN SENTRA B13 SUNNY 90/95

T1060

TRAPECIO DEL RH 54500-52Y10



<https://ikoyama.com/img/T1061.png>

[https://ikoyama.com/img/T1061\(2\).png](https://ikoyama.com/img/T1061(2).png)

NISSAN SENTRA B14 SUNNY ALMERA 96/99

T1061

TRAPECIO DEL LH 54501-0M010



<https://ikoyama.com/img/T1062.png>

[https://ikoyama.com/img/T1062\(2\).png](https://ikoyama.com/img/T1062(2).png)

NISSAN SENTRA B14 SUNNY ALMERA 96/99

T1062

TRAPECIO DEL RH 54500-0M010



<https://ikoyama.com/img/T1063.png>

[https://ikoyama.com/img/T1063\(2\).png](https://ikoyama.com/img/T1063(2).png)

NISSAN SENTRA B15 SUNNY 00/06 ALMERA 00/13

T1063

TRAPECIO DEL LH 54501-4M410



<https://ikoyama.com/img/T1064.png>

[https://ikoyama.com/img/T1064\(2\).png](https://ikoyama.com/img/T1064(2).png)

NISSAN SENTRA B15 SUNNY 00/06 ALMERA 00/13

T1064

TRAPECIO DEL RH 54500-4M410



<https://ikoyama.com/img/T1065.png>

[https://ikoyama.com/img/T1065\(2\).png](https://ikoyama.com/img/T1065(2).png)

NISSAN TIIDA AD 05/14 WINGROAD 07/12

T1065

TRAPECIO DEL LH 54501-EW000



<https://ikoyama.com/img/T1066.png>

[https://ikoyama.com/img/T1066\(2\).png](https://ikoyama.com/img/T1066(2).png)

NISSAN TIIDA AD 05/14 WINGROAD 07/12

T1066

TRAPECIO DEL RH 54500-EW000



<https://ikoyama.com/img/T1108.png>

[https://ikoyama.com/img/T1108\(2\).png](https://ikoyama.com/img/T1108(2).png)

NISSAN URVAN 00/12 CARAVAN HOMY 01/12 URVAN 12/UP

T1108

TRAPECIO DEL LH SUP 54525-VX100



<https://ikoyama.com/img/T1109.png> [https://ikoyama.com/img/T1109\(2\).png](https://ikoyama.com/img/T1109(2).png)

NISSAN URVAN 00/12 CARAVAN HOMY 01/12 URVAN 12/UP

TRAPECIO DEL RH SUP 54524-VX100

T1109



<https://ikoyama.com/img/T1106.png> [https://ikoyama.com/img/T1106\(2\).png](https://ikoyama.com/img/T1106(2).png)

NISSAN VERSA 12/17 MARCH 10/UP ALMERA 11/16

TRAPECIO DEL LH 54501-1HM0B

T1106



<https://ikoyama.com/img/T1107.png> [https://ikoyama.com/img/T1107\(2\).png](https://ikoyama.com/img/T1107(2).png)

NISSAN VERSA 12/17 MARCH 10/UP ALMERA 11/16

TRAPECIO DEL RH 54500-1HM0B

T1107



<https://ikoyama.com/img/T1227.png> [https://ikoyama.com/img/T1227\(2\).png](https://ikoyama.com/img/T1227(2).png)

NISSAN X-TRAIL QASHQAI 08/13

TRAPECIO DEL DER 54500-JG000

T1227



<https://ikoyama.com/img/T1226.png> [https://ikoyama.com/img/T1226\(2\).png](https://ikoyama.com/img/T1226(2).png)

NISSAN X-TRAIL QASHQAI 08/13

TRAPECIO DEL IZQ 54501-JG000

T1226



<https://ikoyama.com/img/T1183.png> [https://ikoyama.com/img/T1183\(2\).png](https://ikoyama.com/img/T1183(2).png)

RENAULT LOGAN 04/12 SANDERO STEPWAY 08/17

TRAPECIO DEL DER 6001547519

T1183



<https://ikoyama.com/img/T1182.png> [https://ikoyama.com/img/T1182\(2\).png](https://ikoyama.com/img/T1182(2).png)

RENAULT LOGAN 04/12 SANDERO STEPWAY 08/17

TRAPECIO DEL IZQ 6001547520

T1182



<https://ikoyama.com/img/T1176.png> [https://ikoyama.com/img/T1176\(2\).png](https://ikoyama.com/img/T1176(2).png)

RENAULT LOGAN 12/17

TRAPECIO DEL LH 545010294R

T1176



<https://ikoyama.com/img/T1177.png>

[https://ikoyama.com/img/T1177\(2\).png](https://ikoyama.com/img/T1177(2).png)

RENAULT LOGAN 12/17

TRAPECIO DEL RH 545004529R

T1177



<https://ikoyama.com/img/T1241.png>

[https://ikoyama.com/img/T1241\(2\).png](https://ikoyama.com/img/T1241(2).png)

RENAULT MASTER III

TRAPECIO DEL LH 8200688871

T1241



<https://ikoyama.com/img/T1240.png>

[https://ikoyama.com/img/T1240\(2\).png](https://ikoyama.com/img/T1240(2).png)

RENAULT MASTER III

TRAPECIO DEL RH 8200688875

T1240



<https://ikoyama.com/img/T1206.png>

[https://ikoyama.com/img/T1206\(2\).png](https://ikoyama.com/img/T1206(2).png)

SUBARU FORESTER 08/13

TRAPECIO DEL DER 20202SC002

T1206



<https://ikoyama.com/img/T1207.png>

[https://ikoyama.com/img/T1207\(2\).png](https://ikoyama.com/img/T1207(2).png)

SUBARU FORESTER 08/13

TRAPECIO DEL IZQ 20202SC011

T1207



<https://ikoyama.com/img/T1070.png>

[https://ikoyama.com/img/T1070\(2\).png](https://ikoyama.com/img/T1070(2).png)

SUZUKI ALTO / DAEWOO TICO MATIZ / CHERY QQ 11/UP

TRAPECIO DEL RH LH 45200-84000

T1070



<https://ikoyama.com/img/T1152.png>

[https://ikoyama.com/img/T1152\(2\).png](https://ikoyama.com/img/T1152(2).png)

SUZUKI ALTO 13/16

TRAPECIO DEL RH LH 45200-M50E30

T1152



<https://ikoyama.com/img/T1178.png>

[https://ikoyama.com/img/T1178\(2\).png](https://ikoyama.com/img/T1178(2).png)

SUZUKI ALTO K10

TRAPECIO DEL LH 45201-58J10

T1178


<https://ikoyama.com/img/T1179.png>
[https://ikoyama.com/img/T1179\(2\).png](https://ikoyama.com/img/T1179(2).png)

SUZUKI ALTO K10

T1179

TRAPECIO DEL RH 45202-58J10


<https://ikoyama.com/img/T1069.png>
[https://ikoyama.com/img/T1069\(2\).png](https://ikoyama.com/img/T1069(2).png)

SUZUKI APV TODOS

T1069

TRAPECIO DEL RH LH 45200-77500


<https://ikoyama.com/img/T1199.png>
[https://ikoyama.com/img/T1199\(2\).png](https://ikoyama.com/img/T1199(2).png)

SUZUKI GRAND VITARA GRAND NOMADE 06/13

T1199

TRAPECIO DEL DER 45201-78K00


<https://ikoyama.com/img/T1198.png>
[https://ikoyama.com/img/T1198\(2\).png](https://ikoyama.com/img/T1198(2).png)

SUZUKI GRAND VITARA GRAND NOMADE 06/13

T1198

TRAPECIO DEL IZQ 45202-78K00


<https://ikoyama.com/img/T1213.png>
[https://ikoyama.com/img/T1213\(2\).png](https://ikoyama.com/img/T1213(2).png)

SUZUKI SWIFT 05/10

T1213

TRAPECIO DEL SUP DER 45201-63J00


<https://ikoyama.com/img/T1212.png>
[https://ikoyama.com/img/T1212\(2\).png](https://ikoyama.com/img/T1212(2).png)

SUZUKI SWIFT 05/10

T1212

TRAPECIO DEL SUP IZQ 45202-63J00


<https://ikoyama.com/img/T1163.png>
[https://ikoyama.com/img/T1163\(2\).png](https://ikoyama.com/img/T1163(2).png)

SUZUKI SWIFT 11/15

T1163

TRAPECIO DEL DER 45201-72L00


<https://ikoyama.com/img/T1164.png>
[https://ikoyama.com/img/T1164\(2\).png](https://ikoyama.com/img/T1164(2).png)

SUZUKI SWIFT 11/15

T1164

TRAPECIO DEL IZQ 45202-72L00



<https://ikoyama.com/img/T1180.png>

[https://ikoyama.com/img/T1180\(2\).png](https://ikoyama.com/img/T1180(2).png)

SUZUKI SWIFT 11/15

TRAPECIO DEL LH 45202-72L00

T1180



<https://ikoyama.com/img/T1181.png>

[https://ikoyama.com/img/T1181\(2\).png](https://ikoyama.com/img/T1181(2).png)

SUZUKI SWIFT 11/15

TRAPECIO DEL RH 45201-72L00

T1181



<https://ikoyama.com/img/T1184.png>

[https://ikoyama.com/img/T1184\(2\).png](https://ikoyama.com/img/T1184(2).png)

SUZUKI SWIFT IGNIS 00/05

TRAPECIO DEL 45200-76G20

T1184



<https://ikoyama.com/img/T1160.png>

[https://ikoyama.com/img/T1160\(2\).png](https://ikoyama.com/img/T1160(2).png)

TOYOTA AVANZA 13/21

TRAPECIO DEL DER 48068-BZ160

T1160



<https://ikoyama.com/img/T1159.png>

[https://ikoyama.com/img/T1159\(2\).png](https://ikoyama.com/img/T1159(2).png)

TOYOTA AVANZA 13/21

TRAPECIO DEL IZQ 48069-BZ160

T1159



<https://ikoyama.com/img/T1236.png>

[https://ikoyama.com/img/T1236\(2\).png](https://ikoyama.com/img/T1236(2).png)

TOYOTA AVANZA 22/UP

TRAPECIO DEL LH 48069-BZ430

T1236



<https://ikoyama.com/img/T1237.png>

[https://ikoyama.com/img/T1237\(2\).png](https://ikoyama.com/img/T1237(2).png)

TOYOTA AVANZA 22/UP

TRAPECIO DEL RH 48068-BZ430

T1237



<https://ikoyama.com/img/T1168.png>

[https://ikoyama.com/img/T1168\(2\).png](https://ikoyama.com/img/T1168(2).png)

TOYOTA CALDINA CORONA 92/98 CARINA 92/97

TRAPECIO DEL DER 48068-20260

T1168



<https://ikoyama.com/img/T1167.png> [https://ikoyama.com/img/T1167\(2\).png](https://ikoyama.com/img/T1167(2).png)

TOYOTA CALDINA CORONA 92/98 CARINA 92/97

TRAPECIO DEL IZQ 48069-20260

T1167



<https://ikoyama.com/img/T1079.png> [https://ikoyama.com/img/T1079\(2\).png](https://ikoyama.com/img/T1079(2).png)

TOYOTA COROLLA 07/13 AURIS 08/UP PRIUS 12/UP 07/13

TRAPECIO DEL LH S/ROTULA 48069-12300

T1079



<https://ikoyama.com/img/T1080.png> [https://ikoyama.com/img/T1080\(2\).png](https://ikoyama.com/img/T1080(2).png)

TOYOTA COROLLA 07/13 AURIS 08/UP PRIUS 12/UP 07/13

TRAPECIO DEL RH S/ROTULA 48068-12300

T1080



<https://ikoyama.com/img/T1096.png> [https://ikoyama.com/img/T1096\(2\).png](https://ikoyama.com/img/T1096(2).png)

TOYOTA COROLLA 2C 3C SW 95/02 2ZRFE 11/14

TRAPECIO DEL LH INF S/ROTULA 48069-12170

T1096



<https://ikoyama.com/img/T1097.png> [https://ikoyama.com/img/T1097\(2\).png](https://ikoyama.com/img/T1097(2).png)

TOYOTA COROLLA 2C 3C SW 95/02 2ZRFE 11/14

TRAPECIO DEL RH INF S/ROTULA 48068-12170

T1097



<https://ikoyama.com/img/T1077.png> [https://ikoyama.com/img/T1077\(2\).png](https://ikoyama.com/img/T1077(2).png)

TOYOTA COROLLA S/ROTULA 01/07 COROLLON

TRAPECIO DEL LH S/ROTULA 48069-12260

T1077



<https://ikoyama.com/img/T1078.png> [https://ikoyama.com/img/T1078\(2\).png](https://ikoyama.com/img/T1078(2).png)

TOYOTA COROLLA S/ROTULA 01/07 COROLLON

TRAPECIO DEL RH S/ROTULA 48068-12260

T1078



<https://ikoyama.com/img/T1188.png> [https://ikoyama.com/img/T1188\(2\).png](https://ikoyama.com/img/T1188(2).png)

TOYOTA HIACE 3L JINBEI FOTON KINGLONG

TRAPECIO DEL SUP DER 48066-29075

T1188



<https://ikoyama.com/img/T1155.png>

[https://ikoyama.com/img/T1155\(2\).png](https://ikoyama.com/img/T1155(2).png)

TOYOTA HIACE 3L JINBEI FOTON KINGLONG

TRAPECIO DEL SUP IZQ 48067-29075

T1155



<https://ikoyama.com/img/T1187.png>

[https://ikoyama.com/img/T1187\(2\).png](https://ikoyama.com/img/T1187(2).png)

TOYOTA HIACE 3L JINBEI FOTON KINGLONG

TRAPECIO DEL SUP IZQ 48067-29075

T1187



<https://ikoyama.com/img/T1111.png>

[https://ikoyama.com/img/T1111\(2\).png](https://ikoyama.com/img/T1111(2).png)

TOYOTA HIACE 5L COMMUTER VAN 05/UP

TRAPECIO DEL INF LH 48069-26160

T1111



<https://ikoyama.com/img/T1110.png>

[https://ikoyama.com/img/T1110\(2\).png](https://ikoyama.com/img/T1110(2).png)

TOYOTA HIACE 5L COMMUTER VAN 05/UP

TRAPECIO DEL INF RH 48068-26160

T1110



<https://ikoyama.com/img/T1104.png>

[https://ikoyama.com/img/T1104\(2\).png](https://ikoyama.com/img/T1104(2).png)

TOYOTA HIACE 5L COMMUTER VAN 05/UP

TRAPECIO DEL LH SUP 48067-29225

T1104



<https://ikoyama.com/img/T1105.png>

[https://ikoyama.com/img/T1105\(2\).png](https://ikoyama.com/img/T1105(2).png)

TOYOTA HIACE 5L COMMUTER VAN 05/UP

TRAPECIO DEL RH SUP 48066-29225

T1105



<https://ikoyama.com/img/T1085.png>

[https://ikoyama.com/img/T1085\(2\).png](https://ikoyama.com/img/T1085(2).png)

TOYOTA HILUX 1GD 2GD 15/UP

TRAPECIO DEL LH INF 48069-0K090

T1085



<https://ikoyama.com/img/T1085M.png>

[https://ikoyama.com/img/T1085M\(2\).png](https://ikoyama.com/img/T1085M(2).png)

TOYOTA HILUX 1GD 2GD 15/UP

TRAPECIO DEL LH INF 48069-0K090

T1085M


<https://ikoyama.com/img/T1086.png>
[https://ikoyama.com/img/T1086\(2\).png](https://ikoyama.com/img/T1086(2).png)

TOYOTA HILUX 1GD 2GD 15/UP

TRAPECIO DEL RH INF 48068-0K090

T1086
<https://ikoyama.com/img/T1086M.png>
[https://ikoyama.com/img/T1086M\(2\).png](https://ikoyama.com/img/T1086M(2).png)

TOYOTA HILUX 1GD 2GD 15/UP

TRAPECIO DEL RH INF 48068-0K090

T1086M
<https://ikoyama.com/img/T1083.png>
[https://ikoyama.com/img/T1083\(2\).png](https://ikoyama.com/img/T1083(2).png)

TOYOTA HILUX 1KD 2KD 05/14

TRAPECIO DEL LH INF 48069-0K040

T1083
<https://ikoyama.com/img/T1084.png>
[https://ikoyama.com/img/T1084\(2\).png](https://ikoyama.com/img/T1084(2).png)

TOYOTA HILUX 1KD 2KD 05/14

TRAPECIO DEL RH INF 48068-0K040

T1084
<https://ikoyama.com/img/T1081.png>
[https://ikoyama.com/img/T1081\(2\).png](https://ikoyama.com/img/T1081(2).png)

TOYOTA HILUX 1KD 2KD 1GD 2GD 05/UP

TRAPECIO DEL LH SUP 48630-0K040

T1081
<https://ikoyama.com/img/T1082.png>
[https://ikoyama.com/img/T1082\(2\).png](https://ikoyama.com/img/T1082(2).png)

TOYOTA HILUX 1KD 2KD 1GD 2GD 05/UP

TRAPECIO DEL RH SUP 48610-0K040

T1082
<https://ikoyama.com/img/T1158.png>
[https://ikoyama.com/img/T1158\(2\).png](https://ikoyama.com/img/T1158(2).png)

TOYOTA RAV4 06/12

TRAPECIO DEL DER 48068-42050

T1158
<https://ikoyama.com/img/T1157.png>
[https://ikoyama.com/img/T1157\(2\).png](https://ikoyama.com/img/T1157(2).png)

TOYOTA RAV4 06/12

TRAPECIO DEL IZQ 48069-42050

T1157



<https://ikoyama.com/img/T1239.png>

[https://ikoyama.com/img/T1239\(2\).png](https://ikoyama.com/img/T1239(2).png)

TOYOTA RAV4 06/18

BRAZO CONTROL SUPERIOR POS LH 48790-42020

T1239



<https://ikoyama.com/img/T1238.png>

[https://ikoyama.com/img/T1238\(2\).png](https://ikoyama.com/img/T1238(2).png)

TOYOTA RAV4 06/18

BRAZO CONTROL SUPERIOR POS RH 48770-42040

T1238



<https://ikoyama.com/img/T1232.png>

[https://ikoyama.com/img/T1232\(2\).png](https://ikoyama.com/img/T1232(2).png)

TOYOTA RAV4 13/18

TRAPECIO DEL LH 4806942060

T1232



<https://ikoyama.com/img/T1233.png>

[https://ikoyama.com/img/T1233\(2\).png](https://ikoyama.com/img/T1233(2).png)

TOYOTA RAV4 13/18

TRAPECIO DEL RH 4806842060

T1233



<https://ikoyama.com/img/T1235.png>

[https://ikoyama.com/img/T1235\(2\).png](https://ikoyama.com/img/T1235(2).png)

TOYOTA RUSH 18/UP

TRAPECIO DEL LH 48069-BZ390

T1235



<https://ikoyama.com/img/T1234.png>

[https://ikoyama.com/img/T1234\(2\).png](https://ikoyama.com/img/T1234(2).png)

TOYOTA RUSH 18/UP

TRAPECIO DEL RH 48068-BZ390

T1234



<https://ikoyama.com/img/T1091.png>

[https://ikoyama.com/img/T1091\(2\).png](https://ikoyama.com/img/T1091(2).png)

TOYOTA YARIS 06/13

TRAPECIO DEL LH 48069-59095

T1091



<https://ikoyama.com/img/T1092.png>

[https://ikoyama.com/img/T1092\(2\).png](https://ikoyama.com/img/T1092(2).png)

TOYOTA YARIS 06/13

TRAPECIO DEL RH 48068-59095

T1092



<https://ikoyama.com/img/T1098.png> [https://ikoyama.com/img/T1098\(2\).png](https://ikoyama.com/img/T1098(2).png)

TOYOTA YARIS 2NZ 3NZ VITZ PROBOX 12mm 99/05

TRAPECIO DEL LH INF 48069-59035

T1098



<https://ikoyama.com/img/T1099.png> [https://ikoyama.com/img/T1099\(2\).png](https://ikoyama.com/img/T1099(2).png)

TOYOTA YARIS 2NZ 3NZ VITZ PROBOX 12mm 99/05

TRAPECIO DEL RH INF 48068-59035

T1099



<https://ikoyama.com/img/T1100.png> [https://ikoyama.com/img/T1100\(2\).png](https://ikoyama.com/img/T1100(2).png)

TOYOTA YARIS 2NZ 3NZ VITZ PROBOX 14mm 99/05

TRAPECIO DEL LH INF 48069-59055

T1100



<https://ikoyama.com/img/T1101.png> [https://ikoyama.com/img/T1101\(2\).png](https://ikoyama.com/img/T1101(2).png)

TOYOTA YARIS 2NZ 3NZ VITZ PROBOX 14mm 99/05

TRAPECIO DEL RH INF 48068-59055

T1101



<https://ikoyama.com/img/T1102.png> [https://ikoyama.com/img/T1102\(2\).png](https://ikoyama.com/img/T1102(2).png)

TOYOTA YARIS ENVIDIA 14/22 ETIOS 17/UP

TRAPECIO DEL LH 48069-09240

T1102



<https://ikoyama.com/img/T1103.png> [https://ikoyama.com/img/T1103\(2\).png](https://ikoyama.com/img/T1103(2).png)

TOYOTA YARIS ENVIDIA 14/22 ETIOS 17/UP

TRAPECIO DEL RH 48068-09240

T1103



<https://ikoyama.com/img/T1093.png> [https://ikoyama.com/img/T1093\(2\).png](https://ikoyama.com/img/T1093(2).png)

VW GOL 08/23 SAVEIRO 15/23 CROSF0X 12/21

TRAPECIO DEL LH S/ROTULA 5U0 407 151 B

T1093



<https://ikoyama.com/img/T1094.png> [https://ikoyama.com/img/T1094\(2\).png](https://ikoyama.com/img/T1094(2).png)

VW GOL 08/23 SAVEIRO 15/23 CROSF0X 12/21

TRAPECIO DEL RH S/ROTULA 5U0 407 152 B

T1094



<https://ikoyama.com/img/T1095.png>

[https://ikoyama.com/img/T1095\(2\).png](https://ikoyama.com/img/T1095(2).png)

VW GOL METROPOLITANO 04/ON

TRAPECIO DEL RH LH S/ROTULA 305407155

T1095

Especialistas en:

CREMALLERAS



 **KOYAMA**
SUSPENSION PARTS


<https://ikoyama.com/img/SRCH001.png>

CHEVROLET N300 MINI VAN 10/14

CREMALLERA MECANICA 24509397

SRCH001
[https://ikoyama.com/img/SRCH001\(2\).png](https://ikoyama.com/img/SRCH001(2).png)
<https://ikoyama.com/img/SRCH002.png>

CHEVROLET SAIL 10/14

CREMALLERA HIDRAULICA 9013810

SRCH002
[https://ikoyama.com/img/SRCH002\(2\).png](https://ikoyama.com/img/SRCH002(2).png)

<https://ikoyama.com/img/SRDA001.png>

DAEWOO TICO F8C

CREMALLERA MECANICA 48500A78B01000

SRDA001
[https://ikoyama.com/img/SRDA001\(2\).png](https://ikoyama.com/img/SRDA001(2).png)

<https://ikoyama.com/img/SRHY004.png>

HYUNDAI ACCENT 11/14 ELECTRONICA

CREMALLERA ASISTIDA 56500-1E500

SRHY004
[https://ikoyama.com/img/SRHY004\(2\).png](https://ikoyama.com/img/SRHY004(2).png)

<https://ikoyama.com/img/SRHY002.png>

HYUNDAI ACCENT/KIA RIO 06/10

CREMALLERA HIDRAULICA 57700-1E100

SRHY002
[https://ikoyama.com/img/SRHY002\(2\).png](https://ikoyama.com/img/SRHY002(2).png)

<https://ikoyama.com/img/SRHY001.png>

HYUNDAI ACCENT/KIA RIO 11/UP

CREMALLERA ASISTIDA 56500-1R001

SRHY001
[https://ikoyama.com/img/SRHY001\(2\).png](https://ikoyama.com/img/SRHY001(2).png)

<https://ikoyama.com/img/SRHY003.png>

HYUNDAI ELANTRA 13/UP

CREMALLERA ASISTIDA 56500-3X200

SRHY003
[https://ikoyama.com/img/SRHY003\(2\).png](https://ikoyama.com/img/SRHY003(2).png)

<https://ikoyama.com/img/SRHY010.png>

HYUNDAI GRAND I10 15/19

CREMALLERA ASISTIDA 56500-B4500

SRHY010
[https://ikoyama.com/img/SRHY010\(2\).png](https://ikoyama.com/img/SRHY010(2).png)



<https://ikoyama.com/img/SRKI001.png>
HYUNDAI/KIA i10 11/UP PICANTO 08/10
CREMALLERA MECANICA 56500-07000

SRKI001



<https://ikoyama.com/img/SRKI002.png>
KIA CERATO 14/20
CREMALLERA ASISTIDA 56500-A7100

SRKI002



[https://ikoyama.com/img/SRKI002\(2\).png](https://ikoyama.com/img/SRKI002(2).png)



<https://ikoyama.com/img/SRHY005.png>
KIA RIO 11/13 MECANICA
CREMALLERA MECANICA 56500-1W100

SRHY005



[https://ikoyama.com/img/SRHY005\(2\).png](https://ikoyama.com/img/SRHY005(2).png)



<https://ikoyama.com/img/SRMI001.png>
MITSUBISHI L200 DKR 04/14
CREMALLERA HIDRAULICA MR333500

SRMI001



[https://ikoyama.com/img/SRMI001\(2\).png](https://ikoyama.com/img/SRMI001(2).png)



<https://ikoyama.com/img/SRMI002.png>
MITSUBISHI L200 DKR 15/UP
CREMALLERA HIDRAULICA 4410A603

SRMI002



[https://ikoyama.com/img/SRMI002\(2\).png](https://ikoyama.com/img/SRMI002(2).png)



<https://ikoyama.com/img/SRNI004.png>
NISSAN NAVARA
CREMALLERA HIDRAULICA 49001-JR800

SRNI004



[https://ikoyama.com/img/SRNI004\(2\).png](https://ikoyama.com/img/SRNI004(2).png)



<https://ikoyama.com/img/SRNI002.png>
NISSAN SENTRA B13 SUNNY
CREMALLERA HIDRAULICA 48001-Q5600

SRNI002



<https://ikoyama.com/img/SRNI001.png>
NISSAN SENTRA B13 SUNNY
CREMALLERA MECANICA 48001-50A00

SRNI001



<https://ikoyama.com/img/SRNI008.png> [https://ikoyama.com/img/SRNI008\(2\).png](https://ikoyama.com/img/SRNI008(2).png)
NISSAN URVAN NV350 12/UP T/ALTO
CREMALLERA HIDRAULICA 49001-3XT0B **SRNI008**



<https://ikoyama.com/img/SRNI003.png> [https://ikoyama.com/img/SRNI003\(2\).png](https://ikoyama.com/img/SRNI003(2).png)
NISSAN VERSA 12/16
CREMALLERA ASISTIDA 48001-9KE1B **SRNI003**



<https://ikoyama.com/img/SRSK001.png> [https://ikoyama.com/img/SRSK001\(2\).png](https://ikoyama.com/img/SRSK001(2).png)
SUZUKI APV 05/23
CREMALLERA HIDRAULICA 48500-61J51 **SRSK001**



<https://ikoyama.com/img/SRSK003.png> [https://ikoyama.com/img/SRSK003\(2\).png](https://ikoyama.com/img/SRSK003(2).png)
SUZUKI GRAND VITARA 06/14 GRAND NOMADE 08/19
CREMALLERA HIDRAULICA 48580-65J51 **SRSK003**



<https://ikoyama.com/img/SRTO013.png> [https://ikoyama.com/img/SRTO013\(2\).png](https://ikoyama.com/img/SRTO013(2).png)
TOYOTA AE140 COROLLA 07/14
CREMALLERA HIDRAULICA 45510-12450 **SRTO013**



<https://ikoyama.com/img/SRTO012.png> [https://ikoyama.com/img/SRTO012\(2\).png](https://ikoyama.com/img/SRTO012(2).png)
TOYOTA AVANZA F651 F652 12/18
CREMALLERA ASISTIDA 45510-BZ130 **SRTO012**



<https://ikoyama.com/img/SRTO011.png> [https://ikoyama.com/img/SRTO011\(2\).png](https://ikoyama.com/img/SRTO011(2).png)
TOYOTA COROLLA 04/UP
CREMALLERA HIDRAULICA 44250-12760 **SRTO011**



<https://ikoyama.com/img/SRTO001.png> [https://ikoyama.com/img/SRTO001\(2\).png](https://ikoyama.com/img/SRTO001(2).png)
TOYOTA COROLLA AE100 ORIGINAL
CREMALLERA MECANICA 45510-12170 **SRTO001**



<https://ikoyama.com/img/SRT0002.png> [https://ikoyama.com/img/SRT0002\(2\).png](https://ikoyama.com/img/SRT0002(2).png)
TOYOTA COROLLA AE101
 CREMALLERA HIDRAULICA 44250-12560 **SRT0002**



<https://ikoyama.com/img/SRT0010.png> [https://ikoyama.com/img/SRT0010\(2\).png](https://ikoyama.com/img/SRT0010(2).png)
TOYOTA HIACE 3L 90/95 MECANICA
 CREMALLERA MECANICA 45510-26020 **SRT0010**



<https://ikoyama.com/img/SRT0004.png> [https://ikoyama.com/img/SRT0004\(2\).png](https://ikoyama.com/img/SRT0004(2).png)
TOYOTA HIACE 5L LH202 BAJO
 CREMALLERA HIDRAULICA 44200-26530 **SRT0004**



<https://ikoyama.com/img/SRT0008.png> [https://ikoyama.com/img/SRT0008\(2\).png](https://ikoyama.com/img/SRT0008(2).png)
TOYOTA HIACE 5L LONGER
 CREMALLERA HIDRAULICA 44200-26550 **SRT0008**



<https://ikoyama.com/img/SRT0007.png> [https://ikoyama.com/img/SRT0007\(2\).png](https://ikoyama.com/img/SRT0007(2).png)
TOYOTA HILUX REVO 1GD 2GD 15/UP 16mm
 CREMALLERA HIDRAULICA 44250-0K730 **SRT0007**



<https://ikoyama.com/img/SRT0005.png> [https://ikoyama.com/img/SRT0005\(2\).png](https://ikoyama.com/img/SRT0005(2).png)
TOYOTA HILUX VIGO 1KD 2KD 04/14
 CREMALLERA HIDRAULICA 44250-0K040 **SRT0005**



<https://ikoyama.com/img/SRT0016.png> [https://ikoyama.com/img/SRT0016\(2\).png](https://ikoyama.com/img/SRT0016(2).png)
TOYOTA RAV4 12/18
 CREMALLERA ASISTIDA 45510-42160 **SRT0016**



<https://ikoyama.com/img/SRT0003.png> [https://ikoyama.com/img/SRT0003\(2\).png](https://ikoyama.com/img/SRT0003(2).png)
TOYOTA YARIS 06/13 NCP
 CREMALLERA MECANICA 45510-52140 **SRT0003**



<https://ikoyama.com/img/SRTO009.png> [https://ikoyama.com/img/SRTO009\(2\).png](https://ikoyama.com/img/SRTO009(2).png)
 TOYOTA YARIS 14/UP
 CREMALLERA MECANICA 45510-0D550
SRTO009



<https://ikoyama.com/img/SRVW002.png> [https://ikoyama.com/img/SRVW002\(2\).png](https://ikoyama.com/img/SRVW002(2).png)
 VOLKSWAGEN BORA 01/15 GOLF IV
 CREMALLERA HIDRAULICA 1J1 422 062 E
SRVW002



 **KOYAMA**®
SUSPENSION PARTS

www.ikoyama.com

[@koyama.peru](https://www.instagram.com/koyama.peru)

